

# भारत का राजपत्र The Gazette of India

प्राधिकार से प्रकाशित  
PUBLISHED BY AUTHORITY

सं. 2] नई दिल्ली, शनिवार, जनवरी 9, 1993/पौष 19, 1914  
No. 2] NEW DELHI, SATURDAY, JANUARY 9, 1993/PAUSA 19, 1914

इस भाग में भिन्न पृष्ठ संख्या दी जाती है जिससे कि यह अलग संकलन के रूप में  
रखा जा सके

Separate Paging is given to this Part in order that it may be filed as  
a separate compilation

## भाग II—खण्ड 3—उप-खण्ड (ii) PART II—Section 3—Sub-Section (ii)

भारत सरकार के मंत्रालयों (रक्षा मंत्रालय को छोड़कर) द्वारा जारी किये गये सांविधिक आदेश और अधिसूचनाएं  
Statutory Orders and Notifications issued by the Ministries of the Government of India (other than  
the Ministry of Defence)

कार्मिक, लोक निकायन तथा पेंशन मंत्रालय  
(कार्मिक और प्रशिक्षण विभाग)

MINISTRY OF PERSONNEL, P.G. & PENSIONS  
(Deptt. of Personnel & Training)

आदेश

ORDER

नई दिल्ली, 23 दिसम्बर, 1992

New Delhi, the 23rd December, 1992

का.आ. 56.—केन्द्रीय सरकार, दिल्ली विशेष पुलिस स्थापन अधिनियम, 1946 (1946 का अधिनियम सं. 25) की धारा 6 के साथ पठित धारा 3 की उपधारा (1) द्वारा प्रदत्त शक्तियों का प्रयोग करने हुए, उत्तर प्रदेश सरकार, सचिवालय लखनऊ की सहमति से, जो आदेश सं. 321-जी-6-पी-3-5 (37)/92 तारीख 27-9-92 द्वारा दी गई थी दिल्ली विशेष पुलिस स्थापन के सदस्यों की शक्तियों और अधिकारिता का विस्तार भारतीय दंड संहिता 1860 (1860 का अधिनियम सं. 45) की धारा 409, 419, 420 और 468 के अधीन दंडनीय अपराध और उक्त अपराधों के संबंध में या उगसे संभव प्रयत्न, बुद्धिगम और षड्यंत्र तथा उक्त दण्डों से उत्पन्न होने वाले ऐसे ही संभव्यता के अन्तर्गत में पुलिस बाना कवि नगर, जिला गाजियाबाद, उत्तर प्रदेश के अपराध मामलों में 93/92 (उच्च स्तर दूर संचार प्रशिक्षण केंद्र गाजियाबाद कपट संबंधी मामला) की बाबत किए गए किसी अन्य अपराधों के अन्वेषण के लिए संपूर्ण उत्तर प्रदेश राज्य पर करती है।

S.O. 56—In exercise of the powers conferred by sub-section (1) of section 5, read with section 6 of the Delhi Special Police Establishment Act, 1946 (Act 25 of 1946), the Central Government, with the consent of the Government of Uttar Pradesh Secretariat, Lucknow, accorded vide No. 321-G-I/VI-P-3-5(37)8/92 dated 27-9-1992 hereby extends the powers and jurisdiction of the members of the Delhi Special Police Establishment to the whole of the State of Uttar Pradesh for investigation of offences punishable U/s. 409, 419, 420 and 468 of Indian Penal Code 1860 (Act 45 of 1860) and attempts abetments and conspiracies in relation to or in connection with the said offences and any other offences committed in the course of the same transactions arising out of the same facts, in regard to case in crime No. 93/92 (Advanced Level Telecom Training Centre, Ghaziabad, fraud case) of Police Station, Kavi Nagar, Distt. Ghaziabad, Uttar Pradesh.

[संख्या 228/12/92-ए.सी.-II]

[No. 228/12/92-AVD.II]

ए. सी. शर्मा, अवसर सचिव

A. C. SHARMA, Under Secy.

नई दिल्ली, 23 दिसम्बर, 1992

क्र.आ. 57.—केन्द्रीय सरकार, दिल्ली विशेष पुलिस स्थापन अधिनियम, 1946 (1946 का 25) की धारा 6 के साथ जोड़त धारा 5 की उपधारा (1) द्वारा प्रदत्त शक्तियों का प्रयोग करते हुए, (जी.आर.-V) विभाग के आदेश स. एफ. 24(8)गृह/जी. आर.-5/92 तारीख 23-10-92 द्वारा प्राप्त राजस्थान सरकार की सहमति से आना बर्से, जिला जयपुर में भारतीय दंड संहिता, 1860 (1860 का अधिनियम 45) की धारा 323, 376, 379 और 147 के अधीन रजिस्ट्रीकृत मामला सं. 399/92 या उक्त मामले से उत्पन्न बैसे ही संव्यवहार क मनुकम में किए गए अन्य अपराध के संबंध में धन्येयण के लिए दिल्ली विशेष पुलिस स्थापन के सदस्यों की शक्तियों और अधिकारिता का विस्तार संवृण राजस्थान राज्य पर करती है।

[संख्या 228/60/92-ग.पो.जी.-II]

ए.सी. शर्मा, अवर सचिव

New Delhi, the 23rd December, 1992

S.O. 57.—In exercise of the powers conferred by sub-section (1) of Section 5 read with Section 6 of the Delhi Special Police Establishment Act, 1946 (Act No. 25 of 1946) the Central Government with the consent of the State Government of Rajasthan vide Home (Gr. V) Department Order No. F. 24(8)Home/Gr. V/92 dated 23-10-92 hereby extends the powers and jurisdiction of the members of the Delhi Special Police Establishment to the whole of the State of Rajasthan for investigation of case No. 399/92 under Sections 323, 376, 379 and 147 Indian Penal Code, 1860 (Act No. 45 of 1860) registered at Police Station Bassi District Jaipur of the Code of Criminal Procedure Code (Act No. 2 of 1974), or any other offences committed in the course of same transaction arising out of the said case.

[No. 228/60/92-AVD.II]

A. C. SHARMA, Under Secy.

दिल्ली मंत्रालय

(आर्थिक कार्य विभाग)

(बैंकिंग प्रभाग)

नई दिल्ली, 22 दिसम्बर, 1992

क्र.आ. 68.—राष्ट्रीयकृत बैंक (प्रबंध और प्रकीर्ण उपबंध)स्कीम, 1970 के खंड 9 के साथ पठित खंड 3 के उपखंड (ग) के अनुसरण में केन्द्रीय सरकार, भारतीय रिजर्व बैंक से परामर्श करने के पश्चात्, एन.ए.आर. वसंत में इलाहाबाद बैंक के मुरादपुर शाखा, पटना में तैनात श्री कमला प्रसाद राय, प्रबंधक (एम. एम. जी. सेक्शन-iii) को 22 दिसम्बर, 1992 से तीन वर्ष की अवधि के लिए या जब तक वे इलाहाबाद बैंक के एक अधिष्ठाता रूप में अपनी सेवा छोड़ नहीं देते, इनमें से जो भी पहले हो, इलाहाबाद बैंक के निदेशक संज्ञ में निदेशक के रूप में नियुक्त करती है।

[सं. एक 9/13/91-पी.ओ.-1]

एम. एस. सानागमन, अवर सचिव

MINISTRY OF FINANCE

(Department of Economic Affairs)

(Banking Division)

New Delhi, the 22nd December, 1992

S.O. 58.—In pursuance of sub-clause (c) of clause 3 read with clause 9 of the Nationalised Banks (Management and Miscellaneous Provisions) Scheme, 1970, the Central Government, after consultation with the Reserve Bank of India, hereby appoints Shri Kamala Prasad Rai, Manager (MMG

Scale-III) presently posted at Muradpur Branch, Patna, Allahabad Bank, as a Director on the Board of Allahabad Bank with effect from the 22nd December, 1992 for a period of three years or until he ceases to be an officer of Allahabad Bank whichever is earlier.

[No. F. 9/13/91-B.O.I.]

M. S. SEETHARAMAN, Under Secy.

नई दिल्ली, 23 दिसम्बर, 1992

क्र.आ.59: राष्ट्रीयकृत बैंक (प्रबंध तथा प्रकीर्ण उपबंध) स्कीम, 1970 के खंड 9 के उपखंड (2) के साथ पठित खंड 3 के उपखंड (ख) के अनुसरण में केन्द्रीय सरकार एन.ए.आर. वसंत, विशेष सहायक, ओरिएंटल बैंक ऑफ़ कामर्स, प्रदात कार्यालय, नई दिल्ली को दिनांक 23 दिसम्बर, 1992 से 22 दिसम्बर, 1993 तक की तीन वर्ष की अवधि के लिये या जब तक वे ओरिएंटल बैंक ऑफ़ कामर्स के एक कार्यवाही के रूप में अपनी सेवा छोड़ नहीं देते हैं, उनमें से जो भी पहले हो, श्री योग राज गुप्त, जो भारत सरकार, वित्त मंत्रालय, आर्थिक कार्य विभाग (बैंकिंग प्रभाग) की अधिसूचना सं. एक. 15/2/89-आई.आर. दिनांक 1-8-1989 के अनुसरण में नियुक्त किए गये थे, के पदान पर ओरिएंटल बैंक ऑफ़ कामर्स के निदेशक बोर्ड में निदेशक नियुक्त करती है।

[सं. 15/2/92-आई.आर.]

सतपाल भाटिया, अवर सचिव

New Delhi, the 23rd December, 1992

S.O. 59.—In pursuance of sub-clause (b) of Clause 3 read with sub-clause (2) of Clause 9 of the Nationalised Banks (Management and Miscellaneous Provisions) Scheme, 1980 the Central Government hereby appoints Shri S. M. Burman, Special Assistant, Oriental Bank of Commerce, Head Office, New Delhi as a Director on the Board of Directors of Oriental Bank of Commerce for a period of three years with effect from 23rd December, 1992 to 22nd December, 1995 or until he ceases to be an employee of Oriental Bank of Commerce whichever is earlier in the place of Shri Yog Raj Gupta appointed under Notification of Government of India, Ministry of Finance, Department of Economic Affairs (Banking Division) No. F. 15/2/89-IR dated the 1st August, 1989.

[No. F. 15/2/92-IR]

S. P. BHATIA, Under Secy

केन्द्रीय उत्पाद शुल्क समन्वयक

अधिसूचना सं. 10/1992

नागपुर, 18 दिसम्बर, 1992

क्र.आ. 60:—श्री सी. जी. सोनिकके, अधीक्षक, केन्द्रीय उत्पाद शुल्क समूह "ब" समन्वयक नागपुर विस्तार की मांग प्राप्त करने पर दिनांक 30-11-1992 को उपरान्त में शासकीय सेवा में निवृत्त हुए।

[प. ग. 11(3)3/92/स्थापना-1/27798]

हरजिंदर सिंह, उप समन्वयक

(आमिष एवं सनकना)

CENTRAL EXCISE COLLECTORATE

NOTIFICATION NO. 10/1992

Nagpur, the 18th December, 1992

S.O. 60.—Shri C. G. Sonikke, Superintendent, Central Excise Group 'B' of Nagpur Collectorate having attained the age of Superannuation retired from Government service on 30-11-1992 in the Afternoon.

[C. No. II(3)3/92 'Estt. I/27798]

HARJINDER SINGH, Dy. Collector (Per. and Vig.)

मानव संसाधन विकास मंत्रालय

(शिक्षा विभाग)

नई दिल्ली, 22 दिसंबर, 1992

MINISTRY OF HUMAN RESOURCE DEVELOPMENT

(Deptt. of Education)

New Delhi, the 22nd December, 1992

का.प्र. 61.—केन्द्रीय सरकार राजभाषा (संघ के सरकारी प्रयोजनों के लिए प्रयोग) नियम 1976 के नियम 10 के उप-नियम (4) के अनुसरण में मानव संसाधन विकास मंत्रालय (शिक्षा विभाग) के निम्नलिखित स्थापन संगठन को जिसमें 80% से अधिक कर्मचारियों ने हिंदी के कार्ये साधक ज्ञान प्राप्त कर लिया है, अभिलेखित करती है:—

भारतीय औद्योगिक संस्थान,  
हौज खास, नई दिल्ली-110 016

[सं. 11011/2/92-रा.पा. ए.]

रमेश कुमार आंगिरस, निदेशक  
(राजभाषा)

S.O. 61.—In pursuance of sub-rule (4) of Rule 10 of the Official Languages (use for official purposes of the Union) Rules, 1976, the Central Government hereby notifies the following autonomous organisation of the Ministry of Human Resource Development (Deptt. of Education), more than 80 per cent staff of which has acquired working knowledge of Hindi :—

Indian Institute of Technology,  
Hauz Khas,  
New Delhi-110016.

[No. 11011/2/92-OLU]

R. K. ANGIRAS, Director (O.L.)

## MINISTRY OF COAL

## CORRIGENDUM

New Delhi, the 21st December, 1992

S.O.—62— In the notification of the Government of India in the Ministry of Coal Number S.O. 924(E) dated the 27th December, 1991, published in the Gazette of India, Extraordinary, Part-II, Section-3, Sub-section(ii) dated the 27th December, 1991, the following corrections are made:—

S.No.	Page Number	Reference	For	Read
1	2	3	4	5
1.	9	In notification, line 1	force—	force
2.	9	Table-1, Serial Number 1, Column 2, line 3 and 4	the Union Territory of Arunachal Pradesh	Arunachal Pradesh
3.	10	Table-1, Serial Number 2, line 2 and 3	the Union Territory of Arunachal Pradesh.	Arunachal Pradesh
4.	10	Table-I, Serial number 4, Column 2, line I	Weekly	Weakly
5.	11	Notes, item 1 (i) line 1 (ii) line 3	ben ben	been been
6.	11	Notes, item 2: (i) line 1 (ii) line 3	'Blendable coals 'semi coking'	'Blendable coals' 'semi coking'
7.	11	Notes, item 4, line 1, after the words "formula"	;	:
8.	11	Notes, item 4, line 7 after the word "reduced"	of	by
9.	11	Notes, item 4, line 10	causes	clauses
10.	11	Notes, item 5, line 2	equilibrative	equilibrating
11.	11	Notes, item 5, line 3	40°C	40°C
12.	11	Notes, Point 6, in table: (i) in column heading 1 (ii) in column heading 2	Grou olatile	Group volatile
13.	12	Table II, Serial number 1, column 1, line 2	Union Territory of Arunachal Pradesh	Arunachal Pradesh.

1.	2	3	4	5	1
14.	12	Table II, Serial number 2, column 1, line 2	Meghalaya	Meghalaya,	
15.	12	Table II, serial number 2, column 1, line 2 and 3	Union Territory of Arunachal Pradesh	Arunachal Pradesh	
16.	13	Table II, serial number 4, column 1, line 1 and 2	Union Territory of Arunachal Pradesh.	Arunachal Pradesh	
17.	13	Table IV, headline	WEEKLY	WEAKLY	
18.	14	Notes, item 2, line 1	comprising	comprising of	
19.	14	Notes, item 5, line 2	segregation/into	segregation into	
20.	14	Notes, item 6(i), line 3, between 'at the' and 'ratio'.	average rate of prices of steam and slack coal in these		
21.	14	Notes, item 7, line 1	weekly	weakly	
22.	14	Notes, item 8, line 2	Rs	Re	
23.	15	Notes, item 9 (ii) , line 1 and 2	Union Territory of Arunachal Pradesh.	Arunachal Pradesh	
24.	15	Notes, item 9(ii), line 2	Per tonne,	per tonne	
25.	15	Notes; item 11, line 2	bodies;	bodies,	
26.	15	Notes, item 12: (i) line 1 (ii) line 3 (iii) line 4 (iv) line 7	hard coke soft coke ad coal 1.35	Hard Coke Soft Coke and Coal by 1.35	
27.	15	Notes, item 16, line 1	soft coke	Soft Coke	
28.	15	Notes, item 16: (i) line 1 (ii) line 3	Beheive percent	Beehive percent	
29.	16	Notes, item 19: (i) line 1 (ii) line 3	price percent	prices percent,	
30.	16	Notes, item 20, line 3	Annexur	Annexure	
31.	16	ANNEXURE, Area-KENDA, under heading COLLIERY, line 8	Chora ODP	Chora OCP	
32.	16	ANNEXURE, Area-KAJORA, under heading COLLIERY, line 15	Jambac OCP	Jambad OCP	
33.	17	ANNEXURE, Area-BAIKUNTHPUR, under heading COLLIERY: (i) line 3 (ii) line 4	Bhatgaon OCP Bisrampur UG	Bhatgaon Bisrampur OCP Bisrampur UG	
34.	17	ANNEXURE, Area-CHIRIMIRI, Under heading COLLIERY; (i) line 11  (ii) line 12	CHIRIMIRI OC + Ug 1&3 CHIRIMIRI OC + Ug 2&4	CHIRIMIRI OC + UG 1&3 CHIRIMIRI OC + UG 2&4	

उद्योग मंत्रालय  
(भारी उद्योग विभाग)

नई दिल्ली, 11 दिसंबर, 1992

क्र.आ. 63.—केन्द्रीय सरकार, राजभाषा (संघ के मातृकीय प्रयोजनों के लिए प्रयोग) नियम, 1976 के नियम 10 के उप-नियम (4) के अनुसरण में निम्नलिखित कार्यालयों को, जिनके 80% कर्मचारियों ने हिन्दी का कार्यसाक्षक ज्ञान प्राप्त कर लिया है, अधिसूचित करती है :-

- (1) एच.एम.टी. लिमिटेड,  
पिजोर-134 101  
जिला—अम्बाला (हरियाणा)
- (2) एच.एम.टी. घड़ी कारखाना,  
रानीबाग—263 126  
नैनीताल (उत्तर प्रदेश)

[सं. ई-11012/(1)/92-हिंदी]

ओ. पी. शरवार, उप-सचिव

MINISTRY OF INDUSTRY  
(Department of Heavy Industry)

New Delhi, the 11th December, 1992

S.O. 63.—In pursuance of sub-rule (4) of rule 10 of the Official Languages (Use for official Purposes of the Union) Rules, 1976, the Central Government hereby notifies the following offices, the 80 per cent staff whereof have acquired the working knowledge of Hindi :—

1. H.M.T. Limited,  
Pinjore-134101  
Distt. Ambala (Haryana).
2. H.M.T. Watch Factory,  
Ranibag-263126  
NAINITAL (Uttar Pradesh).

[No. E-11012(1)/92-Hindi]

O. P. SHARVAR, Dy. Secy.

विद्युत मंत्रालय

नई दिल्ली, 21 दिसंबर, 1992

क्र.आ. 64.—भारतीय बिजली अधिनियम, 1910 (1910 का 9) की धारा 36(क) की उपधारा 2(क) के अनुसरण में केन्द्रीय सरकार, केन्द्रीय विद्युत् प्राधिकरण के अध्यक्ष श्री वार्ड. पी. गुप्ता को श्री हर्षण स्वरूप के स्थान पर केन्द्रीय विद्युत् बोर्ड का अध्यक्ष नामित करती है।

[संख्या 25/13/92-डी. (एम. ई. बी.)]

एम. एल. शर्मा, डैस्क अधिकारी

MINISTRY OF POWER

New Delhi, the 21st December, 1992

S.O. 64.—In pursuance of Sub-section 2(a) of Section 36A of the Indian Electricity Act, 1910 (9 of 1910), the Central Government is pleased to nominate Shri Y. P. Gambhir, Chairman, Central Electricity Authority as Chairman of the Central Electricity Board vice Shri Krishna Swarup.

[No. 25/13/92-D(SEB)]

M. L. SHARMA, Desk Officer

स्वास्थ्य और परिवार कल्याण मंत्रालय

नई दिल्ली, 15 दिसंबर, 1992

क्र.आ. 65.—केन्द्रीय सरकार, भारतीय आयुर्विज्ञान परिषद् अधिनियम, 1956 (1956 का 102) की धारा 11 की उपधारा (2) द्वारा प्रस्तुत शक्तियों का प्रयोग करने द्वारा, भारतीय आयुर्विज्ञान परिषद् से परामर्श करने के पश्चात्, उक्त अधिनियम की प्रथम अनुसूची में निम्नलिखित और संशोधन करती है, अर्थात् :—

- (1) प्रथम अनुसूची में, "मद्रास विश्वविद्यालय" शीर्षक के नीचे की प्रविष्टियों के पश्चात् निम्नलिखित प्रविष्टि अन्तःस्थापित की जाएगी, अर्थात् :—  
"डिप्लोमा इन मेडिसिन डी. एम. (ज. वि.)"  
(जठरांत्र विज्ञान)
- (2) "डॉ. एम. जी. भार. आयुर्विज्ञान विश्वविद्यालय, मद्रास" शीर्षक के नीचे की प्रविष्टियों के पश्चात् निम्नलिखित प्रविष्टि अन्तःस्थापित की जाएगी, अर्थात् :—  
"डिप्लोमा इन मेडिसिन डी. एम. (ज. वि.)"  
(जठरांत्र विज्ञान)
- (3) "महात्मा गांधी विश्वविद्यालय" शीर्षक के नीचे की प्रविष्टियों के पश्चात् निम्नलिखित प्रविष्टियाँ रखी जाएंगी, अर्थात् :—  
"डॉक्टर ऑफ मेडिसिन एम. डी. (सम. प्रा.)"  
(समुदाय आयुर्विज्ञान)  
"डॉक्टर ऑफ मेडिसिन एम. डी. (श.र.वि.)"  
(शरीर रचना विज्ञान)
- (4) "गोहाटी विश्वविद्यालय" शीर्षक के नीचे की प्रविष्टियों के पश्चात् निम्नलिखित प्रविष्टि रखी जाएगी, अर्थात् :—  
"डॉक्टर ऑफ मेडिसिन एम. डी. (स्वा. प्रा.)"  
(न्याय आयुर्विज्ञान)

[सं. वी. 11015/33/92-एम.ई. (यू.जी.)]

आर. विजयकुमारी, डैस्क अधिकारी

MINISTRY OF HEALTH & FAMILY WELFARE

(Department of Health)

New Delhi, the 15th December, 1992

S.O. 65.—In exercise of the powers conferred by sub-section (2) of section 11 of the Indian Medical Council Act, 1956 (102 of 1956), the Central Government after consulting the Medical Council of India hereby makes the following further amendments in the First Schedule to the said Act, namely :—

- (1) In the First Schedule, under the heading "UNIVERSITY OF MADRAS" after the entries, the following entry shall be inserted, namely :—  
"Diploma in Medicine (Gastroenterology) .. D.M. (Gastroenterology)"
- (2) under the heading "Dr. M.G.R. MEDICAL UNIVERSITY, MADRAS", after the entries, the following entry shall be inserted, namely :—  
"Diploma in Medicine (Gastroenterology) .. D.M. (Gastroenterology)"
- (3) under the heading "MAHATMA GANDHI UNIVERSITY", after the entries, the following entries shall be inserted, namely :—  
"Doctor of Medicine (Community Medicine) .. M. D. (Comm. Med.)"  
"Doctor of Medicine (Physiology) .. M.D. (Physiology)"

श्रीमान श्री. जयशंकर प्रसाद ने 1 जनवरी, 1991 को ज्ञान प्रतिष्ठान, 1952 की तारीख के अंतर्गत एक अधिसूचना जारी करके 13 जनवरी, 1993 को नए छात्रक कुर्बंवा के छात्रों को तथा परिस्थितिओं को ध्यान में रख कर ही प्रवेश किया था। इस कुर्बंवा में आश्रमशाला के निकट सहायक छात्रा में छः कक्षाओं की बात चली गई थी। श्री जी एन. विद्यार्थी

कहाविर में निरक्षरों का बहुत कम, आसानी से तथा प्रो. ए. ए. कोष प्रोविडर, खान इंजीनियरिंग, डिप्लोमा स्कुल आका भाईस, धनबाद को कोष स्थापना का निष्पत्ति (अन्वेषण) निपुणता किया गया था।

2. मैंने दुर्घटना स्थल के बारे में साथ 7 अक्टूबर, 1991 को चार स्वायत्त का कार्य प्रारंभ कर दिया। शीघ्र ही मैंने आसपास के पत्तों को सुनवाई की तथा स्वतंत्रता का प्रक्रिया निर्धारित की, तथा ही पत्तों को प्रदर्शनों के आधारों के अनुसार होने की प्रतीति प्रदान की।

3. कार्यकारी संघों के प्रतिनिधियों के संघ के लिए होने वाले सार्वभौमिक तथा पश्चिम बंगाल निवास सार्वभौमिक चुनावों में चुनाव सुदूर के कारण मैंने मई और जून, 1991 में सुनवाई की और तारीख निर्धारित नहीं की। चुनावों के हो जाने के बाद ही सवालों से पुछाछ तथा प्रत्यक्ष का कार्य शुरू हो सका। मैंने जुलाई से अक्टूबर, 1991 के बीच प्रत्यक्ष-मौल में सभी सवालों से पुछाछ की तथा निष्पत्तियों और कुछ सवालों के साथ एक बार फिर महावीर खान का दौरा किया, ताकि उन घटनाक्रमों की पुनः संरचना की जा सके जो दुर्घटना के लिए उत्तरदायी थे।

4. मुझे धर्म संज्ञापन में धर्म सचिव के कार्यों के अधिकृत प्राप्त स्वायत्तता निपुणता किया गया था। इसके बादजुलुस जुलाई से अक्टूबर, 1991 तक सुनवाई पूरी कर ली गई। पत्तों के विलीन तक नवंबर 1991 में प्रस्तुत किया उसके परधान मैंने साथ तथा पत्तों के निष्पत्ति के लिए निष्पत्तियों के साथ बैठक आयोजित की।

5. गोटे तीर पर महावीर कोलियरी में घासक दुर्घटना उस समय हुई जब 55 गीटर की गहराई में स्थित एक गैलरी किनारे काम चल रहा था। एक पुरानी, बेकार पड़ी हुई शीफ्ट जिसमें पानी भरा हुआ था से जुड़ गई। शीफ्ट के ऊपर स्थित ताल के पानी जमाव स्थलों से बहुत तेजी के साथ पानी अंदर आ रहा था। छः घण्टों की शान्त रही। उन ताल में विभिन्न स्थलों पर कार्य कर रहे 65 व्यक्ति फंसे गए क्योंकि उनके बाहर निकलने का रास्ता बंद हो गया था। उन व्यक्तियों ने कार्यस्थल के ऊंचाई वाले भाग में शरण ली, इस हिस्से में पानी नहीं आ। उन्हें दुर्घटना के लगभग 75 घंटे के भीतर बाहर निकाला गया। इसके लिए स्थानीय तौर पर निर्मित उम्पात के मैकेनिक को गहराया वेनी पड़ी जिसे एक पहिए को सहायता से इस कार्य के लिए भूमि में फेंक बड़े छिद्र के माध्यम से खान में उतारा गया था। इस अस्थिर स्थिति कार्य ने, जिसे पहली बार भारत में इस्तेमाल किया गया और जेम्स हवसे पहले संसार में कही थी इसी की नींव पर प्रयोग नहीं किया गया।

संसार माध्यम का बहुत अधिक ध्यान आकर्षित किया गया।

6. मेरा मानना है कि घासक दुर्घटना का कारण उस गली में जिस में खनन कार्य चल रहा था और उसका खनन करने हुए एक पुरानी बेकार, पानी से भरी शीफ्ट की ओर बढ़ा जा रहा था, में एक केन्द्रीय तथा पार्श्व छिद्र (बोर होल) की व्यवस्था का न होना था। अगर हमने से ही ऐसा बोर होल होता तो खान के अधिकारियों का मानना ही था कि पानी से भरी शीफ्ट के बारे में पूर्व चेतावनी दे दी जाती और दुर्घटना टल जाती। कोयला खान विनियम, 1957 के विनियम 127 में प्रस्ताव ऐसे पड़ोस बोर होल का होगा अनिवार्य है। खान मुख्यालय निदेशालय द्वारा काम की अनुमति प्रदान करने हुए स्पष्ट रूप से कहा था कि इस प्रकार के बोर होल की व्यवस्था होगी चाहिए। इसके विनिरुद्ध गली उस क्षेत्र में बंद रही की निषेधन प्रस्ताव निषेधन। काम के लिए अनुमति नहीं किया था तबकि धर्म अनुमति होने से 100 मीटर आगे थी। घटनास्थल घासक दुर्घटना में अनुमति: क्षेत्र, जहाँ अंशतः अज्ञान के कारण जनवरी 1988 में काम शुरू हुआ था, की जेलरी में काम प्रारंभ होने के कारण एचि किया के बाद हो गई थी। इस प्रकार यह दुर्घटना पानी लापरवाही के कारण है जिसका जिम्मेदारी महावीर खान के एजेंट और प्रबंधन पर उनके धर्म काम करने वाले कुछ विरुद्ध अधिकारियों पर हुई।

7. यही यह प्रस्ताव प्रस्ताव किया होता कि पानी इस वर्गोष खानों और हमारे देश की कोयला खानों में पानी भर जाने के कारण हुई साथ बड़ी दुर्घटनाओं में कुछ समाधान है और का पानी भर जाने के कारण होने वाली दुर्घटनाओं तथा विनियमों की रोकथाम के लिए कोयला खान विनियम 1957 में आगे संशोधन अनिवार्य अपेक्षित है। संशोधन में यह पाया गया है कि पानी में सूचित कोयला खानों में पानी जमा होने के कारण हुई कुछ बड़ी दुर्घटनाएं निम्नलिखित हैं--

- (i) मूडन कोलियरी (मध्य प्रदेश) में 10 दिसंबर, 1954 को घटित दुर्घटना जिसमें 63 व्यक्तियों की मृत्यु हुई।
- (ii) सेकुल सिया कोलियरी (बिहार) में 20 फरवरी, 1958 को घटित दुर्घटना जिसमें 23 व्यक्तियों की मृत्यु हुई।
- (iii) दमुआ कोलियरी (मध्य प्रदेश) में 5 जनवरी, 1960 को घटित दुर्घटना जिसमें 16 व्यक्तियों की मृत्यु हुई।
- (iv) सितवांग कोलियरी (मध्य प्रदेश) में 19 नवंबर, 1975 को घटित दुर्घटना जिसमें 10 व्यक्तियों की मृत्यु हुई।
- (v) चाकुआला कोलियरी (बिहार) में 27 दिसंबर, 1975 को घटित दुर्घटना जिसमें 375 व्यक्तियों की मृत्यु हुई, और;
- (vi) हुल्लाडीह कोलियरी (बिहार) में 14 सितंबर, 1983 को घटित दुर्घटना जिसमें 19 व्यक्तियों की मृत्यु हुई। इन दुर्घटनाओं की जांच करने के उद्देश्य से निपुण जांच न्यायालय की रिपोर्टों में पता चलता है कि इसमें से अधिकांश दुर्घटनाएं परिहार्य मानवीय त्रुटियों और गंभीर लापरवाही के कारण हुई। जांच न्यायालयों में से कुछ की सिफारिशों के अनुसरण में भारत सरकार ने समय-समय पर कोयला खान नियमावली में संशोधन किया है। लेकिन दुर्घटनाओं के कारण लापरवाही और सांख्यिक विनियमों की अक्षमता के कारण निम्न कोयला खानों में पानी जमा हो जाने के कारण दुर्घटनाएं और विपदाएं होती रही हैं। प्रत्यक्ष में का विचार है कि इस दिशि में कोयला खान विनियम, 1957 में आगे किसी संशोधन में अपने आगे ऐसे दुर्घटनाएं बन्द नहीं हो पाएंगी और निम्न 127 के प्रावधानों का पालन नहीं किया गया था। इस घासक दुर्घटना को कण कहाता तो कुछ भिन्न नहीं है।

8. अंत में मैं यह कहना चाहूंगा कि मेरे प्रयास और उन लोगों के प्रयास जिन्होंने इस प्रति में मेरे साथ सहयोग किया है, सभी सफल माने जाएं यदि कोयला खान विनियम के संशोधन प्रावधानों का पालन कोयला खान के प्रबंधन और उनके कार्यपालकों द्वारा किया जाए और इस उद्देश्य के लिए आवश्यक आवश्यकता पैदा की जाए।

9. मैं न्यायिक प्रक्रिया की हार्दिक धन्यवाद देना चाहूंगा जिन्होंने बहुत धन्यवाद के साथ इस कार्य के लिए अपना बहुमूल्य समय दिया। मेरी प्रार्थना पक्षकारों का भी उनके हार्दिक सहयोग के लिए धन्यवाद देना चाहूंगा।

ह/-

(पी. आ. होला)

महावीर खान स्वायत्त  
धर्म सचिव प्रथम,  
रकी मार्ग, नई दिल्ली-110001

## विषय-सूची

अध्याय	विषय	पृष्ठ
I	जॉब न्यायालय	
1.1	भूमिका . . . . .	48-49
1.2	श्री के.पी. शर्मा का जॉब न्यायालय . . . . .	52
1.3	श्री पी.सी. होंडा का जॉब न्यायालय . . . . .	52
1.4	न्यायालय की प्रक्रिया . . . . .	53
1.5	न्यायालय में सूत्रबद्धी . . . . .	53
II	सामान्य सूचना	
2.1	महावीर खान . . . . .	54
2.2	प्रबंधन . . . . .	54
2.3	भू-विज्ञान . . . . .	54
2.4	इससे पूर्व का खनन कार्य . . . . .	54
2.5	वर्किंग . . . . .	55
III	कानून की समीक्षा	
3.1	कोयला खानों में जल भरने के खतरे के विरुद्ध सांविधिक उपबंध . . . . .	55
3.2	भारत . . . . .	55
3.3	विकसित देश . . . . .	56
IV	जल प्लावन विपदा	
4.1	भारत में जल प्लावन के कारण होने वाली दुर्घटना का सामान्य विश्लेषण . . . . .	56
4.2	जल प्लावन के कारण भारत में दुर्घटना प्रमुख दुर्घटना . . . . .	56-57
V	दुर्घटना	
5.1	दुर्घटना . . . . .	57
5.2	लापता व्यक्तियों की खानबीन . . . . .	59
5.3	सहायता कार्य . . . . .	59
VI	निरीक्षण	
6.1	दुर्घटना स्थल का प्रथम निरीक्षण . . . . .	59
6.2	भूतल निरीक्षण . . . . .	59
6.3	विशेष निरीक्षण . . . . .	59
6.4	निष्कर्ष . . . . .	59
VII	मृदे	
7.1	न्यायालय के समक्ष शिवाग्नीश विषय . . . . .	59
7.2	शापट नं. 34 का विस्तार . . . . .	60-61
7.3	पानी का सामान्य विश्लेषण . . . . .	61-62
7.4	पूर्व में स्थापित लंबा बोरहोल . . . . .	62-63
7.5	शामकाल की अनुमति . . . . .	63-64
7.6	एडवॉक बोरहोल . . . . .	64-65
7.7	दुर्घटना के संबंधित अन्य पृष्ठ . . . . .	65-66



अध्याय VIII	विषय कारण	विषय सूची	पृष्ठ
8.1	गवाही का विशेषण गाफ्ट नं. 34 का विस्तार		66
8.2	पानी का असामान्य रिसाव		66
8.3	40 डिग्री का पुनः चालू किया जाना		66
8.4	एडवॉस बोरहोलम		67
IX	उत्तरदायित्व		
9.1	उत्तरदायित्वों का विशेषण		67
9.2	एजेंट-मह-प्रबंधक		67-68
9.3	सुरक्षा अधिकारी		68
9.4	सहायक प्रबंधक		68
9.5	सर्वेक्षक		69
9.6	उच्चतर प्रबंधन		69
9.7	अन्य		69
X	निष्कर्ष		
10.1	निष्कर्षों का सारांश		70
10.2	सिफारिशें		70-71
10.3	खर्चों का वसूली		71
10.4	आभार		71
घटुबंधों की सूची			
अनुबंध संख्या			
1	13 नवंबर, 1989 को हुई पाठक दुर्घटना के कारण मारे गए व्यक्तियों की सूची		71
2	श्री के०सी० शर्मा की नियुक्ति की अधिसूचना		71
3	श्री पी०सी० होला की नियुक्ति की अधिसूचना		72
4	श्री पी०सी० होला द्वारा दी गई अंशदेकिता		72
5	श्री पी० सी० होला द्वारा पत्रकारों को जारी की गयी नोटिस		72
6	प्रबंधन के गवाहों की सूची		72
7	नृनिधन के गवाहों की सूची		73
8	न्यायालय के गवाहों की सूची		73
9	प्रबंधन के प्रदर्शों की सूची		73-74
10	नृनिधन के प्रदर्शों की सूची		75
11	महाभारत खान का वर्णन		75
12	कोषला खास विनियम, 1957 के विनियम 127 का मूखपाठ		75
13	दुर्घटना स्थल के फोटोपिक्त		77
14	उप पक्षियों और उनके प्रतिनिधियों के नाम जिन्होंने गवाहों की जाँच और उनके निष्कर्ष के प्रयुक्त शब्द संश्लेषों की सूची		77
ए.एस.पी.	--खान के परिष्कार की योजना		
सी.डी.एस.	--केन्द्रीय डिस्पेंसर पद्धति		
सी.एस.पी.	--केन्द्रीय खास योजना और डिवाइस संस्थापन		
डी.आई.			
सी.एस.एस.	--कोषला खास विनियम		
नृ.इ.ए.	--नृनिधन के गवाह		
डी.वी.	--खास सुरक्षा महाविशेषज्ञ		
एस.एस.			

**प्रयुक्त शब्दों की सूची**

एम डब्ल्यू	— 'प्रबंधनों' के अभाव
यू. डब्ल्यू.	— 'प्रमाण' के अभाव
ई. सी. एल.	— 'गै इन्स्टैं कोलफील्डर' विधि.
प्रव.	— 'प्रवर्त'.

**अध्याय-1**

- 1.1 भूमिका
- 1.2 श्री के. सी. शर्मा का न्यायालय
- 1.3 श्री पी. सी. होता का न्यायालय
- 1.4 न्यायालय को कार्यवाही
- 1.5 न्यायालय की सुनवाई

**अध्याय-1**

1.1.1 पश्चिम बंगाल के बर्दवान जिले में मै. इन्स्टैं कोलफील्डर, लि. (बोले इंडिया लि. की एक सहायक कंपनी) के महावीर धान के भूमिगत कार्यस्थलों में 13 नवंबर, 1989 को सुबह तड़के पानी भर जाने के कारण एक घातक दुर्घटना हुई। इस दुर्घटना में 8 छानकों की मृत्यु हो गई जिनके नाम अनुबंध I में दिये हैं। 65 छानिक शहर ही फंस गये थे क्योंकि उनके बाह्य निकलने का रास्ता बंद हो गया था। करीब 75 घंटों के बाद उन्हें बाहर निकाला जा सका। बोर होल ड्रिल करके और स्थानीय रूप से निमित्त चरबी द्वारा संतृप्तित इस्पात फेसून को नीचे भेजकर उनकी बचाव गया। बाद में हाथ से संतृप्तित इस चरबी के स्थान पर डीजल से संतृप्तित बौल का प्रयोग किया गया। बचाव पड़ति, जिसका प्रयोग भारत में पहली बार किया गया था और इतने बड़े पैमाने पर निचव में इसका कहीं प्रयोग नहीं किया गया था, जो प्रसार माध्यमों ने खूब सगहा।

1.1.2 ज्ञान अधिनियम, 1952 के अधड 24 के उप खण्ड (1) द्वारा प्रदत्त शक्तियों का प्रयोग करते हुए श्रम मंत्रालय, भारत सरकार ने 16 अप्रैल, 1990 को एक अधिसूचना जारी की जिसके द्वारा दुर्घटना के कारणों और संगत परिस्थितियों की औपचारिक जांच करने के लिये श्रम मंत्रालय के सेवा नियुक्त अपर सचिव श्री के. सी. शर्मा को इस उद्देश्य के लिये नियुक्त किया गया। इसी अधिसूचना में जांच न्यायालय के निर्धारकों के रूप में निम्नलिखित व्यक्तियों को भी नियुक्त किया गया था:—

1 श्री बी. एन. विजारी, सहायक, कोलियरी मजदूर सभा, प्रमनमोर, जिला बर्दवान पश्चिम बंगाल।

2 श्री. ए. के. घोष, प्रोफेसर, गार्डनिंग इंजीनियरिंग, इंस्टीट्यूट ऑफ माइंस, सतयाद।

श्रम मंत्रालय की संगत अधिसूचना अनुबंध II पर भी गई है।

1.2.1 श्री के. सी. शर्मा के ज्ञान न्यायालय की पहली बैठक 24 मई, 1990 को हुई और जिसमें यह निर्देश दिया गया कि समस्त पक्षों में नोटिस प्रकाशित करवाये जाये ताकि संबंधित

पक्ष ज्ञाना लिखित बयान दे सकें। ज्ञान न्यायालय ने यह भी निर्णय किया कि यह नैज्जल माइन एनलिंग एण्ड डिवाइज इंस्टीट्यूट (सी. एम. पी. डी. आई), प्रमनमोर के परिसर में 10 जुलाई, 1990 से सुनवाई प्रारंभ करेगा।

1.2.2 जांच न्यायाधीश ने 10-11 जून, 1990 को निर्धारकों, प्रबंधकों के प्रतिनिधियों तथा ज्ञान सुरक्षा महाविभाग (डी. जी. एम. एम.) के साथ एटना स्थल का दौरा किया। तत्पश्चात् 2 जुलाई, 1990 से न्यायालय ने सी. एम. पी. डी. आई, प्रमनमोर में औपचारिक सुनवाई प्रारंभ की। ज्ञान सुरक्षा महाविभाग ने ज्ञान अधिनियम, 1952 की धारा 7 के अन्तर्गत जटिल किये गये महावीर धान की दुर्घटना में संबंधित सभी कागजात प्रस्तुत किये जिन्हें जांच न्यायालय ने अपने कब्जे में कर लिया। तथापि जांच न्यायालय को 7 जुलाई, 1990 को कलकत्ता उच्च न्यायालय का एक आदेश प्राप्त हुआ जिसमें उच्च न्यायालय ने जांच न्यायालय के एक पक्ष कोल माइंस आफिशर्स एसोसिएशन द्वारा भारतीय संविधान के अनुच्छेद 226 के अन्तर्गत दायर रिट याचिका की सुनवाई तक जांच न्यायालय की कार्यवाही पर स्थगन दिया था। धन. जांच न्यायालय ने 7 जुलाई, 1990 के बाद अपनी कार्यवाही स्थगित कर दी।

1.3.1 16 अप्रैल, 1990 की पूर्व अधिसूचना में 3 जनवरी 1991 की आदेश संशोधन करते हुए भारत सरकार श्रम मंत्रालय ने श्री के. सी. शर्मा के स्थान पर श्री पी. सी. होता, अपर सचिव, श्रम मंत्रालय को जांच के लिये नियुक्त किया। इस संशोधन में 3 जनवरी, 1991 को जारी की गई अधिसूचना अनुबंध III पर दी गई है।

1.3.2 चूंकि कलकत्ता उच्च न्यायालय ने श्री के. सी. शर्मा की जांच पर स्थगन दिया था यह अपनी नियुक्ति के बाद श्री. पी. सी. होता ने उच्च न्यायालय को एक अधिनियम दी कि वे पूर्व में श्री के. सी. शर्मा द्वारा की गई जांच प्रक्रिया में जो त्रुटि रहेंगे वह कि वे अपनी प्रक्रिया स्वयं तय करेंगे। श्री पी. सी. होता द्वारा कलकत्ता उच्च न्यायालय को दी गई अंतिम रिपोर्ट की एक प्रति अनुबंध VI पर संलग्न है।

1.3.3 कलकत्ता उच्च न्यायालय ने निर्देश दिया कि श्री पी. सी. होता कानून के अनुसार तय किये में उपर्युक्त जांच शुरू करेंगे। इस परिस्थितियों में कोल माइंस आफिशर्स एसोसिएशन द्वारा दायर रिट याचिका रद्द कर दी गई और जांच न्यायालय की कार्यवाही स्थगित करने का आदेश मानन में दिया गया।

1.3.4 तदनुसार 21 मार्च, 1991 को गणों को नोटिस जारी करके सुनवाई के लिए 8 अप्रैल, 1991 को सी. एम. पी. डी. आई, प्रमनमोर में उपस्थित होने के लिये कहा गया। पक्षों में यह भी अनुशेष किया गया कि वे इन संबंध में उनके द्वारा दिये गये लिखित बयान को प्रमाणित करने के लिये गवाहों की एक पूर्ण सूची प्रस्तुत करें। पक्षों को जारी किये गये नोटिस की एक प्रति अनुबंध V पर दी गई है।

1.3.5 चौथे जांच न्यायाधीश के रूप में 7 अप्रैल, 1991 को प्रो. ए. के. घोष, निवृत्त तथा मैजिस्ट्रेट इन्स्टैं कोलफील्डर वि. (ई. सी. एल.) तथा ज्ञान सुरक्षा महाविभाग के कुछ अधिकारियों के साथ दुर्घटना स्थल का दौरा किया।

1.4.1 जीव न्यायालय ने 8 अप्रैल, 1991 को सी एन पी डी आई, आसतमोल में सुनवाई की। निर्धारक एवं पक्षकार उपस्थित थे। पक्षों को सुनने तथा निर्धारकों के साथ विचार-विमर्श करके मते विस्तारित प्रवेश दिया—

(क) कलकत्ता जीव न्यायालय के आदेश के अनुसरण में जीव न्याय ने प्रारंभ की जाणूना लिखित पक्षों द्वारा आ के.सी. जॉर्ज के जीव न्यायालय में प्रस्तुत किए गए लिखित नोट, ज्ञापन तथा गवाहों की सूची इस जीव न्यायालय के लिए भी देय मानी जाएगी।

(ख) पक्षों को अधिक से अधिक 30 अप्रैल, 1991 तक पूरक नोट, ज्ञापन तथा गवाहों की अतिरिक्त सूची, यदि कोई हो, प्रस्तुत करने का एक और अवसर दिया जाएगा।

(ग) यदि पक्ष अधिसूच्य आदि की प्रति चाहें तो यह प्राप्त हो जाएगी।

(घ) जीव न्यायालय सार्वजनिक है और इसका अपना पक्ष प्रभावशाली ढंग से प्रस्तुत करने के लिए पक्षों को, यदि वे ऐसा चाहें, किसी पक्षीन या किसी ऐसे व्यक्ति/व्यक्तियों जिनसे मामले को प्रस्तुत करने में सहायता मिले, के माध्यम अपना पक्ष प्रस्तुत कर सकते हैं। ऐसे पक्षों की इसके लिए जीव न्यायालय में लिखित अनुरोध करना चाहिए और जीव न्यायालय सामान्य तौर पर इसकी अनुमति दे देगा।

1.5.1 नौवीं लोक सभा के सामाजी सुनवाई और पश्चिम बंगाल विधान सभा के चुनाव तथा इन चुनावों में कार्यकारी संघों के प्रतिनिधियों की व्यवस्था को उद्घाटन में रखते हुए सी एन पी डी आई, आसतमोल में पक्षों की गणना सुनवाई की तारीख 15 से 22 जुलाई, 1991 के लिए निर्धारित की।

1.5.2 13 जलाई, 1991 को जन सुनवाई शुरू हुई तो श्री के. बाल, बाल सुखा महाविदेक से उनके द्वारा बाल अधिनियम, 1952 की धारा 28 के अंतर्गत की गई भुचंडता की जीव के दौरान बाल अधिनियम, 1952 की धारा 7(2) के अंतर्गत जन्म किए गए कागजान प्रस्तुत करने के लिए कहा गया। तत्पश्चात् श्री के बाल ने न्यायालय को जन्म किए गए कागजानों की पूर्वी प्रतों की और मते पाया कि यह सूची उस सूची के समान है जो कि पिछ. जीव न्यायाधीश श्री के.सी. जॉर्ज द्वारा अपने कब्जे में लिए गए जन्म कागजानों की सूची है।

1.5.3 15 से 22 जुलाई, 1991 के दौरान आसतमोल में प्रबंध-संघ के 16 गवाहों के साथ जिरह की गई। इस अवधि के दौरान संघों के प्रतिनिधियों को उन कागजानों का निरीक्षण करने की अनुमति प्रदान की गई जो कि बाल सुखा महाविदेक द्वारा जन्म किए गए थे तथा जिन्हें जीव न्यायालय ने अपने कब्जे में रखा था। इन निरीक्षणों के दौरान जीव न्यायालय के सचिव मौजूद थे।

1.5.4 20 से 26 सितंबर, 1991 को आसतमोल में हुई जीव न्यायालय की अगला सुनवाई के दौरान 6 गवाहों (प्रबंधसंघ तथा संघ के तीन-तीन गवाह) से जिरह की गई। इस अवधि के दौरान प्रबंधसंघ के दो गवाहों से भी जिरह की गई।

1.5.5 जीव न्यायालय की अंतिम सुनवाई आसतमोल में 24 से 26 अक्टूबर, 1991 के दौरान हुई। इस सुनवाई में जीव न्यायालय द्वारा बुलाए गए संघ के तीन गवाह तथा एक गवाह (श्री एस.के. सेनगुप्ता, सहायक प्रबंधक, महावीर खान) के साथ जिरह की गई। तथापि न्यायालय के एकमात्र गवाह शर्मा श्री एस.के. सेनगुप्ता के मामले में कोई जिरह नहीं की गई। आतक दुर्घटना के लिए उत्तरदायी

घटनाओं के क्रम की पुन व्यवस्थित करने तथा अन्य संबंधित मामलों के लिए जीव न्यायालय ने निर्धारकों तथा कुछ गवाहों के साथ 26 अक्टूबर, 1991 को एक बार फिर भुचंडता स्थल का दौरा किया।

1.5.6 24 से 26 अक्टूबर, 1991 के दौरान पक्षों के साथ विचार-विमर्श के बाद यह भी निर्णय लिया गया कि वे केवल लिखित तर्कों प्रस्तुत करेंगे तत्पश्चात् जीव न्यायालय के सचिव को 12 और 13 नवम्बर, 1991 को आसतमोल में रहने तथा लिखित तर्कों स्वीकार करने का निवेश दिया।

1.5.7 12 और 13 नवंबर, 1991 को जीव न्यायालय के सचिव ने आसतमोल का दौरा किया तथा प्रबंधसंघ और संघों से लिखित तर्कों स्वीकार किए।

1.5.8 जुलाई और अक्टूबर, 1991 के दौरान आसतमोल में जीव न्यायालय की सुनवाई के दौरान बयानों को सामान्यलिपि में लिखकर मते साक्ष्यों की व्यक्तिगत रूप से रिकार्ड किया। चूंकि कुछ गवाह अंग्रेजी में निपुण नहीं थे अतः उनसे उस भाषा में प्रश्न पूछे गए जिनसे वे जानते थे (अर्थात् हिन्दी और बंगाली)। तथापि मते उनसे बयानों का ब्रह्म न्याया-लय में अंग्रेजी में अनुवाद किया और सामान्य लिपि में उन्हें रिकार्ड किया। जैसे ही बयान समाप्त हुए पक्षों की गवाहों के बयानों की फोटोकॉपी देन के प्रयास किए गए।

गवाहों के बयानों की प्रतियां निराकार रूप से पक्षों को भेजी गईं ताकि वे अपने आप को जिरह के लिए तैयार कर सकें। जीव न्यायालय की इस तत्परता की प्रबंधसंघ तथा संघ दोनों ने सराहना की।

1.5.9 12 और 13 नवम्बर, 1991 को लिखित तर्कों प्राप्त हो जाने के पश्चात् 20 से 23 नवंबर, 1991 तथा 25 और 26 दिसंबर, 1991 को जीव न्यायालय की रिपोर्ट को अंतिम रूप देने के लिए बयानों, तर्कों तथा अन्य संगन सामग्री पर विचार करने के लिए दिल्ली में मिले।

1.5.10 जीव न्यायालय की रिपोर्ट अम मंत्रालय के अधिकारी को प्रस्तुत कर दी गई थी।

1.5.11 इस रिपोर्ट में प्रबंधसंघ द्वारा पक्ष किए गए गवाहों को प्रबंधसंघ के गवाह (एम डब्ल्यू), संघ द्वारा पक्ष किए गए गवाहों को संघ के गवाह (यू डब्ल्यू) और जीव न्यायालय द्वारा बुलाए गए गवाहों को न्यायालय के गवाह (पी डब्ल्यू) के रूप में रिकार्ड किया गया है। प्रबंधसंघ संघ तथा न्यायालय के गवाहों को सूची क्रमशः अनुबंध VI, VII और VIII पर दी गई है।

1.5.12 वे ज्ञापन तथा कागजान जिन्हें प्रबंधसंघ ने प्रार्थित करने का अनुरोध किया था उन्हें प्रबंधसंघ प्रार्थन (एक्स एम) तथा जिन्हें कर्मचारी संघों द्वारा प्रार्थित करने का अनुरोध किया गया था सघ प्रार्थन (एक्स डब्ल्यू) कहा गया है। क्रमशः अनुबंध IX तथा X पर प्रबंधसंघ तथा कर्मचारी संघों के प्रार्थन की सूची दी गई है।

## अध्याय-2

### 2.1 महावीर खान

### 2.2 प्रबंधसंघ

### 2.3 भू-विज्ञान

### 2.4 पूर्व का उपखनन

### 2.5 अतिरिक्त

2.1.1 महावीर खान पश्चिम बंगाल के बर्द्धमान जिले के रानीगंज कोयला क्षेत्र में स्थित है। यह आसन्नमोल स्टेशन से 18 किमी पूर्व तथा कलशना से लगभग 18.2 कि मी उत्तर पश्चिम में स्थित है। महावीर खान की भौगोलिक स्थिति, मूल की विशेषता, स्वामित्व आदि का संक्षिप्त विवरण अनुबंध — XI पर दिया गया है।

2.2.1 महावीर खान 1975 में श्री कॉल इंडिया लिमिटेड की सहायक श्री ईस्टर्न कोयलीन्डम लि के स्वागिरक्ष में है। प्रशासनिक सुविधा के लिए श्री ईस्टर्न कोयलीन्डम लि को दो इकाइयों में विभाजित किया गया है, प्रथम ईस्टर्न और वेस्टर्न इकाइयों- प्रत्येक प्रभाग का प्रमुख एक क्रियात्मक निदेशक होता है। क्रियात्मक निदेशक (कंसल्टनट डावरेक्टर की श्रेणी अधिनियम, 1952 की धारा 76 के अन्तर्गत नामित स्वामी) के रूप में अधिसूचित किया जाता है। नियमित रूप पर एक आंतरिक सुरक्षा संगठन (आई एस यो) काम कर रहा है। ईस्टर्न इकाई की 63 जानू खानों के साथ 6 क्षेत्रों में विभाजित किया गया है। महावीर खान पुनरुद्धारिता क्षेत्र में स्थित है जिसमें महावीर खान सहित ग्यारह जानू खानें शामिल हैं। दुर्घटना के समय मोहम्मद कलीम (एम डब्ल्यू 17) महावीर खान का एजेंट व प्रबंधक था। वह जून, 1987 से प्रबंधक था और बाद में एजेंट व प्रबंधक नियुक्त किया गया था। अगस्त 13 नवम्बर 1989 के मनुस्मृत दिन तक उसे उत्पन्न खान में दो साल से अधिक का अनुभव प्राप्त था। मोहम्मद कलीम (एम. डब्ल्यू. 17) की कोयला खान का प्रबंध करने में सक्षमता के लिए प्रबंधक का प्रथम श्रेणी प्रमाणपत्र प्राप्त था। उसने कोयला खानों में प्रशिक्षु के रूप में काम आरंभ किया था और नवम्बर, 1989 तक उसे लगभग 28 वर्ष का अनुभव प्राप्त था।

2.2.2 दुर्घटना के समय श्री एम के सेनगुप्ता (सी डब्ल्यू 1) और श्री के. वस्ता (एम डब्ल्यू 19) महावीर खान के सहायक प्रबंधक थे और खानों के पास क्षमता का द्वितीय श्रेणी प्रबंधक प्रमाणपत्र था। श्री पी. एल. बनेर्जी (एम डब्ल्यू 16) महावीर खान के सुरक्षा अधिकारी थे और वे मोहम्मद कलीम, एजेंट एवं प्रबंधक (एम डब्ल्यू 17) के प्रति उत्तरदायी थे। श्री पी. एल. बनेर्जी के पास कोयला खानों में दक्षता का प्रथम श्रेणी प्रबंधक प्रमाणपत्र था।

2.2.3 श्री पी. एल. ठाकुर (एम डब्ल्यू 16) एक सर्वेक्षक थे। उनके पास सर्वेक्षक सक्षमता प्रमाणपत्र है। कोयला खान नियमावली, 1957 (सी एस आर 1957) के विनियम 49 में उनके कर्तव्य दिए गए हैं। संक्षेप में खान अधिनियम और विनियमों के अन्तर्गत उनके अपेक्षित कर्तव्य सही संवर्धन और देखरेख करना और ऐसी योजनाएं एवं संरक्षण तैयार करना और उनका पता लगाना जैसा कि प्रबंध निदेश दे। यह उल्लेख करना संगत होगा कि सर्वेक्षक के वैधानिक कर्तव्य हैं कि जब खान का कार्य उसकी सीमा बाँटने या पानी भर स्थल से लगभग 75 मीटर दूर रह जाए तो वह संपूर्ण तथ्यों का रिपोर्ट करें। एक अन्य सर्वेक्षक तथा कृष सहायक उनके पास कोयला खान उत्खनन का औपचारिक सक्षमता प्रमाण पत्र नहीं था बल्कि केवल अनुभव मात्र था, श्री ठाकुर (एम डब्ल्यू 15) को सहायता कर रहे थे।

2.2.4 खान में 13 औरतें तथा 32 सिन्धार थे। उनके पास इस प्रकार की नियुक्ति के लिए अपेक्षित वैधानिक प्रमाणपत्र था। श्री शिवदाम चटर्जी, औरतों (एम डब्ल्यू 9) कर्मचारियों के निरीक्षक के रूप में नियुक्त थे।

2.3.1 रानीगंज कोयला क्षेत्र की कोयला सीमा लांशर गोडवाला पट्टी की बाबुदा श्रेणी की रानीगंज स्ट्रेट में संबंधित थी। सहायक सामान्य शुकाथ दक्षिण और दक्षिण पूर्व की ओर 2° से 35° के बीच था। कई स्थानों पर निम्न गोडवाला क्षेत्र में डीलाराइट डाइक के रूप में आग्नेय चट्टानें हैं। यहाँ पर 1.2 मीटर की 10 कोयला सीमा है, जो कि रानीगंज स्ट्रेट से सबसे मोटाई से ऊपर है। कोयला सीमा का

नाम अधिकांशतः उन गाँवों के नाम पर है जिनसे होकर वे गुजरती हैं, यहाँ तक कि एक ही सीमा का नाम विभिन्न कोयला क्षेत्र के विभिन्न भागों में अलग अलग पाया जाता है। रानीगंज कोयला क्षेत्र में चट्टान कम से सीमा का सामान्य कम आर-एम्स से आर-आई है।

2.3.2 महावीर खान के क्षेत्र में आर - 9 के बराबर सीमा सीमा सीमा नामक उच्चतम सीमा है जिसकी मोटाई लगभग 6 मीटर है। इस क्षेत्र के लगभग बीच बीच भाग में यह सीमा स्थित है। खान क्षेत्र के दक्षिणी भाग में नेगा सीमा नामक एक दूसरी सीमा है, आर-8 के बराबर, में स्थित इस सीमा की मोटाई लगभग 8 मीटर है। मोंथर सोल और नेगा सीमा के बीच की दूरी 51 मीटर है। दमोदर नदी के किनारे खान आहूत के साथ दक्षिण की ओर आगे बढ़ने पर आर-7 के बराबर नारायणपुरी सीमा नामक तीसरी सीमा स्थित है। नारायण सीमा की मोटाई लगभग 3.3 मीटर है। नेगा और नारायणपुरी सीमा के बीच की दूरी लगभग 24 मीटर है। नारायणपुरी सीमा से 30 मीटर तीसरे आर-6 के बराबर 3 मीटर मोटी बंगरा सीमा है। इन सभी सीमों का कम इस प्रकार है :-

सीमा पाल सीमा	6 मीटर मोटी
बीच की दूरी	50 मीटर
नेगा सीमा	8 मीटर मोटी
बीच की दूरी	24 मीटर
नारायणपुरी सीमा	3.25 मीटर मोटी
बीच की दूरी	80 मीटर
बंगरा सीमा	3 मीटर

2.3.3 इन कोयला सीमों की उत्तरपूर्वी दिशा में सामान्य गहराई 25 से 1 है। कोयला सीमों के बीच के भाग में कोयला चट्टानों का संवृद्ध है। इस क्षेत्र में उत्तर की तरफ एक 60 मीटर ऊँचे फाट की छोटो छोटो अपेक्षाकृत कोई अन्य भू-वैज्ञानिक अवस्था नहीं है। 1 मीटर से 6 मीटर तक के कई अन्य छोटे फाट भी हैं। इस क्षेत्र में कुछ डाइक भी हैं। दक्षिण क्षेत्र जो उठा हुआ भाग है में एक बहुत बड़ा डाइक है। इस डाइक को किसी भी स्थान से पार नहीं किया गया है और इसका वास्तविक मोटाई भी अभी तक अज्ञात है। इनके अलावा एक मोटाई से कम मोटाई वाले कई छोटे डाइक हैं। भारतीय कोयला क्षेत्रों में अन्य कोयला सीमों की तुलना में नारायणपुरी सीमा का कठोर कोयला क्षेत्र समझा जाता है।

2.4.1 महावीर खान और उसके समीप के क्षेत्र, भारत में कोयला खनन के प्रथम केन्द्रों में से एक है। 13 नवम्बर, 1989 को हुई दुर्घटना का कारण इन पुराने और परित्यक्त कार्यस्थलों में पानी भर जाना है। अतः संक्षेप में इस क्षेत्र के पूर्व कोयला खान के इतिहास की समीक्षा करना लाभदायक होगा। अब कुछ ब्रिटिश उद्योगियों ने रानीगंज में कोयला खान का कार्य शुरू किया था तथा पता चला कि रिजर्व के अनुसार भारत में पहली बार कोयला खनन का कार्य 1774 में हुआ था। 1815 में इमारा गाँव के नजदीक रानीगंज सीमा में गड्डे खोद गए जो अभी महावीर खान के अहूत के भीतर स्थित है। 1843 में इस कोयला क्षेत्र में खनन कार्य बंगाल कोल कंपनी नामक संयुक्त पूंजी कंपनी द्वारा किया जाता रहा था। 1855 में रानीगंज तक रेल लाइन विस्तार के बाद इस क्षेत्र में कोयला खनन का कार्य तेजी से विकसित हुआ लेकिन 19वीं शताब्दी के मध्य तक भी भारत में कोयला खनन का कार्य वैज्ञानिक रीति से नहीं किया जाता था और कार्य योजनाओं का विवरण भी नहीं रखा जाता था। 1860 के आसपास अग्रजोकोकल सत्र आर्क इंडिया के अध्यक्ष श्री थॉमस होल्डाम ने खान योजना की स्थिति पर असंतो

संभव करने हुए निम्नलिखित विवरण दिया :—

“विभिन्न एक या दो भागों में गीयह नहरों में प्रसमर्थ है कि भूमिगत कार्यों को एक ही बरतना में सर्वेक्षण नहीं किया गया या योजना नहीं बनाई गई। जहाँ तक कार्यस्थलों के निर्माण का प्रश्न है किसी एक व्यक्ति की स्मरण शक्ति में ही कोई सूचना प्राप्त की जा सकती है ..... मुझे यह कहने हुए प्रसन्नता हो रही है कि यह पद्धति कुछ मामलों में बदल गई है और कम से कम एक मामले में योजनाओं का विवरण रखा जा रहा है और मश्राणा करना है कि अन्य मामलों में भी ऐसा ही किया जाएगा .....।”

2.4.2 खनन का भीषण चौड़ी भूमियों में खनन करने हुए आगे बढ़ना और बीच में छोटे छोटे खंड छोड़ने जाना है और चूंकि कोयले की भूमिगत कार्यस्थलों में मनुष्य द्वारा निकालना पड़ता है, अतः एक गैरट के केवल छोटे क्षेत्र में काम किया जा सकता है जो कि समय के साथ परिवर्तनशील हो जाती है और जो कि खनन जोखिम का एक बहुत बड़ा कारण हो सकता है।

2.4.3 पूर्व की कोयला खनन के ये ऐतिहासिक साक्ष्य महावीर खान और उसके श्रीम पास के क्षेत्र की संरक्षित में आज भी देखे जा सकते हैं।

2.5.1 पुनर्गठित महावीर खान कानजबाक की तीन लघु खानों को मिलाकर बनाया गया था जिसे इन खान को तीन इकाइयाँ कहा जाता है। यहाँ पर सीयरसोल सीम सबसे ऊँची कोयला बिगा है जिसमें 60 फीट पूर्व इसमें निजी कोयला कंपन द्वारा काम किया जा रहा था। सीम में कार्य समाप्त हो गया था, उसे परिवर्तित छोड़ दिया गया और वर्तमान में यह पानी से भरी हुई है।

2.5.2 सीयरसोल सीम के 51 मीटर नीचे नेगा सीम स्थित है जो कि 7.5 मीटर से 8.7 मीटर मोटी है। इस सीम में महावीर खान की सभी तीन इकाइयों की सुचना में सबसे अधिक काम हुआ है। महावीर इकाई में मुख्य पूर्व रेलवे लाइन की उत्तर दिशा में स. ए. और बी पिटों के माध्यम से नेगा सीम में खनन हुआ। ए. और बी पिट के ऊँचाई वाले भाग की ओर धरती पूरा रेलवे लाइन की दोनों तरफ नेगा सीम में खनन तरकारीय बंगाल कॉल के वि. से संबंधित रानीगंज कॉलिअरी द्वारा किया जाता रहा। इसके कारण ए. और बी पिट के नेगा सीम कार्यक्षेत्र में कोयले का एक बैरियर बनाया गया। योजना के अनुसार बैरियर 60 मीटर है। रानीगंज कॉलिअरी के नेगासीम के कार्य क्षेत्रों के बारे में विस्तृत विवरण इस रिपोर्ट में भाग दिया जाएगा।

2.5.3 नेगा सीम के 24 मीटर नीचे नरायनपुरी सीम स्थित है जो कि 1.8 से 3.3 मी. मोटा है। महावीर इकाई में नरायनपुरी को मोटाई 3.25 मीटर है और यह पिट ए. और बी के माध्यम से काम करती है। इसे रानीगंज कॉलिअरी के नेगा सीम के पानी भरे क्षेत्र के नीचे विकसित किया जा रहा है।

2.5.4 पूर्व का स. अगल कोल काना का रानीगंज कॉलिअरी द्वारा बनाई गई नेगा सीम के नरायनपुरी 120 हेक्टेयर क्षेत्र में जो कि पूर्व रेलवे लाइन के दोनों ओर फैला है, में बहुत अधिक पुराना कार्यक्षेत्र है। कार्य की कोई विश्वस्त योजना जिसमें “एक्स्प्लॉरेंट” माइन प्लान” (ए एन पी) नामक यह योजना भी शामिल है। जैसे कि कांल सीम की परिस्थिति करने से एकदम हल होना कारण आवश्यक होता है, जे. इस्टन कॉलिअरिअल के पास उपलब्ध नहीं है। महावीर खान के कार्यालय में उपलब्ध योजना की प्रमाणिकता सदस्य धा बताया इस पर एकता के हस्ताक्षर नहीं थे। यह योजना मुख्य रेलवे लाइन के दोनों तरफ के छोटे क्षेत्र पर बहुत अधिक प्रभाव से कार्यवाही होना देखाता है। रेलवे लाइन

की उत्तर तथा दक्षिण दिशा में स्थित कार्यस्थलों के दो गैरट खार, भूमि के माध्यम से एक दूसरे के साथ जुड़े हुए हैं।

### अध्याय - III

3.1 कोयला खानों में जनजावन के खार के विच्छेद सांख्यिक संबंध।

3.2 भारत

3.3 विकसित देश

3.1.1 दुर्घटना जन भर जाने के कारण हुई थी अतः भारत और विदेशों की भूमिगत कोयला खानों में जनजावन के खतरों से संबंधित सांख्यिक उपकरणों की समीक्षा की गई।

3.2.1 कोयला खान विनियम, 1957 का विनियम 127 का उपबन्ध अभियोजन बताया जाने से संबंधित है तथा भूमिगत कोयला खान में उसी खान या समीप की खान के कार्यस्थलों से जन या अन्य तरल पदार्थों का अवर याता रोक्ने के उपबन्ध बनाता है। विनियमन खान अधिनियम, 1952 का प्रा. 57 के खड्ड/खण्डों के अन्तर्गत बताया गये हैं। कोयला खान विनियम, 1957 के विनियम 127 का संपूर्ण पाठ संबंध-XII पर दिया गया है।

3.2.2 यह देखा जा सकता है कि विनियम कोयला खान विनियम, 1957 के विनियम 127(3) में जा चरदुका या परिवर्तित कार्यस्थलों जिनका भाग नहीं की गई था और उनमें पानी तथा अन्य तरल पदार्थ नहीं पाये गये, के 60 मीटर के अंतर खनन कार्य करने के लिये खानों के मुख्य निर्वाहक जिसे खान सुरक्षा महा-निदेशक (डी जी एम एन) भी कहा जाता है कि अनुमति प्राप्त करने की व्यवस्था है। चूंकि नारायणपुरी सीम जनजावित नेगा सीम के 24 मीटर नीचे स्थित है अतः कोयला खान विनियम, 1957 का विनियम 127 नारायणपुरी सीम में खनन कार्यों पर भी लागू होता है।

3.2.3 कोयला खान विनियम, 1957 के विनियम 127 जिसे समय-समय पर संशोधित किया गया था, का एक लोक दस्तावेज है। न तो खान अधिनियम, 1901 और न ही उपसूचित अधिनियम के अन्तर्गत बनाई गई सामान्य नियमावली, 1908 में भूमिगत कोयला खानों के जल से भरे कार्यस्थलों की ओर बहुत समय रखा जाने वाली किसी मासधानी का निर्धारण किया गया है। यहाँ तक कि खान अधिनियम, 1901 के खान पर खान अधिनियम, 1923 को प्रतिस्थापित किया गया तब भी इन मासधानियों की व्यवस्था नहीं की गई। 1936 में खान अधिनियम, 1923 में एक संशोधन करके खानों में पानी भरने का शकट होना और उसके कारण उत्पन्न होने वाले खारे के विच्छेद विनियम बनाने के लिये केन्द्र सरकार को शक्ति प्रदान की गई थी। इस प्रकार खान अधिनियम 1923 के अन्तर्गत बताया गये भारतीय कोयला खान विनियम, 1926 (आई सी एम आर 1926) में 1936 के बाद पहली बार जनजावित या अप्रयुक्त कार्यस्थलों के 100 फीट (30 मीटर) के क्षेत्र में खनन करते समय बरती जाने वाली मासधानी का निर्धारण किया गया है। मासधानियों में गली की चौड़ाई और ऊँचाई को 8 फीट (2.4 मीटर) तक सीमित रखना तथा कार्यस्थल पर केन्द्रीय जोरहोत और दोनों तरफ पर्याप्त फर्शक बॉम्बहोत और जहाँ आवश्यक हो अधिक से अधिक 15 फीट (4.5 मीटर) के अंतर पर कार्यस्थल के ऊपर और नीचे जोरहोत को व्यवस्था करना। यह भी निर्धारित किया गया है कि खनन करते हुए आगे बढ़ते से इन बॉम्बहोत का पर्याप्त दूरी पर रखा जाना चाहिये और यह दूरी किसी भी क्षण में 10 फीट (3 मीटर) से कम नहीं होना चाहिये। 1951 में सभा प्रवेश की एक कोयला खान में जनजावन का कारण हुए विनाश जिनमें 63 खननों की मृत्यु

हो गई थी तथा कोयला खान (खसिया) विनियम, 1955 के फलस्वरूप जलप्लावन स्थलों के निरुद्ध काम करने के प्रतिबंधों की भी अधिक कठोर बना दिया गया है। संशोधित विनियमों में बुरों के बारे में सांविधिक प्रतिबंध विस्तृत लिखे गए सुरक्षा महानिदेशक की अनुमति प्रेषित है 100 फीट (30 मीटर) से बढ़ाकर 150 फीट (45 मीटर) कर दी गई है। कोयला खान विनियम, 1957 द्वारा फाई सी एम आर, 1928 और कोयला खान (खसिया) विनियम, 1955 को समाप्त कर दिया गया है। भूमिगत पानी के जमाव के खतरे को रोकने के लिये कोयला खान विनियम, 1957 के विनियम 127 में प्रावधान किये गये हैं। तथापि सांविधिक रूप से प्रतिबंधित क्षेत्र को 45 मीटर से बढ़ाकर 60 मीटर कर दिया गया। दिसम्बर, 1975 की वास्तवता खान बुर्यटना, जिनमें 375 खानों की मृत्यु हो गई थी, के बाद कोयला खान विनियम, 1957 के विनियम, 127 में व्यापक संशोधन किये गये थे। इनमें से कुछ संशोधन इस प्रकार हैं।

(क) जलप्लावित कार्यस्थलों के 60 मीटर के अंदर कार्य अनुमति के लिये खान सुरक्षा महानिदेशक को प्रस्तुत आवेदन के साथ योजनाओं और उन खण्डों की प्रतियाँ संलग्न करना आवश्यक है जिसमें अन्य भागों के साथ-साथ निम्नलिखित दिखाया गया हो— सभी अनुपयुक्त और परित्यक्त कार्यस्थलों के सटीक के कार्यस्थलों से संबंधित इसकी रूपरेखा अनुमति में विहित प्रस्तावित कार्यस्थल की रूपरेखा, खाफा और पड़ति, फास्ट, डाइक और अन्य भू-वैज्ञानिक गड़बड़ियाँ और प्रबंधन के पास उपलब्ध अन्य सूचनाएँ तथा खान सुरक्षा महानिदेशक द्वारा घोषित किसी अन्य भाग के बारे में सूचना।

(ख) जब खान सुरक्षा महानिदेशक द्वारा अनुमति प्राप्त हो जाती है तो अनुमति में निविष्ट भागों के अंतर्गत ही प्लान और पड़ति होनी चाहिये और इसमें कोई अंतर नहीं होना चाहिये बल्कि कि किसी ऐसे अंतर के निर्माण के लिये खान सुरक्षा महानिदेशक द्वारा पुनः अनुमति न दी गई हो।

(ग) यह भी आवश्यक है कि ऐसे कार्यस्थलों की सही लंबाई और चौड़ाई, बनाये गये वॉर हॉल, प्रत्येक वॉर हॉल की लंबाई का रिकार्ड इस उद्देश्य के लिये रखाई गई एक निश्चिंद किताब में रखा जाये और इसमें दर्ज की गई प्रविष्टियों पर प्रतिष्ठित इस उद्देश्य के लिये नियुक्त सक्षम अधिकारी द्वारा हस्ताक्षर और प्रबंधक द्वारा प्रति हस्ताक्षर किया जाए।

(घ) किसी भूमिगत कोयला खान के कार्यक्षेत्र में किसी भी स्थल पर जब ज्यादा पानी के रिसाव की घटना हो तो परामर्श काम बंद करने के प्रावधानों में जलप्लावित क्षेत्र के 60 मीटर के भीतर के कार्यक्षेत्र भी शामिल है।

(ङ) तथापि कोयला खान विनियम, 1957 का विनियम 127 को अधिक लचीला भी बनाया गया है क्योंकि इसमें खान सुरक्षा महानिदेशक को ये शक्तियाँ दी गई हैं कि यदि वे उचित समझें तो गैर-रंग के आकार के प्रतिबंधों में ढील दे सकते हैं और एंटांटर बोर्डिंग बनाने की शर्तों में छूट प्रदान कर सकते हैं।

3.2.3 1983 में जलप्लावन के कारण हरिनाथोड दुर्घटना जिसमें 19 खानों की मृत्यु हुई और जलप्लावित क्षेत्रों के सटीक कार्य करने से प्राप्ता अनुमति को खान में रखने हुए विनियम 127 को पुनः 1990 में संशोधित किया गया था। इसमें अनुपयुक्त और परित्यक्त कार्यस्थल के बीच अंतर समाप्त करने के लिये निविष्ट प्रावधान किये गये हैं। हरों जलप्लावित क्षेत्रों का गलत मानने के लिये दोन दिन फाई सी एम आर की सही सफाई के लिये भी बताया गया है।

3.3.1 इस स्थिति में यहाँ जलप्लावित क्षेत्रों के सटीक कार्य करने से संबंधित विकसित देशों के भूमिगत कोयला खानों के सांविधिक प्रावधानों की समीक्षा करना संगत होगा। प्रायः, सभी देश जलप्लावित क्षेत्रों के सटीक कार्य करने समय कुछ सांविधिक प्रतिबंध लगाते हैं। जलप्लावित क्षेत्रों और कार्यस्थलों के बीच सुरक्षा विवर/बैरियर छोड़ने के रूप में ये प्रतिबंध लगाये जाते हैं। सुरक्षा विवर के भीतर कुछ प्रतिबंधों के अधीन ही एक निश्चित सीमा में खान करने की अनुमति दी जाती है। प्रायः इन प्रतिबंधों की प्रकृति में खान की चौड़ाई और ऊँचाई सीमित करना तथा एंटांटर बोर्डिंग के कवर के अंतर्गत कार्यक्षेत्रों को आगे बढ़ाया जाना शामिल है।

3.3.2 संयुक्त राष्ट्र फेडरल कानून में यह निविष्ट है कि यदि पुराने भूमिगत कार्यक्षेत्रों का कोई विश्वसनीय प्लान उपलब्ध नहीं है तो जलप्लावन के कारण दुर्घटनाओं को रोकने के लिये ऐसे कार्यस्थलों के 60 मीटर के भीतर एंटांटर बोर्डिंगों का प्रावधान किया जाना होता है।

इस संबंध में संयुक्त राष्ट्र का कानून कोयला खान विनियम, 1957 के विनियम 127 की ही तरह का है।

3.3.3 फ्रांस की कोयला खानों के विनियमन में पानी भर जाने के खतरों के विरुद्ध कार्यक्षेत्रों की सुरक्षा प्रेषित होती है। इसमें यह भी प्रेषित है कि पानी भर जाने को रोकना वाले क्षेत्रों, गलियों या आगे बढ़ाये जाने वाले क्षेत्रों के पहले करीब 3 मीटर लंबा एंटांटरबोर्डिंग बनाया जाये।

3.3.4 ब्रिटन के कोयला खान विनियमों में यह प्रेषित है कि जब किसी खान के किसी अनुपयुक्त कार्यक्षेत्र के 45 मीटर भीतर कोई कार्य किया जा रहा है तो प्रबंधक आवश्यक सुरक्षात्मक उपायों का प्रबंध करता है इसमें निरोधकों तथा कर्मचारियों के प्रतिनिधियों को इस संबंध में पूर्व सूचना देना शामिल है, इसके अलावा इसमें ऐसे कार्यक्षेत्रों में पालन की जाये वाली प्रक्रिया योजना भी शामिल है ताकि यह सुनिश्चित किया जा सके कि पानी या किसी अन्य प्रथम बहाव का खतरा न हो सके।

3.3.5 भूमिगत पानी के खतरों से संबंधित विभिन्न देशों के उपरोक्त सांविधिक प्रावधानों की समीक्षा से यह पता चलता है कि इनके सांविधिक सुरक्षा उपाय संयुक्त राष्ट्र, अमेरिका, फ्रांस और ब्रिटन जैसे विकसित देशों के बराबर हैं।

#### अंश-4

अंशानुक्रम के कारण दुर्घटनाएँ

4.1 भारत में अंशानुक्रम के कारण दुर्घटनाओं का वार्षिक विवरण

4.2 भारत में जलप्लावन के कारण प्रमुख दुर्घटनाएँ।

4.2.1 हमारे देश की कोयला खानों में दुर्घटनाओं में एक तिहाई व्यक्तियों की मृत्यु जलप्लावन के कारण होती है। जलप्लावन के कारण प्रमुख विपदाएँ 10 दिसम्बर, 1954 को म्यूटन बिकली कोलियरी (मध्य प्रदेश), 20 फरवरी, 1958 को सैन्ट्रल भोवरा कोलियरी (बिहार), 05 जनवरी, 1960 को मधुबा कोलियरी (मध्य प्रदेश), 18 नवम्बर, 1975 को डिनेवरा कोलियरी (मध्य प्रदेश), 27 दिसम्बर, 1975 को धानावाड़ा कोलियरी (बिहार) तथा 14 दिसम्बर, 1983 को हरिनाथोड कोलियरी (बिहार) में हुई जिनमें क्रमशः 63, 28, 16, 10, 375 तथा 19 व्यक्तियों की मृत्यु हुई।

4.2.1 दिसम्बर, 1954 में म्यूटन बिकली कोलियरी (मध्य प्रदेश) में दुर्घटना जब मगर दुर्घटना डिनेवरा में 16 मीटर की गहरी गहरी तथा अन्य सीमा की परित्यक्त जलप्लावित बर्किंग से जुड़ गई।

दो सीमा के बीच पृथक्करण जैसे अपप्रोफाल्ट (ऊपर की ओर फैले की खराबी) के कारण उस क्षेत्र में ऊपरी सीमा के बराबर के स्तर के निर्माण सीमा को खोया गया। यह दुर्घटना मुख्यतः गलत खान योजना और भारतीय कोल खान विनियमन 1926 के विनियमन 74, जिसे कोल खान विनियमन, 1957 के विनियमन 127 के द्वारा निरस्त कर दिया गया था, का अनुपालन न किए जाने के कारण हुई। फरवरी, 1958 में सीटूर भोवरा कोलियरी (विहार) में आपत्तिका के कारण दुर्घटना उस समय हुई जबकि भूमिगत प्रवाहन खान सीमा को पार कर गया तथा यह समीपवर्ती कोलियरी के जलाप्लावित प्रवाहन में जा मिला। यह दुर्घटना मुख्यतः बिना उचित सर्वेक्षण तथा उचित योजनाओं के समीपवर्ती कोलियरी में अवधिकार प्रवेश तथा जनसंचालन क्षेत्रों के 60 फी. के अन्दर बढ़ते हुए प्रवाहन के सम्बन्ध में कोयला खान विनियमन, 1957 के विनियमन 127(3) और (5) के उल्लंघन के कारण हुई। जनवरी, 1960 में दम्प्रा कोलियरी (मध्य प्रदेश) में दुर्घटना उस समय हुई जबकि प्रवाहन अपप्रोफाल्ट के कारण जलाप्लावित क्षेत्र की ओर बढ़ गया। खराबी वाले क्षेत्र में दो प्रवाहनों के बीच 1.8 मी. का अन्तराल में दुर्घटना को दहाया मिला।

4.2.2 भारतीय खान इन्डिया में सबसे अधिक आतंक दुर्घटना दिसम्बर, 1975 में चासनाला (विहार) में हुई जिसमें आपत्तिका के कारण 325 व्यक्तियों की मृत्यु हो गई। चासनाला में पूर्व प्रवाहन ने लगभग वर्ष 1949 में संचालन फाट-फाड़त निकालने समय पुराने प्रवाहनों से असावधानी पूर्वक जुड़ने के कारण दिसम्बर, 1975 में दुर्घटना होने से लगभग 26 वर्ष पहले काम करना बन्द कर दिया था।

4.2.3 चासनाला में हुई दुर्घटना के कुछ प्वाइंट यही हैं जो अब हुई दुर्घटना के हैं। दोनों मामलों में ऊपरी पुराने जलाप्लावित प्रवाहनों से आप्लावन हुआ तथा तत्काल इसके बाद घातक हो गई। चासनाला कोलियरी के मामले में, सीमा के साथ-साथ चलने वाली मुख्य इन्फ्लेक्सी की लम्बाई प्लान में इसकी दायवर्धक लम्बाई में बहुत कम दिखाई गई थी। महाधीर खान के मामले में कलेषकर पुरानी तथा पतित्यक्त शावट को प्लान में निचली सीमा तक बढ़ा हुआ नहीं दिखाया गया था। इसके अतिरिक्त, दोनों मामलों में सम्बन्धित प्रवेशकों ने खान सुरक्षा महानिदेशक द्वारा प्रवाहन के लिए अनुमोदित न किए गए क्षेत्र में काम किया तथा उन्होंने कोयला खान विनियमन, 1957 के विनियमन 127 का उल्लंघन किया। सितम्बर, 1983 में हुरीलाबीह कोलियरी (विहार) में दुर्घटना उस समय हुई जबकि दो भ्रमण शलग समतल रेखाओं में मोटी सीमा के विकसित होने से ऊपरी कोयले की पतली सतह प्रवाहक बढ़ गई। ऊपरी समतल रेखा जो हीदी का एक भाग थी के प्रवाहन से पानी निचली समतल रेखा की ओर बढ़ गया जिससे 19 व्यक्तियों की मृत्यु हो गई। यह दुर्घटना मुख्यतः गलत योजना तथा कोल खान विनियमन 1957 के विनियमन 127 के उल्लंघन के कारण हुई।

4.2.4 इन दुर्घटनाओं के कारणों के विश्लेषण ने पता चला कि ये दुर्घटनाएं मुख्यतः गलत खान योजनाओं तथा कोल खान विनियमन 1957 के विनियमन 127 के उल्लंघन आदि के कारण हुई। दूसरे शब्दों में, ये दुर्घटनाएं ऐसी आपराधिक लापरवाही के कारण हुई जिससे बचा जा सकता था।

#### प्रधायक—5

##### 5.1 दुर्घटना

##### 5.2 गुप्तगुदा व्यक्तियों की पहचान करना

##### 5.3 बचाव कार्य

5.1.1 इस स्थिति में यह संगत होगा कि उन घटनाओं के काम की पुनरीक्षा की जाय जिसके कारण दुर्घटना हुई। स्पष्ट है कि 12 दिसम्बर, 1949 को नीचरी पारी में कार्य सम्पन्न की तरह प्रारम्भ हुआ। लगभग कुछ सीमा में तीन प्रवाहन भाग पतित्यक्त "को" निर

रहित शेष, 31 भाग 42 और 42 भाग 42 निरस्त भाग थे। इन सभी में दुर्घटना के बाद प्रवाहन प्रवाहनों में 221 कार्य निरस्त थे।

5.1.2 समस्त प्रवाहनों का औसत प्रवाहनी श्री फोर्जदार सिंह (एम डब्ल्यू-1) था। 42 भाग 42 निरस्त भाग, जहाँ दुर्घटना हुई, का सरदार तथा फाटफाट करमण श्री दीन पाण्डे (एम डब्ल्यू-13) तथा श्री चन्द्रधारी बराय (एम डब्ल्यू-14) था।

5.1.3 पारी की शुरुआत में, 42 भाग 42 भाग के 40 डिप के म में वास्तु शाट छेद टिल किए गए। इन शाट छेदों की लम्बाई लगभग 1-2 फी. थी। कोयला फाटिंग मजदूर खनन होने के कारण फीम पर कोई अन्तर्काट नहीं थी।

5.1.4 शाट फायरिंग श्री चन्द्रधारी बराय (एम डब्ल्यू-14) के साथ श्री बांगी राजधर (एम डब्ल्यू-5) और राम धवतार खुसिया, श्री दलुया मोदी और श्री प्यार चन्द्र पांडे हैल्पर थे इस भाग के शब्द फेसों में फाट फायरिंग पूरी करने के बाद, वे लगभग प्रातः 4.00 बजे 40 डिप फीम पर पहुँचे। श्री चन्द्रधारी बराय (एम डब्ल्यू-14) ने साक्ष्य दिया कि उसने फीम में टिल किए गए नाग शाट होल में से छह को चार्ज किया। इनमें से चार शाट होल फोर्जदार स्तर के थे और गैर दो नीचरी के लगभग मध्य में "कट होल" थे। तथापि श्री बांगी राजधर (एम डब्ल्यू-5) के अनुसार सभी शाट होल को फीम में एक ही समय में चार्ज किया गया। वे, थिससेटों तथा तात्कालिक विद्युत अधिक विस्फोटक पराणों का प्रयोग किया गया। इसके बाद श्री चन्द्रधारी बराय (एम डब्ल्यू-14) द्वारा छह शाट होल डिस्चार्ज किए गए। धुआँ तथा भाप हट जाने के बाद वे गैर शाट होल को चार्ज करने के लिए फीम तक गये। जबकि श्री बांगी राजधर (एम डब्ल्यू-5) का कहना है कि वे गैर गैर छह शाट होल को जोड़ने गए। जब श्री बांगी राजधर (एम डब्ल्यू-5) तबड़े हुए कोयले के नीचे से शाट फायरिंग केवल बाहर निकाल रहा था। श्री श्री चन्द्रधारी बराय (एम डब्ल्यू-14) को सामने वाले फीम तथा अपने पीछे से त्रेक होने की आवाज सुनाई दी। इसके तत्काल बाद उन्होंने फीम के दाहिनी तरफ से गंदा पानी फुहार की तरह बहता देखा, श्री बांगी राजधर (एम डब्ल्यू-5) को अपना काम छोड़ना पड़ा। श्री चन्द्रधारी बराय (एम डब्ल्यू-14) ने श्री बांगी राजधर (एम डब्ल्यू-5) को बाहर निकाल, अपने साथियों तथा बीमारों को डकड़ दिया और पानी के प्रवाहनात अन्तर्काट की नेतायनी देना हुआ फीम से बाहर दीक्षा। अपने में, श्री चन्द्रधारी बराय (एम डब्ल्यू-14) को भाग के हावला के निरस्त श्री दीन पाण्डे (एम डब्ल्यू-13) मिला तथा उसने उसकी पानी के प्रवाहनात अन्तर्काट के बारे में बताया। श्री दीन पाण्डे (एम डब्ल्यू-13) ने उसकी उस भाग के सभी व्यक्तियों को बाहर निकालने के लिए कहा तथा उनकी पानी के प्रवाहनात के बारे में 21 फाट कट भाग के कार्यकर्ता को सूचित किया। श्री दीन पाण्डे ने 40 डिप डिप फीम पारी के प्रवाहनात अन्तर्काट के बारे में लगभग प्रातः 4.30 बजे सी डी एम टेरीफोन पर श्री फोर्जदार सिंह (एम डब्ल्यू-1) को बताया। श्री फोर्जदार सिंह (एम डब्ल्यू-1) ने जित दीप पर हाजिरी केबिन से 21 सक्षम फाट शि पर सी डी एम टेरीफोन पर तत्काल सवकें किया परन्तु दृष्टां से कोई उत्तर नहीं था। दुर्घटना की सूचना प्रतिकर्मी एवं प्रत्यक्ष सी. क्लीव (एम डब्ल्यू-17) को भेज दी गई। फिर उसने सी.डी.एम. टेरीफोन पर मुख्य अधिकारी श्री पी एल बनर्जी को दुर्घटना की सूचना दी। इसके पश्चात् उत्तरी टर्मिनी केबिन से श्री जित डीपिंग भाग के सक्षम श्री सावन्ध महा। वे टेरीफोन पर सम्पर्क किया। उसने श्री रामबन्ध महा की "बी" पिट भाग से सभी व्यक्तियों को बाहर निकालने तथा सूचित सभी व्यक्तियों को बाहर निकालने के लिए सभी भागों की सूचना करने के आदेश दिए। उसी सी डी एम आरेक्टर की भी निर्देश दिए कि वह सी डी एम में उपस्थित माइक्रोफोन सुनिता से सूचित सभी व्यक्तियों को बतावनी दे तथा उन्हें बाहर जाने के निर्देश पानी दीन पाण्डे (एम डब्ल्यू-13) और श्री फोर्जदार सिंह (एम डब्ल्यू-1) ने 21 फाट कट सेक्शन की ओर फाट की कोशिश की परन्तु पानी रुका

की पहुँच गया। शक्ति से कर्मचारी के हस्ताक्षर के लिए कुछ नहीं कर सका। वे वे पिट सतह की ओर दौड़े जहाँ वे श्री पी.एन. बनर्जी (एम डब्ल्यू-16) से मिले। श्री पी.एन. बनर्जी (एम डब्ल्यू-16) के साथ श्री फौजदार सिंह (एम डब्ल्यू-1) तथा श्री दौदन पाण्डे (एम डब्ल्यू-13) संरक्षण की ओर वापिस आये। तथापि, 8 लेवल के निकट उन्होंने देखा कि पानी उत्पादन की ओर से बह रहा है। फिर श्री पी.एन. बनर्जी (एम डब्ल्यू-16) ने पिट की ओर गए और श्री दौदन पाण्डे (एम डब्ल्यू-13) तथा श्री फौजदार सिंह (एम डब्ल्यू-1) स. "ए" पिट की ओर आये। इस घांका से कि स्थिति बदल न हो जाए, वे तत्काल बाहर आ गए। पिट के बाहर वे श्री. कालिम, अधिकारी एवं प्रबालक (एम. डब्ल्यू-17) से मिले। श्री फौजदार सिंह (एम डब्ल्यू-1) दोबारा स. "ए" पिट के मध्य से श्री दौदन पाण्डे (एम डब्ल्यू-13) आकाशक तथा श्री. कालिम (एम डब्ल्यू-17) के साथ भूमि के नीचे गए। परन्तु उन्होंने देखा कि पिट की सतह से ही पानी लगभग सीने तक पहुँच गया है। यह महसूस करते हुए कि पिटों के माध्यम से कर्मचारियों को बचाने की कोई गुंजाइश नहीं है, वे लगभग प्रातः 5.30 बजे बाहर वापिस आ गए।

5.2.1 शक्ति कुछ कर्मचारों की डिप्ट के मध्य से नागरिकपुरी सीम से नेगा सीम आने की संभावना थी, श्री पी. एन. बनर्जी (एम डब्ल्यू-16) अन्यो के साथ नेगा सीम के समीपस्थ यूनिट के निमज्जन होल से नीचे गए। तथापि उन्होंने कहा नेगा सीम के केवल दो पम्प खराबियों को पाया जो बाहर ले जाये जाने की प्रतीक्षा कर रहे थे।

5.2.2 हाजिरी रजिस्टर की तत्काल जाँच करने से पता लगा कि खान के नीचे 221 कर्मकार गए थे, जिनमें से 150 कर्मकार बाहर आ चुके थे और शेष 71 कर्मकार के बारे में यह अनुमान था कि वे भूमि के नीचे फँस गए। फंसे हुए खनिकों में से अधिकतम 21 फास कट भाग के थे और शेष 42 फास कट भाग के थे। सौभाग्य से सी.डी. एन टेलीफोन के द्वारा फंसे हुए खनिकों के दो ग्रुपों से शीघ्र सम्पर्क हो गया। फंसे हुए खनिकों ने बताया कि वे पानी के बढ़ाव के कारण, जिससे उनका पहुँच रास्ता बन्द हो गया है, पिट की सतह पर पहुँचने में असमर्थ हैं।

फंसे हुए खनिकों की गिनती करने तथा शीघ्र ही बाहर आ जाने वाले खनिकों की गिनती से पता चला कि पैसंड खनिक भूमि के नीचे फँस गए थे। अतः छद्म खनिकों के लापता होने की घांका थी। बाय में, पैसंड फंसे हुए खनिकों को सी डी एन टेलीफोन से निर्देश दिए गए कि वे उत्पादन की ओर जाय क्योंकि बरमाछिद्र के माध्यम से बाहर से उनके साथ सीधे सम्पर्क करने के प्रयास किए जायेंगे। यह बताया सन होस कि आप्लावन की स्थिति में श्री सी डी एन टेलीफोन की कार्यरता से प्रारम्भिक अवस्थाओं में बचाव कार्य में महत्वपूर्ण योगदान मिला।

5.3.1 13 नवम्बर को लगभग प्रातः 10.00 बजे, खान सुरक्षा महानिदेशालय तथा मैसर्स ई.सी.एल. के सख्तिष्ठ अधिकारी महावीर खान पर पहुँचे। यह शीघ्र ही स्पष्ट हो गया कि दुर्घटना नागरिकपुरी सीम के पुरानी तथा जलाशयित शाण्ट स. 34 से जुड़े कारण हुई थी तथा उत्पादन की ओर दक्षिम पानी रहित नहीं जहाँ फंसे हुए खनिक आशय से सकंसे। यह भी पता चला कि नेगा सीम के गण दूरग्रांथ (माउंट ओप) के पीछे नागरिकपुरी सीम में उत्पादन की ओर पहुँचे डिप्ट किए गए कुछ अन्वेषणापक छेदों से वास्तव में दक्षिम में बाधा था गयी थी। इस प्रकार यह महसूस किया गया कि बरमाछिद्र के माध्यम से फंसे हुए खनिकों से सम्पर्क स्थापित किया जा सकता था। फंसे हुए खनिकों के सातावरण के बारे में मोटे तौर पर अनुमान था कि उनके लिए लगभग दो सप्ताह तक सामान्य वातावरण अच्छा रहेगा। अतः यह महसूस किया गया कि फंसे हुए खनिकों को धामन खतरा नहीं था।

5.3.2 आप्लाव स्थिति के लिए एक इन्जिन रिंग लाया गया तथा तलाशी दल द्वारा शीघ्र ही तैयार किए गए मौजूदा बरमा छिद्र स. 3 का गाय 14 नवम्बर को प्रातः 2.30 बजे तक खोड़ा करके 20 से सी.

कर बिना गया। सी डी एन टेलीफोन से फंसे हुए खनिकों को स. 3 बरमा छिद्र के नीचे एक्क होने के निर्देश दिए गए। पूर्ण सप्ताह तथा बरमा छिद्र के माध्यम से स्थापित की गई संचार व्यवस्था और इसके खारों और फंसे हुए खनिकों के सुरक्षित होने से खनिकों के सुरक्षित बचाव की चिन्ता जो पहले बनी हुई थी वह कम हो गयी।

5.3.3 फंसे हुए खनिकों के बचाव के लिए एक बड़े व्यास का बरमा छिद्र ड्रिल करने के लिए उत्पादन की ओर बाहर तत्काल एक उपयुक्त स्थान का चयन किया गया। 14 नवम्बर को प्रातः 9.30 बजे प्रचालन कार्य प्रारम्भ किया गया तथा 15 नवम्बर को लगभग दोपहर के 3.30 बजे 52 सें.मी. व्यास का बरमा छिद्र पूरा कर दिया गया। जर्मनी डिजाइन पर आधारित कञ्जेश्वर दरवाजों सहित एक स्टील कैप्सूल स्वदेशी रूप से तैयार की गई। एक अस्थाई तिपाई का निर्माण किया गया और घिरनी स्थापित की गई तथा घिरनी प्रचालित (कैप्सूल) के माध्यम से मैसर्स ई.सी.एल. के सख्तिष्ठ मुख्य खनन इंजीनियर, श्री जी.एम. गिल, जो बचाव कार्य में प्रशिक्षित थे, को 16 नवम्बर को लगभग प्रातः 2.20 बजे भूमिगत वकिम पर उतारा गया। शक्ति हस्तक्षेपित घिरनी से फंसे हुए खनिकों को बाहर लाने में समय लग रहा था, कुछ खनिकों को बचाने के बाद इसे केन द्वारा प्रतिस्थापित किया गया। फंसे हुए पहले खनिक को 16 नवम्बर को प्रातः 2.40 बजे तथा अन्तिम खनिक को उभी दिन प्रातः 8.40 बजे बाहर लाया गया। बचाव की इस प्रणाली को भारत में पहली बार प्रयोग किया गया। इससे पहले इसने बड़े पैमाने पर ऐसी बचाव प्रणाली का प्रयोग धियव में नहीं किया गया था। इन बचाव किया का संचार माध्यम से काफी प्रचार हुआ।

5.3.4 इसके बाद, छ. लापता व्यक्तियों की तलाश शुरू की गई। तलाशी दलों को कैप्सूल के माध्यम से भेजा गया तथा 18 नवम्बर को प्रातः तक दिन और रात तलाश जारी रही। इसके पश्चात्, बरमा छिद्र के माध्यम से तलाशी दलों को भेजना रोक दिया गया क्योंकि बरमा छिद्र के अक्षेपित भाग से फिमलन के सकंसे मिने। तदोपरान्त, पिटों को पानी रहित कर दिया जाने पर, छद्म लापता खनिकों की तलाश जारी रखी गई। दुर्भाग्यवश इन छद्म खनिकों को जीवित नहीं बनाया जा सका। एक के बाद एक उनकी लाश पाई गई। अन्तिम लाश 23 दिसम्बर, 1989 को काफी प्रयासों के बाद मिली।

## अध्याय-VI

### 6.1 दुर्घटना स्थल का प्रथम निरीक्षण

### 6.2 मतर्हा निरीक्षण

### 6.3 द्वितीय निरीक्षण

### 6.4 डिप्लॉगिंग

6.1.1 7 अप्रैल, 1991 को मैं दुर्घटना स्थल का निरीक्षण करने के लिए महावीर खान गया। निरीक्षण के दौरान श्री. ए.के. चौर, भूतकनकर्ता (असेसर), श्री. के. पान, खान सुरक्षा महानिदेशक, श्री टी.के. देव, निदेशक (तकनीकी), मैसर्स ई.सी.एल. तथा खान सुरक्षा महानिदेशालय और मैसर्स ई.सी.एल. के प्रथम अधिकारी श्री. श्री साध थे। श्री बी.एन. मिश्रा भूतकनकर्ता उपस्थित नहीं हो सके। हम स. ए पिट के रास्ते से नागरिकपुरी सीम तक नीचे गए तथा स्थिती से हावड़ा तक ईस्टर्न मेसब लाइन के सीधे - पैरन रहे। रास्ते में मैने पानी के अन्वर्ध से हुए निराश को देखा जिससे हमें पता था कि फंकीत तथा पैकिंग लापरी हुए कर सख्तिष्ठ लेवल तैयार कर जमा हो गई थी। गस वह स्थान भी दिखाया गया जहाँ ने छ में से कुछ लाप मिली थी। 33 लेवल पर मैने भूमिगत टेलीफोन पड्डि (अन्ति. सी.डी. एल. पड्डि) का रिसीवर देखा जिसका प्रयोग फंसे हुए खनिकों द्वारा बाहर आपरेटर से सम्पर्क करने के लिए किया गया था। इन रिपोर्ट



में मैंने पहले बताया है कि सी.बी.एस. पद्धति के कारगर रूप से कार्य किया गया इसमें सफलता पूर्वक बड़ा कार्य में महत्वपूर्ण भूमिका अदा की।

6.1.2 33 पूर्वी लेबल लुईस स्ट्रोक के साथ चले हुए, मैंने सवान्त रोक (स्टॉपिंग) पर पानी द्वारा छोड़े गए निशान देखे। इसमें मुझे भविष्य में हुए पानी के बढ़ाव के अधिकतम स्तर का काफी अंदाजा हो गया। 40 डिग्री आक 28 लेबल के अंकन के चारों ओर, मैंने कार्य पर पूरी पर्यवर के दो बड़ धाक देखे। मैंने पानी के प्रवाह से सूजी हुई तथा टेढ़ी हुई हाथेल परियों को भी देखा। 40 डिग्री के प्रवेश मार्ग के साथ-साथ चलते हुए, मुझे स्पष्टतः महसूस हुआ कि 40 डिग्री पर गैलरी अपनी सामान्य उत्तर पूर्वी दिशा से अकस्मात विचलित हो कर लगभग दक्षिण की ओर हो गई जिससे 40 डिग्री पुरानी शाफ्ट सं. 34 से जुड़ गई। ठीक उसी स्थान को गोलाशम (बाउंडर्स) तथा कंकड़ों से आच्छादित कर दिया गया जहाँ 40 डिग्री आक 28 लेबल से पुरानी तथा परिवर्तन शाफ्ट सं. 34 का कार्य बन्द कर दिया था। 40 डिग्री आक 28 लेबल के प्रवेश द्वार के सार चलते हुए मैंने उस गैलरी में फ्लैक बरमा छिद्र का केवल एक निशान देखा। दुर्घटना स्थल का दौरा करने के बाद में 29 लेबल के साथ-साथ समीपस्थ 39 डिग्री पर गया तथा 27 लेबल आक 39 डिग्री पर की फलक (फेम) का निरीक्षण किया जहाँ से वर्ष 1988 में एक लम्बा बरमा छिद्र ड्रिल किया गया था। मैंने 27 लेबल पर गैलरी में ड्रिल किए गए फ्लैक बरमा छिद्र देखे। मैंने 27 लेबल आक 39 डिग्री पर पिल्लर की सतहों पर रिसाव जल के निशान भी देखे। फ्लैक बरमा छिद्रों के नीचे थे। निशान मुस्पष्ट थे। भूमे दुर्घटना स्थल पर जाने गया निरीक्षण करने में तीन घण्टे लगे।

6.2 8 अप्रैल, 1991 को मैं खान गुरुआ महाविद्यालय तथा ई.सी.एस. के कुछ अधिकारियों के साथ सतह पर परिष्करण शाफ्ट सं. 33 और 31 का निरीक्षण करने गया। शाफ्टों के चारों ओर बन्द-पेड़ थे। निरीक्षण के दौरान, कुछ ग्राहक लोगों ने मुझे बताया कि 13 नवम्बर 1989, को दुर्घटना से पहले सतह पर शाफ्ट सं. 33 और 34 बिजुई नहीं देती थी क्योंकि वे मिट्टी से ढकी हुई थी और इस पर वनस्पति उगई गई थी। बाद में मैंने उन बरमा छिद्र के स्थल का निरीक्षण किया जहाँ से कैमूल द्वारा कथे हुए खनिजों का निकाला गया था। रास्ते में मैंने सड़क पर पड़े गड़े (गोटरोव) को देखा जो शाफ्ट दुर्घटना को तत्काल बाद हो गया था।

6.3 7 अप्रैल, 1991 को किए गए प्रथम छिद्रे का उद्देश्य मुख्यतः दुर्घटना स्थल की दशाओं का प्रत्यक्ष रूप से मूल्यांकन करना तथा 26 अक्तूबर, 1991 को किए गए छिद्रे की ओर का उद्देश्य उन घटनाओं का पुनः प्रदर्शन करना था जिनके कारण दुर्घटना हुई। 26 अक्तूबर, 1991 को चन्द्रशारी बराय (एम कुल्लू 14) तथा भीमो राजभार (सू. उल्लू-5) ने उन घटनाओं को उस के बारे में पुनः बताया जिसके कारण 13 नवम्बर, 1989 को उन अभागि मुख्य को 40 डिग्री फेम पर विस्फोट के बाद दुर्घटना हुई।

6.4.1 दुर्घटना स्थल के निरीक्षण के आधार पर मेरी रिपोर्ट निम्नांकित है :-

(1) 40 डिग्री गैलरी आक 28 लेबल के प्रवेश द्वार पर केवल एक फ्लैक बरमा छिद्र के निवाह, जिसे गार्डों के साथ किया फ्लैक बरमा छिद्र होने का कोई सबूत नहीं था। न्यायन्य निष्कर्ष के योजनार्थ द्वितीय निरीक्षण के दिन 40 डिग्री गैलरी तथा 27 के लेबल के कोटोशक तैयार किए गये जो अनुबंध-II पर हैं।

(2) यद्यपि यह स्वीकार किया जा सकता था कि देगा रॉय से पानी के अत्यधिक के कारण गैलरी की सतहों पर कुछ

निक्षेप था, लेकिन 40 डिग्री गैलरी के साथ किसी फ्लैक बरमा छिद्र होने का ऐसा कोई सबूत प्रमाण नहीं था जिससे विनिश्चित स्तरागतों पर फ्लैक बरमा छिद्रों की ड्रिलिंग के बारे में सलाहकार को सतह लिये गये शक्यों पर प्रतिक्रिया दिखे होना हो।

(3) 40 डिग्री गैलरी के साथ दुर्घटना स्थल के निकट तथा 27 लेबल पर गैलरी की चौड़ाई को प्रतिबिम्बित रूप से मापा गया जिसमें पता चला कि दुर्घटना से पहले गैलरी की चौड़ाई प्रारम्भ में लगभग 1.2 मी. थी।

(4) 28 लेबल तथा 40 डिग्री गैलरी के अंकन को सतह पर खाली स्थान या जहाँ से पर्यवर का एक बड़ा धाक खींचकर निकाला गया था और इसमें 40 डिग्री गैलरी के उत्पलवन की ओर लगभग साधा दिक्कर दिखाया गया था।

(5) 28 लेबल तथा 27 लेबल गैलरियों, जिनकी 28 लेबल तथा 31 के बीच कोंपरे का हल्का परत शामिल है, के साथ दुर्घटना स्थल पर, भू-विज्ञान का ऐसा कोई स्पष्ट प्रमाण नहीं था जिससे घातक दुर्घटना हो।

6.4.2 दुर्घटना स्थल के निरीक्षण के आधार पर, मुझे प्रबंधकों के कुछ भाषियों द्वारा दिए गए इस तर्क के समर्थन में कोई प्रमाण नहीं मिला है कि 8 नवम्बर, 1989 के बाद से 40 डिग्री गैलरी को चालित करने समय मध्य तथा फ्लैक बरमा छिद्रों को खोखा था। 1987 के विनियमन 127 में या गई लानि के अनुसार, मुख्यस्थित तरफ के ड्रिल किया जा रहा था। यह तर्क दिया जा सकता था कि मध्य बरमा छिद्रों का कोई सबूत नहीं होना क्योंकि कोलना निकालने समय से मध्य हो जाते थे परन्तु यदि 40 डिग्री आक 28 लेबल पर फ्लैक बरमा छिद्रों को व्यवस्था की जाता तो दुर्घटना स्थल का निरीक्षण करने समय वे दिखाई देते। उदाहरण के तौर पर, वर्ष 1989 में 27 लेबल पर पूर्वी बरमा छिद्र किए गए थे। जब मैंने दुर्घटना स्थल के समीपस्थ क्षेत्र का निरीक्षण किया और 27 लेबल तक गया तो वे फ्लैक बरमा छिद्र साबित दिखाई दे रहे थे।

## अध्याय-VII

- 7.1 निम्नांकित के समक्ष गुद्दे
- 7.2 शाफ्ट संख्या 34 का विस्तार
- 7.3 लानि का असामान्य रिसाव
- 7.4 एडवांस तथा बरमा छिद्र
- 7.5 प्रकाश (बकिंग) की अनुमति
- 7.6 एडवांस तथा छिद्र
- 7.7 दुर्घटना में निर्दिष्ट अन्य मापदंड

7.1.1 जैसाकि पहले बताया गया है कि दुर्घटना उस समय हुई जबकि विनिश्चित 40 डिग्री फेम आक 28 लेबल पुरानी तथा जवाबदायित्व शाफ्ट सं. 34 से जुड़ गया। दिखाई दिए गए घातकों तथा प्रस्तुत किए गए विनिश्चित गार्डों के आधार पर जोल सलाहकार के समक्ष निम्न-लिखित गुद्दे थे :-

(1) क्या पुरानी तथा परिवर्तन शाफ्ट सं. 34 के नारायणकुली शीम तक विस्तार था जलवायु महावीर शाह के अधिकारियों एवं प्रबंधक तथा उनके राष्ट्रीय कार्यरत साथ कार्यचारियों को था और क्या शाफ्ट की गार्डों का पता लगाने के लिये उन्होंने कर्मव्यवस्थापना नहीं की।

- (2) क्या उक्त कार्यवाहियों को पानों के अंशमाल्य रिमाइ का पूर्व विचारना हो गई था जिनसे पता चले कि बंकिम जला-प्लांटि। शाफ्ट संख्या 34 के गड़दना जा रही है।
- (3) क्या उक्त कार्यवाहियों का समूह बरमा छिद्रों की व्यवस्था करके समाधान हो गया था कि शाफ्ट सं. 34 का नारायण-कुंरो रोसा तम विश्वास नहीं हुआ है।
- (4) क्या उक्त कार्यवाहियों को 40 डिग्री गैलरी जॉफ 28 नेक्ल प्रचालित करने के लिए खान मुख्या महानिदेशालय की प्रचालन अनुमति थी।
- (5) क्या 40 डिग्री गैलरी ऑफ 28 नेक्ल को नष्ट तथा पूर्णक बरमा छिद्रों के उपयुक्त खतर से विकसित कर दिया गया था।
- (6) और दुर्घटना से संबंधित अन्य मामले।

7.1.2 इन कारणों तथा परिस्थितियों का पता लगाने के लिए इन मामलों का विवेचन वाद के पैराग्राफों में किया गया है जिनके कारण यह दुर्घटना हुई।

7.2.1 मो. कालिम, अधिकारी एवं प्रबंधक एम डब्ल्यू-17 (तथा तथा अन्यो का वर्ष तक या कि उन्हें भरसक प्रयासों के बावजूद यह जानकारी नहीं थी कि शाफ्ट सं. 34 नेमा सीम से आगे बढ़ गई है। इसके दूसरी ओर कार्यवाही वृत्तियों के प्रतिनिधियों का आरोप था कि शाफ्ट सं. 34 के नेमा सीम से आगे बढ़ जाने का पता लगाने के लिए अधिकारी एवं प्रबंधक तथा अन्यो ने पर्याप्त प्रयास नहीं किए।

7.2.2 अधिकारी एवं प्रबंधक, मो. कालिम (एम डब्ल्यू-17) तथा अन्य निम्नलिखित आधार पर इस निष्कर्ष पर पहुंचे कि शाफ्ट सं. 34 नेमा सीम से आगे नहीं पहुंची थी :-

(1) श्री गो.एल. बेनर्जी, मुख्या अधिकारी (एम डब्ल्यू-16) ने बताया कि महावीर खान में लगभग एक सौ पुरानी शाफ्टें हैं और उनमें से कुछ शाफ्ट सतह से भारी पड़ी हैं। शाफ्ट सं. 34 की ऐसी भारी हुई एक शाफ्ट थी और यह सतह पर नजर नहीं आती थी। बहुत सी पुरानी शाफ्टों को खान के प्लान में दर्शाया गया था। सांविधिक प्लान एजेंडविट एम-II में शाफ्ट सं. 34 की भी सतह से भरा हुआ दर्शाया गया था। इसको गहराई नहीं दी गई थी।

(2) पुरानी प्लानों में दर्शाया गई गहराई वाली सभी शाफ्टों से पता चला कि ये केवल नेमा सीम तक पहुंच गई थीं। कोई भी शाफ्ट ऐसा नहीं था जो नीचे की नारायणकुंरो सीम तक पहुंची हो।

(3) पुरानी शाफ्टों को पुराने प्लान अनुरेखित करके सांविधिक योजना एजेंडविट एम-II में अंकित किया गया था। वर्ष 1976 में, महावीर खान के तत्कालीन सर्वेक्षक द्वारा एक जीव सर्वेक्षण किया गया। इस सर्वेक्षण में उपलब्ध पुरानी शाफ्टों की गहराई मापी गई तथा उनको अद्यतनता का भी स्थापन किया गया। तथापि, एक सौ पुरानी शाफ्ट ऐसा नहीं पाई गई थी नेमा सीम से आगे पहुंची थी। शाफ्ट सं. 34 सतह पर नजर नहीं आता था और सतहों क्षेत्र पर एक निजा बनस्पति बोधका था। बूँकि यह सतह पर नजर नहीं आती थी इसको गहराई नहीं मापी जा सकी।

(4) वर्ष 1981 में नारायणकुंरो सीम अज्ञातस्थित नेमा सीम के नीचे विकसित हो गई थी और यह विकास भी कई पुरानी शाफ्टों के नीचे किया गया था। परन्तु इनमें से कोई भी शाफ्ट नारायणकुंरो सीम तक बढ़ी हुई नहीं पाई गई।

(5) श्री गो.एल. अकर (एम डब्ल्यू-15) तथा श्री. कालिम (एम डब्ल्यू-17) के अनुसार कोई ऐसा दस्तावेज रिपोर्ट उपलब्ध नहीं था जिससे पता चले कि शाफ्ट सं. 34 नारायणकुंरो सीम तक बढ़ गई है।

महावीर खान के पूर्व अधिकारी श्री के. के. मास (एम डब्ल्यू-18) के अनुसार अज्ञात के क्षेत्र को वर्ष 1926 की फेस्टिव प्लान तथा 1950 की रिवेन्यू प्लान में भी पुरानी शाफ्ट सं. 34 को नहीं दर्शाया गया।

(6) वर्ष 1925 की सीमा बंजान क्षेत्र कम्पनी की रानीगंज कोलियरी और 2 रानीगंज सीम की परिपक्व प्लान प्लान (एएमपी) (दस्तावेज एम/2ए) में शाफ्ट सं. 34 की समीपस्थ खान का सतह पर दर्शाया गया। एएमपी में शाफ्ट की गहराई 86 फुट (25.3 मी.) रिपोर्ट की गई जिससे पता चला कि यह केवल नेमा सीम तक बढ़ी हुई है।

(7) मो. कालिम (एम डब्ल्यू-17) ने निरीक्षण से सतह पर शाफ्ट सं. 34 का पता लगाने का प्रयास किया परन्तु वह पता नहीं लगा सका क्योंकि शाफ्ट पूर्णतः धरा हुई थी और गहरी भूमि का प्रयोग बनस्पति उगाने के लिए किया जाता था।

(8) वर्ष 1989 में, मो. कालिम (एम डब्ल्यू-17) को शाफ्ट सं. 34 की अनुमानित स्थिति की ओर नारायणकुंरो सीम में 27 झेलवन 30 डिग्री से झिल किया हुआ नमूना 40 गो. लंबे बरमा छिद्र का पता चला तथापि, यह लम्बा बरमा छिद्र न तो शाफ्ट को छू रहा था और न ही बरमा छिद्र से पानी का कोई रिमाइ था जिससे पता चलता कि शाफ्ट सं. 34 नारायणकुंरो सीम तक चला हुई है।

7.3.2 तथापि, कार्यवाही वृत्तियों का तर्क था कि मो. कालिम तथा अन्य खान अधिकारी स्थायी सतहों विशेषताओं के सम्बंध में करके सतह पर शाफ्ट सं. 34 का पता लगा सकते थे। वृत्तियों के सर्वेक्षण अनुसार बूँकि मो. कालिम (एम डब्ल्यू-17) और अन्य अधिकारियों ने शाफ्ट सं. 34 के विस्तार का पता लगाने के लिए न तो ऐसा कोई सर्वेक्षण किया और न ही कोई विशेष प्रयास किए इसीलिए ये कर्तव्य परावर्तना निदान में अभिकल रहे जिससे दुर्घटना हुई।

7.2.4 जीव स्वाधीन के रूप में मैंने दोनों पक्षकारों के उक्त तर्कों पर विचार किया। स्वाधीन के समझ ऐसा कोई साध्य प्रस्तुत नहीं किया गया जिससे पता चले कि शाफ्ट सं. 34 सतह पर दिखाई देती थी। सतह पर शाफ्ट सं. 34 के घेरे निरीक्षण के दौरान मैं उस क्षेत्र में अन्य बनस्पति देखी जिसके बोल में कहीं कहीं बनस्पति बोधका थे। मेरे निरीक्षण के दौरान उपस्थित यातायात जांचों ने भी मुझे बताया कि शाफ्ट दुर्घटना होने से पहले शाफ्ट सं. 34 सतह पर दिखाई नहीं देती थी।

7.2.5 अगला प्रश्न है कि क्या मो. कालिम (एम डब्ल्यू-17) तथा अन्यो द्वारा उचित प्रयास किए जाने से सतह पर शाफ्ट सं. 34 का पता लगाया जा सकता था। यह माना गया है कि पुरानी योजनाओं से अनुरेखण तथा पुनः अनुरेखण के कारण और सर्वेक्षण की अयथार्थता के कारण प्लान में दर्शाई गई शाफ्ट सं. 34 की स्थिति में गलती होने की संभावना है। चूंकि महावीर खान का सतहों क्षेत्र विस्तृत था और इस में ऊर्ध्व योग्य तथा क्षैत्र भूमि थी, जिसकी कोई प्रमुख सतही विशेषता नहीं थी, इसीलिए मिट्टी की अनजान परत के नीचे दबी हुई केवल 3 मी. व्यास की शाफ्ट का पता लगाना बहुत सासान न रहा होगा। समस्या तभी समझी जा सकती है जब यह देखा जाए कि महावीर खान के छह वर्षों कि. सी. सतही क्षेत्र पर 36 से अधिक घरी हुई शाफ्टें हैं। प्रश्न मेरा विचार है कि सतह पर घरी हुई शाफ्ट सं. 34 का पता लगाना अधिकारी एवं प्रबंधक, श्री. कालिम (एम डब्ल्यू-17) तथा अन्यो के लिए वास्तव में संभव नहीं था।

7.2.6 मो. कालिम (एम डब्ल्यू-17) तथा अन्य व्यक्तियों ने शाफ्ट सं. 34 की गहराई के संबंध में ए.एम.पी. (दस्तावेज एम/2ए) पर अधिक निर्भर किया परन्तु ए.एम.पी. (दस्तावेज एम/2ए) समीपस्थ 1 व 2 पिट बंकिम का था और न कि शाफ्ट सं. 34 से की गई बंकिम का ए.एम.पी. (दस्तावेज एम/2ए) में, शाफ्ट सं. 34 की केवल समीपस्थ खान का सतही विशेषता के रूप में दिखाया गया था। दूसरे ए.एम.पी. (दस्तावेज

एम/27) में यह रिपोर्ट दिया गया था कि "पुरानी शीट सं. 34 गहराई 86 फुट करीब करीब स्थिति पुरानी योजना में थी गई। इस प्रकार, ऐसी एएमपी (दस्तावेज एम/27) के आधार पर मो. कालिम (एम डब्ल्यू-17) को पुरानी शाफ्ट सं. 34 तथा इसका केवल गया सीम तक विस्तार को अनुमानित स्थिति स्वीकार नहीं करनी चाहिए थी। कोयला खानों में लगभग 28 वर्ष के अनुभव से मो. कालिम (एम डब्ल्यू-17) को इसकी जानकारी अवश्य थी कि गलत स्थान के कारण कायना खानों में सावधान के कारण पहले कई दुर्घटना हुई हैं। इस परिप्रेक्ष्य में उसे तथा सुरक्षा अधिकारी, श्री पी एल बैनर्जी, (एम डब्ल्यू-16) को एएमपी (दस्तावेज एम/27) के आधार पर ही शाफ्ट सं. 34 के नेमा सीम से खाने न बढ़ने के बारे में आवश्यक नहीं होना चाहिए था।

7.2.7 जलप्लावनितेया सीम के नीचे नारायणपुरी सीम की विकसित करने की अनुमति देने समय, खान सुरक्षा महानिदेशक ने पूर्व वरमा छिद्रों की व्यवस्था शामिल की थी यद्यपि प्रभावित अनुमति के लिए आवेदन करते समय तत्कालीन अधिकारों ने ऐसे बरमा छिद्रों के बारे में छूट की मांग की थी। स्पष्टतः खान सुरक्षा महानिदेशक को नारायणपुरी सीम में पुरानी बकिम की संभावना की आशंका थी और एएमपी (दस्तावेज एम/27) पर विश्वास नहीं था यह एक और कारण था कि मो. कालिम (एम डब्ल्यू-17) तथा श्री पी. एल बैनर्जी को बहुत ध्यानपूर्वक आगे बढ़ना चाहिए था क्योंकि 40 डिग्री ऑफ 28 लेवल ऐसा स्थान था जहाँ पुरानी शाफ्ट सं. 34 के होने की संभावना थी। यह तब है कि खानों (दस्तावेज एम/XI) में दो गई पुरानी शाफ्ट सं. 34 की ओर 27 लेवल फेन से एक लम्बा बरमा छिद्र ड्रिल किया गया यद्यपि बरमा छिद्र ने इसे अन्तर्द्वेषित नहीं किया। परन्तु यह निष्पत्ति साध्य नहीं हो सकती था कि शाफ्ट सं. 34 नारायणपुरी सीम तक बढ़ी हुई नहीं थी। इन बातों का को संभावना है कि लम्बा बरमा छिद्र केवल 3 मो. खान की शाफ्ट को अन्तर्द्वेषित न कर सके जैसा कि इन मामलों में हुआ। मो. कालिम (एम डब्ल्यू-17) तथा श्री पी. एल बैनर्जी (एम डब्ल्यू 16) की इतना अनुभव अवश्य रख थे कि उनकी इस बात की जानकारी थी।

7.2.8 दुर्घटना स्थल की योजना (दस्तावेज एम/12) से पता चलता है कि शाफ्ट सं. 34 को बकिम स्थान (दस्तावेज एम/11) पर दी गई स्थिति 6.5. मो. दक्षिण पश्चिम में गिराई हो गई। इस प्रकार अधिकारों एवं प्रबंधक मो. कालिम (एम डब्ल्यू-17) तथा श्री पी एल बैनर्जी, सुरक्षा अधिकारी (एम डब्ल्यू-16) ने एकल लम्बे बरमा छिद्र द्वारा उन्नत ध्वंस करायें गये आंकड़ों पर निर्भर रह कर गलती की कि शाफ्ट सं. 34 नारायणपुरी सीम तक बढ़ी नहीं है।

7.2.9 अब एक प्रश्न उठता है कि जब और कैसे से शाफ्ट सतह पर दिखाई दी। 13 नवम्बर, 1989 की प्रातः को दुर्घटना होने के कुछ बाद भरी हुई शाफ्ट सं. 34 सतह पर दिखाई दी। सीधी देर बाद शाफ्ट सं. 34 के निकट सतह पर धसकन तथा गहरे हो गए। इस बात को काफी संभावना है कि जब पानी नेमा सीम से निचला नारायणपुरी सीम की ओर बढ़ने लगा तो पनका जिससे शाफ्ट भरी हुई थी, खुल गया और सतह पर शाफ्ट सं. 34 दिखाई देने लगी।

7.3.1 अब मुझे यह विवरण करने दे कि क्या पानक दुर्घटना से एक दम पहले 40 डिग्री ऑफ 28 लेवल पर पानी का कोई अनामान्य रिसाव था। यह माना गया है कि सीम की ओर पानी का अनामान्य रिसाव यह सुस्पष्ट बतावती है कि बकिम किसी जलाप्लावित क्षेत्र की ओर जा रही है। कर्मचारी युनिटों ने बताया कि बकिम के पुरानी शाफ्ट सं. 34 के निकट होने के समय पानी का रिसाव अधिक था, परन्तु अधिकारों एवं प्रबंधक मो. कालिम (एम डब्ल्यू-17) तथा अन्य अधिकारियों का कहना था कि पानी का रिसाव सामान्य था। मो. खान वि. 1957 के विनियमन 127 में अन्य बातों के सामना यह व्यवस्था की गई है कि यदि किसी बकिम में किसी स्थान पर सीम की ओर पानी को अनामान्य रिसाव का पता चलता है या यदि ऐसा कोई आशंका या संदिग्ध हो तो ऐसी

बकिम को तत्काल बन्द कर दिया जाएगा और ऐसे रिसाव की सूचना तत्काल खान सुरक्षा महानिदेशक को दी जाएगी। तथा ऐसी बकिम का और विस्तार खान सुरक्षा महानिदेशक की लिखित पूर्व अनुमति तथा उसमें विनिर्दिष्ट बातों के अधीन किया जाएगा।

7.3.2 नारायणपुरी सीम की बकिम सामान्यतः शुष्क है। 1 दिसम्बर, 1988 में पुरानी शाफ्ट सं. 33 और 34 के निकट विकास कार्य करते समय पूर्व अधिकारों श्री के. के. दास (एम डब्ल्यू-18) ने 26, 27 तथा 28 लेवल ऑफ 39 डिग्री को पानी (फैसिन) में पानी के अनामान्य रिसाव की ओर ध्यान दिया। अधिकार, श्री पी. एल. डब्ल्यू (एम डब्ल्यू-15) ने पानी के इन अनामान्य रिसाव को और बकिम के पुरानी शाफ्ट सं. 34 की ओर जाने के बारे में अपनी तात्त्विक सर्वेक्षण डायरी में लिखा। मो. खान वि. 1957 के विनियमन 19 के अधीन अनामान्य रिसाव डायरी पर प्रबंधक मो. कालिम (एम डब्ल्यू-17) द्वारा प्रति हस्ताक्षर किए गए। पूर्व अधिकारों श्री के. के. दास (एम डब्ल्यू-18) ने भी उन पलकों में पानी के अनामान्य रिसाव की चेष्टा तथा इसे पानी निरीक्षण रिपोर्ट पुस्तक (दस्तावेज डब्ल्यू-15) में लिखा। इन क्षेत्र में बकिम बन्द कर दी गई तथा खान सुरक्षा महानिदेशक को सूचित कर दिया गया। इसके पश्चात् पूर्व अधिकारों, श्री के. के. दास (एम डब्ल्यू/18) ने 19 जनवरी, 1988 को खान सुरक्षा महानिदेशक को निम्ने पत्र (दस्तावेज एम/5) में बताया कि उक्त रिसाव को खान में रखने हुए उसने पहले खान सु. महा. द्वारा अधीनस्थ की गई। (दस्तावेज एम/5) शाफ्ट सं. 35 और 34 के निकट विकास परिणामों में परिवर्तन का पता लगाया तथा श्री के. के. दास (एम डब्ल्यू-18) ने पानी निरीक्षण रिपोर्ट (दस्तावेज डब्ल्यू/5) में लिखा कि 13 जनवरी, को देखा गया रिसाव 28 जनवरी, 1988 को रिपोर्ट प्रस्तुत करने समय कम हो गया था। परन्तु उसकी टिप्पणी सरपरे अनुमान पर आधारित थी न कि वास्तविक माप पर। श्री के. के. दास (एम डब्ल्यू/18) ने अपने बयान में यह भी कहा कि 27 लेवल पर छत में दरार से पानी का रिसाव हो रहा था। यदि यह ऐसा था तो उसने अपनी निरीक्षण रिपोर्ट (दस्तावेज डब्ल्यू-5) में यह भी रिपोर्ट किया होता। उसने ऐसा नहीं किया इसके विपरीत उसने लिखा कि छत और दोषाई (साईड) अच्छा थी। इसके प्रतिरिक्त, श्री के. के. दास (एम डब्ल्यू-18) का बकिम योजना (दस्तावेज एम/11) में दो शाफ्ट सं. 34 का स्थिति को और 27 लेवल ऑफ 39 डिग्री से मिल किए गए एक लम्बे बरमा छिद्र का पता लगा। तथापि, शाफ्ट सं. 34 बरमा छिद्र में नहीं रही था जैसा कि पहले बताया गया है। फिर भी श्री के. के. दास (एम डब्ल्यू-18) खान पूर्वक आने बड़ा और उन क्षेत्र में और विकास कार्य नहीं किया तथा पुरानी शाफ्ट सं. 34 से लगभग 100 मो. दूर संशोधित परियोजना में कार्य करने के लिए जायरी, 1988 में था. सु. महा. की फिर से अनुमति ली। प्रत्य यह है कि श्री के. के. दास (एम डब्ल्यू-18) ने जनवरी, 1988 के बाद 27 लेवल पर बकिम पर और कार्य क्यों नहीं किया। स्पष्ट था कि 27 लेवल पर पानी का रिसाव इतना अधिक था कि उसने नई परियोजना को बकिम के लिए था. सु. महा. की अनुमति ली। श्री के. के. दास (एम डब्ल्यू-18) ने अपने बयान में बताया था कि वह 27 लेवल पर एक लम्बा बरमा छिद्र करके पानी के रिसाव का अन्तर्द्वेषित करने के लिए प्रयत्न समय चाहता था। अब श्री के. के. दास (एम डब्ल्यू-18) का कार्य प्रणाली में सावधानी पश्चात् पूर्व अधिकारों, श्री के. के. दास (एम डब्ल्यू 18) ने 19 जनवरी, 1988 को खान सुरक्षा महानिदेशक को निम्ने पत्र (दस्तावेज एम/5) में बताया कि उक्त रिसाव के खान को खान में रखने हुए उसने पहले खान सुरक्षा महानिदेशक द्वारा अधीनस्थ की गई। (दस्तावेज एम/5) से शाफ्ट सं. 33 और 34 के निकट विकास परिणामों में परिवर्तन का पता लगाया। तथापि श्री के. के. दास (एम डब्ल्यू-18) ने पानी निरीक्षण रिपोर्ट (दस्तावेज डब्ल्यू/5) में लिखा कि 13 जनवरी, को देखा गया रिसाव 28 जनवरी, 1988 को रिपोर्ट प्रस्तुत करने समय कम हो गया था। परन्तु उसकी टिप्पणी सरपरे अनुमान पर आधारित थी न कि वास्तविक माप पर। श्री के. के. दास (एम डब्ल्यू-18) ने अपने बयान में यह भी कहा कि 27 लेवल पर छत में दरार से पानी का रिसाव हो रहा

था। यदि यह ऐसा था तो उनमें अपनी विशेष रिपोर्ट (इस्थाब्लिशमेंट 5) में यह भी रिकार्ड किया होता। उसने ऐसा नहीं किया इसके विपरीत उसने लिखा कि छत्र और बीदर (साईडिंग) अच्छी थी। इसके प्रतिस्तरण भी के के दास (एम डब्ल्यू 18) की बर्तमान योजना (इस्थाब्लिशमेंट 11) में भी शामिल सं. 34 की स्थिति की ओर 27 लेबल ऑफ 39 डिग्री में डिल किए गए एक खंडे बरमा छिद्र का पता लगा। तथापि, रॉबर्ट से. 34 खंडे बरमा छिद्र से जुड़ी नहीं थी जैसा कि पहले बताया गया है। फिर भी, श्री के के दास (एम डब्ल्यू 18) ध्यानपूर्वक जाने बढ़ा और उस क्षेत्र में और विकास कार्य नहीं किया तथा पुनः रॉबर्ट सं. 34 में लगभग 100 मी. दूर संशोधित परियोजना में कार्य करने के लिए जनवरी, 88 में खान सुरक्षा महानिदेशक की फिर से अनुमति थी। प्रश्न यह है कि श्री के के दास (एम डब्ल्यू 18) ने जनवरी, 1988 के बाद 27 लेबल पर वर्तमान पर और कार्य क्यों नहीं किया। स्पष्ट था कि 27 लेबल पर पानी का रिसाव होना अधिक था कि उसने नई परियोजना की बर्तमान के लिए था. सु. महा. की अनुमति थी। श्री के के दास (एम डब्ल्यू 18) ने अपने बयान में बताया था कि वह 27 लेबल पर एक लम्बा बरमा छिद्र करके पानी के रिसाव का अवलोकन करने के लिए अधिक समय चाहता था। अतः श्री के के दास (एम डब्ल्यू 18) की कार्यप्रणाली में लापरवाही सर्वाधिक महत्वपूर्ण थी। जब श्री के. के. दास (एम डब्ल्यू 18) ने सावधान रहने संबंधी इस प्रकार का संकेत दे दिया तो श्री. कान्तिम (एम डब्ल्यू 17) जो श्री के के दास के अधीन महाबोर खान का प्रबंधक था और जिसे इस संबंध में सभी विकास कार्यों की जानकारी थी, को खान सु. महा. की अनुमति के बिना नवम्बर 8, 1989 को 40 डिग्री गैररी ऑफ 28 लेबल (जो 39 डिग्री ऑफ 27 लेबल के बहुत नजदीक था तथा शामिल सं. 34 के भी नजदीक था) में कार्य आरम्भ नहीं करना चाहिए था। यह बताया महत्वपूर्ण है कि घातक दुर्घटना 30 डिग्री गैररी ऑफ 28 लेबल में कार्य शुरू करने के पांच दिन के बाद हो गई।

7.3.3 इस बात का माध्य विद्यमान है कि 30 डिग्री फोर ऑफ 28 लेबल को लगभग दो वर्ष बाद 8 नवम्बर, 1989 को दोबारा आरम्भ किया गया। श्री दोस्त पाण्डे (एम डब्ल्यू 10) श्री रामशंकर सरदार (एम डब्ल्यू 12) श्री शिवदास नेटर्जी (एम डब्ल्यू 9) श्री मिहिर कुमार नेटर्जी (एम डब्ल्यू 10) तथा श्री पन्नाचारी धराय (एम डब्ल्यू 14) सहित प्रबंधक के अधिकतम साक्षियों ने बताया कि 12 नवम्बर, 1989 को 30 डिग्री वर्किंग से पानी का कोई रिसाव नहीं था। तथापि, श्री गणेश राय (एम डब्ल्यू 5) ने बताया कि वे कार्मिकों की 32 आसकट की फलकों में रिसाव वाले पानी में पानी की योजना में भरा करते थे। दुर्घटना के दिन गैररी पार्स में 30 डिग्री के सोलर, श्री नूर मोहम्मद (एम डब्ल्यू 4) ने कहा कि 30 डिग्री फोर पर कुछ रिसाव के अभाव में यह काम शुरू था। इसके विपरीत यूनिक्स द्वारा पेश किए गए श्री राम नन्द मल्लो (एम डब्ल्यू 5) और श्री मंगी राजभार (एम डब्ल्यू 5) जैसे साक्षियों ने बताया कि 12 नवम्बर, 1989 को गैररी पार्स में 30 डिग्री को छत्र तथा फॉर फोर के पानी का रिसाव जाया था। 30 डिग्री फोर पर सुरक्षा खान के लिए पायवर्ती कोला घूल का निर्मित रखने के लिए पानी छिड़कों को कोई व्यवस्था नहीं थी। तथापि यह व्यवस्था इन भाग की अन्य फलकों में की गई थी।

7.3.4 प्रश्न यह है कि क्या घातक दुर्घटना से पहले पूर्व 30 डिग्री फोर ऑफ 28 लेबल पर पानी का रिसाव असामान्य था। यदि यह असामान्य था, तो अधिकारी एवं अधिकारी श्री. कान्तिम (एम डब्ल्यू 17) और उनके अंतर्गत अन्य अधिकारियों की ओर जवाबदायित्व बर्तमान के होने की पूर्व चेतावनी का चाहिए था और आवश्यक पूर्व सावधानी बरतना चाहिए था। यद्यपि प्रबंधक के अधिकतम साक्षियों (अर्थात् एम डब्ल्यू 9) ने बताया कि पानी का कोई असामान्य रिसाव नहीं था, लेकिन कप्तान यूनिक्स के सभी साक्षियों (अर्थात् एम डब्ल्यू 5) ने घातक दुर्घटना से ठीका पूर्व 30 डिग्री फोर पर पानी का असामान्य रिसाव के

बारे में बताया। तथापि, कार्यकारी, यूनिक्स के साक्षियों द्वारा पानी का रिसाव की जांच असामान्य बताई गई थी। रामनन्द मल्लो (एम डब्ल्यू 4) ने पानी के अधिक रिसाव के बारे में बताया जिससे सामान्य बर्तमान पर प्रभाव पड़ा। श्री मंगी राजभार (एम डब्ल्यू 5) जो अब सेवा निवृत्त हो गए हैं का बयान था कि दुर्घटना से पहले 30 डिग्री फोर पर पानी का रिसाव असामान्य था जो दुर्घटना के बाद लगभग 100 मी. दूर लगा कि श्री मंगी राजभार (एम डब्ल्यू 5) अप्रत्यक्ष तथा विपरीत साक्षी है। यदि उनके व्यवहार तथा सोचे गांधे-और मरल उत्तरों से प्रभावित हुआ। घातक दुर्घटना से पहले 30 डिग्री फोर पर पानी के असामान्य रिसाव के बारे में उनके बयान पर मेरा विश्वास है और मेरा विचार है कि श्री. कान्तिम (एम डब्ल्यू 17) और उनके अधीन अन्य अधिकारियों की तारापत्रकरी संम. जो अप्रत्यक्ष रूप से में जवाबदायित्व क्षेत्र में बर्तमान जाने की पर्याप्त जानकारी थी। स्वाभाविक है कि बर्तमान के पहले अधिक निरुद्ध जवाबदायित्व शापट के होने में 30 डिग्री फोर पर पानी का असामान्य रिसाव हुआ।

7.3.5 पूर्व अधिकारी, श्री के. के. दास (एम डब्ल्यू 19) और श्री. कान्तिम (एम डब्ल्यू 17) ने बताया कि 29, 27 तथा 28 लेबल की छत्र, जहाँ से वर्ष 1988 में पानी का रिसाव हुआ, धराय की ओर इसके लिए टोंग टेक (नोट) का आवश्यकता थी। तथापि दुर्घटना के पश्चात् इन बर्तमान के भेरे निरीक्षण के दौरान न तो छत्र में दरार और न छत्र धराय था तथा न ही टोंग टेक जाया हुई थी। यह छत्र उस भाग की अन्य बर्तमान का तरह सामान्य प्रतीत होती थी। उस क्षेत्र की योजना (इस्थाब्लिशमेंट 11) में जो भौतिक बाधा के होने का पता नहीं चलता था। मैंने था 27 लेबल ऑफ 39 डिग्री विशेषकर जहाँ 1988 में बर्तमान फलक बरमा छिद्र डिल किए गए थे, की दायार पर रह गए पानी के रिसाव के निशान देखे थे अतः वर्ष 1988 में 27 लेबल पर पानी का असामान्य रिसाव किसी आंशिक बाधा के कारण नहीं था बल्कि यह इसलिए था कि बर्तमान जवाबदायित्व शापट सं. 34 के अधिक निरुद्ध क्षेत्र की ओर बढ़ रहा था।

7.3.6 जैसा कि पहले ही बताया जा चुका है कि जनवरी, 1989 में पानी के असामान्य रिसाव के कारण 30 डिग्री की बर्तमान को बन्द कर दिया गया था और इस रिसाव को सप्तिहिक गुरुक में रिकार्ड किया गया था तथा खान सुरक्षा महानिदेशक को भी सूचित कर दिया गया था। अतः श्री. डा. वि. 1957 के विधियन 127 (5) की अपेक्षा अनुसार रा. सु. महा. की लिखित अनुमति के बिना श्री. कान्तिम (एम डब्ल्यू 17) की भी 8 नवम्बर, 1989 को 40 डिग्री फोर आक 28 लेबल को दोबारा शुरू करने का अधिकार नहीं था इस पर श्री. पी. गुरु बर्तमान गुरुक अधिकारी (एम डब्ल्यू 16) द्वारा भी आपत्ति नहीं की गई थी जिससे प्रमुख कार्यकारी खान में सुरक्षा सुनिश्चित करता था। श्री के दास (एम डब्ल्यू 10) महाबोर प्रबंधक ने भी पत्र जानते हुए भी विरोध नहीं किया कि 30 डिग्री ऑफ 28 लेबल ऐसा क्षेत्र है जहाँ पानी का अव्यक्त रिसाव है जहाँ कि वर्ष 1988 में काम बन्द कर दिया गया था और इस क्षेत्र में काम शुरू किया जाता था सु. महा. की बर्तमान अनुमति के अभाव में नहीं आता।

7.3.7 अब दुर्घटना शापट सं. 34 का पता लगाने के लिए वर्ष 1988 के में डिल किए गए लम्बे बरमा छिद्र के बारे में साक्ष्य का विवरण देन प्रकाश है। जनवरी 1988 में 28-27 तथा 28 लेबल फलकों (फैसिंग) पर पानी का रिसाव हुआ और सर्वेक्षक का पता पता जकर (एम डब्ल्यू 16) ने 30 लेबल पर प्रबंधक श्री. कान्तिम (एम डब्ल्यू 17) और पूर्व अधिकारी श्री के. के. दास (एम डब्ल्यू 18) को बताया कि बर्तमान शापट सं. 34 की ओर जा रहा है। इस प्रकार दुर्घटना शापट सं. 34 का अनुमानित स्थिति का और 27 लेबल ऑफ 39 डिग्री से एक लम्बा बरमा छिद्र डिल किए जाने का उद्देश्य किया गया। इन लम्बे बरमा छिद्र को डिल करने का उद्देश्य था कि शापट सं. 34 का पता लगाना 29 डिग्री फोर पर था. सु. महा. की बर्तमान अनुमति

(दस्तावेज एम/6) की शर्तों का अनुपालन भी किया जाय। श्री पी. एल. ठक्कर (एम. डब्ल्यू. 15) ने बरमा छिद्र की दिशा बताई जिससे कि यह नारायणपुरी सीमा में शापट सं. 34 की अन्तर्धीन कर सके। उनसे 27 लेबल आंक 39 डिग्री केस की स्थिति के अनुसंधान के अन्तर्धीन प्लान (दस्तावेज एम/11) पर दर्शाई गई शापट सं. 34 की स्थिति पर साक्षात् बरमा छिद्र की दिशा तथा लम्बाई का अनुमान लगाया। संश्लेषक द्वारा अंकित स्थान के आधार पर डिग्री और रोड मांफ्री (एम. डब्ल्यू. 8) में 27 लेबल के केस के लगभग मध्य में 133 फुट (40 मी.) लम्बा छिद्र ड्रिल किया। ड्रिलिंग कार्य श्री पी. एल. बैनर्जी (एम. डब्ल्यू. 16) के देख रेख में किया गया। श्री पी. एल. ठक्कर (एम. डब्ल्यू. 15) ने लम्बे बरमा छिद्र की लम्बाई भारी तथा हल्की दिशा का मसौदा किया जैने पुर्वतना न्यय के निरीक्षण के दौरान जब लम्बा बरमा छिद्र को देखा इस प्रकार मेरा समाधान हो गया है कि लम्बे बरमा छिद्र को शापट सं. 34 का पता लगाने के लिए साम्प्रत में वर्ष 1989 में ड्रिल किया गया।

7.4.2 श्री. कालिम (एम. डब्ल्यू. 17) ने खान बकिंग प्लान (दस्तावेज एम/11) में दर्शाई गई शापट सं. 33 और 34 की स्थिति में गलती की संभावना को स्वीकार किया। तथा श्री पी. एल. बैनर्जी (एम. डब्ल्यू. 16) ने बताया कि इस लम्बे बरमा छिद्र के सम्भाव्य विचलन को रोकना सम्भव नहीं था और उनके पास यह आज करने के लिए ऐसा कोई उपकरण उपलब्ध नहीं था कि क्या लम्बा बरमा छिद्र वास्तव में अपने स्थान से हट गया है। श्री पी. एल. ठक्कर (एम. डब्ल्यू. 15) ने बताया कि यदि डिग्री पर्याप्त सावधानी न करते तो बरमा छिद्र के विचलित होने का पूरी संभावना थी। इस प्रकार लम्बे बरमा छिद्र के विचलित होने तथा पुरानी शापट सं. 34 की अन्तर्धीन न करने को समाधान था। श्री. कालिम (एम. डब्ल्यू. 17) और श्री पी. एल. बैनर्जी (एम. डब्ल्यू. 16) के पूर्णतः विश्वस्त होने का कोई आधार नहीं था कि 133 फुट (40 मी.) का लम्बा बरमा छिद्र पुरानी शापट सं. 34 की पार गया है।

7.4.3 तबोपलान, प्रबंधन द्वारा दुर्वर्तना स्वयं का सर्वेक्षण किया गया तथा एक प्लान (दस्तावेज एम/12) तैयार की गई इसमें बताया गया कि शापट सं. 34 की वास्तव में खान बकिंग प्लान (दस्तावेज सं. एम/11) में दर्शाई गई स्थिति में 6.5 मी. दूर था। अतः लम्बा बरमा छिद्र नारायणपुरी सीमा में पुरानी शापट सं. 34 की अन्तर्धीन करने में असमर्थ रहा। इस प्रकार, वर्ष 1988 में 27 लेबल पर केवल एक लम्बा बरमा छिद्र ड्रिल करने से सुनिश्चितता को गलत भावना पैदा हो गई कि कि शापट सं. 34 नारायणपुरी सीमा तक नहीं पहुँचा है।

7.5.1 28 लेबल पर 40 डिग्री पर कार्य करने के लिए अधिकृत-एवं-प्रबंधक श्री. कालिम (एम. डब्ल्यू. 17) द्वारा खा. सु. महा. को बकिंग अनुमति प्राप्त किए जाने के बारे में विस्लेषण इस प्रकार है। कर्मचारी युनियनों द्वारा लिखित आरोप लम्बाया गया कि खा. सु. महा. की बिना किसी बकिंग अनुमति के 40 डिग्री साफ 28 लेबल की 8 नवम्बर 1988 में विकसित किया जा रहा है। हमारे और प्रबंधन का तर्क था कि उनके पास खा. सु. महा. की वैध अनुमति है और इसलिए 40 डिग्री साफ 28 लेबल के जांच को अनुमति है।

7.5.2 श्री. खा. दि. 1957 के विनियमन 107 में अपेक्षा की गई है कि विनिर्दिष्ट शर्तों के अधीन खा. सु. महा. की बिना पूर्ण लिखित अनुमति के किसी बकिंग विस्तार या किस जलसंचयित अकिंग के 60 मी. के अन्तर नहीं किया जाएगा। विनियमन में यह भी अपेक्षा की गई है कि ऐसी किसी बकिंग के विस्तार की अनुमति के लिए प्रत्येक आवेदन पर के साथ प्लान संलग्न किए जाएँ जिनमें अन्य बातों के साथ-साथ दस्तावेज बकिंग की रूप रेखा, व्यू तथा निधि दी गई हो। यदि बकिंग के विस्तार के लिए खा. सु. महा. द्वारा अनुमति दे दी जाती है तो इसका विस्तार पूर्णतः अनुमोदित योजना, विधि और इसमें विनिर्दिष्ट शर्तों के अन्तर्गत में किया जाएगा। बकिंग अनुमति में दो गई

शर्तों में अधिकतम एवं न्यूनतम द्वारा कोई परिवर्तन किए जाने का कोई भी कारण नहीं है जब तक ऐसी परिवर्तन को संतोखा खा. सु. महा. द्वारा अनुमोदित न किया गया हो।

7.5.3 दिसम्बर, 1983 में प्रबंधन ने मुखा रेखने लाइन के दक्षिण में नारायणपुरी सीमा क्षेत्र को विकसित करने की अनुमति के लिए आवेदन किया आवेदन पत्र (दस्तावेज एम/4) के साथ प्रस्ताव को गई योजना में पुरानी शापट सं. 33 तथा 34 के बीच विकास की परियोजना दर्शाई गई। इस विकास के लिए खा. सु. महा. के 12 मार्च, 198 के पत्र सं. एस-3/173 (बी डी. एम. बी) II-बी 84/1062 (दस्तावेज एम/5) के तहत बकिंग अनुमति प्रदान की गई थी, इनमें बहु क्षेत्र शामिल किया गया था जहाँ 13 नवम्बर, 1989 की दुर्वर्तना हुई। बकिंग अनुमति में अपेक्षा की गई थी कि पुरानी शापट जगाए गए स्थान के ऊपर हो। इस अनुमति के अनुसार होत स्थलों में शापट की रोकेने हुए शापट सं. 33 तथा 34 की स्थिति में पत्र 26 लेबल तथा 31 लेबल के बीच के क्षेत्र को विकसित किया जा सकता था। इस प्रकार, वर्ष 1984 में बकिंग अनुमति प्रदान करने समय, खान मुखा महाविभाग ने भी मुखा पूर्वोपायों की और पर्याप्त ध्यान दिया था।

7.5.4 तथापि, पूर्व अधिकारी, श्री के. के. दाम (एम. डब्ल्यू. 18) ने 19 जनवरी, 1988 के अपने पत्र सं. ई सं. एल : एम-बी डी-बी 88/198 में पुरानी शापट सं. 31 के विपट 26 लेबल साफ 38 डिग्री तथा 27 लेबल आंक 39 डिग्री केसों (सिग) में पानी के अनायास रिसाव का ध्यान में रखते हुए खा. सु. महा. से विकास परियोजनाओं में परिवर्तन की अनुमति मांगी।

7.5.5 योजना के प्रोजेक्शन की तुलना 1983 (प्रदर्श-एम/4) के लिए अनुमति के अनुप्रयोग के साथ 1988 (प्रदर्श-एम/7) में करने पर पता चलता है कि संशोधित प्रोजेक्शन (प्रदर्श-एम/7) में 26 और 31 स्तरों के बीच किए जा रहे कार्य की पुरानी शापट सं. 33 एवं 34 की और जाने नहीं किया जाना चाहिए था। पुरानी शापटों को 32 स्तर से शापट के बाद बाइपास किया जाना था। 41 श्राव कट नामक भ्रमने खान कट की शापट सं. 33 से 45 मीटर की दूरी पर और शापट सं. 34 से 100 मीटर की दूरी पर हटाया जाना था 41 काम कट के गहराई वाले भाग का पानी विकास करने का प्रस्ताव नहीं था।

7.5.5 खान मुखा महा. के दिनांक 2 मार्च, 1988 (प्रदर्श-एम/8) के अपने पत्र सं. एस-3/22.03/062/II ए/88/623 में नए प्रोजेक्शन (प्रदर्श-एम/7) के अनुसार नारायणपुरी सीमा का विकास करने के लिए संशोधित अनुमति दी थी। तथापि, खान मुखा महा. के पूर्व अनुमति सं. 1062 दिनांक 12 मार्च, 1984 (प्रदर्श-एम/5) में निर्धारित शर्तों की कटवा नहीं गया था।

7.5.6 पूर्व एजेंट, श्री के. के. दाम (एम. डब्ल्यू. 18), प्रबंधक, सु. कार्यालय (एम. डब्ल्यू. 17), मुखा अधिपति श्री पी. एल. बैनर्जी (एम. डब्ल्यू. 16) का यह विचार था कि 1984 की अनुमति (प्रदर्श-एम/5) द्वारा मंजूर की गयी विकास का प्रोजेक्शन तब भी वैध था जब उन्होंने विशेष करणों से प्रोजेक्शन (प्रदर्श-एम/7) में संशोधन के लिए इच्छा व्यक्त की थी और तबतुसार उन्होंने 1988 (प्रदर्श-एम/8) की अनुमति मिली थी। हमारे कार्यों में, 1988 की अनुमति 1984 का अनुमति का अतिक्रमण नहीं करती थी और इसलिए नवम्बर 8, 1989 से 28 स्तर पर 40 डिग्री का विकास अनुमति प्राप्त क्षेत्र में किया गया था। मेरे विचार से खान मुखा महा. के लिए "1983 की अनुमति" में वर्गीकृत कटी हुए यह उल्लेख करना अनावश्यक नहीं था कि "1984 की अनुमति" कर दी गयी थी। इस प्रकार का उल्लेख स्वतः स्पष्ट था, क्योंकि पूर्व एजेंट श्री के. के. दाम (एम. डब्ल्यू. 18) ने स्वयं शापट सं. 34 के लंबाई का 27 एवं 38 स्तरों के बीच बताया था कि

रिसने को घटना की देखरेख हुए संशोधन का अनुसंधान किया था। इसके अलावा, प्रबंधन का यह कथन कदापि मानने योग्य नहीं है, क्योंकि यथोक्त विनियमन 127 (5) में स्पष्ट रूप से कहा गया है कि यदि ज्यादा पानी रिसने के कारण किसी विशेष क्षेत्र में एक बार कार्य रोक दिया जाता है तो उस क्षेत्र में पुनरा कार्य तब तक नहीं शुरू किया जाएगा, जब तक खान सुरक्षा महाविभाग से लिखित रूप में तभी अनुमति प्राप्त न हो जाए। इस मामले में, खान सुरक्षा महाविभाग ने कोई नया अनुमति नहीं दी थी। अतः 28 नवंबर के 40 डिग्री के पानी 8 नवंबर 1989 से खनन कार्य शुरू करना, जिसकी जनवरी, 1988 में ज्यादा पानी रिसने के कारण बंद कर दिया गया था, बिल्कुल गलत था। श्री. कलीम (एम. डब्ल्यू. 17) श्री पी. एन. बनर्जी (एम. डब्ल्यू. 16) और श्री के. दत्त (एम. डब्ल्यू. 18) वरिष्ठ और उत्तरदायी अधिकारी हैं और इनके पास प्रबंधक कृपाया का प्रमाणपत्र है। इन अधिकारियों को विनियम के इस महत्वपूर्ण महसूस करना चाहिए था।

7.5.5 प्रबंधन का यह कहना है कि जब पानी जमाव क्षेत्र एक ही सीमा में स्थित होता है, तब यह आवश्यक होता है कि एक बाँध का बोरहोल और चनेक अगल बगल बोरहोल ड्रिल किया जाए, लेकिन यदि प्रस्तावित कार्यक्षेत्र के ठीक ऊपर पानी जमाव स्थल विद्यमान है तो 3 मीटर लंबे अगल बगल बोरहोल बनाना आवश्यक होता है और धागे किसी शैक्षणिक छात्रों की संभावना का पता लगाने के लिए केवल एक बाँध का बोरहोल बनाना अपेक्षित होता है। लेकिन इस बल्ल में ज्यादा दम नहीं है, जैसा कि आने के निरीक्षण से स्पष्ट हो जाएगा।

7.5.6 नंगा और नारायणपुरी सीमा के बीच का अंतर केवल 24 मीटर है और एक अज्ञात गहराई का पुराना शाफ्ट है, जो गावद नारायणपुरी सीमा तक बढ़ गया हो। नारायणपुरी सीमा तक एक पुराने शाफ्ट था ऊपर वाले सीमा के डिप्टी के गार्डम से नारायणपुरी सीमा में पुराने कार्यक्षेत्रों के होने की संभावना से इनकार नहीं किया जा सकता। अतः यह माना नहीं जा सकता, जैसा कि प्रबंधन का कथन है, कि पानी जमाव क्षेत्र केवल ऊपर वाले सीमा में स्थित था और इस प्रकार आगे अगल बगल छेद करना आवश्यक नहीं था। खान सु. महा. निदेशालय की अनुमति (प्रवेश एम/5) में इन सभी संभावनाओं का ध्यान रखा जाना था, क्योंकि खान सुरक्षा महा. ने सेन्ट्रल बोरहोल के साथ उचित संख्या में अगल बगल भी बोरहोल बनाने का आदेश दिया था।

7.5.7 इसका यदि विस्तृत रूप से वर्णन किया जाए तो इस प्रकार है:— मद्रासीर खान के नारायणपुरी सीमा के लिये खान सुरक्षा भागा, की 1984 और 1988 में दी गयी कार्य अनुमति पूर्णतया विनियमन 127(6) (क) के अनुसार थी, जिसके द्वारा यह अपेक्षित था कि जब पानीजमाव क्षेत्रों की आर कार्य बढ़ाया जाये तो कार्यक्षेत्र के मध्य भाग के सर्वांग कम से कम एक बोरहोल बनाया जाये और दोनों और उचित संख्या में फलैक बोरहोल बनाये जायें, और जहाँ आवश्यक हो कार्य स्थल के ऊपर और नीचे भी बोरहोल बनाये जायें जिनकी एक दूसरे से दूरी 5 मीटर से ज्यादा न हो। ऐसे सभी बोरहोल बनाए जाए और कार्यक्षेत्र के गहरे उचित दूरी से इस पर ध्यान रखा जाये और किसी भी मामले में यह दूरी 3 मीटर से कम न हो। इन प्रावधानों का पालन विधेय रूप से इस उद्देश्य के लिये प्राधिकृत खान अधिकारी द्वारा, जिसके पास प्रबंधक या सौभर मैन का प्रमाणपत्र हो, किया जाना अपेक्षित है। संश्ल विनियमन के अन्तर्गत, पारंपरिक की ऊँचाई और चौड़ाई तथा बोरहोल की गहराई उनकी लंबाई और विना का रिकार्ड एक रजिस्टर में दर्ज किया जाना अपेक्षित है और इस रजिस्टर पर प्रोसेसिंग इस उद्देश्य के लिये प्राधिकृत अधिकारी द्वारा हस्ताक्षर और प्रबंधक द्वारा प्रमाणित किया जाना होता है। इन रिकार्डों का पालन श्री. कलीम एजेंट-नई प्रबंधक (एम. डब्ल्यू-17) और उनके पर्यवेक्षण कार्य कर रहे कर्मचारियों द्वारा नहीं किया गया।

7.6.1 अब मुझे सबसे ज्यादा महत्वपूर्ण मुद्दे से संबंधित साक्ष्यों का विश्लेषण करना है कि क्या 8 नवंबर 1989 से शुरू किए गए चासीसर्वे डिप के गुरुत्वे पर किये जा रहे कार्य में सेन्ट्रल और फलैक बोरहोल की उचित सुरक्षा थी मोहम्मद कलीम (एम. डब्ल्यू. 17) ने यह कहा है कि खान सुरक्षा महाविभाग की कार्य अनुमति तथा कीयला खान नियमावली, 1957 के विनियमन 127 की अपेक्षाओं का पालन सुनिश्चित करने के काम में उन्होंने ट्रिलिंग मशीन जनशक्ति और पर्यवेक्षण जैसी प्राविधिक अथ संरचनाओं की व्यवस्था की थी। एडवांस बोरहोल का सामान्य कीयला डिपों में ड्रिल किया गया था। इन प्रावधान में मुद्दे पर एक सेन्ट्रल बोरहोल और गुरुत्वे से 45° पर दो फलैक बोरहोल शामिल थे। फलैक होल की लंबाई 3 मीटर से 3.6 मीटर तक थी और इनके दोनों रिबों में ड्रिल किया गया था। होल ड्रिल करने के उद्देश्य से 1.8 मीटर 3.6 मीटर और 5.4 मीटर की लम्बाई वाले स्टील ट्रिलों के तीन सेटों सहित एक कायदा ड्रिल का प्रावधान किया गया था।

7.6.2 इस बात के प्रमाण हैं कि जून 1989 तक एडवांस ट्रिलिंग गैंग की गतिविधि निर्यात रूप में उपलब्ध करवाई गई थी। ट्रिलिंग गैंग के ये कर्मकार, जिनकी ट्रिलर कहा जाता है के नाम श्री. कुलदीप दास (ए. डब्ल्यू. 1) भारी दुसाद और बिंदु धावरी थे। यह ट्रिलिंग गैंग प्रथम पारी के आरम्भिक घंटों में जिन में पहुँच जाया करता था और बढ़ाए जाने के लिए प्रस्तावित सभी मुद्दों से बोरहोल ट्रिलिंग का कार्य उन्नी दिन समाप्त कर दिया करता था। तथापि जून 1989 में मोहम्मद कलीम (एम. डब्ल्यू. 17) एजेंट सह प्रबंधक द्वारा ट्रिलिंग गैंग को बंद कर दिया गया और ड्रिलों की अन्य कार्यों में लगा दिया गया था। श्री. कुलदीप दास (ए. डब्ल्यू. 1) के अनुसार चूँकि जून 1989 में ट्रिलिंग गैंग को बंद कर दिया गया था इसी लिए कोई एडवांस बोरहोल ड्रिल नहीं किया गया था। श्री. कलीम (एम. डब्ल्यू. 17) और श्री पी. एन. बनर्जी (एम. डब्ल्यू. 16) ने यह कहा है कि जनशक्ति के बेहतर उपयोग के लिये एडवांस ट्रिलिंग गैंग को बंद कर दिया गया था। तथापि एडवांस बोरहोल के ट्रिलिंग का कार्य प्रथम पारी के सामान्य मजदूरों द्वारा किया जा रहा था और ऐसी एडवांस सेन्ट्रल बोरहोल और फलैक बोरहोल का प्रावधान 40 डिग्री फेस में किया था, जब 8 नवंबर 1989 से इसको प्रारम्भ किया गया था। उसके बाद प्रबंधन द्वारा प्रस्तुत गवाहों के अनुसार इन सभी बोरहोल की नियमित रूप से ड्रिल किया जाता था और 12 नवंबर 1989 को पहली पारी में एडवांस सेन्ट्रल बोरहोल की 3.6 मीटर से 5.4 मीटर तक बढ़ाया गया था 3.9 मीटर से 3.6 मीटर की लम्बाई वाले दो बोरहोल की 40 डिग्री फेस के रिब में ड्रिल किया गया था। इन एडवांस बोरहोल की ट्रिलिंग श्री. भिदिन कुमार चटर्जी (एम. डब्ल्यू-16) और श्री सी. डी. सिंह (एम. डब्ल्यू. 11), सौभरमैन के पर्यवेक्षण में की गयी थी। उन्होंने सभी एडवांस बोरहोल की लम्बाई की सही पाया था। दूसरी पारी में, श्री शिवदास चटर्जी (एम. डब्ल्यू. 9) सौभरमैन ने एडवांस बोरहोल की जाँच की और उन्हें पाया जाता कि इसको लम्बाई 3.6 मीटर थी। उन्होंने एडवांस फलैक बोरहोल की जाँच की और इसे लम्बाई पाया तीसरी पारी में श्री. दत्त पाण्डेय, सववार (एम. डब्ल्यू. 13) ने जो 40 डिग्री फेस के सेन्ट्रल बोरहोल की जाँच की और उन्हें पता चला कि इसकी लंबाई 3 मीटर से अधिक थी। शाद कायर श्री चंद्रशेखर बरोड़े (एम. डब्ल्यू. 14) ने यह कहा कि कुर्बटना के दिन 40 डिग्री फेस में शाद काज करने के पूर्व, उन्होंने अपना 1.8 मीटर लंबा छड़ी से सभी सेन्ट्रल और फलैक बोरहोल की जाँच की थी और उन्होंने अपने कहा कि ये होल उस समय 1.8 मीटर से ज्यादा लंबे थे। तथापि श्री. धनी राजभर (एम. डब्ल्यू. 5), जिन्होंने कुर्बटना के ठीक पहले 40 डिग्री फेस शाद-हाल की जाँच किया था, ने यह कहा कि फेस में की गई एडवांस और फलैक बोरहोल नहीं था। उन्होंने दावा किया कि ये शाद होल और एडवांस बोरहोल में शाद समझते हैं।

गणेश राय (एम. डब्ल्यू 5) और श्री राम शंकर महतो (एम. डब्ल्यू 4) जैसे अन्य गवाहों ने भी फेस में कोई एडवांस होल नहीं देखा।

7.6.3 यहाँ एक उल्लेखनीय बात यह है कि वैसे सभी गणितज्ञों जिन्होंने यह कहा है कि एडवांस और होल ड्रिल किए गये थे, वे इस होलों की ड्रिल करने वाले एक भी ड्रिलर का नाम तक नहीं बताया। केवल एक गवाह श्री सी. डी. मिह (एम. डब्ल्यू-11) ने माधुरी पासवान नामक एक ड्रिलर का नाम बताया। लेकिन वे भी उस ड्रिलर के पदनाम के बारे में निश्चित नहीं थे। आरंभ में उन्होंने कहा कि यह ड्रिलर एक सामान्य मजदूर है लेकिन बाद में उसका पदनाम ड्रिलर के रूप में बताया। चूंकि एडवांस बोरहोल की ड्रिलिंग निर्दिष्ट रूप से होती है, जैसा कि एजेंट-सह प्रबंधक श्री कर्मीम (एम. डब्ल्यू-17) और उनके अधीनस्थ कार्य कर रहे कर्मचारियों का कहना है अतः यह असंभव है कि एजेंट-सह प्रबंधक से नीचे के कर्मचारियों में से किसी का भी, जो 28-स्तर के 40 डिग्री एडवांस बोरहोल के पर्यवेक्षण से संबंध है, इस एडवांस बोरहोल ड्रिल करने वाले किसी भी व्यक्ति का नाम बाद न हो। दूसरी बात यह है कि एक सामान्य कोयला ड्रिल से 5.4 मीटर के एक एडवांस बोरहोल की ड्रिल करने से अधिक रूप से ड्रिल रांड में परिवर्तन होता है। ड्रिल हॉल का मध्य में ड्रिल किया जाता तथा फेस से 45° पर ड्रिल किया जाता अपेक्षित होता है। अतः इस बात से उत्पन्न नहीं किया जा सकता है कि एडवांस बोरहोल को ड्रिल करने में उसकी कुशलता चाहिये जितनी की फेस के साट होल का ड्रिल करने के लिये अपेक्षित होती है। यह असंभव है कि यह कार्य नैमित्तिक आधार पर इस काम पर लगाये गये सामान्य मजदूरों से हो सकता है, जैसा कि श्री कर्मीम, एजेंट-सह प्रबंधक (एम डब्ल्यू 17) और अन्य अधिकारियों का दावा है।

इसके अलावा इस स्वायालय के समक्ष एवाट के रूप में प्रस्तुत किसी भी पर्यवेक्षी अधिकारी ने कोयला खान नियमावली, 1957 के नियम 127 (6) के अन्तर्गत निर्दिष्ट जर्नों के अधीन एडवांस होल के पर्यवेक्षण का उत्तरदायित्व स्वीकार नहीं किया गया। श्री कर्मीम (एम. डब्ल्यू 17) ने यह कहा कि उन्हें याद है कि उन्होंने इस उद्देश्य के लिये दो ओवर सैनों की प्राधिकृत किया था, पर वे श्री मुखर्जी को डेपुटी कमिश्नर और का नाम नहीं बता सके। तथापि, कोई ऐसे व्यक्ति अर्थात् श्री मुखर्जी को प्रबंधक द्वारा गवाह के रूप में पेश नहीं किया था। श्री मिहिर चटर्जी, ओवरमैन (एम. डब्ल्यू 10) ने एडवांस बोरहोल के पर्यवेक्षण का उत्तरदायित्व केवल उस हद तक स्वीकार किया है उनकी आमतौर पर श्री कर्मीम (एम. डब्ल्यू 17) एजेंट सह प्रबंधक द्वारा एडवांस बोरहोल के कार्य का पर्यवेक्षण करने को कहा जाता था, पर कोयला खान नियमावली, 1957 के नियम 127 के अन्तर्गत अपेक्षित तरीके से ऐसे बोरहोल के निरीक्षण के लिये उनको अधिकृत नहीं किया गया था। श्री कर्मीम (एम. डब्ल्यू-17) ने यह स्वीकार किया कि 28 स्तर के बगल वाले 40 डिग्री या महावीरान के अन्य कार्य मुहानों पर एडवांस बोरहोल का प्रतिवार्य रिकार्ड रखा गया।

7.6.4 एडवांस सेन्ट्रल बोरहोल को 5.4 मीटर अथवा ड्रिल से और फलैक बोरहोल को 3.0 मीटर से 3.6 मीटर लंबा ड्रिल से की मानिटिंग की पद्धति और प्रक्रिया तथा फेस से 45° का स्थल टिप्पण प्रबंधक श्री कर्मीम (एम. डब्ल्यू 17) द्वारा साफ शब्दों में बताया गया था। साध्यों के विप्लेक्षण से यह पता चलता है कि कभी भी पर्यवेक्षी टास्क फेस पर जाता था, तथा वे एडवांस बोरहोल की ताल-बोख करने थे। एवाट रिकार्ड रखने और इसको मानिटिंग से की कोई नियमित व्यवस्था नहीं थी।

7.6.5 दुर्घटना के बाद 40 डिग्री फेस के मेरे निरीक्षण के उन मेरे फलैक बोरहोल गैलरी के शुरू में एक को छोड़कर, के किसी प्रमाण को नहीं देखा। वे फलैक बोरहोल यदि ड्रिल किए जाते हैं तो जेबे में छोड़ दिया जाता है। इस मुद्दे पर स्वायालय के प्रश्न के मेरे श्री पी. एल. बनर्जी (एम. डब्ल्यू 16) और श्री के. दत्ता

(एम. डब्ल्यू 19) ने यह कहा कि जब पानी का सोया फूटा तो फलैक बोरहोल पानी में डूब गये और पानी के कारण इनका निष्पान मिट गया। तथापि, 40 डिग्री चौड़ाई जिनके के अन्य गैलरी की तरह ही है, प्रदर्शित करीब 4.2 म. 4.5 मीटर इतनी चौड़ाई है। विचारों और उन सामान्यतः उसी तरह उबल खाबल दिखायी देने हैं, जैसा कि कोई गैलरी ब्लास्टिंग के बाद विकसित की जाती है। अतः श्री पी. ए. बनर्जी (एम. डब्ल्यू-16) तथा प्रबंधक और इन्डियन माइन मैनजर्स एसोसिएशन का यह कथन कि फलैक बोरहोल को सामान्यतः पानी के प्रवाह से मिट गया, निष्काय करने योग्य नहीं है। इसी तरह, अन्य जाने जाने पानी के प्रवाह के कारण फलैक और कोयला खान से पानी बोरहोल के बंद हो जाने की सम्भावना का भी स्वीकार नहीं किया जा सकता क्योंकि दुर्घटना स्थल पर मेरे द्वारा किये निरीक्षण संबंधी विप्लेक्षण से इस बात की पुष्टि नहीं होती।

7.6.6 दुर्घटना स्थल पर निरीक्षण के दौरान किए गये विप्लेक्षण के आधार पर, जिसमें साफ पता चलता है कि फलैक बोरहोल नहीं किये गये थे, श्री मेरी राजभर जैसे पर्यवेक्षी गवाह (एम. डब्ल्यू. 5), बोरहोल के न्यूनतम प्रतिवार्य रिकार्ड प्रस्तुत करने में खान प्रबंधक की असफलता और ऐसे किसी भी एक गवाह को पेश नहीं किया जाना जिसने वामन में एडवांस बोरहोल ड्रिल किया था, मेरा यह विचार है कि दुर्घटना की तारीख 12 नवम्बर 1989 को 40 डिग्री फेस में कोई एडवांस सेन्ट्रल और फलैक बोरहोल ड्रिल नहीं किया गया था। यह कोयला खान नियमावली, 1957 के नियम 127(6) का पूर्ण रूप से जानबूझकर किया गया उल्लंघन था।

7.6.7 दुर्घटना स्थल पर अपने निरीक्षण के दौरान मैंने देखा कि 40 डिग्री गैलरी जिनके की किसी अन्य गैलरी से भिन्न नहीं हैं। फलैक होल की व्यवस्था वाले मसीप के अन्य गैलरीयों सहित किसी अन्य गैलरी की चौड़ाई, लंबाई और रूपरेखा है। 40 डिग्री गैलरी का विचारों में, गैलरी के आरंभ एक फलैक बोरहोल को छोड़कर कोई अन्य फलैक बोरहोल होने का कोई प्रमाण नहीं है।

7.6.8 मेरे विचारों में श्री पी. एल. बनर्जी (एम. डब्ल्यू-16) श्री सी. डी. मिह (एम डब्ल्यू-11) श्री मिहिर कुमार चटर्जी (एम. डब्ल्यू 10), श्री बंद्योपध्याय बराई (एम. डब्ल्यू 14) और श्री के. दत्ता का यह कथन कि 4.2 मीटर की सामान्य चौड़ाई के मुकाबले 10 डिग्री गैलरी चौड़ाई केवल 3 मीटर थी, अवश्य थी। यह कथन संभवतः इस बात को व्योचित ठहराने के उद्देश्य से दिया गया था कि 40 डिग्री में बताये गये फलैक बोरहोल अन्दर जाने वाले पानी के कारण साट हो गये थे जिससे अन्ततः इसकी चौड़ाई 4.2 मीटर हो गई।

7.7.1 दुर्घटना स्थल का प्लान 40 डिग्री गैलरी में सीधे घुमाव प्रदर्शित करता है, जो ग्राफ्ट में 34 से तनेक्षण के समीप है। श्री के. दत्ता (एम डब्ल्यू 19), श्री मिहिर कुमार चटर्जी (एम डब्ल्यू 10) श्री सी. डी. मिह (एम. डब्ल्यू 11), श्री बृजनु पांडेय (एम डब्ल्यू 13) और श्री चन्द्रधारी बराई (एम. डब्ल्यू 14) जैसे प्रबंधक की तरफ गवाहों ने यह बयान दिया है कि दुर्घटना के दिन फेस के पीछे 40 डिग्री गैलरी की गहव रेखा ज्यादा से ज्यादा 3 मीटर से 3.6 मीटर की थी। तथापि सर्वेक्षक श्री पी. एल. ठक्कर ने यह याद किया कि 8 नवम्बर 1989 से पुनः शुरू होने के बाद उन्होंने 40 डिग्री गैलरी के मध्य रेखा की मापजाख कभी नहीं की थी। उन्होंने यह भी बयान दिया कि 8 नवम्बर और दुर्घटना वाले दिन 13 नवम्बर के बीच उन्होंने कभी भी 40 डिग्री गैलरी का दौरा नहीं किया। यह हो सकता है कि उनके सहायकों ने मध्य रेखा को आगे बढ़ाया हो, पर इस बारे में भी वे दाखल नहीं थे। गैलरी के ऐसे सीधे घुमाव के कारणों के बारे में किसी भी गवाह या किसी भी पक्षकार ने कुछ भी नहीं कहा। यह हो सकता है कि प्लान में ग्राफ्ट सं. 34 का संभावित स्थल का ध्यान रखते हुए इस गैलरी को जानबूझकर घुमाया गया हो ताकि इसके नीचे ज़ाईव किया जा सके और यह निश्चित हो सके कि बनने वाला फलैक शापट के समीप हो। 40 डिग्री गैलरी के डाल के पास पुराने ग्राफ्ट सं. 31

से एक इनसैट की उपस्थिति एक अन्य संभावना हो सकती है। जब गैलरी का कार्य अभी रुक रहा था इनसैट के साथ लगा बैरियर छोटा हो गया और अंततः यह नकारा ही गया। पुराने और परित्यक्त शाफट से संबंध के परिणामस्वरूप एक तीव्र दक्षिणवर्ती धुआँ बन गया। अपने निरीक्षण के दौरान चार्लिस डिग गैलरी की पुराने लम्बाई के आकार प्रकार में मैंने अधिक अंतर अनुभव नहीं किया। सतः मुझे यह सम्भव नहीं लगता है कि पहले यह एक शाफट इन्सैट या शाफट संख्या 34 में एक गैलरी विद्यमान थी। इसके अलावा सभी प्रत्यक्षदर्शी गवाहों के इन बयान के अनुसार कि एक मध्य रेखा का प्रावधान था, और इसके विपरीत हमका कोई साक्ष्य विद्यमान न होने के गैलरी में घुसाव होने की तीव्रता सम्भावना से न इंकार करता हूँ। इस प्रकार मैं यह महसूस करता हूँ कि यह सम्भव है कि गैलरी में जानबूझकर परिवर्तन किया गया था।

7.7.2 जैसे कि पहले भी कहा गया है, पुराने शाफट संख्या 34 के समीप के 40 डिग फेस को उस क्षेत्र में ज्यादा पानी रिसने के कारण जनवरी 1988 से बन्द कर दिया गया था। उस समय 28 स्तर से इस फेस की दूरी ज्यादा से ज्यादा 10 से 12 फीट की थी (3 से 3.6 मी)। बाद में 28 स्तर के समीप के 40 डिग के जंक्शन पर धनंत समय तक समान परिवर्तन करने के लिये रिटैन चरखी स्थापित कर दी गयी। श्री. कलीम (एम डब्ल्यू-17) ने यह बयान दिया है कि चार्लिस डिग गैलरी का नवम्बर, 1989 में फिर से शुरू किया गया जबकि श्री के. दत्त (एम डब्ल्यू 19) ने यह बयान दिया है कि इसको नवम्बर 1989 के प्रथम सप्ताह में पुनः शुरू किया गया। श्री मिहीर कुमार चटर्जी (एम. डब्ल्यू 10), श्री जिशदास चटर्जी (एम डब्ल्यू 9) और श्री सी. डी. सिंह (एम डब्ल्यू 11) जैसे अन्य गवाहों ने यह बयान दिया है कि 40 डिग में इसको 8 नवम्बर 1989 से पुनः शुरू किया गया। अतः मेरा मानना है कि 28 स्तर के समीप 40 डिग फेस जो पुराने शाफट संख्या 34 से जुड़ गया था और जिसके कारण यह घातक दुर्घटना हुई, को दुर्घटना के ठीक 5 दिन पहले 8 नवम्बर 1989 से पुनः शुरू किया गया।

7.7.3 अलग-अलग मुद्दा यह है कि क्या शाफट संख्या 34 से 40 डिग गैलरी के जुड़ जाने के अन्य कारण और परिस्थितियाँ थीं श्री पी. एल. बनर्जी (एम. डब्ल्यू 16) ने यह दावा किया है कि शाफट संख्या 34 और गैलरी के बीच 3 मीटर से भी ज्यादा के एक कोयला बैरियर के अचानक टूट जाने के कारण यह सम्बन्ध (कनेक्शन) स्थापित हुआ।

7.7.4 दुर्घटना के पहले, 40 डिग फेस की लम्बाई का आकलन श्री राम शंकर सरदार (एम डब्ल्यू 12) श्री शिव दास चटर्जी (एम डब्ल्यू 9), श्री सी. डी. सिंह (एम डब्ल्यू 11) और श्रीमिहीर कुमार चटर्जी (एम. डब्ल्यू 10) जैसे अन्य गवाहों द्वारा किया गया जो कि करीब 40 से 45 फीट के बीच था, (12 से 17 मी.)

7.7.5 40 डिग गैलरी की लम्बाई और दुर्घटना स्थल के प्लान प्रवर्ग एम 12 से निर्धारित पुराने शाफट संख्या 34 के बारे में उपरोक्त गवाहों के आकलन के आधार पर श्री पी. एल. बनर्जी (एम. डब्ल्यू - 16) ने यह बयान दिया है कि दुर्घटना होने के ठीक पहले शाफट संख्या 34 और 40 डिग फेस के बीच का बैरियर 3 मीटर से ज्यादा का था। लेकिन मैंने यह स्वीकार नहीं किया है क्योंकि विभिन्न गवाहों द्वारा बतायी गयी 40 डिग फेस की लम्बाई केवल नेत्रानुमान पर आधारित थी। और वास्तव में इसकी कोई नाप जो नहीं की गई थी।

#### अध्याय-VIII

##### 8.1 साक्ष्यों का विश्लेषण

शाफट सं. 34 का एकसेक्शन

##### 8.2 पानी का असामान्य रिसाव

##### 8.3 40 डिग का पुनः शुरू किया जाना

##### 8.4 एडवांस बोर होल

##### 8.5 स्तरों का गिरावटा (मुवमेंट)

##### 8.6 पानी परस्पर का डोला होना

##### 8.7 दुर्घटना का कारण

8.1 यह सर्वविदित था कि नारायणपुरी सीम के 24 मीटर ऊपर पुराने रॉन्गल जालियरी के नेमा सीम के कार्यस्थलों में पानी भरा था इससे अनेक पुराने शाफट भी थे, जिनमें से कुछ की गहराई अभी तक प्रमाण नहीं है। ऐसा है एक पुराना शाफट संख्या 34 था, जो सबसे से नारा भूमा था और जिसकी गहराई भी ज्ञात नहीं थी। खान प्रबंधन ने यह बयान दिया है कि उन्होंने उपसब्ध पुराने प्लान और बस्तावेज का अध्ययन किया, लेकिन इससे भी पुनः शाफट की गहराई का पता नहीं चला। तथापि समीप के कार्यस्थल के एक ए.एम.पी. ने शाफट संख्या 34 की गहराई 86 फीट होने का संकेत दिया, जो कि उस क्षेत्र नेमा सीम की गहराई के बराबर है। खान सुरक्षा महा. ने 1934 में विकास की अनुमति (प्रवर्ग-एम/5) देने की बहुत ही सतर्क से थीर. उन्होंने नारायणपुरी सीम तक पुराने शाफट के बड़ आने का प्रमाण का ध्यान रखते हुए पानी और सेट्रल एडवांस होल का प्रावधान करने की शर्त की इसमें शामिल कर दिया 1988 में जब पुराने शाफट सं. 34 के समीप विकास कार्य हो रहा था तब खान प्रबंधन ने भी ज्यादा पानी के रिसाव की बात देखी थी। ऐसा कि पहले भी उल्लेख किया गया है, उन्होंने विकास कार्य रोक दिया और कीयला खान नियमावली, 1957 के विनियमन 127 (5) के अन्तर्गत अपेक्षित शर्तों के अनुसार खान सुरक्षा महामिनेशालय की सूचित किया कि शाफट सं. 34 का वास्तविक स्थल गंदेहा स्वद था अतः प्रबंधन ने उपसब्ध, दशावधि और सूचना प्राप्त करने के अन्य स्त्रोतों के माध्यम से जानकारी लेनी चाही, ताकि शाफट सं. 34 की गहराई निश्चित की जा सके। तथापि, उनकी इसकी गहराई के बारे में कोई निश्चित सूचना नहीं मिली। उन्होंने प्रत्यक्ष निरीक्षण करके भी शाफट सं. 34 के स्थान का निश्चित करने का प्रयास किया, लेकिन वे असफल रहे क्योंकि शाफट सं. 34 मलबे से भर गया था। बाद में, खान प्रबंधन ने 39 डिग के समीप 27 स्तर से एक संज्ञा बोरहोल करके शाफट का स्थान निश्चित करने का प्रयास किया। लेकिन न बोरहोल का संपर्क पुराने शाफट से हुआ और न इससे पानी का रिसाव हुआ। खान प्रबंधन से यह स्वीकार किया कि पुराने प्लान में पता लगाने, प्लान के छोटे हो जाने की संभावना और सर्वेक्षण शीर नक्शा बनाने में हुयी त्रुटि के कारण बर्किंग प्लान (प्रवर्ग-एम/II) में दर्शाया गया शाफट सं. 34 की स्थिति में गलती की संभावना थी। उन्होंने यह भी स्वीकार किया कि शायद लंबे बोरहोल को दिना में परिवर्तन हो गया था। शाफट करीब 40 मीटर लंबे एक बोरहोल द्वारा केवल 3 मीटर अंतर के एक पुरुषने शाफट के स्थान का पता लगाने का तरीका बहुत पुराना था।

8.2 1988 में खान प्रबंधन ने कार्य स्थिति करने और संभावित पुराने शाफट सं. 34 के बाइपास द्वारा विकास कार्य की दिना में परिवर्तन करने का सही निर्णय लिया। 26, 27 और 28 स्तरों पर पानी के असामान्य रिसाव के कारण प्रोजेक्शन में परिवर्तन का आवेदन किया गया। इस क्षेत्र से करीब 100 मीटर की दूरी पर संशोधित प्रोजेक्शन प्लान की मंजूरी खान सुरक्षा महा. द्वारा मार्च, 1988 में दी गयी (प्रवर्ग-एम/8)

8.3 नवंबर 1989 में संशोधित प्रोजेक्शन 1988 (प्रवर्ग-एम 8) के अनुसार जब विकास कार्य हो रहा था तब 42 फास बट भाग में एक बड़ा संवर्धन में प्रशा. बंदने में एक नया कार्य क्षेत्र दुर्घटना के उद्देश्य श्री. कलीम (एम डब्ल्यू. 17) ने सर्वेक्षण कार्यालय में प्लान का अध्ययन किया और 28 स्तर के समीप 40 डिग फेस का पुनः शुरू करने का निर्णय लिया। जैसा कि पहले भी उल्लेख किया गया है। इस फेस में किया जा रहा कार्य 1988 से बंद कर दिया गया था। प्रबंधन के इस कथन कि इस क्षेत्र में केवल वायु संचार में सुधार करने के लिये 8 नवंबर 1989 से 40 डिग फेस को पुनः शुरू किया गया था, की स्वीकार नहीं किया जा सकता क्योंकि वायु संचार प्रणाली में सुधार करने के लिए अन्य उपाय भी मौजूद थे। 40 डिग के पाम कार्य शुरू करके श्री. कलीम (एम. डब्ल्यू. 17) ने कीयला खान नियमावली 1957 के विनियमन 127 (5) के प्रावधानों का शाफट उल्लंघन किया, जिसके द्वारा अपेक्षित था कि कार्य शुरू करने के पूर्व खान सुरक्षा महा. से अनुमति ली जाए दूसरे शब्दों में, ज्यादा पानी रिसाव के कारण जनवरी, 1988 में शाफट



सं. 34 के पास जब कार्य एक बार बंद कर दिया गया था, तब कोयला खान नियमावली, 1957 के विनियमन 127(5) के अन्तर्गत ऐसे कार्य को अपने आप पुनः शुरू करने के लिए मो. कमीशन प्राधिकृत नहीं थे। इस प्रकार मैं समझता हूँ कि मो. कमीशन ने खान सुरक्षा महा. की अनुमति के बिना ग्रीर कोयला खान नियमावली, 1957 के विनियमन 127(3) का उल्लंघन करते हुए 40 डिप, जो पानी जमाव क्षेत्र के 60 मीटर के भीतर स्थित है, का विकास कार्य 8 नवंबर, 1989 से शुरू कर दिया।

8.4 अनेक गवाहों ने यह बयान दिया है कि जून 1989 से एक नियमित कार्यक्रम द्वारा उचित तरीके से एडवांस बोरहोल की ड्रिलिंग बंद कर दी गयी थी। बाव में, एडवांस बोरहोल को कथित रूप से सामान्य मजदूरों द्वारा ड्रिल करवाया जाता था। एसी ड्रिलिंग के लिये कथित रूप से काम पर लगाये गये ये सामान्य मजदूर नियमित नहीं थे बल्कि उनको नैमित्तिक आधार पर काम में लगाया गया था। ये कर्मकार अपेक्षाकृत अनुभवी कर्मकार थे जबकि नियमित ड्रिलर कुशल कर्मकार होते हैं। 40 डिप के दोबारों में किसी प्लैक बोरहोल का भी निशान नहीं है। यह संकेत देने के लिये भी कोई रिकार्ड नहीं है कि ऐसे बोरहोल ड्रिल किये गये थे। एडवांस बोरहोल को ड्रिल करने वाले कर्मकारों को प्रबंधन द्वारा गवाह के रूप में पेश किया गया। एजेंट सह-प्रबंधक द्वारा ऐसे एडवांस बोरहोल के ड्रिलिंग का पर्यवेक्षण करने के लिये किसी सक्षम प्राधिकारी की नियुक्ति भी नहीं की गयी थी। एडवांस बोरहोल के प्रावधानों से संबंधित ग्यूसतम सांख्यिक रिकार्ड रखने सहित किसी अन्य दस्तावेजी साक्ष्यों के न होने से, ऐसे बोरहोल की ड्रिलिंग के लिये नियमित कर्मकारों और ड्रिलिंग के पर्यवेक्षण के लिये सक्षम प्राधिकारी की नियुक्ति न करने से, ऐसे बोरहोल की खंवाई और दिशा मापने की पद्धति और मेरे निरीक्षण के दौरान कार्यस्थल पर प्लैक बोरहोल के न होने से मैं इस निष्कर्ष पर पहुँचा हूँ कि 40 डिप फेस में सेन्ट्रल बोरहोल भी ड्रिल नहीं किया गया था।

8.5 कुछ अन्य साक्ष्य भी हैं, क्योंकि सुरक्षा अधिकारी श्री पी.एल. बनर्जी (एम. डब्ल्यू. 16) ने बताया है कि एक बड़े भू-स्तर के खिसकने के कारण 40 डिप फेस और शाफ्ट सं.-34 के बीच का कोयला बैरियर टूट गया। इंडियन माइन मेनेजर्स एसोसिएशन का भी यही तर्क है। श्री चंद्रधारी बर्राई (एम. डब्ल्यू. 14), जब वे 40 डिप फेस में दूसरी बार शाफ्ट फायर कर रहे थे तब उन्होंने फेस के आगे और पीछे छत की चट्टान टूटने की आवाज सुनी। 40 डिप और 28 स्तर के जंक्शन से भूतल पत्थरों के बड़े टुकड़ों का खिसकना और सतह पर पोटहोल बन जाना भूस्तर खिसकने का साक्ष्य बताया गया है। यदि चट्टान टूटने की आवाज हुई होती तो वह न केवल श्री चंद्रधारी बर्राई (एम. डब्ल्यू. 14) को सुनाई देती बल्कि 28 लेबन के आसपास उपस्थित अन्य कर्मकारों को भी सुनाई देती। लेकिन इस बात का कोई साक्ष्य नहीं है कि अन्य कर्मकारों ने किसी भी चीज की टूटने की आवाज सुनी। मेरे विचार से 27 स्तर और 40 डिप के बीच एक मीटर से भी कम मोटे कोयला रिब और छत पर किसी भी दृष्टव्य प्रमाण के न होने सहित 50 डिप के करीब बड़े भू-स्तर मुवमेंट के बारे में किसी सबूत के न होने के कारण इस प्रकार की घटना के होने की संभावना को नकारता है। अतः यह कहना उचित नहीं होगा कि ऊपर स्थित नेगा सीम में पुराने और परित्यक्त स्ट्रक के टूटने के कारण हुये भूस्तर मुवमेंट से 40 डिप गैलरी और शाफ्ट सं.-34 के बीच का कोयला यदि बैरियर टूट गया। यदि ऐसा कोई भूस्तर मुवमेंट हुआ रहता तो इससे कहीं-कहीं पोटहोल होने की बजाए भूमि का बहुत बड़ा भाग नीचे खिसक गया होता। पोटहोल का बनना पुराने कार्यस्थल से पानी निकालने के बाद आमतौर पर देखा जाती है।

8.6 यह कहना उचित नहीं होगा कि 40 डिप की सतह और 20 स्तर जंक्शन से बड़े पत्थरों की चट्टानों के खिसकने का और इन चट्टानों के करीब आधा पिलर की दूरी पर चले जाने का कारण भूस्तरिय मुवमेंट था, जिसके कारण यह घातक दुर्घटना हुयी। यह संभव हो सकता है कि मूलतः हलका होने के कारण फ्लोर स्टीन ढीला हो गया हो।

जब अचानक पानी अंदर आया तो शायद पत्थरों का ढीला खंड अपनी वास्तविक स्थिति से करीब आधे पिलर की दूरी पर चला गया। किसी भी स्थिति में 40 डिप और 28 स्तर के जंक्शन की मतह पर पत्थर ढीला होने की घटना का इस घातक दुर्घटना से कोई संबंध नहीं है।

8.7 साक्ष्य के आधार पर मैं यह समझता हूँ कि उस पर स्थित परित्यक्त और पानी से भरे नेगा सीम से जुड़े नारायणपुरी सीम में एडवांस 40 डिप गैलरी और पानी से भरे शाफ्ट सं.-34 के बीच सीधे संपर्क के कारण यह घातक दुर्घटना हुई। नारायणपुरी सीम में पानी से भरे शाफ्ट सं.-34 की ओर बड़े 28 स्तर के समीप 40 डिप गैलरी में सेन्ट्रल और प्लैक बोरहोल न होने के कारण यह दुर्घटना हुई। ऐसे दो र्होल का होना कोयला खान नियमावली, 1957 के विनियमन 127(6) के अन्तर्गत अनिवार्य है तथा खान सुरक्षा महा. की कार्य अनुमति द्वारा अपेक्षित है। इसके अलावा 28 स्तर के समीप 40 डिप गैलरी की खान सुरक्षा महा. द्वारा कार्य करने के लिये गैर मंजूरी कुल क्षेत्र में पानी से भरे शाफ्ट सं.-34 की ओर बढ़ाया गया था। अतः गैर मंजूरी कुल क्षेत्र जहाँ ज्यादा पानी रिमने के कारण जनवरी, 1988 में खनन कार्य बंद कर दिया गया था, की गैलरी में कार्य शुरू करने के पांच दिनों के भीतर यह घातक दुर्घटना थी। यह गैर मंजूरी कुल क्षेत्र खान सुरक्षा महा. द्वारा खनन कार्य के लिये मंजूर क्षेत्र से करीब 100 मीटर की दूरी पर था। इस प्रकार यह घातक दुर्घटना अभियोध्य मानवीय लापरवाही के कारण थी।

## अध्याय IX

### 9.1 वायित्व का विश्लेषण

### 9.2 एजेंट व प्रबंधक

### 9.3 सुरक्षा अधिकारी

### 9.4 सहायक प्रबंधक

### 9.5 सर्वेक्षक

### 9.6 उच्च प्रबंधक

### 9.7 अन्य

9.1 दुर्घटना के कारणों का पता लग जाने के पश्चात् इसके लिए जिम्मेदार कौन था इसका पता लगाना होगा। दुर्घटना के कारणों से यह स्पष्ट है कि यह अभियोध्य मानवीय लापरवाही के कारण से हुई। निम्न-लिखित पैराग्राफों में मैंने उत्तरवायित्व के निर्धारण के लिए साक्ष्यों का विश्लेषण किया है :-

9.2.1 मो. कमीशन (एम. डब्ल्यू. 17) जून, 1987 से खान प्रबंधक और जुलाई, 1988 से एजेंट-सह-प्रबंधक हैं। अतः वे दिसम्बर, 1987 से 13 नवम्बर, 1989 तक की खान की घटनाओं से पूर्णतः परिचित हैं। खान के पुराने शाफ्ट सं. 33 और 34 के समीप 26, 27 और 28 स्तर के पास के कार्यस्थलों में दिसम्बर, 1987 में ज्यादा पानी की रिमाव की घटना देखी गयी और पूर्व एजेंट श्री के. के. दास (एम. डब्ल्यू. 18) द्वारा जनवरी, 1988 में उस क्षेत्र में कार्य स्थगित कर दिया गया था। तब उन्होंने ज्यादा पानी रिमाव को दखते हुए विकास की दिशा में परिवर्तन करने के लिए खान सुरक्षा महा-निदेशक के पास आवेदन दिया। जनवरी, 1988 में खान सुरक्षा महा. को विद्युत संशोधन आवेदन सहित शाफ्ट सं. 34 को 100 मी. की दूरी से बाह्यपास करने की प्रोजेक्शन योजना (प्रवर्ण—एम/7) के बारे में मो. कमीशन (एम. डब्ल्यू. 17) को प्रबंधक की हैसियत से जानकारी थी। संशोधित प्रोजेक्शन को मंजूर करते हुए अनुमति पत्र (प्रवर्ण एम/8) की प्रति खान सुरक्षा महा. द्वारा प्रबंधक मो. कमीशन (एम. डब्ल्यू. 17) को मार्च, 1988 को भेजी गयी। 1988 में, शाफ्ट सं. 34 की संभावित स्थिति की ओर 27 स्तर से एक लंबा बोरहोल ड्रिल किया गया। चूँकि लंबे बोरहोल का संपर्क शाफ्ट सं. 34 से नहीं हुआ और बोरहोल से पानी का भी रिमाव नहीं हुआ, अतः मो. कमीशन (एम. डब्ल्यू. 17) ने यह अनुमान लगाया कि

पुराना शाफ्ट केवल नेगा सीम तक ही था। स्पष्ट है, इन प्रारूप मानकों आधार पर मो. कलीम (एम. डब्ल्यू. 17) जैसे एक अनुभवहीन प्रबंधक के लिए यह समझना उचित नहीं था कि पुराने शाफ्ट सं. 34 का विस्तार केवल नेगा सीम तक ही था।

9.2.3 नवंबर 1989 में जब खान सुरक्षा महा. द्वारा मंजूर नियमित क्षेत्रों के कार्यस्थल में बहुत सारे डाइक मिले तो मो. कलीम (एम. डब्ल्यू. 17) ने सर्वेक्षण कार्यालय में संपर्क करके, और सर्वेक्षण से प्लान के बारे में विचार-विमर्श करके 28 स्तर फ्रेम के समीप 40 डिप में कार्य पुनः शुरू करने का निर्णय लिया। उन्होंने यह भी कहा कि उन्होंने खान सुरक्षा से संबंधित खान सुरक्षा महा. के पूर्व के सभी अनुमति पत्रों और अन्य पत्राचारों का अध्ययन किया। इस प्रकार मो. कलीम इस बात से पूर्ण रूप से अवगत थे कि ज्यादा पानी रिसाव के कारण जनवरी, 1988 में शाफ्ट सं. 34 के समीप कार्य बंद कर दिया गया था। उन्हें कोयला खान नियमावली 1957 के विनियमन 127(5) के प्रावधानों के बारे में भी जानकारी थी, जिसके द्वारा यह अपेक्षित था कि ज्यादा पानी के रिसाव के कारण जिन कार्य स्थलों को बंद कर दिया गया है उनको खान सुरक्षा महा. की लिखित पूर्व अनुमति के बिना आगे नहीं बढ़ाया जा सकता। चूंकि ऐसी कोई अनुमति प्राप्त नहीं की गयी थी अतः नवंबर 1989 से उनके द्वारा स्वयं ही 40 डिप को पुनः शुरू करवाए जाने की घटना कोयला खाद्य नियमावली 1957 के विनियमन 127(5) का ज्ञानवृद्धकर किया गया उल्लंघन है।

9.2.2 मो. कलीम (एम. डब्ल्यू. 17) ने यह भी स्वीकार किया है कि खान सुरक्षा महा. के अनुमति पत्र (प्रदर्शन एम 18) और कोयला खान नियमावली 1957 के अंतर्गत प्रेषित एडवांस सेन्ट्रल और फ्लैक बोर्ड-होल तथा कार्य का प्लान का रिकार्ड नहीं रखा गया। उन्होंने एडवांस होल के ड्रिलिंग का पर्यवेक्षण करने के लिये किसी सक्षम अधिकारी को भी प्राविष्ट नहीं किया। यह कोयला खान नियमावली 1957 के विनियमन 127(6) (ख) का स्पष्ट उल्लंघन था। एडवांस बोर्ड-होल को ड्रिल करने के लिये उन्होंने नियमित ड्रिलिंग गैंग का भी प्रावधान नहीं किया और इसके स्थान पर इस कार्य के लिये सामान्य मजदूरों जैसे अशुभल कर्मचारियों को नैमित्तिक आधार पर कार्य में लगाया। यह दुःखद बात है कि मो. कलीम (एम. डब्ल्यू. 17), जिनके पास वर्षों का अनुभव है, इस स्पष्ट खतरे को पहचान नहीं सके। यह खतरा अमानक नहीं आया बल्कि पर्याप्त पूर्वसूचनाओं के लक्षण के बावजूद आया। मो. कलीम (एम. डब्ल्यू. 17) ने या तो भ्रामक विश्वास के कारण या इस गलत धारणा के कारण, कि शाफ्ट सं. 34 नेगा सीम के आगे नहीं गई है, खतरे को भांपने में असमर्थ रहे जिसके परिणामस्वरूप यह घातक दुर्घटना हुयी। अतः मैं उन्हें 13 नवंबर 1984 को महावीर खान में घटित दुर्घटना का प्रमुख दोषी व्यक्ति मानता हूँ। लेकिन दुर्घटना के मो. कलीम (एम. डब्ल्यू. 17) को प्रमुख दोषी मानते हुये भी साफ्य देने में उनकी दुर्लक्षता तथा जिस रीति से उन्होंने सच्चाई से बयान दिया है, प्रशंसनीय है। उन्होंने यह भी बयान दिया है कि वे खान-कार्यों का संचालन कर रहे थे और उन्हें कोयला उत्पादन की उस सीमा के बारे में निर्वेक्ष नहीं दिया गया जिसके बाद सुरक्षा विनियमनों का उल्लंघन हो सकता है। जब के दौरान उचित व्यवहार के लिये मो. कलीम (एम. डब्ल्यू. 17) निश्चय हो प्रशंसा के पात्र हैं।

9.3.1 क्रमानुक्रम में श्री पी. एल. बनर्जी (एम. डब्ल्यू. 16) खान में मो. कलीम (एम. डब्ल्यू. 17) के बाव अग्रोन्स्य अधिकारी है। उन्होंने महावीर खान में जून 1988 से सुरक्षा अधिकारी के रूप में कार्य किया। 1983 से उन्होंने उक्त खान के सहायक प्रबंधक के रूप में भी कार्य किया। इस प्रकार वे 1983 से लगातार खान में कार्य करते आ रहे थे। उनकी ह्यूटी में पानी भरने की घटना सहित सभी संभावित खतरों के स्रोत के बारे में प्रबंधक (अर्थात् मो. कलीम) को जानकारी देना शामिल है। उनको खान के विभिन्न भागों का भवनोक्तन करके प्रबंधक को इस बात की रिपोर्ट देनी होती है कि खान अधिनियम और इसके अन्तर्गत बनाये गये विनियमनों का पालन किया जा रहा है या नहीं।

9.3.2 श्री पी. एल. बनर्जी ने कहा कि उन्होंने पुराने प्लान का अध्ययन किया और उन्हें पता चला कि शाफ्ट सं.—34 में मलवा भरा है। कार्यक्षेत्रों का प्लान बनाने के लिये उन्होंने खान कार्यालय में उपलब्ध विभिन्न प्लानों का उपयोग किया। सतह पर शाफ्ट सं.—34 उनकी नजर नहीं आई। जनवरी 1988 में उन्होंने 27 स्तर के पास ज्यादा पानी का रिसाव देखा था और इसके लिये एक लंबा बोर होल ड्रिल करवाने का इंतजाम किया था। उनके बयान के अनुसार लंबे बोरहोल की धुमाव की संभावना के बारे में भी उनकी जानकारी थी। उन्होंने खान सुरक्षा महा. की 1984 की अनुमति (प्रदर्शन एम. 15) और 1988 की अनुमति (प्रदर्शन एम 18) का अध्ययन किया था और अनुमति के शर्तों में यादगिर 18 नवंबर, 1989 से 40 डिप फेस को पुनः शुरू किये जाने के बारे में भी उनकी जानकारी थी। उन्होंने यह भी बताया कि 40 डिप फेस से पानी का रिसाव नहीं हो रहा था और 8 नवंबर 1989 से कार्य शुरू किये जाने के बाद फ्लैक और सेन्ट्रल बोर होल के बायरे में फेस को आगे बढ़ाया जा रहा था। वे किन उन्होंने बयान दिया कि प्रत्येक कार्यक्षेत्र फेस में एडवांस बोरहोल को आगे बढ़ाने के पहले इन बोरहोलों की ड्रिलिंग सुनिश्चित करने के लिये उनके पास कोई पद्धति नहीं थी। उन्होंने कार्य-क्षेत्रों के निरीक्षण के दौरान ऐसे बोरहोलों की मापिटिंग सुनिश्चित की तथापि उनके बयान के अनुसार बर्किंग फेसों के निरीक्षणों की कोई निर्धारित समय सूची नहीं थी। मैंने पहले भी स्पष्ट किया है कि गैर मंजूरी कृत कार्य क्षेत्र में ज्यादा पानी के रिसाव के बावजूद एडवांस बोर होल तैयार किये बिना 40 डिप फेस को आगे बढ़ाये जाने के कारण यह घातक दुर्घटना हुयी। इन उल्लंघनों के बारे में श्री पी. एल. बनर्जी (एम. डब्ल्यू. 16) को जानकारी थी। इस प्रकार उन्होंने कोयला खाद्य नियमावली 1957 के विनियमन 41 ए और बी (iii) के अंतर्गत अपने कर्तव्यों का पालन नहीं किया, क्योंकि पानी भर जाने के एक संभावित स्रोत के रूप में शाफ्ट सं. 34 के बारे में उन्होंने एजेंट-सह प्रबंधक (एम. डब्ल्यू. 17) को सूचना नहीं दी। अपने निरीक्षणों के दौरान न तो उन्होंने सेन्ट्रल और फ्लैक बोरहोल ड्रिल किये जाने पर ध्यान नहीं दिया बल्कि कोयला खान नि. 1957 के विनियमन 41 ए (1) (एफ) के साथ पठित कोयला खान नि. 1957 के विनियमन 127(6) का उल्लंघन करते हुये बिना बोरहोल बनाये 40 डिप फेस को आगे बढ़ाने की ज्ञानवृद्धकर अनुमति दी। अतः यह स्पष्ट है कि श्री पी. एल. बनर्जी (एम. डब्ल्यू. 16) ने कोयला खान विनियमन 1957 के विनियमन 41 ए (1) (जी.) के साथ पठित विनियमन 127 का उल्लंघन करते हुए 40 डिप फेस के एडवांस बोरहोल की सुरक्षात्मक ड्रिलिंग पद्धति को सुनिश्चित करने के लिये भी कोई उपाय नहीं किया। इस प्रकार यह स्पष्ट है कि संभावित खतरों को जानते हुए श्री पी. एल. बनर्जी (एम. डब्ल्यू. 16) ने कोयला खाद्य नियमावली 1957 के विनियमन 41 ए (1) (जी.) के अंतर्गत प्रेषित सुरक्षा उपायों के पालन करने के लिये उचित कदम नहीं उठाया। अतः इन दुर्घटना के लिये वे भी उत्तरदायी हैं।

9.4.1 महावीर खान में दो सहायक प्रबंधक थे। एक का नाम श्री के. दत्त (एम. डब्ल्यू. 19) और दूसरे का नाम श्री एस. के. सेतगुप्ता (मो. डब्ल्यू. 1) है। श्री के. दत्त ने सहायक प्रबंधक के रूप में महावीर खान में 1979 से कार्य करना प्रारंभ किया। उन्होंने 7 नवंबर और 12 नवंबर, 1989 के बीच 40 डिप का दो बार निरीक्षण किया और 12 नवंबर 1989 को दूसरी पारी में भी इसका निरीक्षण किया। उन्हें इस बात की जानकारी थी कि ज्यादा पानी रिसाव के कारण 40 डिप फेस में जनवरी 1988 से काम बंद कर दिया गया था। उन्हें इस बात की भी जानकारी थी कि उपस्थित नेगा सीम में पूर्णतः पानी भरा है। उन्होंने बयान दिया कि 40 डिप फेस उचित लम्बाई के एडवांस सेन्ट्रल और फ्लैक बोरहोल का प्रावधान किया था लेकिन इतना साफ बयान देने के बावजूद भी न तो उन्होंने इस उद्देश्य के लिये रखे जा रहे किसी रिकार्ड से इस बयान को साबित किया न ही ऐसा स्वतंत्र गवाह प्रस्तुत किया जो यह कह सके कि ऐसे बोरहोल नियमित रूप से बनाये जाते थे। उन्होंने यह भी साबित नहीं किया कि तैलरी आगे बढ़ाये जाने से पहले पर्यवेक्षी अधिकारियों द्वारा ऐसे बोरहोल की उचित जांच होती थी।

9.4.2 आ: इस क्षेत्र के सहायक प्रबंधक के रूप में वे यह सुनिश्चित करने में असफल रहे कि को. खा. नि. 1957 के विनियमन 127 (6) के साथ पठित को. खा. नि. 1957 के विनियमन पर की अपेक्षाओं के अनुसार 40 डिप फेस में एडवांस बोरहोल की ड्रिलिंग हो रही थी। इस प्रकार से उन्होंने भी कानून का जानबूझकर उल्लंघन किया जिसके कारण बुर्चटना हुयी और इस बुर्चटना के लिये वे भी उत्तरदायी हैं।

9.4.3 दूसरे सहायक प्रबंधक श्री एस. के. सेनगुप्ता (सी. डब्ल्यू. 1) ने खान में अक्टूबर 1989 से ही कार्यभार ग्रहण किया। वे कुछ दिनों के अवकाश पर थे इसके बाद उनकी किसी अन्य विकास कार्य का जिम्मा दिया गया और उन्होंने बुर्चटना स्थल के 42 क्रास-कट क्षेत्र का पर्यवेक्षण का कार्य नहीं किया। इस प्रकार इस घातक बुर्चटना के लिये वे उत्तरदायी नहीं हैं।

9.5.1 श्री पी. एल. ठक्कर (एम. डब्ल्यू. 15) 1957 में महाबोर खान के सर्वेयर थे। उन्होंने जनवरी 1988 में 27 स्तर के ज्यादा पानी के रिसाव की घटना देखी। उन्होंने इस बात को अपनी सांविधिक सर्वेक्षक क्षमता में रिखाई किया तथा यह भी सूचना राज की कि पानी से भरे शाफ्ट सं. 34 का कार्य क्षेत्र बंद रहा है। इस क्षमता को प्रबंधक मो. कलीम (एम. डब्ल्यू. 17) द्वारा प्रति हस्ताक्षरित किया गया। उनकी यह ह्यूटी थी कि वे प्रबंधक को इस बात की सूचना दें कि हो रहा कार्य पानी से भरे शाफ्ट सं. 34 के पास पहुंच रहा था। उन्होंने इस मामले में भी ऐसा ही किया। पूर्व एजेंट श्री के. के. दास (एम. डब्ल्यू. 18) ने यह बयान दिया कि उन्हें इस बात का स्मरण है कि श्री पी. एल. ठक्कर (एम. डब्ल्यू. 15) ने उन्हें एक रिपोर्ट दी थी कि 27 स्तर का कार्य क्षेत्र परित्यक्त शाफ्ट सं. 34 की ओर बंद रहा था। मो. कलीम (एम. डब्ल्यू. 17) ने यह भी स्वीकार किया कि श्री पी. एल. ठक्कर (एम. डब्ल्यू. 15) की क्षमता द्वारा पानी भर जाने के खतरे की ओर भी उनका ध्यान आकर्षित किया गया था। इस प्रकार श्री पी. एल. ठक्कर (एम. डब्ल्यू. 15) ने को. खा. नि. 1957 द्वारा प्रदत्त शक्तियों के अधीन अपनी ह्यूटी का उचित ढंग से पालन किया।

9.5.2 इस स्थिति में, मैं बुर्चटना के लिये श्री पी. एल. ठक्कर (एम. डब्ल्यू. 15) को उत्तरदायी नहीं मानता हूँ।

9.6.1 जिरहु के बोरान मो. कलीम (एम. डब्ल्यू. 17) ने यह बयान दिया कि पर्यवेक्षकों से विचार कर के ही वे कोयला उत्पादन का लक्ष्य निर्धारित करते रहे थे। यह एक संयुक्त निर्णय था और यह महा-प्रबंधक द्वारा जो कि उनका वरिष्ठ अधिकारी था, आरोपित स्वेच्छाचारी निर्णय नहीं था। इसके अलावा कार्य के दौरान यदि कोई समस्या थी तो वे उत्पादन लक्ष्य पर विचार-विमर्श करने और इसमें संशोधन करने के लिये स्वतंत्र थे। उन्होंने इस आरोप का खंडन किया कि उत्पादन लक्ष्य में कमी होने की संभावना के कारण उन्होंने अतिरिक्त प्रोजेक्शन में स्थित खान में बेरोक-टोक खनन कार्य किया। कार्य अनुमति के लिए खान सुरक्षा महा. को प्रस्तुत आवेदन के संबंध में उन्होंने बयान दिया कि महाप्रबंधक की औपचारिक अनुमति अपेक्षित नहीं है फिर भी उन्होंने ऐसे मामलों पर महाप्रबंधक से विचार किया। उन्होंने बयान दिया कि खान सुरक्षा विनियमनों के प्रवर्तन के लिये एजेंट सह प्रबंधक के रूप में उनके पास पर्याप्त शक्तियाँ थीं। उनके ठीक ऊपर वरिष्ठ अधिकारी कुनस्तोरिया क्षेत्र के महाप्रबंधक थे। महाप्रबंधक की क्षेत्रीय सुरक्षा अधिकारी, जो उनका स्टाफ कार्यकारी है, द्वारा सुरक्षा मामलों पर सलाह दी गयी थी। मो. कलीम (एम. डब्ल्यू. 17) ने पानी भर जाने के संभावित खतरे के बारे में क्षेत्रीय सुरक्षा अधिकारी और महाप्रबंधक से विचार-विमर्श किया था। मो. कलीम (एम. डब्ल्यू. 17) ने यह बयान दिया है कि इन अधिकारियों ने उनको सदैव खान सुरक्षा महा. की "अनुमति" का पालन करने की सलाह दी थी। इस प्रकार मो. कलीम (एम. डब्ल्यू. 17) ने यह स्वीकार किया कि 8 नवंबर, 1989 से 28 स्तर के पास 40 डिप में उनके आदेश से कार्य शुरू किया गया और इससे उनके वरिष्ठ अधिकारियों का कुछ लेना-देना नहीं था। इसके अलावा ऐसा कोई गवाह नहीं है जिसने

8 नवंबर 1989 में 40 डिप का गैलरी में कार्य शुरू होने के बारे में महाप्रबंधक को जानकारी के संबंध में जांच स्थापना के समक्ष बयान दिया हो। इस बात का भी कोई साक्ष्य नहीं है कि महाप्रबंधक को इस बात की जानकारी थी कि सुरक्षा विनियमनों का उल्लंघन किया जा रहा था और गैलरी को बढ़ाते समय एडवांस सेन्ट्रल बोर फलैक बोरहोल नहीं बनाये गये थे। महाप्रबंधक ग्यारह खानों के प्रभारी हैं। जिनमें से एक महावीर खान है। उनके लिये यह संभव नहीं था कि वे को. खा. नि. 1957 के विनियमन 127 के अनुसार एडवांस बोरहोल बनाने के लिए खान सुरक्षा महा. की अनुमति में निहित शर्तों के प्रवर्तन का पर्यवेक्षण करें। तबनुसार, मैं कुनस्तोरिया क्षेत्र के महाप्रबंधक को इस बुर्चटना के लिये उत्तरदायी नहीं मानता हूँ।

9.7.1 श्रीवर मेन और रिसदार जैसे पर्यवेक्षी कर्मचारियों द्वारा भी चूकें हुयी हैं। इन चूकों का विश्लेषण इस प्रकार है :-

9.7.2 श्री निहिर कुमार चटर्जी (एम डब्ल्यू 10) श्रीवरमेन जो सामान्य पारी कहे जाने वाली प्रथम पारी में स्थायी रूप से तैनात थे। उन्होंने बयान दिया है कि चूक उनका कार्य विविध प्रकृति का है और जबकि एडवांस बोरहोल के पर्यवेक्षण के लिये औपचारिक रूप से नियुक्त नहीं किया गया था, बल्कि एजेंट-सह प्रबंधक मो. कलीम (एम. डब्ल्यू 17) आमतौर पर उनसे ऐसे बोरहोल के ड्रिलिंग आदि का पर्यवेक्षण करने को कहा करते थे। श्री सी.डी. सिंह (एम. डब्ल्यू 4) 42 क्रासकट क्षेत्र के शिफ्ट श्रीवरमेन थे और 12 नवंबर, 1989 की पहली पारी में वे ह्यूटी पर थे। श्री शिवराम चटर्जी श्रीवरमेन (एम डब्ल्यू 9) और श्री फौजदार सिंह (एम डब्ल्यू 1) अन्य दो श्रीवर मेन थे जिनकी 12 नवंबर 1989 को क्रमशः दूसरी और तीसरी पारी में ह्यूटी पर लगाया गया था।

9.7.3 श्री निहिर कुमार चटर्जी (एम. डब्ल्यू. 10) और श्री सी.डी. सिंह (एम. डब्ल्यू 4) ने 12 नवंबर, 1989 को पहली पारी में 40 डिप फेस में 5.4 मीटर लेबे एडवांस सेन्ट्रल बोरहोल और दो फलैक बोरहोल की निश्चित ड्रिलिंग करने का दावा किया है। श्री शिवराम चटर्जी (एम डब्ल्यू 9) ने उसी दिन की दूसरी पारी में उन एडवांस बोरहोलों की नापजोख करने का दावा किया है। इन सभी श्रीवर मेनों ने यह दावा किया है कि 40 डिप फेस में ज्यादा पानी का रिसाव नहीं था।

9.7.4. जैसा कि मैंने पहले भी कहा है कि 12 नवंबर, 1989 को 28 स्तर के समीप 40 डिप फेस में कोई एडवांस बोरहोल नहीं था और उन्ही दिन फेस से ज्यादा पानी का रिसाव हुआ रहा था। अतः एडवांस बोरहोल की ड्रिलिंग और ज्यादा पानी न रिसने के संबंध में इन श्रीवर मेनों के बयान पर मैं विश्वास नहीं करता हूँ।

9.7.5. श्री फौजदार सिंह (एम डब्ल्यू 1) ही अकेले 12 नवंबर, 1989 की तीसरी पारी में जब बुर्चटना हुयी थी, श्रीवर मेन को ह्यूटी पर थे और उनके चार्ज में अधिक दूरी पर स्थित तीन क्षेत्र थे। अतः बुर्चटना होने के पूर्व 40 डिप फेस का निरीक्षण करने का अवसर उन्हें नहीं मिला।

9.7.6. श्री राम शंकर सरकार (एम डब्ल्यू 12) और बूदन पाण्डेय (एम डब्ल्यू 13) 12 नवंबर, 1989 की दूसरी और तीसरी पारी में 42 क्रासकट क्षेत्र में ह्यूटी पर थे। मैं उनके बयान पर भी विश्वास नहीं करता कि 40 डिप फेस में एडवांस बोरहोल थे और फेस में से ज्यादा पानी का रिसाव नहीं हो रहा था।

9.7.7. श्री चंद्र धारी बर्राई (एम डब्ल्यू. 14) 12 नवंबर, 1989 की तीसरी पारी में 40 डिप फेस के शाट फायरर की ह्यूटी पर थे। मैं उनके इस बयान पर भी विश्वास नहीं करता कि उन्होंने बुर्चटना वाले दिन 13 नवंबर, 1989 को शाट फायरर करने के पहले 40 डिप फेस के एडवांस और फलैक बोरहोल की जांच कर ली थी।

9.7.8. खान सुरक्षा का प्रथम उत्तरदायित्व प्रबंधन पर है। खान के सहायक कर्मचारियों से यह अपेक्षा होती है कि वे उनके आदेशों का पालन करें। मैंने पहले भी कहा है कि इस बात की जानकारी एजेंट सह-प्रबंधक (एम. डब्ल्यू. 17) और अन्य वरिष्ठ अधिकारियों को थी कि 40 डिप फेस में एडवांस बोरहोल ड्रिल नहीं किये गये हैं और इससे ज्यादा पानी रिस रहा है। यदि एजेंट सह-प्रबंधक और अन्य वरिष्ठ कर्मचारी सतर्क रहते और खान सुरक्षा के अपने उत्तरदायित्व के प्रति सतर्क रहते तो उन्होंने एडवांस बोरहोल की ड्रिलिंग करवा ली होती और ज्यादा पानी के रिसाव की ओर ध्यान दिया होता।

उनके द्वारा स्थिति को हाथ से निकलने देने के कारण अधीनस्थ कर्मचारियों जैसे ओवरमैनों, सिरदारों तथा सोट फाइवरों को गलत संकेत मिले। अतः उनकी गलतियों के बावजूद भी मैं सर्वश्री मिहिर कुमार चटर्जी (एम डब्ल्यू 10), सी. डी. सिंह (एम डब्ल्यू 11), शिवदास चटर्जी (एम डब्ल्यू 9), राम शंकर सरकार (एम डब्ल्यू 12), बौदन पाण्डे (एम डब्ल्यू 13) चन्द्रधारी बराई (एम डब्ल्यू-14) को घातक दुर्घटना के लिए जिम्मेदार नहीं ठहराता हूँ।

9.7.9 पानी भर जाने के कारण हुई अधिकांश दुर्घटनाओं तथा आपदा के कारणों का विश्लेषण यह दर्शाता है कि खान में कार्यरत उच्चाधिकारी मूल रूप से जिम्मेदार होते हैं, परन्तु सामान्य कर्मकार तथा उनके पर्यवेक्षकों जैसे सोटफाइवरों, सिरदारों तथा ओवरमैन के लिए सुरक्षा पैरामीटर की जानकारी अपेक्षित है। सामान्यतः पानी भर जाने के कारण हुयी किसी दुर्घटना पहले कुछ अपसामान्य संकेत तथा लक्षणों जैसे बहुत अधिक पानी की सीपेज इत्यादि होती है। यह जरूरी है कि भूमिगत कोयला-खानों में काम करने वाले प्रथम स्तर के पर्यवेक्षक तथा कर्मकार ऐसे सूचक लक्षणों/कारणों की पहचान कर उन्हें प्रबंधन के उच्च स्तर की जानकारी में लाएं। यह आवश्यक है कि पर्यवेक्षकों तथा कर्मकारों को इस प्रकार का प्रशिक्षण दिया जाना चाहिए और सुरक्षा संबंधी ज्ञान उन्हें दिया जाना चाहिए।

9.7.10 कर्मकारों के निरीक्षकों के संस्थान तथा सुरक्षा समिति को इस आशय से कानूनी समर्थन दिया गया है कि कर्मकारों की सुरक्षा में संस्थानों के क्रियाकलाप दुर्घटनाओं तथा गम्भीर संकट की घटनाओं को कम करने में महत्वपूर्ण भूमिका निभाएंगे। इस मामले में कर्मकारों के निरीक्षक तथा सुरक्षा समिति उनसे अपेक्षित उम्मीदों पर खरे नहीं उतरे। कर्मकारों के निरीक्षक ने अस्वीकृत क्षेत्र में 40 डिप को पुनः प्रारम्भ करने के कारणों के बारे में छुट्टाछ नहीं की। उन्होंने यह भी सुनिश्चित नहीं किया कि 40 डिप फेस बोरहोलों खुदायी भी पहले से कर ली जाए। इसक विपरीत उसने मेरे सामने पानी के अपसामान्य सीपेज न होने तथा 12 नवम्बर, 1989 को 40 डिप फेस पर बोर होलों को पहले से ही खुदायी के बारे में गलत बयान दिया।

9.7.11 लगभग सभी पर्यवेक्षक स्टाफ और अनेक कर्मकारों को इस बात की जानकारी थी कि उपरिस्थायी नेगासीम में काफी पानी जमा था। फिर भी खान में पानी भर जाने के खतरे का मामला सुरक्षा समिति जिसकी बैठक महीने में लगभग एक बार होती है के सामने विचार के लिए नहीं आया।

9.7.12 यह सही है कि खान की सुरक्षा की जिम्मेदारी प्रबंधन की है। परन्तु यह भी सही है कि इसे बिना कर्मकारों के तथा ट्रेड यूनियन के प्रतिनिधियों के सक्रिय सहयोग के प्राप्त नहीं किया जा सकता है। इस मामले में यह प्रतीत होता है कि एडवांस बोरहोल को व्यवस्था तथा फेस पर पानी की अपसामान्य सीपेज की जानकारी कुछ कर्मकारों द्वारा स्थानीय ट्रेड यूनियन नेताओं के ध्यान में लायी गयी थी। दुर्भाग्य से ऐसी सूचना होने पर उनके द्वारा भी कोई अनुकूल कारवाई नहीं की गई।

अध्याय-10

10.1 निष्कर्षों का सा

10.2 सिफारिशें

10.3 खर्चा की वसूली

10.4 आभार

10.1.1 13 नवम्बर, 1989 को महावीर खान की नारायण-कूरी सीम में घटित घातक दुर्घटना का कारण पुराने पड़े हुए उपरिस्थायी तथा साफ्ट सं. 34 के कार्यों से जलाक्रांत नेगा सीम से पानी का तेज बहाव था। परित्यक्त तथा जलाक्रांत साफ्ट सं. 34 जिसे 28 लेवल के पास 40 डिप गैलरी को बढ़ाते हुए नारायणकु सीम तक जोड़ा गया था के कारण दुर्घटना हुयी और इससे 6 बहुमूल्य जाने गयी।

10.1.2 यह दुर्घटना, जलाक्रांत साफ्ट सं. 34 की ओर जाने वाली 40 डिप गैलरी में पर्याप्त संख्या में मध्य तथा फलैंक बोर होल्स उपलब्ध न कराये जाने के कारण हुयी। यदि ऐसे विकसित बोरहोल्स कवर उपलब्ध कराये गये होते तो अधिकारीभण जलाक्रांत साफ्ट के खतरे के बारे में सावधान हो जाते और इस प्रकार से घातक दुर्घटना को टाला जा सकता था। ऐसे विकसित बोरहोल्स कोयला खान नियमावली 1957 के 127 विनियम के अन्तर्गत आवश्यक है। खान सुरक्षा महानिदेशक द्वारा जारी कार्य सम्बन्धी अनुमति में भी स्पष्ट रूप से उल्लेख था कि ऐसे बोरहोल्स उपलब्ध कराये जाने चाहिए थे। इसके अतिरिक्त 28 लेवल के पास तक 40 डिप गैलरी को खान सुरक्षा महानिदेशक द्वारा कार्य कर के लिए स्वीकृत परिवर्धन प्रलेखन से दूर लगभग 100 मी. अनाधिकृत क्षेत्र में बढ़ा दिया गया था। यह घातक दुर्घटना 28 लेवल के पास 40 डिप गैलरी जहां पानी की अपसामान्य सीपेज के कारण जनवरी, 1988 में खनन कार्य रोक दिया गया था, में कार्य प्रारम्भ कि जाने के मात्र 5 दिन के भीतर ही हो गयी। मेरे विचार से यह घातक दुर्घटना सर्व श्री मों. कलीम, एजेंट तथा प्रबंधक तथा पी. एल. बनर्जी सुरक्षा अधिकारी तथा महावीर खान के सहायक प्रबंधक श्री के. दत्ता की गम्भीर लापरवाही के कारण घटी है। इन तीनों अधिकारियों ने कोयला खान नियमावली 1957 के विनियम 127 के प्रावधानों तथा साथ ही साथ खान सुरक्षा महानिदेशक द्वारा जारी की गयी कार्यानुमति में निर्धारित शर्तों का उल्लंघन किया है।

10.2.1. हमारे देश की भूमिगत कोयला खानों में बाढ़ के कारण अन्य घोर विपदाओं की तरह यह घातक दुर्घटना कोयला खान विनियमों के संगत प्रावधानों के अनुपालन में मनुष्य द्वारा की गयी चूक के कारण हुयी। जबकि संगत कोयला खान विनियमों का अनुपालन ही ऐसे घातक और घोर विपदाओं को रोक सकता है, चिन्ता की बात यह है कि समय-समय पर इसकी पुनरावृत्ति होती है। मेरे विचार में कर्मकारों को तथा प्रथम पंक्ति के पर्यवेक्षक कर्मचारियों जैसे शॉट फाईर्स, सिरदारों तथा ओवरमैनों को इस बारे में कानूनी प्रावधानों के साथ-साथ उनकी जिम्मेदारियों के प्रति अवगत कराना बाढ़ संबंधी खतरे के संकेतों के बारे में पहले से सचेत रहने के लिए उपयुक्त रूप से उन्हें प्रशिक्षित करना जिससे कि समय पर दोष निवारक उपाय किए जा सकें। मैंने यह भी पाया कि कर्मकारों के निरीक्षण के स्थान तथा सुरक्षा समिति जो कि काफी हद तक सुरक्षा चेतना जगा सकती है को सुदृढ़ करने की पर्याप्त गुंजाइश है।

10.2.2. चूंकि जलाक्रांत वर्किस आने वाले समय में क्रीयला खनन में सम्भावित जोखिम के स्रोत बने रहेंगे। इन जोखिमों का अधिक यथार्थ रूप से पता लगाने के लिए किसी प्रणाली की खोज अविरल रूप से की जानी चाहिए। \*\*\*\*बाढ़ के सम्भावित जोखिमों के निर्धारण के लिए मानवोचित निर्णय पर भरोसा करने में अनेक कठिनाइयाँ हैं जैसा कि कोयला खानों में अनेक दुर्घटनाओं तथा घोर संकटों की प्रचुर मात्रा से ज्ञात होत है। अतः भारत के कोयला उद्योग को जलाक्रांत कार्यप्रणाली की पहचान तथा रूप रेखा बनाने के लिए अधिक विकसित तकनीक अपनानी चाहिए जिससे कि बाढ़ के समय मानव द्वारा की गयी चूक से दुर्घटनाएं तथा भारी संकट उत्पन्न न हों। संक्षेप में, मैं निम्नलिखित सिफारिशें करता हूँ :—

- (i) शिक्षा और प्रशिक्षण के कार्यक्रमों में वृद्धि के द्वारा जोखिमों का पता लगाने की आवश्यकता को देखते हुए प्रथम पंक्ति के पर्यवेक्षकों तथा कर्मचारियों के अभिज्ञान का विकास करना ;
- (ii) सुरक्षा समिति तथा कर्मचारियों के निरीक्षक संस्थानों को सक्रिय करना जिससे कि वे भूमिगत कोयला खानों की सुरक्षा आवश्यकताओं को तर्क संगत बना सकें ;
- (iii) भूमिगत कोयला खान कर्मचारियों के मन में सुरक्षा कानूनों तथा विनियमों के प्रावधानों के अनुपालन की आवश्यकता को बैठाना ;
- (iv) जलाक्रांत कार्यों की विद्यमानता का पता लगाने के लिए ड्रीलिंग एडवान्स बोरहोल्ट के लिए अर्थसंरचना व्यवस्था ;
- (v) भूमिगत संचित जलाशयों का पता लगाने तथा रूप रेखा बनाने के लिए अनुसंधान एवं विकास प्रयासों के जरिये नयी तकनीकियों का विकास ।
- (vi) संकट के समय खान में फंसे हुए खनिकों के लिए केन्द्रीयकृत स्थान पर बड़े डायमीटर आकार की बोरिंग सुविधाओं की व्यवस्था ।

10.3. रिपोर्ट के अन्तिम भाग का संबंध न्यायालय के खर्चों की वसूली से है। खान अधिनियम, 1952 की धारा 63 के अन्तर्गत बनायी गयी खान नियमावली, 1955 के नियम 22 में स्पष्ट किया गया है कि यदि किसी जांच न्यायालय को यह पता चलता है कि दुर्घटना प्रवन्धन की असावधानी अथवा लापरवाही के कारण हुयी है तो न्यायालय इस पर आध-व्ययों की वसूली मालिक एजेंट अथवा मैनेजर से वसूल करने के निर्देश जारी कर सकता है, रिपोर्ट से यह पता चलता है कि यह दुर्घटना एजेंट तथा मैनेजर की लापरवाही और अन्य अधिकारियों द्वारा कोयला खान विनियमावली, 1957 के विनियम 12.7 का अनुपालन न किए जाने के कारण हुयी। लेकिन क्योंकि खर्चों की वसूली के आदेश करने के बारे में जांच न्यायालय का अपना विवेकाधिकार है और क्योंकि न्यायालय के खर्चों को न्यूनतम रखा गया है तथा चूकचर्ता अधिकारी केन्द्र सरकार के सार्वजनिक उपक्रम के हैं। मैं आदेश देता हूँ कि जांच न्यायालय को लागत की वसूली किसी भी पक्ष अथवा कर्मचारी से नहीं की जायेगी।

10.4. रिपोर्ट को समाप्त करने से पूर्व मैं निर्धारणकर्ता श्री बी. एन. तिवाड़ी और प्रो. ए.के. घोष की सहायता के लिए उनका आभार प्रकट करता हूँ। वे न्यायालय की लगभग सभी बैठकों में उपस्थित रहे। अनेक व्यवस्तताओं के बावजूद भी उन्होंने कोर्ट के सामने साक्ष्य तथा दलीलों पर विचार-विमर्श तथा उनका मूल्यांकन करने में अपना बहुमूल्य समय दिया। मैं, इस्टर्न कोलफील्ड लि., उनके एडवोकेट श्री बी. जोशी तथा कर्मचारी यूनियन के प्रतिनिधियों जो कि इस कार्यवाही में पक्षकार थे का भी आभारी हूँ। मैं रिपोर्ट के इस भाग में उनके नामों का भी उल्लेख करना चाहता था किन्तु स्थानाभाव के कारण मैं ऐसा नहीं कर पाया तथापि कर्मचारी यूनियन के प्रतिनिधियों जिन्होंने इस कोर्ट के समक्ष शहान्त के बारे में तथा जिरह में भाग लिया है कि एक सूची अनुलग्नक XIV पर है। मैं, श्री एस.सी. चटर्जी, क्षेत्रीय निदेशक सेन्ट्रल माइन प्लानि तथा डिजायन इन्स्टिट्यूट, आसनसोल और उनके अधिकारियों जिन्होंने आसनसोल में इस न्यायालय को कार्य करने के लिए अधिसंरचना सहायता उपलब्ध करायी, के लिए उनका आभार प्रकट करता हूँ

हू०

(पी.सी. होता)

महाबीर कोर्ट आफ इन्व्वारी  
श्रम शक्ति भवन, रफी मार्ग,  
नई दिल्ली-110001

ह./—

(बी.एन. तिवाड़ी)

निर्धारणकर्ता

ह./—

(प्रो.ए.के. घोष)

निर्धारणकर्ता

अनुलग्नक-I

महाबीर माइन में 13 नवम्बर, 1989 को घटित घातक दुर्घटना में जान गंवाने वाले व्यक्तियों की सूची।

क्रम सं.	नाम	पदनाम	आयु
1.	सीताराम दुसाद	टिम्बर मजदूर	52
2.	फन्ना लाल तिवारी	" "	54
3.	श्रामन्दी तुरी	लोडर	45
4.	विशु हाजम	विस्फोटक ले जाने वाले	51
5.	शंभु नुनिया	लाइन मजदूर	54
6.	झारी बिसरा	लोडर	54

अनुलग्नक-II

जांच न्यायालय

की नियुक्ति संबंधी

अभिलेखना

श्रम मंत्रालय

अभिलेखना

नई दिल्ली, दिनांक 16 अक्टूबर, 1990

का. आ. 327(ई):—13 नवम्बर, 1989 को पश्चिम बंगाल राज्य के बर्दवान जिले में स्थित मैसर्स ईस्टर्न कोलफील्ड लि० की महाबीर कोलियरी में एक दुर्घटना हुई थी जिसमें कई व्यक्तियों की जान गयी थी;

और केन्द्रीय सरकार का विचार है कि दुर्घटना के कारणों और परिस्थितियों की औपचारिक जांच की जाये ;

अतः केन्द्रीय सरकार खान अधिनियम, 1952 (1952 का 35) की धारा 24 की उपधारा (1) द्वारा अन्तः-अन्तः-संस्थानों का प्रयोग करते हुए श्री के. सी. शर्मा, अवकाश प्राप्त अपर सचिव श्रम मंत्रालय को इस बारे में जांच करने के लिए एतद्वारा नियुक्त करती है और उस जांच के लिए निर्धारकों के रूप में नियुक्त करती है।

- (1) श्री बी. एन. तिवाड़ी,  
महासचिव  
कोलियरी मजदूर सभा (एटक),  
जी. टी. रोड, आसनसोल,  
जिला बर्दवाई (पश्चिम बंगाल)

- (2) प्रो. ए. के. घोष,  
प्रोफेसर आफ माइनिंग इंजीनियरिंग,  
इंडियन स्कूल आफ माइन्स,  
घनकष -826004 (बिहार)

[क्रा. सं. एन 11015/1/90 आई एस एच-II]

हू०/—

आर. टी. पाण्डे, उप सचिव

अनुसूचक—III

श्री पी. सी. होता की नियुक्ति के संबंध में अधिसूचना

भारत का राजपत्र प्रसाधारण  
[भाग II—खण्ड 3 (ii)]  
श्रम मंत्रालय  
अधिसूचना

नई दिल्ली, 3 जनवरी 1991

का. प्रा. 3(ई):—भारत सरकार श्रम मंत्रालय की अधिसूचना का. प्रा. सं. 327(ई) दिनांक 16 मई, 1990 में प्राप्ति प्राप्त करते हुए केन्द्रीय सरकार एतद्वारा श्री पी. सी. होता, अपर सचिव, भारत सरकार श्रम मंत्रालय को श्री के. सी. शर्मा के स्थान पर महावीर कोलियरी में हुई बुर्दना के कारणों और परिस्थितियों की जांच के लिए तुरन्त प्रभाव से नियुक्त करती है।

[का. सं. एन-11015 /1/90-आई एस एच-II]  
ह. /-

प्रार. टी. पाण्डेय, उप सचिव

अनुसूचक—IV

महनीय कलकत्ता उच्च न्यायालय को श्री पी. सी. होता द्वारा दी गई अंतरटेकिंग।

कलकत्ता उच्च न्यायालय में न्यायालय प्रवेश सं. 7650(डब्ल्यू) 1990 में श्री पी. सी. होता, महावीर कोलियरी बुर्दना जांच न्यायालय का लिखित व्यक्तव्य—कोज भाईन्स प्राक्सिस प्राफ इंडिया बनाम महावीर कोलियरी बुर्दना जांच न्यायालय

मुखे, 18-11-1989 को महावीर कोलियरी में हुई बुर्दना के कारणों और परिस्थितियों की जांच करने के लिए श्री के. सी. शर्मा के स्थान पर भारत सरकार, श्रम मंत्रालय अधिसूचना सं. एन-11015/1/90 आई. एच० एच-II, दिनांक 8-1-1991 (प्रति संलग्न ) के अनुसार जांच न्यायालय के रूप में नियुक्त किया गया है।

मेरा कथन है कि उक्त जांच के संचालन के लिए श्री के. सी. शर्मा द्वारा प्रपनायी गयी प्रक्रिया का पालन करने के लिए बाध्य नहीं हुई। मुझे यह भी कहना है कि संबंधित पक्षकारों से विचार विमर्श करके उक्त जांच संचालन के लिए मैं अपनी प्रक्रिया प्रपनागा।

पी. सी. होता  
महावीर कोलियरी बुर्दना जांच न्यायालय  
अनुसूचक —V

कोर्ट आफ इन्क्वारी द्वारा पक्षकारों के लिए जारी की गयी सूचना

सूचना

महावीर कोलियरी में हुए बुर्दना के कारणों और परिस्थितियों की जांच करने के लिए केन्द्र सरकार द्वारा खान अधिनियम की धारा 24 के अन्तर्गत जारी अधिसूचना संख्या का. प्रा. 3(ई) दिनांक 3-1-1991 के अनुसार प्रघोषणाधरी को श्री के. सी. शर्मा के स्थान पर नियुक्त किया गया है तथा खान नियमावली, 1958 के नियम 21 के अधीन प्रेषित जांच न्यायालय की प्रक्रिया प्रपना के लिए न्यायालय की प्रथम बैठक सी. एम. पी. बी. आई. (समिति कक्ष), प्रासनमोल में दिनांक 8-4-1991 को पूर्वाह्न 10 बजे होगी। एतः प्राप से अनुरोध है कि उक्त तिथि को दिए गये समय पर न्यायालय में उपस्थित होने की कृपा करें।

2. प्रापसे अनुरोध है कि प्रापके संगठन की ओर से पहले से ही दायर किए गये निश्चित ध्यानों में किए गये अनुरोधों को प्रमाणित करने के लिए बिरह किए जाने वाले प्रस्तावित गवाहों की क्रमवार पूरी सूची जिसमें इस बात का उल्लेख किया गया हो कि न्यायालय के सामने कौन से गवाह ब्याज देंगे, प्रस्तुत करें।

ह. /-

(पी. सी. होता )  
महावीर कोलियरी कोर्ट आफ इन्क्वारी

सेवा में  
सभी पक्षकारों की प्रेषित

अनुसूचक—VI

प्रबन्धन के गवाहों की सूची

क्रम संख्या	नाम	पदनाम	गवाह की संख्या
1	2	3	4
1. सर्वश्री फौजदार सिंह	ओवर मैन	एम डब्ल्यू —1	
2. रामचन्द्र महतो	माईनिंग सिरदार	एम डब्ल्यू —2	
3. शालिग्राम सिंह	पिट क्लर्क	" —3	
4. नूर मोहम्मद	लोडर	" —4	
5. गणेश राय	यू. जी. लोडर	" —5	
6. जयदेव मोडल	माईनिंग सिरदार	" —6	
7. भूलम मोडल	शांट फाइटर	" —7	
8. रमेश माझी	फिटर बोरिंग अपरेटर	—8	
9. शिवदास चटर्जी	ओवर मैन	" —9	
10. मिहीर कुमार चटर्जी	ओवर मैन	" —10	
11. सी. डी. सिंह	ओवर मैन	" —11	

1	2	3	4
12.	रामशंकर सरकार	मार्निंग सिरदार	एम डब्ल्यू—12
13.	बोदन पाण्डे	मार्निंग सिरदार	"—13
14.	चन्द्र धारी बराई	शाटर फाईरर	" —14
15.	पी. एल. ठक्कर	सर्वेयर	"—15
16.	पी. एल. बनर्जी	सुरक्षा अधिकारी	"—16
17.	मोहम्मद कलीम	प्रबन्धक एजेन्ट	"—17
18.	के. के. दास	एजेन्ट	"—18
19.	के. दत्ता	सहायक प्रबन्धक	"—19

## अनुलग्नक VII

## कर्मचारी यूनियन के गवाहों की सूची

क्रम संख्या	नाम	पदनाम	गवाह संख्या
1.	कुजवीपा दास	ड्रिलर	यू. डब्ल्यू—1
2.	मुन्म तूरी	यू.जी. लोडर	"—2
3.	छदी हरिजन		"—3
4.	रामचन्द्र महतो	लोडर	"—4
5.	भागी राजभार	ड्रेमर ड्रिलर	"—5
6.	राम सुधार चौबे	ओवर मैन	"—6

## अनुलग्नक VIII

## कोर्ट गवाहों की सूची

क्रम संख्या	नाम	पदनाम	गवाह संख्या
1.	श्री सन्त कुमार सेनगुप्ता	सहायक प्रबन्धक	सी. डब्ल्यू—1

## अनुलग्नक

## प्रबन्धन द्वारा प्रस्तुत दस्तावेजों की सूची

## (दस्तावेज-एम)

क्रम संख्या	दस्तावेज संख्या	दस्तावेजों का विवरण
1.	एम/1	श्री स्वपन घटक का हूँड प्लान (42-एल-धारा) (कच्चे में किए गये प्रलेखों का सी 5)
2.	एम 2 (ब)	दि बंशज कोल कं. लि. रानीबंज कोलियरी रानीबंज सीम का प्लान जिसे ए.एम.पी.नं. 1121 से निकाला गया (ट्रेसिंग नं. 1746, 25-7-25)

क्र म सं.	दस्तावेज संख्या	दस्तावेजों का व्यौरा
3.	एम/2 (ख)	वि बंगाल कोल कं. लि., रानीगंज कोलियरी, रानीगंज सीम का प्लान जिसे ए.एम.पी. नं. 1121 से निकाला गया (ट्रेसिंग नं. 1743, 25.7.25) ए० एम० पी० नं० 1211 के फार्म नं. 1, से (दो पृष्ठ)
4.	एम/3	महाबीर कोलियरी के एजेंट से खान सुरक्षा महानिदेशक को लिखे गये पत्र संख्या इ.सी.एल./एम.बी (पी)/4009 दिनांक 16 17/12/83 के पत्र की फोटो प्रति
5.	एम/4	विकास अनुमति प्लान, प्लान सं. ई.सी.एल./एम.बी./एम.यू/20, दिनांक 16-12-1983
6.	एम/5	पत्र सं. एस 3/173 (बी.डी.) (एम.बी.)II-बी/84/1061 दिनांक 12-3-1984 की फोटो प्रति
7.	एम/6	महाबीर कोलियरी के एजेंट द्वारा खान सुरक्षा महानिदेशक को भेजे गये पत्र सं. ई.सी.एल./एस.बी.आई. विका 88/198 दिनांक 19-1-88 की फोटो प्रति
8.	एम/7	सी.एम.आर. 105, 126 तथा 127 के अधीन नेगा सीम की जलाकृत कार्यों के नीचे/एन/के सीम में प्रस्तावित विकास कार्यों का परिवर्तित प्रक्षेपण दर्शाने वाला महाबीर कोलियरी (आर) का इ.सी.एल. प्लान सं. ई.सी.एल./एम.बी./62, दिनांक 16-1-88
9.	एम/8	खान सुरक्षा महानिदेशक द्वारा एजेंट महाबीर कोलियरी को लिखे दिनांक 22-3-88 के पत्र सं. एस. 3/22-03-062/11ए/88 की फोटो प्रति
10.	एम/9	प्लान सं. इ.सी.एल./एम.बी./20 दिनांक 16-12-83 के प्रक्षेपणों पर अध्यारोपित प्लान सं. इ.सी.एल./एम.बी./62/62 दि. 16-1-88 के प्रक्षेपण दर्शाने वाला इ.सी.एल. प्लान का भाग
11.	एम/10	खान सुरक्षा महानिदेशक से प्राप्त दिनांक 2-8-83 के पत्र सं. एस-3/173 (बी डी) (एम बी) 11-बी/83/4472 की फोटो प्रति
12.	एम/11	अनुरेखण कागज पर सं. 13 दिनांक 14-5-75 से 24-4-88 तक नारायणकुरी सीम की कार्य योजना (जस्त किए गये प्रलेखों का सी 4) (केवल अनुरेखण)
13.	एम/12	दुर्घटना के पश्चात महाबीर कोलियरी की इ.सी.एल. नारायणकुरी सीम से प्राप्त दुर्घटना स्थल का नक्सा
14.	एम/12(क)	दिखाये गये स्थल "क" से स्थल "ख" से पत्थर के बड़े टुकड़े को हटाने की स्थिति दर्शाने वाला नक्शा ।



अनुलग्नक

## कर्मचारियों की यूनिटन के दस्तावेजों की सूची (दस्तावेज—डब्ल्यू)

क्रम सं. दस्तावेजों का व्योरा	दस्तावेज की संख्या
1. श्री स्वपन घटक का हाथ का नक्शा	डब्ल्यू/1
2. इ.सी.एल. पत्र सं. जी.एम./के.एम.टी. 17/540/88 दिनांक 25-7-88 (जब्त किए गये प्रलेखों का बी-1)	डब्ल्यू/2
3. इ.सी.एल. पत्र सं. ई.सी.एल./एम.बी. (आर.) 98 सुरक्षा/297 दिनांक 22-2-89 (जब्त किए गये प्रलेखों का बी.2)	डब्ल्यू/3
4. इ.सी.एल.पत्र सं. इ.सी.एल./एन.बी. (आर.) '88 सुरक्षा/318 दिनांक 28/30-1-88	डब्ल्यू/4
5. भूतपूर्व एजेंट श्री के.के. दास की अनुदेश पुस्तिका के पृष्ठ सं. 1 से 3 (1-11-88 से 10-13-88 तक) जब्त कागज़ों का ए-6	डब्ल्यू/5
6. इ.सी.एल.पत्र सं. इ.सी.एल./सुरक्षा आर एन यू. 1683 दिनांक 14-1-88 (जब्त प्रलेखों का बी-8)	डब्ल्यू/6
7. जांच न्यायालय को दिए गये इ.सी.एल. के मुख्य जापनों के साथ संलग्न प्लेट सं. 4	डब्ल्यू/7
8. खान अधिनियम की धारा 7(2) के अन्तर्गत खान सुरक्षा द्वारा जब्त किए गये रजिस्टर, अभिलेख पत्र तथा नक्शों की सूची	डब्ल्यू/8
9. पत्र सं. एम 11.591 (बी) 87 14040 एफ. दिनांक 30-11-1961	डब्ल्यू/9
10. एन.के.सीम में पानी के खतरे संबंधी नक्शा (जब्त किए गये प्रलेखों का सी.1)	डब्ल्यू/10

## अनुलग्नक XI

## महावीर खान का संक्षिप्त वर्णन

महावीर खान जिला बर्दवान, पश्चिम बंगाल के रानीगंज कोलफील्ड के दक्षिण पूर्वी भाग में स्थित है। भौगोलिक रूप से यह खान लगभग  $25^{\circ} 26'$  से  $23^{\circ} 38'$  अक्षांश उत्तर तथा  $87^{\circ} 05'$  से  $87^{\circ} 07'$  देशांतर पूर्व के बीच स्थित है। इस खान का कुल सतही क्षेत्र लगभग 612 हेक्टेयर है।

इस खदान का कार्यालय पूर्वी रेलवे के रानीगंज रेलवे स्टेशन के लगभग 2 किलोमीटर उत्तर पूर्व तथा ग्रांड ट्रंक रोड के लगभग 2 किलोमीटर दक्षिण में स्थित है। रानीगंज रेलवे स्टेशन को जी. टी. रोड से जोड़ने वाले उपमार्ग से निकलती हुई एक पक्की सड़क इस खदान के कार्यालय को जाती है।

महावीर खदान मैसर्स ईस्टर्न कोलफील्ड लि. की है जिसका गठन देश की ईर कोकिंग कोयला खानों के राष्ट्रीयकरण के लगभग दो वर्ष पश्चात् 1975 में सार्वजनिक क्षेत्र उपक्रम के रूप में किया गया था। राष्ट्रीयकरण के समय प्राप्त-पास कार्यरत निजी स्वामित्व वाली तीन खानों तथा एक बन्द पट्टी खदान को मिलाकर महावीर खदान का गठन किया गया था। तीन कार्यरत खानें महावीर काजोरा सिन्क्रेटिक तथा सोयरसोरा 3128 GI/92—5

खानें थीं। बन्द पट्टी रानीगंज खान तत्कालीन को मैसर्स बंगाल कोल कंपनी की थी।

महावीर खदान की मुख्य विशेषतायें यह हैं उसकी भू-संपत्ति पर पुराना झगरा तथा नया झगरा पांड और रानीगंज कस्बे का कुछ भाग है हावड़ा से दिल्ली जाने वाला मुख्य पूर्वी रेल मार्ग उत्तर-पश्चिम से दक्षिण पूर्व को जाता है तथा महावीर खदान की भू-संपत्ति की लगभग दो बराबर भागों में विभाजित करता है। महावीर खदान तथा उसके आसपास के क्षेत्र को हमारे देश में कोयला खनन के लिए प्रथम क्रम के क्वा में मान्यता दी गयी थी।

कोयला खान विनियमावली, 1957 के विनियम 127 का पाठ—

127. भूमिगत जल-प्लाट से खतरा :—

(1) किसी खान अथवा ग्रन्थ पास वाला खान के कार्यों से पानी अथवा अन्यतरल पदार्थ के हमले की रोक-बाम के लिए प्रत्येक खान में समुचित व्यवस्था की जायेगी।

(2) जहां निम्नलिखित में से किसी में कार्य किया जा रहा हो—

(2) जहाँ निम्नलिखित में से किसी में कार्य किया जा रहा हो—

(1) किसी सीम अथवा भाग अथवा सीम के नीचे अथवा भाग, में या

(2) सीम के किसी स्थान अथवा भाग में जो कि किसी नीची सीम अथवा भाग में किसी दूसरे स्थान की अपेक्षा किसी नीचे सीम पर है अथवा

(3) सीम के किसी ऐसे स्थान में जहाँ से कोई छूटि उपरी सीम के द्वारा जाती है, जिसमें पानी अथवा अन्य तरल पदार्थ का संवय शामिल है अथवा हो सकता है,

कार्यस्थलों में पानी अथवा अन्य तरल पदार्थ के जाने को रोकने के लिए पर्याप्त पूर्वोपाय किए जायेंगे।

3. कोई भी कार्य जो कि किसी ऐसे अप्रचलित अथवा परित्यक्त कार्य के 60 मीटर की दूरी के अन्दर किए गये हों (वह ऐसे कार्य नहीं होंगे जिनका निरीक्षण किया गया हो और पानी अथवा अन्य किसी तरल पदार्थों के संवयन से मुक्त पाया गया हो), चाहे वह उसी खान अथवा किसी पास वाली खान में भागे नहीं बढ़ाये जायेंगे जब तक कि मुख्य निरीक्षक की लिखित में पूर्ण अनुमति न हो और ऐसी शर्तों पर जो मुख्य निरीक्षक इस प्रकार की अनुमति में निर्दिष्ट करे।

परिभाषा:— इस उपविनियम के प्रयोजनार्थ उपयुक्त कार्य स्थलों के बीच की दूरी का अर्थ होगा उसी सीम के कार्य स्थलों अथवा किन्हीं दो सीम या भागों के बीच कम से कम दूरी चाहे वह समतल सीधे (ऊर्ध्वाकार) अथवा झुके रूप से, जैसी भी स्थिति हो, किसी भी दिशा में मापी गयी हो।

2 ( \* \*)

उपयुक्त विनियमों के उप-विनियम (4), (5) और (6) को निम्न प्रकार प्रतिस्थापित किया जायेगा:

"3(4)(क) उप-विनियम (3) में उल्लिखित किसी कार्य को बढ़ाने संबंधी अनुमति के लिए प्रत्येक आवेदन के साथ प्लान तथा भाग की दो प्रतियाँ जिसमें निम्न बातें दर्शाई गयी हों:—

(1) उस कार्य के बारे में ऐसे सभी कार्यस्थल जो प्रयोग में न लाए जा रहे हों अथवा परित्यक्त कार्यस्थल तथा उपरी सतह से ऐसे सभी अप्रचलित और परित्यक्त कार्य स्थलों की गहराई की रूप रेखा।

(2) प्रस्तावित उस कार्य की रूप रेखा सन्धान तथा कार्यविधि जिसके लिए अनुमति मांगी गयी है।

(3) उप-विनियम की धारा (i) अथवा (ii) में विनिर्दिष्ट कार्य से सम्बन्धित छुटियों, नहरों (पतनालों) तथा अन्य भौगोलिक बाधाएँ, और

(4) ऐसी अन्य कोई सूचना जो प्रबन्धन के पास उपलब्ध हो तथा अन्य व्योरे या सूचना जिसकी मुख्य-निरीक्षक को आवश्यकता हो।

(ख) उप विनियम (5) में उल्लिखित किसी बकिस् के विस्तार के लिए भागे जब कभी अनुमति प्रदान की जाती है, तो उसका विस्तार

तथा प्लान स्वीकृत विधि के अन्तर्गत तथा उसमें विनिर्दिष्ट शर्तों के अनुसार ही किया जाएगा ऐसी अनुमति से हट कर कुछ भी नहीं किया जाएगा जब तक कि उसके लिए भी मुख्य निरीक्षक का अनुमोदन प्राप्त न कर लिया गया हो।

5. जब कभी पानी का रिमाव जो सामान्यतः सीम में अथवा किसी कार्य स्थल पर दिखायी नहीं देती, अथवा वहाँ ऐसा संदेह या शक हो तो ऐसा कार्य तुरन्त रोक दिया जायेगा और ऐसे रिमाव प्राप्ति के बारे में मुख्य निरीक्षक और क्षेत्रीय निरीक्षक को सूचना दी जायेगी। ऐसे कार्य मुख्य निरीक्षक की लिखित में पूर्वानुमति के बिना कार्य भागे नहीं बढ़ाया जाएगा और यदि अनुमति मिल जाती है तो उसमें मुख्य निरीक्षक द्वारा निर्दिष्ट शर्तों के तहत ही वह कार्य भागे बढ़ाया जाएगा।

(6) (क) उप-विनियम (3) अथवा उप-विनियम (5) में उल्लिखित किसी कार्य-स्थल की ऊँचाई 2-4 मीटर से अधिक नहीं होगी तथा कार्यस्थल के मध्य भाग के आस-पास कम से कम एक बोरहोल तथा प्रत्येक सिरे पर पर्याप्त बोरहोल और कार्यस्थलों के ऊपर तथा नीचे जहाँ भी आवश्यक हो वहाँ ज्यादा से ज्यादा पांच मीटर की दूरी पर बोर होल्स किए जायेंगे। ऐसे सभी बोर होल्स को चालू स्थिति में रखा जायेगा, और ये बोरहोल कार्य के पहले पर्याप्त दूरी पर और यह दूरी किसी भी स्थिति में तीन मीटर से कम नहीं होगी और उन्हें निरन्तर चालू स्थिति में रखा जाएगा ये पूर्वोपाय/संरक्षणात्मक किसी अधिकारी, जिसके पास नैतिक अथवा और मन का प्रमाण-पत्र विशेष तौर पर प्रयोजनार्थ हो की सीधी निगरानी में किए जायेंगे।

(ख) धारा (क) में विनिर्दिष्ट अधिकारी द्वारा जिल्द-बन्द पृष्ठों वाली पुस्तिका में, जिसमें ऐसे कार्य स्थल को वास्तविक ऊँचाई तथा चौड़ाई चालू बोर होलों की संख्या प्रत्येक बोर होल की सम्बाई, प्रत्येक बोर होल का स्थान तथा दिशा जिस ओर वह चलाया जा रहा था दर्शाने वाला अभिलेख रखा जायेगा तथा उसमें की गयी प्रविष्टियों को ऐसा सक्षम व्यक्ति तारीख सहित हस्ताक्षर द्वारा प्रमाणित करेगा और उस पर हर रोज प्रबन्धक प्रति हस्ताक्षर करेगा। प्रत्येक ऐसे कार्य के उपयुक्त विवरण दर्शाने वाला प्लान तथा भाग तैयार किया जाएगा और रखा जायेगा तथा और उन्हें हर 15 दिन में कम से कम एक बार अद्यतन किया जायेगा।

(7) जब तक मुख्य निरीक्षक द्वारा उप-विनियम (8) के अन्तर्गत लिखित में मुख्य छूट प्रदान नहीं की जाती है तब तक उप-विनियम (6) के सभी प्रावधानों का कड़ाई से पालन किया जायेगा, जबकि उप-विनियम (3) अथवा उप-विनियम (5) में उल्लिखित किसी कार्य का विस्तार करने चाहे ऐसे कार्यों को बढ़ाने के लिए अनुमति प्रदान की गयी हो अथवा नहीं उप-विनियम (6) के समस्त अथवा किसी प्रावधान का अनुपालन अपेक्षित है।

(8) यदि मुख्य निरीक्षक इस बात से सन्तुष्ट है कि किसी खान अथवा उसके किसी भाग में परिस्थितियाँ उप-विनियम में विनिर्दिष्ट सभी अथवा कोई प्रावधान इस प्रकार का है कि उसका अनुपालन अनावश्यक अथवा अव्यावहारिक है तो वह लिखित में आदेश निकाल कर उप-विनियम (6) की निहित सभी अथवा किन्हीं शर्तों तथा अपेक्षाओं में ढील दे सकता है परेक्षित कर सकता है अथवा समाप्त कर सकता है और यदि वह समझे कि किसी खान अथवा उसके किसी भाग में परिस्थितियाँ ऐसी हैं कि उनके बारे में अपेक्षित प्रतिरिक्त पूर्वोपाय किए जाने हैं, तो वह, उप-विनियम (6) में विनिर्दिष्ट उन पूर्वोपायों के प्रतिरिक्त लिखित में एक आदेश द्वारा ऐसे प्रतिरिक्त अपेक्षित पूर्वोपाय कर सकता है।

## अनुलग्नक—XIII

## दुर्घटना स्थल का चित्र

दुर्घटना स्थल की ओर गैलरी प्रवेश द्वारा से दिखाया गया 40 डिग्री गैलरी का बाहिरी रिव साइड का चित्र।




चित्र (क) कनेक्शन स्थल से लगभग 20 फीट दूर



चित्र (ख) आगे 20 फीट दूर दुर्घटना स्थल का चित्र



चित्र (ग) आगे 20 फीट



चित्र (घ) गैलरी का अन्तिम छोर



चित्र (ङ) : गैलरी का अन्तिम छोर

## अनुलग्नक—14

संगठन तथा प्रतिनिधियों की सूची जिन्होंने गवाहों से जिरह की।

क्रम संख्या	नाम	संगठन का नाम जिसका प्रतिनिधित्व किया
1.	श्री ए. मेसी, सचिव श्री सुनील सेन, संगठन सचिव	सी. एम. एस. (इटक) सी. एम. एस. (इटक)
2.	श्री जे. पी. गोस्वामी, सचिव	सी. एम. एस. आई (सीटू)
3.	श्री पी. एन. शर्मा श्री एल. एन. महाशर्मा सचिव (सुरक्षा)	कोल मजदूर यूनियन (इटक) आई एन एम डब्ल्यू एक (इटक)
	श्री एस. एस. चौधरी, सचिव	सी० एम० यू (इटक)
4.	श्री कवि पांडा चटर्जी, संगठन सचिव, श्री जयंत पोदार, महासचिव	सी०एम०सी० (एच०एम०एस०) सी०एम०सी० (एच०एम०एस०)
5.	श्री एच०एस० मुखर्जी, उपाध्यक्ष	के. एम. सी.

1	2	3
श्री राकेश कुमार, मुख्य संगठन सचिव		के एम सी
6. श्री डी. एम. दास, महासचिव,	आई एन एन ई डब्ल्यू ए	
7. श्री के प्रसाद, महासचिव,	ए आई एम एस	
8. श्री जे के बनर्जी, महासचिव	आई एन एम आई एम एस ए	
9. श्री बी. जॉर्ज, एडवोकेट	इ सी एस	
10. श्री डी. डी. मुखर्जी,	सी एम बी ए	
श्री जे. बनर्जी, जवाबदाता	सी एम बी ए	
11. श्री ए. के. मजुमदार	आई एम एस ए	

### MINISTRY OF LABOUR

New Delhi, the 17th August, 1992

S.O. 69.—In pursuance of section 27 of the Mines Act, 1952 (35 of 1952), the Central Government hereby publishes, as Annexure to this notification, the following report submitted to it under sub-section (4) of section 24 of the said Act by the Court of Inquiry appointed to hold an inquiry into the causes of and circumstances attending the accident which occurred on the 13th November, 1989 in the Mahabir Colliery M/s Eastern Coalfields Limited (A Subsidiary of Coal India Limited) in the district of Burdwan, State of West Bengal).

“Report of the Court of Inquiry on the accident which occurred on the 13th November, 1989 at Mahabir Colliery in Burdwan District, State of West Bengal.

[File No. N-11015/2/92-ISH-II]

R. T. PANDEY, Dy. Secy.

### REPORT UNDER SECTION 24 OF THE MINES ACT 1952 ON THE FATAL ACCIDENT DUE TO INUN- DATION AT THE MAHABIR MINE OF MESSRS EASTERN COALFIELDS LIMITED ON NOVEMBER 13, 1989

[VOLUME I—Main Report with Annexures—VOLUME  
II—Oral Depositions VOLUME III—Exhibits]

On January 3, 1991 the Ministry of Labour issued a Notification under Section 24 of the Mines Act 1952 appointing me to inquire into the causes of and the circumstances attending the fatal accident on November 13, 1989 resulting in loss of six lives at Mahabir Mine near Asansol. Shri B. N. Tewari, General Secretary, Colliery Mazdoor Sabha, Asansol and Prof. A. K. Ghose, Professor of Mining Engineering, Indian School of Mines, Dhanbad, were appointed Assessors to the Court of Inquiry.

2. I commenced the Court of Inquiry on April 7, 1991 with a visit of the site of the accident. On the following day I heard the parties at Asansol and laid down the procedure of the Court, inter alia, permitting the parties to be represented through lawyers.

3. I did not fix any date for hearing in May and June, 1991 as the representatives of the Employees Unions were busy in the General Elections to the Parliament and the

elections to the West Bengal Legislative Assembly. Only after the elections were over, the work of examination and cross-examination of witnesses could commence. Between July—October, 1991 I examined all the witnesses at Asansol and also made another visit of the Mahabir Mine with the Assessors and some witnesses to reconstruct the sequence of events leading to the accident.

4. I was appointed as the Court of Inquiry in addition to my duties as Additional Secretary in the Ministry of Labour. In spite of it, the hearing could be completed during July—October, 1991. The written arguments were submitted by the parties in November, 1991 and thereafter I had meetings with the Assessors to analyse the evidence and the arguments.

5. Broadly speaking, the fatal accident at the Mahabir Mines occurred when an advancing gallery at a depth of 55m. got connected with an old, abandoned and waterlogged shaft. There was heavy inrush of water through the shaft from the waterlogged workings of the overlying seam connected to it. Six miners lost their lives. 65 miners working at different places in the same seam were trapped as their exists were cut off. These miners managed to take shelter on the rise side of the workings, which was free from water. They were rescued within about 75 hours of the accident by a locally fabricated steel capsule which was lowered with a winch through a large-diameter borehole drilled for the purpose. The unique rescue operation, which was tried in India for the first time and had never been tried elsewhere in the world on such a large scale, attracted considerable media attention.

6. I have held that the cause of the fatal accident was the failure to provide central and flank boreholes in a gallery advancing towards an old, abandoned and waterlogged shaft. Had such advance boreholes been provided, the officials of the mine would have been forewarned of the waterlogged shaft ahead and the fatal accident averted. Such advance boreholes are mandatory under Regulation 127 of the Coal Mines Regulation, 1957. The working permission granted by the Directorate General of Mines Safety also clearly laid down that such boreholes were to be provided. Moreover, the gallery was advanced in an area not approved for working by the Directorate General of Mines Safety but was about 100 m. away from the approved area. Incidentally the fatal accident occurred within only five days of commencement of workings in the gallery in the unapproved area where mining had been stopped in January, 1985 due to unusual seepage of water. Thus the accident was due to culpable negligence attributable to the Agent-cum-Manager of the Mahabir Mine and some senior officials working under him.

7. It would be relevant to assess whether the present accident has points of similarity with some of the major disasters due to inundation in coal mines of our country and whether any further amendment of the Coal Mines Regulations 1957 at this stage would be required to prevent accidents and disasters due to inundation. It is found on review that some major disasters due to inundation in underground coal mines in India have been as follows :

- (i) Newton Chickil Colliery, (Madhya Pradesh) on December 10, 1954 with 63 deaths;
- (ii) Central Bhowrah Colliery (Bihar) on February 20 1958 with 23 deaths;
- (iii) Damua Colliery (Madhya Pradesh) on January 5 1960 with 16 deaths;
- (iv) Silewara Colliery (Madhya Pradesh) on November 18, 1975 with 10 deaths;
- (v) Chasnalla Coliery (Bihar) on December 27, 1975 with 375 deaths; and
- (vi) Hurriladih Colliery (Bihar) on September 14, 1981 with 19 deaths.

The Reports of the Courts of Inquiry appointed for the purpose indicate that most of these disasters took place due to avoidable human failure and culpable negligence. In pursuance of the recommendations of some of those Courts of Inquiry, Government of India have amended the Coal Mine

Regulations from time to time. But unfortunately, accidents and disasters due to inundation in under-ground coal mines continued to occur mostly due to culpable negligence and disregard of the statutory Regulations. Therefore, I do not think any further amendment of the Coal Mines Regulation, 1957 at this stage can by itself prevent such tragic occurrences and Regulation 127 *ibid* contains all the necessary measures to guard against dangers of inundation from underground water. But unfortunately even in the most tragic disaster at Chasnalla (December 27, 1975), provisions of Regulation 127 said were not complied with due to culpable negligence. The tragic story of this fatal accident is also no different.

8. While concluding, I must say that my efforts and efforts of others, who have cooperated with me in conducting the

inquiry, would be amply rewarded if the relevant provisions of the Coal Mines Regulations are followed scrupulously by the management of the Coal Mines and their workforce and necessary awareness is created for the purpose.

9. I may place on record my sincere thanks to the Assessors, who in spite of numerous engagements, spread their valuable time for the inquiry. My thanks are also due to the parties for their willing cooperation.

December 31, 1991.

(P. C. HOTA),  
Mahabir Court of Inquiry

Sharm Shakti Bhawan  
Rafi Marg, New Delhi-110001

## CONTENTS

CHAPTER	SUBJECT	PAGE
I	COURT OF INQUIRY	
1.1	Introduction	81
1.2	Court of Inquiry of Shri K. C. Sharma	81
1.3	Court of Inquiry of Shri P. C. Hota	81—82
1.4	Procedure of the Court	82
1.5	Hearing of the Court	82
II	GENERAL INFORMATION	
2.1	Mahabir mine	82
2.2	Management	82—83
2.3	Geology	83
2.4	Early mining	83
2.5	Workings	83
III	REVIEW STATUTE	
3.1	Statutory provisions against danger of inundation in coal mine	84
3.2	India	84
3.3	Developed countries	84—85
IV	INUNDATION DISASTER	
4.1	General analysis of disaster due to inundation in India	85
4.2	Prominent disasters due to inundation in India	85
V	ACCIDENT	
5.1	The accident	85—86
5.2	Checking the missing persons	86
5.3	The rescue	86
VI	INSPECTION	
6.1	First inspection of the site of accident	86
6.2	Surface inspection	87
6.3	The second inspection	87
6.4	Observations	87

CHAPTER	SUBJECT	PAGE
VII	ISSUES	
7.1	Issues before the Court	87
7.2	Extension of Shaft No. 34	87-88
7.3	Unusual seepage of water	88-89
7.4	Advance long borehole	89-90
7.5	Permission for working	90-91
7.6	Advance boreholes	91-92
7.7	Other issues connected with the accident	92
VIII	CAUSE	
8.1	Analysis of evidence—extension of Shaft No. 34	92
8.2	Unusual seepage of water	92
8.3	Restarting of 40 dip	92-93
8.4	Advance boreholes	93
8.5	Strata movement	93
8.6	Loosening of stone	93
8.7	Cause of the accident	93
IX	RESPONSIBILITY	
9.1	Analysis of responsibility	93
9.2	Agent-cum-Manager	93-94
9.3	Safety Officer	94
9.4	Assistant Manager	94
9.5	Surveyor	94
9.6	Higher Management	94
9.7	Others	94-95
X	CONCLUSION	
10.1	Summary of findings	95
10.2	Recommendations	95-96
10.3	Recovery of expenses	96
10.4	Acknowledgement	96

## LIST OF ANNEXURES.

ANNEXURE NO.	SUBJECT	PAGE
I	List of persons who lost their lives due to the fatal accident on November, 13, 1989	96
II	Notification of the appointment of Shri K.C. Sharma	97
III	Notification of appointment of Shri P.C. Hota	97
IV	Undertaking of Shri P.C. Hota	97
V	Notice issued by Shri P.C. Hota to the parties	97
VI	List of Management Witnesses	97-98
VII	List of Union Witnesses	98

ANNEXURE NO.	SUBJECT	PAGE
VIII	List of Court Witnesses	98
IX	List of Management Exhibits	99
X	List of Union Exhibits	99-100
XI	Description of Mahabir mine	100
XII	Text of Regulation 127 of CMR 1957	100
XIII	Photographs of site of accident	101
XIV	Name of the parties and their representatives who examined and cross-examined the witnesses	102

#### LIST OF ABBREVIATION USED

AMP	—	Abandonment Mine Plan
CDS	—	Central Despatcher System
CMPDI	—	Central Mine Planning and Design Institute
CMR	—	Coal Mines Regulation
CW	—	Court Witness
DGMS	—	Director General of Mines Safety
MW	—	Management Witness
UW	—	Union Witness
ECL	—	Messers Eastern Coalfields Limited
Exh	—	Exhibit

#### CHAPTER I

##### 1.1 INTRODUCTION

##### 1.2 COURT OF SHRI K. C. SHARMA

##### 1.3 COURT OF SHRI P. C. HOTA

##### 1.4 PROCEDURE OF THE COURT

##### 1.5 HEARING OF THE COURT

1.1.1 In the early hours of November 13, 1989 a fatal accident due to inundation took place in the underground workings of the Mahabir mine of M/s. Eastern Coalfields Limited (A Subsidiary of Coal India Ltd.) in the district of Burdwan, West Bengal. In this accident, six miners lost their lives. Their names are at Annexure—I. 65 miners were also trapped as their exists were cut off. They were rescued after almost seventy-five hours. The method of rescue was by drilling of borehole and lowering a winch-operated steel capsule fabricated locally. Later, the manually operated winch was replaced by a diesel operated crane. This method of rescue which was tried for the first time in India and had not been tried elsewhere in the world on such a large scale received considerable media attention.

1.1.2 In exercise of powers conferred by sub-section (1) of Section 24 of the Mines Act, 1952, Government of India in the Ministry of Labour issued a notification on April 16, 1990 appointing Shri K. C. Sharma, retired Additional Secretary in the Ministry of Labour, for holding a formal inquiry into the causes of and circumstances attending the accident. In the same notification, the following were appointed as assessors to the Court of Inquiry :

1. Shri B. N. Tewary, General Secretary, Colliery Mazdoor Sabha, Asansol, District Burdwan West Bengal.

2. Prof. A. K. Ghose, Professor of Mining Engineering Indian School of Mines, Dhanbad, Bihar.

The relevant notification of the Ministry of Labour is at Annexure-II.

1.2.1 The Court of Inquiry of Shri K. C. Sharma held its first meeting on May 24, 1990 and directed to issue notices in newspapers calling upon the interested parties to file their written statements. The Court of Inquiry also decided that it would commence hearing from July 10, 1990 in the premises of the Central Mine Planning and Design Institute (CMPDI), Asansol.

1.2.2 The Court of Inquiry visited the site of accident on June 10-11, 1990 along with the Assessors, representatives of the management and the Director-General of Mines Safety (DGMS). Thereafter the hearing of the Court was formally started from July, 1990 at the CMPDI, Asansol. The DGMS produced all the documents seized under Section 7 of the Mines Act, 1952 in connection with the accident from the Mahabir mine and these documents were taken possession by the Court of Inquiry. On July 7, 1990, however, the Court of Inquiry received an order of the Hon'ble High Court of Calcutta granting stay of the proceeding pending hearing of the writ petition filed under Article 226 of the Constitution of India by the Coal Mines Officers' Association, a party in the Court of Inquiry. Thus the Court of Inquiry stayed its proceeding from July 7, 1990 onwards.

1.3.1 In partial modification of the earlier Notification of April 16, 1990, on January 3, 1991, Government of India in the Ministry of Labour appointed Shri P. C. Hota, Additional Secretary, Ministry of Labour to hold the inquiry in place of Shri K. C. Sharma. The Notification issued in this regard on January 3, 1991 is at Annexure-III.

1.3.2 As the Calcutta High Court had stayed the inquiry of Shri K. C. Sharma, Shri P. C. Hota on his appointment

gave an undertaking to the High Court that he would not be bound by the procedure of the earlier inquiry of Shri K. C. Sharma and that he would devise his own procedure. A copy of the 'undertaking' of Shri P. C. Hota to the Calcutta High Court is at Annexure IV.

1.3.3 The Calcutta High Court directed that Shri P. C. Hota will start the said inquiry de novo in accordance with the law. In the circumstances, the Writ Petition filed by the Coal Mines Officers' Association was dismissed and the order of stay of the proceedings of the Court of Inquiry was vacated.

1.3.4 Accordingly, on March 21, 1991 notice was issued to parties to attend the hearing before the Court of Inquiry at the CMPDI Asansol, on April 8, 1991. The parties were also requested to submit a complete list of witnesses to substantiate the written statements filed by them in this behalf. A copy of the notice issued to the parties is at Annexure V.

1.3.5 On April 7, 1991, as the Court of Inquiry, I visited the site of accident with Prof. A. K. Ghose, the Assessor and some officials of M/s. Eastern Coalfields Ltd. (ECL) and the DGMS.

1.4.1 On April 8, 1991, the Court of Inquiry met at the CMPDI, Asansol. The Assessors and the parties were present. After hearing the parties and in consultation with the Assessors, I passed the following order :—

- (a) in accordance with the order of the Hon'ble Calcutta High Court, the inquiry will start 'de novo' but the written notes, memoranda and list of witnesses already submitted by the parties to the Court of Inquiry of Shri K. C. Sharma shall be considered as valid for this Court of Inquiry also ;
- (b) the parties would get another opportunity to file supplementary notes, memoranda and additional list of witnesses, if any, latest by April 30, 1991 ;
- (c) if the parties desire copies of depositions etc. they would be supplied the same expeditiously ;
- (d) The Court of Inquiry is statutory and therefore to enable parties to represent their case effectively, they would be allowed if they so desire to be represented by a lawyer or to make use of the services of any such person/persons who may be of help in presenting the case. Such parties may make a request in writing in this behalf and the Court of Inquiry shall ordinarily accord such permission.

1.5.1 In view of the ensuing General Election to the Ninth Lok Sabha and election to the West Bengal Assembly and pre-occupation of representatives of Employees' Unions in this regard, I fixed the next date for hearing of the parties at the CMPDI, Asansol from July 15 to 22, 1991.

1.5.2 On July 15, 1991 when the hearing commenced, Shri K. Paul, Director-General of Mines Safety (DGMS) was asked to present the documents etc. seized under Section 7(2) of the Mines Act, 1952 during his inquiry into the accident under Section 23 of the Mines Act, 1952. Accordingly, Shri K. Paul, submitted the list of seized documents to the Court and I found that these were the same as the documents contained in the list of seized documents taken possession of by the earlier Court of Inquiry of Shri K. C. Sharma.

1.5.3 Between July 15—22, 1991, at Asansol, as many as 16 witnesses of the Management were examined and cross-examined. During this period, inspection by the representatives of the Union of documents seized by the DGMS and kept in the custody of the Court of Inquiry was permitted. The Secretary of the Court of Inquiry was present during such inspection.

1.5.4 During the next hearing of the Court of Inquiry at Asansol between September 20—26, 1991, six witnesses (three witnesses of the management and three witnesses of the Union) were examined and cross-examined. Two witnesses of the Management were also cross-examined during this period.

1.5.5 The last hearing of the Court of Inquiry at Asansol was from October 24 to 26, 1991, when three witnesses of the Union and one witness summoned by the Court of Inquiry (Shri S. K. Sengupta, Assistant Manager of Mahabir mine) were examined and cross-examined. There was, however, no cross-examination in case of the sole Court witness (i.e. Shri S. K. Sengupta). On October 26, 1991, the Court along with the Assessors and some witnesses made another visit of the site of accident to reconstruct the sequence of events leading to the fatal accident and other related matters.

1.5.6 During October 24—26, 1991, it was also decided in consultation with the parties that they would submit only written arguments. Accordingly, I directed the Secretary of the Court of Inquiry to be at Asansol on November 12 and 13, 1991 and receive the written arguments.

1.5.7 On November 12 and 13, 1991, the Secretary of the Court of Inquiry visited Asansol and received the written arguments from the Management and the Unions.

1.5.8 During the hearings of the Court of Inquiry at Asansol between July and October, 1991 I recorded the evidence personally by writing down the depositions in long hand. Since some witnesses were not proficient in English, they were asked questions in languages they knew (i.e. Hindi and Bengali). Their depositions were, however, translated into English by me in the open Court and were recorded by me in long hand. Effort was made to supply the photocopies of depositions of witnesses to the parties as soon as the deposition were over.

Invariably, copies of depositions of witnesses in examination-in-chief were supplied to the parties to enable them to prepare themselves for cross-examination. This promptness on the part of the Court of Inquiry was appreciated both by the management and the Unions.

1.5.9 After receipt of the written arguments on November 12 and 13, 1991, myself and the Assessors met at Delhi during November 20—23, 1991 and December, 25-26 1991 to consider the depositions, arguments and other relevant matters for finalizing the Report of the Court of Inquiry.

1.5.10 The Report of the Court of Inquiry was submitted to the Secretary, Ministry of Labour, Government of India on December 31, 1991.

1.5.11 In this Report the witnesses produced by the management have been recorded as Management Witness (MW), those produced by the Union as Union Witness (UW) and the witness called by the Court as Court witness (CW). The list of management, union and court witnesses are at Annexures VI, VII and VIII respectively.

1.5.12 The plans and documents which the Management requested to be made exhibits are called Management Exhibits (Exh. M) and the plans and documents requested to be made exhibits by the Employees' Union are called Union Exhibits (Exh. U). Annexures IX and X give the list of Management's and Employees' Union's exhibits respectively.

## CHAPTER II

### 2.1 MAHABIR MINE

### 2.2 MANAGEMENT

### 2.3 GEOLOGY

### 2.4 EARLY MINING

### 2.5 WORKINGS

2.1.1 Mahabir mine is situated in the Ranigarj Coalfield in the district of Burdwan, West Bengal. It is about 18 km east of the Asansol Railway Station and about 182 km north-west of Calcutta. A brief description of the geographical location, surface features, owner ship etc. of the Mahabir mine is at Annexure—XI.

2.2.1 Since 1975, the Mahabir mine is owned by M/s. ECL, a Subsidiary of M/s. Coal India Ltd. For administrative convenience, the M/s. ECL is divided into two divisions, viz., Eastern and Western Division—each division being headed by a functional Director. The functional Directors



are notified as 'Nominated Owner' under Section 76 of the Mines Act, 1952. At the Corporate level there is an internal Safety Organisation (ISO). The Eastern Division is divided into six areas with 63 workings mines. Mahabir mine is in the Kunustoria Area, which has eleven working mines including the Mahabir mine. At the time of the fatal accident, Md. Kalim (MW-17) was the Agent-cum-Manager of the Mahabir mine. He was the Manager from June, 1987 and later appointed as Agent-cum-Manager. Hence on the fateful day of November 13, 1989, he had more than two years of experience as Manager in the said mine. Md. Kalim (MW-17) holds a Manager's first class certificate of competency to manage a coal mine. He started his career as an apprentice in the coal mines and by November, 1989 had about 28 years of experience.

2.2.2 At the time of the accident, Shri S. K. Sengupta (CWT) and Shri K. Dutta (MW-19) were Assistant Managers of Mahabir mine and both of them held second class manager's certificate of competency. Shri P. L. Banerjee (MW-16) was the Safety Officer of the Mahabir mine and he was reporting to Md. Kalim, Agent-cum-Manager (MW-17). Shri P. L. Banerjee (MW-16) held a first Class Manager's Certificate of Competency for Coal Mines.

2.2.3 Shri P. L. Thacker (MW-15) was the Surveyor. He holds a Surveyor's Certificate of Competency. His duties are as contained in Regulation 49 of Coal Mines Regulations, 1957 (CMR 1957). In short, his duties were to make accurate surveys and levellings and prepare such plans and sections and tracing thereof as the Manager may direct or as may be required by the Mines Act and the Regulations. It is relevant to mention that the statutory duty of the Surveyor is to record full facts when the workings of the mine have approached to about 75 m. from the mine boundary or from disused or waterlogged workings. Shri Thacker (MW-15) was assisted by another qualified surveyor and a few assistants who did not have any formal certificate of competency in coal mining but had only experience.

2.2.4 The mine had 13 overmen and 32 sirdars. They held statutory certificates required for such appointments. Shri Shibdas Chatterjee, Overman, (MW-9) was appointed as the Workmen's Inspector.

2.3.1 The coal seams of Raniganj Coalfield belong to the Raniganj stage of the Damuda series of Lower Gondwana System. The general inclination of the strata is towards south and south east varying from 2° to 35°. At places, igneous intrusion in the form of dolerite dykes traverse the Lower Gondwanas. There are ten coal seams of 1.2 m. and above in thickness associated with Raniganj stage. The coal seams are mostly named after the village in which they occur and the same seam is even found to have different names in different parts of the coalfields. The generalised sequence of the seams in descending order in Raniganj Coalfields is from R-X to R-I.

2.3.2 In the property of the Mahabir mine, the topmost seam is called Searsole seam corresponding to R-IX and is about 6 m. thick. The seam outcrops almost in the central of the part of the property. On the southern part of the property is the outcrop of the second seam called the Nega seam which is about 8.0 m. in thickness corresponding to R-VIII. The parting between the Searsole and the Nega seams is 51 m. Further on the south side, along the mine boundary almost on the bank of the river Damodar is the outcrop of the third seam called the Narainkuri seam corresponding to R-VII. The Narainkuri seam is about 3.3 m. in thickness. The parting between the Nega and the Narainkuri seam is 24 m. Lying 80 m. below the Narainkuri seam is 3 m. thick Bogra seam corresponding to R-VI. The sequence of the seams is as follows :—

Searsole seam	— 6 m. thick
Parting	— 50 m.
Nega seam	— 8 m. thick
Parting	— 24 m.
Narainkuri seam	— 3.25 m.
Parting	— 80 m.
Bogra seam	— 3 m.

3128 GT/92—6

2.3.3 The coal seams have a gentle dip of 1 in 25 in north-easterly direction. The parting between the coal seams consists of coal bearing rock formation. The property is relatively free from geological disturbances except for a major upthrow fault of 60 m. on the northern side. There are also a few small faults having a throw of 1 m. to 6 m. The property is traversed by a few dykes. On the south side, which is also the rise, there is a major dyke. This dyke had not been crossed at any place, and the width is not exactly known. In addition, there are a few small dykes having a thickness of less than a metre. Narainkuri seam is considered as a hard coal when compared to other coal seams in Indian Coalfields.

2.4.1 The Mahabir mine and the adjoining area was the very first centre of coal mining in India. The fatal accident on November 13, 1989, took place due to inundation from very old and abandoned workings. Therefore, it would be interesting to briefly review the history of early coal mining in this area. The first recorded coal mining in India dates back to 1774 when some British entrepreneurs started coal mining around Raniganj. Around 1815, pits were sunk in the Raniganj seam near Egara village presently within the boundary of the Mahabir mine. Since 1843, the coalfield was systematically exploited by a newly-formed joint stock company called the Bengal Coal Company. With extension of the railway line upto Raniganj in 1855, coal mining of this area got a big boost. But even by the middle of the 19th century, coal mining in India was not very scientific and plans of workings were mostly not maintained. Around 1860, Mr. Thomas Oldham, Superintendent of Geological Survey of India, left his "Minutes" on the unsatisfactory state of affairs of the mine plans as follows :

"Up to last year or two I am unable further to state that in no single instance was survey of underground workings made or plans kept. The memory of the 'old men' was only source from which information could be obtained as to the extent of the workings .....

I am glad to say that this system or want of system, has been changed in some cases and plans are now kept, certainly in one case, and I hope also in others .....

2.4.2 The method of mining was essentially driving wide galleries and leaving small pillars, and as coal had to be hauled manually from underground workings, only a small area could be worked from a shaft, which in course of time became abandoned and could constitute a potential source of mining hazard.

2.4.3 These historical evidence of early coal mining could still be seen in the property of Mahabir mine and the surrounding area.

2.5.1 The reconstituted Mahabir mine is formed by amalgamating three small adjoining mines since called the three units of the mine. Here Searsole seam is the topmost coal seam. It had been worked by a private coal company about 80 years ago. The seam had been exhausted, abandoned and presently lying waterlogged.

2.5.2 Lying 51 m. below the Searsole seam is the Nega seam which is 7.5 m. to 8.7 m. in thickness. It has been extensively worked in all the three units of the Mahabir mine. In the Mahabir unit, Nega seam had been worked on the northern side of the main Eastern Railway line through No. A and B Pits. Towards the rise side of A & B Pits on both side of main Eastern Railway line, the Nega seam had been worked by Raniganj Colliery belonging to the erstwhile M/s. Bengal Coal Company Limited, leaving a barrier of coal with the Nega seam working seam workings of A and B Pits. As per plan, the barrier is 60 m. More details about the workings of the Nega seam of Raniganj Colliery will appear in the later part of this report.

2.5.3 Lying 24 m. below the Nega seam is the Narainkuri seam which is about 1.8 to 3.3 m. in thickness. In the Mahabir unit, the Narainkuri seam is 3.25 m. in thickness and is worked through A and B Pits. It is being developed beneath the waterlogged workings of the Nega seam of the Raniganj Colliery.

2.5.4 There are extensive old workings in the Nega seam in an area of about 120 hectares on both sides of the main

Eastern Railway line, made by the Raniganj Colliery of the erstwhile M/s. Bengal Coal Company. No reliable plan of the workings, including the plan which is required to be prepared immediately before abandoning a coal seam also called the 'Abandonment Mine Plan' (AMP), was available with M/s. ECL. A plan which was available at the office of the Mahabir mine was of doubtful authenticity. It did not bear any signature. This plan indicated extensive workings standing on small stooks on both side of the main railway line. The two sets of workings on the north and south side of the railway line was inter-connected by four galleries.

### CHAPTER III

#### 3.1 STATUTORY PROVISIONS AGAINST DANGER OF INUNDATION IN COAL MINES

##### 3.2 INDIA

##### 3.3 DEVELOPED COUNTRIES

3.1.1 The accident took place due to inundation and hence a review is made of the statutory provisions relating to danger of inundation in underground coal mines of India and abroad.

3.2.1 The provision of Regulation 127 of CMR 1957 relates to the precautions to be taken and provisions to be made in an underground coal mine to prevent inrush of water or other liquid matter from the workings of the same mine or adjoining mine. The Regulations have been framed under clause(s) of Section 57 of the Mines Act, 1952. The full text of Regulation 127 of CMR 1957 is at Annexure XII.

3.2.2 It may be seen that Regulation 127(3) of CMR 1957 requires a working permission from the Chief Inspector of Mines who has been also designated as the Director-General of Mines Safety (DGMS) for working within 60 m of dis-used or abandoned workings which have not been examined and found free from accumulation of water or other liquid matter. Since the Narainkuri seam is 24 m below the waterlogged Nega seam, provisions of Regulation 127 of CMR 1957 were also to govern mining operations in the Narainkuri seam.

3.2.3 Regulation 127 of CMR 1957 which had been amended several times has an interesting history. Neither the Mines Act, 1901 nor the General Rules, 1958 framed under the aforesaid Act laid down any precautions to be taken while approaching waterlogged workings in underground coal mines. Even when the Mines Act, 1901 was replaced by the Mines Act, 1923, such precautions were not provided for. It was only in 1936 by an amendment of the Mines Act, 1923 the Central Government was empowered to frame regulations to provide against inrush of water or accumulation of water in the mines and dangers arising therefrom. Thus the Indian Coal Mines Regulation, 1926 (ICMR 1926) framed under the Mines Act, 1923 laid down for the first time after 1936 the precautions to be taken while approaching within 100 feet (30 m.) of waterlogged or dis-used workings. The precautions included restriction of width and height of the gallery to 8 feet (2.4 m.) and provisions of a Central borehole at the working face and sufficient flank boreholes on each side, and where necessary boreholes above and below the workings at an interval not more than 15 feet (4.5 m.). It was also laid down that such boreholes are to be maintained at a sufficient distance in advance of the workings and such distance shall in no case be less than 10 feet (3 m.) Following a disaster due to inundation in a coal mine in Madhya Pradesh in 1954 (Newton Chickli Colliery) where 63 miners lost their lives and following the enactment of Coal Mines (Temporary) Regulations, 1955, the restrictions of working near waterlogged workings were made more stringent. The revised Regulations included increasing the distance of Statutory restricted area requiring working permission of the DGMS from 100 feet (30 m.) to 150 feet (45 m.). The CMR, 1957 repealed ICMR 1926 and Coal Mines (Temporary) Regulation, 1955. The provisions against danger from underground inundation was contained in Regulation 127 of CMR 1957. The statutory restricted area was however increased from 45 m. to 60 m. Following the Chasnalla mine disaster in December, 1975 in which 375 miners lost their lives, there were major amendments in

Regulation 127 of CMR 1957. Some of these amendments were:

- (a) In the application to the DGMS seeking working permission within 60 m. of waterlogged workings, it is mandatory to furnish copies of plans and sections showing inter alia, outlines of all disused or abandoned workings in relation to the working approaching them; the outlines, the layout and the method of the proposed working for which the permission was sought; faults, dykes and other geological disturbances, and such other informations that is available with the management and any other information required by the DGMS.
- (b) Once the permission is granted by the DGMS the workings shall be extended strictly in accordance with the plan and the method approved under the conditions specified in such permission and there shall be no variation therefrom unless such variation is again approved by the DGMS.
- (c) It is also necessary to maintain record showing the exact height and width of such workings, the number of boreholes driven, the length of each borehole, the places at which and the direction in which each borehole was driven in a bound-paged book kept for the purpose and the entries therein are required to be signed by a competent person appointed for the purpose and counter-signed by the manager every day.
- (d) The provision of immediate stoppage of work when unusual seepage of water is noticed at any place in any working in an underground coalmine was extended to the workings which are also within 60 m. of the waterlogged workings.
- (e) however Regulation 127 of the CMR 1957 was also made more flexible as it vested the DGMS with powers to grant relaxation from restrictions in the size of the gallery and exemptions from advance boreholes if deemed fit.

3.2.3 Following the Hurriladih disaster due to inundation in 1983 when 19 miners lost their lives and in the light of experience gained while working near waterlogged workings, Regulation 127 was again amended in 1990. It was made more specific to eliminate ambiguity between dis-used and abandoned workings. It also laid down the precautions to be taken while drilling holes for probing into water bodies.

3.3.1 At this stage, it would be relevant to review the statutory provisions in underground coal mines in some advanced countries regarding working near waterlogged areas. Almost all countries impose certain statutory restrictions while working near water logged workings. The restriction is in the form of leaving safety pillar/barrier between the water-body and the workings. Workings are permitted to a certain limit within the safety pillar subject to certain restrictions. These are usually in the form of restricting the width and height of the galleries as well as advancing the workings under cover of advance boreholes.

3.3.2 The U.S. Federal law specifies that if there is no reliable plan of an old underground working, advance boreholes have to be provided within 60 m. of such workings to avert accidents and disasters due to inundation. In this respect, the U.S. law is almost similar to Regulation 127 of CMR 1957.

3.3.3 The French Regulations for coal mines require protection of the workings against risks of inrush of water. It also requires that galleries or workings driven in a region where an inrush of water is feared should be preceded by divergent boreholes of at least 3 m. in length.

3.3.4 The Coal Mines Regulations of the United Kingdom require that when any workings in a mine would be within 45 m. of any disused workings, the Manager shall take necessary precautionary measures. This includes giving advance notice in this respect to the Inspectorate as well as workers' representatives, along with a scheme which shall lay down the procedure to be followed in such workings de-

signed to ensure that inrush of water or other liquid matter does not occur.

3.3.5 The above global review of the statutory provisions regarding the danger from underground water indicates that our statutory safety precautions are at par with advanced countries such as USA, France and the United Kingdom.

#### CHAPTER-IV

##### DISASTERS DUE TO INUNDATION

#### 4.1 GENERAL ANALYSIS OF DISASTERS DUE TO INUNDATION IN INDIA

#### 4.2 PROMINENT DISASTERS DUE TO INUNDATION IN INDIA

4.1 About one third of the deaths in disasters in coal mines of our country is accounted for by inundation. The prominent disasters due to inundations are those of Newton Chickli colliery (Madhya Pradesh) on December 10 1954 with 63 deaths; Central Bhowrah colliery (Bihar) on February 20, 1958 with 23 deaths; Damua colliery (Madhya Pradesh) on January 5, 1960 with 16 deaths; Silewara colliery (Madhya Pradesh) on November 18, 1975 with 10 deaths; Chasnalla colliery (Bihar) on December 27, 1975 with 375 deaths and Hurriladih colliery (Bihar) on September 14, 1983 with 19 deaths.

4.2.1 The disaster at Newton Chickli Colliery (Madhya Pradesh) in December, 1954 occurred when a development gallery got connected to an old and abandoned waterlogged workings of overlying seam. The underlying seam had been brought to the same level as that of the upper seam in that area due to an upthrow fault equal to the parting between the two seams. The disaster occurred primarily due to inaccurate mine plan, as well as non-compliance of Regulation 74 of the ICMR 1926, which was repealed by Regulation 127 CMR 1957. The disaster due to inundation at the Central Bhowrah colliery (Bihar) in February, 1958 occurred when the underground workings crossed the mine boundary and got connected to the waterlogged workings of the adjoining colliery. The disaster occurred primarily due to encroachment in the adjoining property without proper survey and proper plans, as well as violation of Regulation 127(3) and (5) CMR 1957 in respect of extending workings within 60 m. of waterlogged areas. The disaster at Damua colliery (Madhya Pradesh) in January, 1960 occurred when the workings were advanced towards the waterlogged area across an up-throw fault. The barrier of 1.8 m. between the two workings in faulted area gave away causing the disaster.

4.2.2 The most tragic disaster in the history of mining in India was that of Chasnalla (Bihar) in December, 1975, when 375 persons lost their lives due to inundation. The old workings at Chasnalla had been abandoned around 1949—about 26 years before December, 1975 when the disaster occurred due to an inadvertent connection with the old workings while driving a ventilator cross-cut.

4.2.3 The disaster at Chasnalla has some points of similarity with that of the present accident. In both the cases, inundation occurred from overlying old waterlogged workings and subsidence followed closely thereafter. In the case of the Chasnalla colliery, the length of the main incline driven along the seam was shown in the plan to be much shorter than its actual length. In the case of Mahabir mine the offending old and abandoned shaft was not shown in the plan to have extended to the underlying seam. Again, in both the cases the respective managements worked in areas not approved for working by the DGMS and in violation of Regulation 127 of CMR 1957. The disaster at Hurriladih colliery (Bihar) in September, 1983 occurred when a thin parting of coal formed as a result of developing a thick seam in two different horizons collapsed suddenly. Water from the workings of the upper horizon which formed a part of the sump flowed to the lower horizon, killing 19

persons. The disaster occurred primarily due to inaccurate plan and contravention of Regulation 147 of CMR 1957.

4.2.4 An analysis of the causes of these disasters would indicate that these disasters had occurred mainly because of inaccurate mine plans, and contravention of Regulation 127 of the CMR 1957 etc. In other words, these disasters took place mostly due to avoidable human failure tantamount to culpable negligence.

#### CHAPTER-V

#### 5.1 THE ACCIDENT

#### 5.2 CHECKING THE MISSING PERSONS

#### 5.3 THE RESCUE

5.1.1 At this stage, it would be relevant to review the sequence of events leading to the accident. Apparently, the work in the third shift of November 12, 1989 started normally. There were three working districts in the Narainkuri seam, namely, 'B' Pit depillaring district 31 cross-cut and 42 crosscut development districts. In all about 221 workers were employed in the workings underground before the accident.

5.1.2 Shri Fouzdar Singh (MW 1) was the Overman in charge of the entire workings. Shri Dodan Pandey (MW 13) was the Sirdar and Shri Chandradhari Barai (MW 14) was the shotfirer respectively of the 42 cross-cut development district, where the accident occurred.

5.1.3 In the beginning of the shift, twelve shot holes were drilled in 40 dip face of 42 cross-cut district. These shot holes were about 1.2 m. in length. There was no under-cut at the face as the coal cutting machine was out of order.

5.1.4 Shri Bhangi Rajbhar (UW 5), Shri Ramawtar Khurasia, Shri Tatua Majhi and Shri Pyar Chand Shaw were helpers attached to the shotfirer Shri Chandradhari Barai (MW 14). After completing shot firing in other faces of the district, they reached 40 dip face at about 4.00 a.m. Shri Chandradhari Barai (MW 14) deposed that he charged six out of the twelve shot holes drilled in the face. Four of these shot holes were at the floor level, whereas the remaining two were the "cut holes" almost in the centre of the gallery. However, according to Shri Bhangi Rajbhar (UW 5) all the twelve shot holes were charged at a time in the face. P<sub>3</sub> explosives and instantaneous electric detonators were used. Thereupon the six shot holes were fired by Shri Chandradhari Barai (MW 14). After clearance of smoke and fumes they went back to the face to charge the remaining six shot holes, where as according to Shri Bhangi Rajbhar (UW 5) they went to connect the remaining six charged shot holes. When Shri Bhangi Rajbhar (UW 5) was pulling out the shot firing cable beneath the broken coal, Shri Chandradhari Barai (MW 14) heard cracking sound from the face ahead and the area behind him. Immediately, they saw muddy water gushing out like a spray from the right (south) side of the face, Shri Bhangi Rajbhar (UW 5) was knocked off his feet. Shri Chandradhari Barai (MW 14), pulled out Shri Bhangi Rajbhar (UW 5), collected his assistants and tools and rushed out of the face shoutings warnings regarding the sudden inrush of water. On the way, Shri Chandradhari Barai (MW 14) met Shri Dodan Pandey (MW 13) near the haulage of the district and the informed him about the sudden inrush of water. Shri Dodan Pandey (MW 13) asked him to evacuate all the persons of the district and he took the task of informing the workers of 21 crosscut district about the inrush of water. Shri Dodan Pandey (MW 13) in turn informed Shri Fouzdar Singh, (MW 1) at about 4.30 a.m. over the CDS telephone about the sudden inrush of water from the 40 dip face. Shri Fouzdar Singh (MW 1) immediately used the CDS telephone at 21 level off 6 dip to contact the attendance cabin at the pit top but there was no response. Information about the accident was sent to the Agent-cum-Manager Md. Kalim (MW 17). Then he contacted Shri P. L. Banerjee, (MW 16), Safety Officer over the CDS telephone and informed him about the accident. Thereafter, he again rang up the attendance cabin and got Shri Ram Chandra Mahato, Sirdar of the 'B' Pit depillaring district. He instructed Shri Ram

Chandra Mahato to evacuate all persons from the 'B' pit district and to inform the other districts over the telephone to evacuate all persons from underground. He also instructed the CDS operator to announce over the microphone facility available with the CDS to warn all persons underground and direct them to evacuate to the surface. Shri Dodan Pandey (MW 13) and Shri Fouzdar Singh (MW 1) tried to go towards 21 crosscut section, but soon water also reached there. Since they could do nothing more to rescue the workers, they rushed towards the pit bottom, where they met Shri P. L. Banerjee (MW 16). With Shri P. L. Banerjee (MW 16), Shri Fouzdar Singh (MW 1) and Shri Dodan Pandey (MW 13) came back towards the section. However, near 8 level, they found water rushing from the rise side. Shri P. L. Banerjee (MW 16) then went towards 'B' pit, whereas Shri Dodan Pandey (MW 13) and Shri Fouzdar Singh (MW 1) came to No. 'A' pit. Fearing the worst, they immediately got upto the surface. At the pit top, they met Md. Kalim, Agent-cum-Manager (MW 17). Shri Fouzdar Singh (MW 1) again went underground through No. 'A' Pit alongwith Shri Dodan Pandey (MW 13), the onsetter and Md. Kalim (MW 17). But they found that water has risen almost chest high in the pit bottom itself. Realising that there was no further scope of rescuing the workers through the pits, they came back to the surface by about 5.30 a.m.

5.2.1 As there was a possibility that some workers might have come from the Narainkuri seam to the Nega seam through the drift, Shri P. L. Banerjee (MW 16) along with others went down through the sinking bucket of the adjoining unit to the Nega seam. They however could not find any one except the two pump khalasis of Nega seam waiting to be hoisted up.

5.2.2 A quick check of the attendance register revealed that out of the 221 workers who had gone down the mine, 150 workers had come out, and thus the remaining 71 workers were presumed to be trapped underground. Most of the trapped miners were from the 21 cross-cut district, and the remaining from the 42 cross-cut district. Fortunately, contact with the two groups of trapped miners could be established soon over the CDS telephone. The trapped miners informed that they were unable to reach the pit bottom due to the rising water, which had cut off their approach route. Counting of the trapped miners and the reconciliation of figures of miners who could quickly come out to the surface, revealed that there were sixtyfive miners who had been trapped underground. Hence six miners were feared to be missing. Later, the sixtyfive trapped miners were guided over the CDS telephone to go towards the rise side as attempts would be made from the surface to establish direct contact with them through a borehole. It would be relevant to mention that the effective functioning of the CDS telephone even under conditions of submergence contributed vitally to the rescue operation in the initial stages.

5.3.1 Around 10 a.m. of November 13, the Senior Officials of the DGMS and M/s. ECL Ltd. reached the Mahabir mine. It soon became clear that the accident had taken place due to a connection in the Narainkuri seam with the old and waterlogged Shaft No. 34 and the workings on the rise side would remain free from water where the trapped miners could take shelter. It also transpired that in the past a few exploratory holes drilled in the rise side of the Narainkuri seam beyond the outcrop of the Nega seam, had in fact punctured the workings. Thus it was felt that communication could be established with the trapped miners through a borehole. A rough estimate of the entrapped air indicated that it would be good enough to permit normal breathing for about two weeks. It was therefore felt that the trapped miners were not in imminent danger.

5.3.2 A drilling rig was brought on emergency basis and existing Borehole No. 3 which had been quickly located by a search party was reamed to 20 cm. diameter by 2.30 a.m. of November 14. Through the CDS telephone, the trapped miners were directed to assemble below the No. 3 Borehole. With clear supply and communication line established through the borehole and with all the trapped miners safely around it, the initial anxiety regarding safe rescue of the miners was reduced.

5.3.3 A suitable site was immediately selected on the surface towards the rise side for drilling a large diameter borehole to rescue the trapped miners. The operation was started around 9.30 a.m. on November 14 and a borehole of 52 cm. diameter was completed around 3.30 p.m. of November 15. A steel capsule with hinged doors based on a German design was fabricated locally. A temporary tripod was erected and winch was installed and through the winch-operated capsule, Shri G. S. Gill, Additional Chief Mining Engineer of M/s. ECL, who was trained in rescue operations, was lowered to the underground workings around 2.20 a.m. on November 16. As the manually operated winch was taking time for hoisting of the trapped miners, this was replaced by a crane after some miners had been rescued. The first trapped miner was brought out by 2.40 a.m. on November 16 and the last one was rescued by 8.40 a.m. of the same day. This unique method of rescue was tried for the first time in India. Never before in the world, such a method of rescue had been tried on such a large scale. The rescue operation received considerable media attention.

5.4.4 Thereafter, search operation was started for the six missing persons. Search parties were sent through the capsule and search continued throughout the day and night till the early hours of November 18. Sending of the search parties through the Borehole was stopped thereafter because the unlined portion of the borehole gave indications of caving in. Subsequently when the pits were de-watered, search for the six missing miners continued. Unfortunately, these six miners could not be rescued alive. Their dead bodies were recovered one after another. The last body was rescued on December 23, 1989 after considerable efforts.

## CHAPTER-VI

### 6.1 First Inspection of the Site of Accident

#### 6.2 Surface Inspection

#### 6.3 The Second Inspection

#### 6.4 Observations

6.1.1 On April 7, 1991 I went to the Mahabir mine to inspect the site of accident. Prof. A. K. Ghose, Assessor, Shri K. Paul, DGMS, Shri T. K. Dev, Director (Technical), M/s. ECL and other officers of DGMS and M/s. ECL also accompanied me during the inspection. Shri B. N. Tewary, Assessor, could not be present. We went down through No. 'A' Pit to the Narainkuri seam and walked beneath the Eastern Railway line from Delhi to Howrah. Enroute I saw the devastation caused by inrush of water which had scoured the ballast and packing materials of the haulage track and deposited it on the adjoining level galleries. The location from which some of the six dead bodies were recovered was also shown to me. At 33 level, I saw the receiver of the underground telephone system (i.e., CDS system) which was used by the trapped miners for communicating with the operator on the surface. Earlier in this Report I have mentioned that the CDS system functioned effectively and played a crucial role in the successful rescue operations.

6.1.2 While proceeding along the 33 east level haulage road, I saw marks left by water on the ventilation stoppings. It gave me a fair idea of the maximum level to which water had risen in the workings. Around junction of 40 dip off 28 level, I saw two big blocks of stone lying on the floor. I also saw haulage rails which had been bent and twisted by the force of water. While proceeding along with drivage of 40 dip, I got the distinct impression that the gallery at 40 dip, had abruptly deviated from its normal north easterly bearing to almost due south connecting 40 dip with old Shaft No. 34. The exact spot where 40 dip off 28 level had punctured the old and abandoned Shaft No. 34 was covered with boulders and rubbles. While proceeding along the drivage of 40 dip off 28 level, I could not see any trace of flank boreholes except one in that gallery. After visiting the site of accident I went along 29 level to adjoining 39 dip and inspected the face at 27 level off 39 dip from where a long borehole had been drilled in 1988. I saw the flank boreholes drilled in the gallery at 27 level. I also saw the marks left by the seepage water along the sides of the pillar at 27 level off 39 dip. These marks were prominent below the flank boreholes. My journey to the site of accident and inspection lasted for about three hours.

6.2 On April 8, 1991 I along with some officers of the DGMS and the ECL, went to inspect the abandoned Shaft Nos. 33 & 34 at the surface. The surrounding area of the shafts was full of wild growth. During the inspection some villagers told me that before the accident on November 13, 1989, Shaft Nos. 33 & 34 were not visible on the surface as they were covered with soil and vegetables had been grown on it. Later I inspected the site of the borehole through which the trapped miners were rescued by a capsule. On the way, I saw a pothole which perhaps occurred shortly after the accident.

6.3 Whereas the first visit on April 7, 1991 was primarily for making a first-hand appraisal of the conditions prevailing at the site of accident, the second visit on October 26, 1991 was for the purpose of a re-enactment of the events leading to the accident. On October 26, 1991, Chandradhuri Burai (MW 14) and Bhangi Rajbhar (UW 5) re-enacted the sequence of events leading to the accident after firing the first round of shots at 40 dip face on the fateful morning of November 13, 1989.

6.4.1 Based on inspections of the site, my observations are as follows :—

1. Except at the entry of 40 dip gallery off 28th level where there was only one flank borehole, there was no evidence whatsoever of any flank boreholes along the rib sides. For the purposes of court records, a mosaic of photographs of 40 dip gallery and the 27th level on the date of second inspection was prepared and is at Annexure-XIII.
2. Even if some scouring of the sides of the gallery due to the inrush of water from Nega seam could be conceded, there was no tell-tale evidence whatsoever of the presence of any flank boreholes along 40 dip gallery which casts serious doubts on the depositions made before the Court regarding drilling of flank boreholes at specified intervals.
3. Random measurements were made of the gallery width, both near the site of accident, along the 40 dip gallery and at 27 level which established that the gallery, as originally driven before the accident was about 4.2 m.
4. The floor of the junction off 28 level and 40 dip gallery showed a void from which a large block of stone had been wrenched off and which moved nearly half a pillar to the rise up the 40 dip gallery.
5. At the accident site, along the 28 level and 27 level galleries including the thin rib of coal between 27 level and 40 dip, there was no visible evidence of any ground movement to which the fatal accident could be attributed.

6.4.2 On the basis of the site inspection I have found no evidence to support the contention made by some witnesses of the management that both central and flank boreholes were being systematically drilled while driving 40 dip gallery from November 8, 1989 onwards as per the stipulations contained in Regulation 127 of CMR 1957. It could be argued that there would be no evidence of central boreholes as these were blasted while extracting coal but if flank boreholes would have been provided at 40 dip off 28 level there would have become visible when the site of the accident was inspected. For example, flank boreholes had been given at 27 level in 1988. When I inspected the adjoining area of the site of the accident and went to the 27 level, I could clearly see those flank boreholes.

## CHAPTER-VII

7.1 Issues before the Court.

7.2 Extension of Shaft No. 34

7.3 Unusual seepage of water

7.4 Advance long borehole

7.5 Permission for working

7.6 Advance boreholes

7.7 Other issues connected with the accident.

7.1.1 As stated earlier, the accident took place when a connection was established between the advancing 40 dip face off 28 level and the old and waterlogged Shaft No. 34. On the basis of evidence recorded and written arguments advanced, the following issues were before this Court of Inquiry.

1. Whether the extension of old and abandoned Shaft No. 34 upto the Narainkuri seam was known to the Agent-cum-Manager, Mahabir mine & other officials working under him and whether they exercised due diligence to find the depth of the shaft;
2. whether the above officials had prior warning such as unusual seepage of water to indicate that the workings were approaching towards waterlogged Shaft No. 34;
3. whether the above officials satisfied themselves by providing long boreholes that Shaft No. 34 had not extended upto the Narainkuri seam;
4. whether the above officials had any working permission of the Directorate General Mines Safety to drive the 40 dip gallery off 28 level;
5. whether the 40 dip gallery off 28 level was advanced with adequate cover of central and flank boreholes;
6. and other issues connected with the accident.

7.1.2 These issues are analyzed in the subsequent paragraphs to come to the findings regarding the causes of and circumstances attending the fatal accident.

7.2.1 Md. Kalim, Agent-cum-Manager (MW 17) and others contended that in spite of their best efforts they were not aware that Shaft No. 34 had extended beyond the Nega seam. The representatives of the employees' Union on the other hand alleged that the Agent-cum-Manager & others did not make adequate efforts to find if Shaft No. 34 had extended beyond the Nega seam.

7.2.2 The Agent-cum-Manager, Md. Kalim (MW 17) and others came to the conclusion that Shaft No. 34 had not gone beyond the Nega seam, on the following basis :

- (1) According to Shri P. L. Banerjee, Safety Officer (MW 16) there are about one hundred old shafts in the Mahabir mine and some of the shafts are filled with debris. Shaft No. 34 was one such filled up shaft and was not traceable on the surface. Many of these old shafts were shown in the plan of the mine. In the statutory plan (Exh. M/11) Shaft No. 34 was, also shown as filled with debris. Its depth was not indicated.
- (2) All the shafts the depths of which were shown in the old plans indicated that these had gone upto the Nega seam only. No shaft had been shown to have gone upto the underlying Narainkuri seam.
- (3) The old shafts were plotted in the statutory plan (Exh. M/11) by tracing from the old plan. In 1976, a check survey was conducted by the then Surveyor of the Mahabir mine. In the above survey the depth of the available old shafts was measured and their locations were also verified. However of the old shafts was found to have gone beyond the Nega seam, Shaft No. 34 was not traceable at the surface, and the area on the surface was a private vegetable garden. Obviously, as

it could not be located at the surface, its depth could not be measured.

- (4) Narainkuri seam had been developed beneath the waterlogged Nega seam since 1961 and this development had been also made beneath a number of old shafts. But none of these shafts was found to have extended upto the Narainkuri seam.
- (5) According to Shri P. L. Thacker (MW 15) and Md. Kalim (MW 17) there were no documents/records available to indicate that Shaft No. 34 had extended upto the Narainkuri seam. According to the former Agent of Mahabir mine, Shri K. K. Das (MW 18) the Cadastral Plan of 1926 as well as the Revenue Plan of 1950 of the surrounding area did not also show old Shaft No. 34.
- (6) The Abandonment Mine Plan (AMP) of the Raniganj seam, 1 & 2 pit, Raniganj Colliery of Mys. Bengal Coal Company of 1925 (Exh. M/2A) showed Shaft No. 34 as a surface feature of the adjoining mine. The depth of the shaft was recorded in the AMP as 86 feet (25.8 m) which indicated that it had extended upto the Nega seam only.
- (7) Md. Kalim (MW 17) tried to locate shaft No. 34 at the surface by visual inspection but he failed to do so as the shaft was completely filled up and the surface land was used for growing vegetable.
- (8) In 1989, Md. Kalim (MW 17) got a long borehole of about 40 m. length drilled from 27 level off 39 dip in the Narainkuri seam towards the expected position of shaft No. 34. However, the long borehole neither touched the shaft nor there was any water percolation from the borehole to indicate that Shaft No. 34 was sunk upto the Narainkuri seam.

7.2.3 The Employees' Union however, contended that the Md. Kalim (MW 17) and other mine officials could have located Shaft No. 34 at the surface by conducting a survey with reference to fixed surface features. According to the Union since the Md. Kalim (MW 17) and other officials did not either conduct any such survey or make any other special efforts, to locate the extent of shaft No. 34 they failed to exercise due diligence resulting in the accident.

7.2.4 As the Court of Inquiry I considered the above arguments of both parties. No evidence was brought before the Court to indicate that Shaft No. 34 was visible on the surface. During my inspection of Shaft No. 34 at the surface, I saw wild growth around the area with some patches of vegetable garden. The villagers who were present during my inspection also informed me that Shaft No. 34 was not visible at the surface before the occurrence of the fatal accident.

7.2.5 The next question is whether the Shaft No. 34 could have been located at the surface by Md. Kalim (MW 17) and others with reasonable efforts. It has been admitted that there is possibility of error in the position of Shaft No. 34 indicated on the plan due to tracing and retracing from old plans as well as due to inaccuracy of survey. Since the surface area of the Mahabir mine was large and consisted of cultivable land and barren land without many prominent surface features, it might not have been very easy to locate a shaft of only 3 m. diameter hidden under an unknown cover of soil. The problem can be appreciated when one observes that there are over 36 filled shafts scattered over six square Km. surface area of the Mahabir mine. Thus, I hold that it was not reasonably possible for the Agent-cum-Manager, Md. Kalim (MW 17) and others to locate the filled up Shaft No. 34 at the surface.

7.2.6 Md. Kalim (MW 17) and others had relied largely on the AMP (Exhibit M/2A) in respect of depth of Shaft

No. 34. But the AMP (Exh. M/2A), was of the adjoining 1 and 2 pit workings and not of workings made from Shaft No. 34. In the AMP (Exh. M/2A), Shaft No. 34 was merely shown as a surface feature of the adjoining mine. Secondly, it was recorded in the AMP (Exh. M/2A) as follows : "old pit No. 34, depth 86 feet. Approximate position taken from old plan." Thus such an AMP (Exh. M/2A) should not have made the Md. Kalim (MW 17) presume the supposed location of old Shaft No. 34 and its extension upto the Nega seam only. With about 28 years of experience in coal mines, Md. Kalim (MW 17) was knowledgeable enough to understand that in the past a number of disasters due to inundation had occurred in coal mines because of inaccurate plans. In this context, he and the Safety Officer, Shri P. L. Banerjee (MW 16) should not have become complacent that Shaft No. 34 did not extend beyond the Nega seam only because the AMP (Exh. M/2A) indicated so.

7.2.7 While granting permission for developing the Narainkuri seam below the waterlogged Nega seam, the DGMS included provision of advance boreholes though while applying for the working permission the then Agent had sought exemption from such boreholes. Obviously the DGMS apprehended possibility of old workings in the Narainkuri seam and had not relied on the AMP (Exh. M/2A). This was yet another reason why Md. Kalim (MW 17) and Shri P. L. Banerjee (MW 16) should have proceeded very cautiously because 40 dip off 28 level was the area where the old Shaft No. 34 was likely to be located. It is a fact that a long borehole was drilled from 27 level face towards the position of old Shaft No. 34 indicated in the plan (Exh. M/11) though the borehole did not intercept it. But it could not be the conclusive evidence that Shaft No. 34 had not extended upto the Narainkuri seam. It is quite likely that a long borehole may fail to intercept a shaft of only 3 m. diameter as in this case. Md. Kalim (MW 17) and Shri P. L. Banerjee (MW 16) were also experienced enough to know it.

7.2.8 The plan of the site of the accident (Exh. M/12) indicates that the Shaft No. 34 had shifted by 6.5 m south west of its position shown on the working plan (Exh. M/11). Thus the Agent-cum-Manager, Md. Kalim (MW 17) and Shri P. L. Banerjee, Safety Officer (MW 16) had erred in relying on the data provided by a single long borehole that Shaft No. 34 had not extended upto the Narainkuri seam.

7.2.9 A question now arises as to when and how did these shafts get exposed on the surface. Soon after the occurrence of the accident on the morning of November 13, 1989 filled Shaft No. 34 got exposed to the surface. It was a little later that subsidence and potholes developed at the surface near Shaft No. 34. It is quite possible that when water flowed from the Nega seam to the underlying Narainkuri seam, the debris column that filled the shaft got washed down, exposing Shaft No. 34 to the surface.

7.3.1 Let me now analyze whether there was any unusual seepage of water at 40 dip off 28 level immediately before the fatal accident. It is accepted that seepage of water not normal to the seam is a positive warning that the workings are approaching a waterlogged area. The Employees' Unions deposed that there was heavy seepage of water while working near the old Shaft No. 34, but the Agent-cum-Manager, Md. Kalim (MW 17) and other officials deposed that the seepage of water was not unusual. Regulation 127 of CMR 1957 lays down, inter alia, that whenever seepage of water which is not normal to the seam is noticed at any place in any workings, or if there be any such suspicion or doubt, such working shall immediately be stopped and the DGMS shall forthwith be informed of such seepage and such workings shall not be extended further except with prior permission in writing of the DGMS and subject to such conditions as he may specify therein.

7.3.2 The workings of the Narainkuri seam is normally dry. In December, 1988 while developing near old Shaft Nos. 33 and 34 the former Agent Shri K. K. Das (MW 18) observed unusual seepage of water from the faces at 26, 27 and 28 level off 39 dip. The Surveyor Shri P. L. Thacker (MW 15) recorded in his statutory surveyor's diary about this



unusual seepage of water as well as the fact that the workings were nearing old shaft No. 34. As required under Regulation 49 of CMR 1957, the diary was counter signed by the Manager Md. Kalim (MW 17). The former Agent Shri K. K. Das (MW 18) also observed the unusual seepage of water in those faces and recorded the same in his inspection report book (Exhibit W/5). The workings in this area was stopped and the DGMS was informed. Thereafter the former Agent, Shri K. K. Das (MW 18), vide his letter of January 19, 1988 (Exhibit M/5) addressed to the DGMS stated that in light of above seepage, he sought change in the projections of development near Shaft Nos. 33 and 34 from those earlier approved by the DGMS (Exh. M/5). Shri K. K. Das (MW 18) however recorded in his inspection report (Exhibit W/5) that the seepage observed by him, on January 13, got reduced when he submitted his report on January 28, 1988. But his observation was based on eye estimation and not on actual measurement. In his deposition, Shri K. K. Das (MW 18) also stated that water was percolating through the cracks in the roof at 27 level. If it was so, he would have also recorded in his inspection report (Exh. W/5). He had not done so. On the contrary he had recorded that the roof and sides were good. Further, Shri K. K. Das (MW 18) got a long borehole drilled from 27 level off 39 dip towards the position of Shaft No. 34 indicated in the working plan (Exh. M/11), Shaft No. 34, was, however, not connected by the long borehole as stated earlier. Nevertheless, Shri K. K. Das (MW 18) proceeded cautiously and did not go ahead with further development in that area and sought fresh permission of DGMS in January, 1988 to work in a revised projection about 100 m. away from old Shaft No. 34. The question is why Shri K. K. Das (MW 18) did not go ahead with the workings at 27 level after January, 1988. It was obvious that the seepage of water at 27 level was so heavy that he sought permission of the DGMS for working a new projection. In his deposition, Shri K. K. Das (MW 18) had stated that he wanted a longer period to observe the seepage of water at 27 level by driving a long borehole. Hence caution was the keynote in the approach of Shri K. K. Das (MW 18). When such was the note of caution sounded by Shri K. K. Das (MW 18), Md. Kalim (MW 17) who was a Manager of the Mahabir Mine under Shri K. K. Das (MW 18) and was aware of all developments in this regard should not have started work in the 40 dip gallery off 28 level (which was very close to 39 dip off 27 level and still closer to shaft No. 34) on November 8, 1989 without any permission from the DGMS. It is significant to note that the fatal accident occurred only after five days of the commencement of work at 40 dip gallery off 28 level.

7.3.3 There is evidence that 40 dip face off 28 level was re-started on November 8, 1989 after a lapse of almost two years. Most of the witnesses of the management, including Shri Dodan Pandey (MW 13), Shri Ram Shankar Sarkar (MW 12), Shri Shivdas Chatterjee (MW 9), Shri Mihir Kumar Chatterjee (MW 10) and Shri Chandradhari Barai (MW 14) stated that there was no seepage of water from 40 dip working on November 12, 1989. However Shri Ganesh Roy (MW 5) stated that they sometimes used to fill their water bottles with the water seeping from faces of 42 cross-cut. Shri Nur Mohammed (MW 4), a loader of 40 dip on third shift of the day of the accident deposed that the district was dry except some seepage at 40 dip face. On the contrary, witnesses produced by the Unions like Shri Ram Chander Mahato (UW 4) and Shri Bhangi Rajbhar (UW 5) reported heavy seepage of water from the roof and face of 40 dip on the third shift of November 12, 1989. There was also no water spraying arrangement provided at 40 dip face, though it was provided in other faces of the district, to suppress air-borne coal dust for safe mining.

7.3.4 The question is whether the seepage of water at 40 dip face off 28 level immediately before the fatal accident was unusual. If it was unusual, the Agent-cum-Manager, Md. Kalim (MW 17) and the officials under him would have been forewarned of waterlogged workings ahead and should have taken necessary precautions. Whereas most of the witness of the management (i.e. MWs) deposed that there was no unusual seepage of water, all the witnesses of the employees' Union (i.e. UWs) deposed regarding unusual seepage of water at 40 dip face immediately before the fatal accident. There was, however variation in the quantity of

seepage of water among the witnesses of the Employees' Union. Shri Ramachandra Mahato (UW 4) deposed regarding heavy seepage of water which affected normal working. Shri Bhangi Rajbhar (UW 5) who has since retired from service, deposed that the seepage of water at 40 dip face prior to the accident was unusual to the extent that it appeared like a mild drizzle. Shri Bhangi Rajbhar (UW 5) appeared to me to be a non-partition and truthful witness. His demeanour and simple and straightforward answers impressed me. I believe him regarding unusual seepage of water at 40 dip face prior to the fatal accident and hold that Md. Kalim (MW 17) and officials working under him had enough warning of the workings approaching a waterlogged area in an otherwise dry Narainkuri seam. Naturally, existence of a waterlogged shaft in such close proximity of the workings did cause unusual seepage of water at 40 dip face.

7.3.5 The former Agent Shri K. K. Das (MW 18) as well as Md. Kalim (MW 17) deposed that the roof of 26, 27 and 28 levels from where seepage of water was observed in 1988 was bad and needed heavy support. However my inspection of these workings after the accident indicated neither presence of cracks and bad roof conditions nor presence of heavy supports. The roof appeared to be normal like any other workings of the district. The plan (Exh. M/11) of the area also did not indicate presence of geological disturbances. I had also observed the marks of seepage of water left in the wall of 27 level off 39 dip particularly where advance flank boreholes had been drilled in 1988. Therefore the unusual seepage of water at 27 level in 1988 was not due to presence of any geological disturbances but because the workings were advancing to an area in close proximity of the waterlogged Shaft No. 34.

7.3.6 As already indicated, the workings of 40 dip had been stopped for unusual seepage of water in January 1988 and this seepage was recorded in the statutory book and the DGMS had also been informed. Therefore Md. Kalim (MW 17) was also not within his right to restart 40 dip face off 28 level on November 8, 1989 without written permission of the DGMS as required under Regulation 127(5) of CMR 1957. This was also not objected to by Shri P. L. Banerjee, Safety Officer (MW 16) whose primary duty was to ensure safety in the mine. The Assistant Manager, Shri K. Dutta (MW 19) also did not protest even though he knew that 40 dip off 28 level was known to be an area of heavy seepage of water where work had been stopped in January, 1988 and commencement of work in this area was not covered by the working permission of DGMS.

7.4.1 Let me now analyze the evidence regarding the long borehole drilled in 1988 to locate the old Shaft No. 34. In January, 1988, seepage of water was observed in 26, 27 and 28 level faces and the Surveyor Shri P. L. Thacker (MW 16) brought this to the notice of the Md. Kalim (MW 17), who was then the Manager, as well as the former Agent Shri K. K. Das (MW 18) that the workings were approaching Shaft No. 34. A long borehole was thus proposed to be drilled from 27 level off 39 dip towards the expected position of old Shaft No. 34. The purpose of the long borehole was to locate Shaft No. 34 and also to comply with the stipulations contained in the working permission of the DGMS (Exh. M/5). Shri P. L. Thacker, Surveyor (MW 15) gave direction of the borehole so as to intercept the Shaft No. 34 in the Narainkuri seam. He made the calculation of the direction and the length of the borehole based on the position of Shaft No. 34 marked on the mine working plan (Exh. M/11) with reference to position of 27 level off 39 dip face. He also gave the bearing of the long borehole at the site. On the basis of the direction marked by the Surveyor, the Driller Shri Ramesh Majhi (MW 8) drilled a long hole of 133 feet (40 m) at almost the centre of the face of 27 level. The drilling operation was done under the supervision of Shri P. L. Banerjee (MW 16). Shri P. L. Thacker (MW 15) measured the length of the long borehole and verified its direction. I saw the above long borehole during the inspection of the site of the accident. I am thus satisfied that the long borehole was in fact drilled in 1988 to locate Shaft No. 34.

7.4.2 Md. Kalim (MW 17) admitted the possibility of error in the location of Shaft No. 33 and 34 in the mine

working plan (Exh. M/11), Shri P. L. Banerjee (MW 16) however stated that it was not possible to take any measure to prevent the likely deviation of the long borehole and there was no instrument available with them to examine whether long borehole has actually deviated. Shri P. L. Thacker (MW 15) stated that there was every chance of the borehole deviating if the drillers did not take adequate care. Thus there was possibility of the long borehole deviating and failing to intersect the old Shaft No. 34. Md. Kalim (MW 17) and Shri P. L. Banerjee (MW 16) had no reasons to be absolutely sure that the long borehole of 133 feet (40 m.) had crossed the old Shaft No. 34.

7.4.3 Subsequently, a survey of the site of accident was conducted by the management and a plan was prepared (Exhibit M/12). It indicated that the actual location of Shaft No. 34 was 6.5 m. away from that shown in the mine working plan (Exhibit No. M/11). The long borehole therefore failed to intersect old Shaft No. 34 in the Narainkuri seam. Thus the drilling of only one long borehole at 27 level in 1988 developed a false sense of security that Shaft No. 34 had not extended upto the Narainkuri seam.

7.5.1 Let me analyze whether the Agent-cum-Manager, Md. Kalim (MW 17) had working permission of the DGMS to work 40 dip at 28 level. It was alleged by the Employees' Unions in the written arguments that 40 dip off 28 level was being developed from November 8, 1989 without any working permission of the DGMS. On the other hand the management argued that they had a valid permission from the DGMS and therefore drivage of 40 dip off 28 level was permitted.

7.5.2 Regulation 127 of CMR 1957 requires that no workings shall be extended within 60 m. of any waterlogged working without prior permission in writing from the DGMS subject to the conditions specified. The Regulation also requires that every application for permission to extend any such workings should be accompanied by plans showing, inter alia, the outlines, the layout and the method of proposed working. Once the permission is granted by the DGMS to extend the working, it shall be extended strictly in accordance with the plan, the method approved and the conditions specified therein. There is no scope for the Agent-cum-Manager to vary the stipulations in the working permission unless such variation is again approved by the DGMS.

7.5.3 In December, 1983, the management applied for permission to develop an area in Narainkuri seam on the south side of the main railway line (Exh. M/5). The plan submitted with the application (Exh. M/4) showed projections of development beneath old Shaft Nos. 33 and 34. Working permission for this development was granted vide DGMS letter No. S-3/173 (BD):(MB):II-B/84/1062 dated March 12, 1984 (Exh. M/5). It included the area where the accident took place on November 13, 1989. The working permission required that old shaft should overlie the pillars formed. According to this permission the area between 26 level and 31 level could be developed beyond the location of Shaft Nos. 33 and 34, leaving the shaft in solid pillars. Thus while granting the working permission in 1984, DGMS had also taken care of safety precautions adequately.

7.5.4 However, in his letter No. ECL : MB : DEV : 88 : 198 dated January 19, 1988 (Exh. M/6), the former Agent Shri K. K. Das (MW 18) sought change in projections of development from the DGMS in the light of unusual seepage of water in the faces of 26 level off 38 dip and 27 level off 39 dip in proximity of the old Shaft No. 34.

7.5.5 A comparison of the projections in the plan accompanying the application for the permission in 1983 (Exh. M/4) with that of 1988 (Exh. M/7) would indicate that in the received projection (Exh. M/7), the workings between 26 and 31 level were not to be advanced any further towards old Shaft Nos. 33 & 34. The old shafts were to be bypassed following a cross-cut from 32 level. The next cross-cut known as 41 cross-cut was to be driven 45 m. away from Shaft No. 33 and 100 m. away from Shaft No.

34. No development was proposed on the dip side of 41 cross-cut.

7.5.5 The DGMS in his letter No. S3/22 03/062/IIA/88/623 dated March 2, 1988 (Ex. M/8) granted modified permission to develop Narainkuri seam according to the new projections (Exh. M/7). However, the terms and conditions stipulated in the earlier DGMS permission letter No. 1062 dated March 12, 1984 (Exh. M/5) remain unaltered.

7.5.6 The former Agent Shri K. K. Das (MW 18), the Manager, Md. Kalim (MW 17), the Safety Officer Shri P. L. Banerjee (MW 16) were of the opinion that the projections for development granted by the permission of 1984 (Exh. M/5) remained valid even when they had sought modification of the projections (Exh. M/7) for specific reason and were granted accordingly the permission of 1988 (Exh. M/8). In other words, the modified permission of 1988 did not supersede the permission of 1984 and therefore the development of 40 dip at 28 level from November 8, 1989 was done in a permitted area. In my opinion it was not necessary for the DGMS to state categorically in the "1988 permission" that the "1984 permission" stood cancelled. Such a cancellation was implicit as the former Agent, Shri K. K. Das (MW 18) had himself sought modification in the "permission" in light of heavy seepage of water at 26, 27 and 28 levels in close proximity of Shaft No. 34. Further such a line of argument for the management is not at all tenable as Regulation 127 (5) ibid clearly stipulates that once a working is stopped in a particular area for unusual seepage of water, the working shall not be restarted in that area without a fresh permission in writing from the DGMS. In this case, the DGMS had given no such fresh permission. Hence resumption of mining from November 8, 1989 at 40 dip at 28 level, where it had been stopped in January 1988, due to unusual seepage of water, was totally unwarranted. Md. Kalim, (MW 17), Shri P. L. Banerjee, (MW 16) and Shri K. Dutta, (MW 19) being senior and responsible officials and holding Managers' certificate of competency should have realized this aspect of the Regulation.

7.5.5 The management have argued that whenever the waterlogged workings are situated in the same seam, it might be necessary to drill one central borehole as well as a number of flank boreholes but if the waterlogged workings are situated vertically above the proposed workings, flank boreholes of 3 m. in length is unnecessary and only a central advance borehole may be required to explore the possibility of existence of geological disturbance ahead. But this line of argument is not sound as the subsequent analysis would indicate.

7.5.6 The parting between the Nega and the Narainkuri seam is only 24 m. and there are old shaft of unknown depth which might have extended upto Narainkuri seam. The possibility of an old shaft extending upto Narainkuri seam or existence of old workings in the Narainkuri seam through drifts from overlying seam, could not be ruled out. Therefore it could not be assumed, as the management have argued, that the waterlogged workings were only in the overlying seam and thus no advance flank hole was necessary. The permission of DGMS (Exh. M/5) was to take care of all these possibilities, as the DGMS had prescribed sufficient number of flank boreholes along with central boreholes.

7.5.7 To elaborate: the working permission of the DGMS both in 1984 and in 1988 for the Narainkuri seam of the Mahabir Mine was in total conformity with Regulation 127(6)(a) which requires that when the workings are advanced towards waterlogged areas, there shall be maintained at least one borehole near the centre of the working face and sufficient flank boreholes on each side, and where necessary boreholes above and below the workings at intervals not more than 5 m. All such bore holes shall be maintained and shall be constantly maintained at sufficient distance in advance of the workings and such distance shall in no case be less than 3 m. These stipulations are required to be carried out under the direct supervision of an official of the mine having a manager's or overman's certificate, specially authorized for the purpose. Under the relevant Regulations, a record of the height and width of the workings as well



as the number of boreholes, their length and direction is required to be maintained in a register and the register is to be signed by the official authorised for the purpose and counter-signed by the manager everyday. These records were not maintained by Md. Kalim, Agent-cum-Manager (MW 17) and the officials under him.

7.6.1 Now let me analyse the evidence regarding the most important issue whether the working at 40 m. face started from November 8, 1989, had adequate protection of advance central and flank boreholes. Md. Kalim (MW 17) deposed that in order to ensure compliance of all the conditions of the working permission of the DGMS as well as the requirements of Regulation 127, of CMR 1957 he had provided necessary infrastructure like drilling machine, manpower and supervision. The advance boreholes were drilled by means of ordinary coal drill. The pattern consisted of a central borehole in the face and two flank boreholes in the jobs at forty five degrees to the face. The length of the flank hole was 3 to 3.6 m. and these were drilled on both the ribs. For the purpose of drilling the holes, a coal drill with three sets of drill steel of 1.8 m., 3.6 m. and 5.4 m. length was provided.

7.6.2 There is evidence that upto June, 1989 a regular advance drilling gang was provided. These workers, in the drilling gang who were designated drillers, were Shri Kuldip Das, (UW 1), Barho Dusad and Bindu Bourl. The drilling gang used to reach the district in the early hours of the first shift and complete drilling of the advance boreholes in all the faces proposed to be advanced on that day. However, in June, 1989, the drilling gang was disbanded by the Agent-cum-Manager, Md. Kalim (MW 17) and the drillers were deployed elsewhere. According to Kuldip Das (UW-1) since the disbandment of the drilling gang in June, 1989, no advance boreholes were drilled. Md. Kalim (MW 17) and Shri P. L. Banerjee (MW 16) stated that for better utilisation of manpower the advance drilling gang was disbanded. However drilling of the advance boreholes was continued by the general mazdoor of the first shift and such advance central and flank boreholes were provided in 40 dip face when it was started on November 8, 1989. Thereafter, according to the witnesses produced by the management, these boreholes were regularly drilled and on the first shift of November 12, 1989, the advance central borehole was extended from 3.6 m to 5.4 m and two flank boreholes of 3.0 m. to 3.6 m. in length was drilled in the ribs of 40 dip face. These advance boreholes were drilled under the supervision of Shri Mihir Kumar Chatterjee (MW-10) and Shri C. D. Singh (MW 11). Overman. They found the length of the advance boreholes to be in order. In the second shift, Shri Shivas Chatterjee (MW 9), Overman checked the advance boreholes and found it to be about 3.6 m in length. He also checked the advance flank boreholes and found them to be in order. In the third shift, Shri Dodan Pandey, Sirdar (MW 13) also checked the central borehole in 40 dip face and found it to be more than 3 m. The shot-firer Shri Chandradhari Barai (MW 14) deposed that before charging the shots in the face of 40 dip on the fateful day, he had also checked the central and flank boreholes with his stemming rod which was 1.8 m. in length and thus he concluded that these holes were more than 1.8 m. However, Shri Bhangi Rajbhar (UW 5) who also charged the shot-holes of 40 dip immediately prior to the accident categorically stated that there was no advance and flank boreholes in the face. He claimed to have known the difference between shot holes and advance boreholes. Other witnesses such as Ganesh Roy (MW 5) and Ram Chandra Mohata (UW 4) also denied having seen any advance holes in the face.

7.6.3 An interesting point is that none of the persons who stated that advance boreholes were drilled, could name even a single driller who drilled those holes. Only one witness, Shri C. D. Singh (MW 11), could recollect the name of a driller called Shri Madhuri Paswan. But he too was also not sure of his designation. Initially he stated the driller to be a general mazdoor but later recollected his designation to be a driller. Since drilling of advance boreholes was a regular affair as claimed by the Agent-cum-Manager Md. Kalim (MW 17) and other officials under him it is highly unlikely that none of the officials from Agent-cum-Manager

downwards, who claimed to be connected with the supervision of advance boreholes at 40 dip on 28 level, could remember the name of even a single person who drilled those advance boreholes. Secondly, drilling of an advance borehole of 5.4 m. by an ordinary coal drill involves change of the drill rods in stages. The drill holes are required to be drilled centrally as well at forty five degrees to the face. Therefore there could be no denial that drilling of advance boreholes required skill, not less than that required for drilling shotholes at the face. It is unlikely that the job could be done by general mazdoors deployed to do the job on a casual basis as claimed by Md. Kalim, Agent-cum-Manager (MW 17) and other officials.

Further, no supervisory officials examined as witness before this Court accepted the responsibility of supervision of the advance holes in terms specified under Regulation 127(6) of CMR, 1957. Md. Kalim (MW 17) stated that he could recollect to have authorised two overmen for this purpose but failed to recall their names, except the name of one Shri Mukherjee. However, no such person (i.e. Shri Mukherjee) could be produced by the management as a witness. Shri Mihir Kumar Chatterjee, Overman (MW-10) accepted the responsibility of supervising the advance boreholes only to the extent he was generally asked by the Agent-cum-Manager Md. Kalim (MW 17) to supervise the work of advance boreholes, but he was not normally entrusted with the supervision of such boreholes as required under Regulation 127 of CMR 1957. Md. Kalim (MW 17) also admitted that no mandatory records of the advance boreholes at a 40 dip of 28 level or at any other working face of the Mahabir mine were maintained.

7.6.4 The manner and the system of monitoring the drilling of advance central borehole upto a length of 5.4 m and flank boreholes 3.0 m to 3.6 m long and at forty five degrees to the face was also not clearly spelt out by the Agent-cum-Manager Md. Kalim (MW 17). From the analysis of the evidence, it appears that only when the supervisory staff would go to the face, they would measure the advance boreholes. There was no regular system either for recording or for monitoring the same.

7.6.5 During my inspection of 40 dip face after the accident, I did not see any signs of flank boreholes except one at the start of the gallery. These flank boreholes, if drilled would have been left in the pillars. On this issue, to a question from the Court of Inquiry, Shri P. L. Banerjee, (MW 16) and K. Dutta (MW 19) stated that the flank boreholes were denuded and washed away by the water when the inrush took place. However the width of 40 dip was like any other gallery of the district i.e. about 4.2 to 4.5 m. The side and roof bore the same jagged look normally seen when a gallery is developed by blasting. Hence the argument put forward by Shri P. L. Banerjee (MW 16) as well as the Management and the Indian Mine Managers' Association that the flank boreholes were washed away cannot be relied upon. Similarly, the possibility of the flank boreholes having been sealed by flowing mud and coal dust due to the inrushing water cannot be accepted as the same is not borne out by observations made during my inspection of the site of accident.

7.6.6 On the basis of the observations during inspection of the site of accident which clearly revealed absence of flank boreholes, evidence of eye witnesses like Shri Bhangi Rajbhar (UW 5), failure of the management of the mine to furnish the minimum mandatory records of boreholes, and failure to produce a single witness who had actually drilled the advance boreholes I am of the opinion that no advance central and flank boreholes were drilled in 40 dip face on the fateful day of November 12, 1989. This was a gross and wilful violation of Regulation 127(6) of CMR 1957.

7.6.7 During my inspection of the site of accident I had observed that 40 dip gallery was no different from any other gallery of the district. It had the same width and height and the same appearance like any other gallery, including the adjacent galleries where flank holes were provided. The sides of the 40 dip gallery exhibited no sign of existence of flank holes except one flank borehole at the start of the gallery.

7.6.8 Therefore, in my opinion the deposition of Shri P. L. Banerjee (MW 16), Shri C. D. Singh (MW 11), Shri Mihir Kumar Chatterjee (MW 10), Shri Chandradhari Barai (MW 14) and Shri K. Dutta (MW 19) that the width of 40 dip gallery was only 3 m. against normal width of 4.2 m. was incorrect. It was possibly made with the motive of justifying the stand that the flank boreholes made along 40 dip gallery had been denuded by the intruding water, ultimately assuming its final width of 4.2 m.

7.7.1 The plan of the site of accident (Exh. M/12) showed an abrupt deviation of 40 dip gallery, near the connection with Shaft No. 34. The management witnesses like Shri K. Dutta (MW 19), Shri Mihir Kumar Chatterjee (MW 10), Shri C. D. Singh (MW 11), Shri Dodan Pandey (MW 13), and Shri Chandradhari Barai (MW 14) deposed that the centre line of 40 dip gallery was hardly 3 m. to 3.6 m. behind the face on the day of the accident. However, the Surveyor Shri P. L. Thacker (MW 15) claimed that he had not marked the centre line of 40 dip gallery after it was restarted on November 8, 1989. He even deposed that he had not visited 40 dip face between November 8, and November 13, the day of the accident. It could be that his assistants had extended the centre line, but he was not sure. No explanation was given either by any witness or by any of the parties to account for such abrupt deviation of the gallery. It could be that the gallery was purposely deviated with reference to the presumed location of Shaft No. 34 in the plan to avoid driving beneath it and to make sure the pillar to be formed encloses the shaft. The other possibility could be the presence of an inset from old Shaft No. 34 oblique to 40 dip gallery. While advancing the gallery the barrier with the inset got reduced and ultimately it failed. The resultant connection with the presumed old and abandoned shaft inset took the form of an abrupt southerly deviation. In my inspection, I had not observed any marked difference in shape and size of 40 dip gallery all throughout its length. Therefore it appears unlikely that there was existence of a shaft inset or a gallery from Shaft No. 34. Further, in view of all the eye witnesses deposing that the centre line was provided and there being no evidence to the contrary, I rule out the third possibility of deviation of the gallery because of absence of suitable centre line. Hence I feel that it is likely that the gallery was purposely deviated.

7.7.2 As already mentioned, 40 dip face which was in close proximity of old Shaft No. 34 was stopped in January, 1988 when unusual seepage of water was observed in that area. At that time the face had hardly extended about 10 feet to 12 feet (3 to 3.6 m.) from 28 level. Later the junction of 40 dip off 28 level housed the return pulley of the endless haulage Md. Kalim (MW 17) deposed that 40 dip gallery was restarted in November, 1989, whereas Shri K. Dutta (MW 19) deposed that it was started in the first week of November, 1989. Other witnesses like Shri Mihir Kumar Chatterjee (MW 10), Shri Shibdas Chatterjee (MW 9) and Shri C. D. Singh (MW 11) deposed that 40 dip face was restarted on November 8, 1989. Therefore, I hold that 40 dip face off 28 level, which got connected with old Shaft No. 34 and caused the fatal accident was restarted on November 8, 1989, barely five days before the accident.

7.7.3 The next point is whether there were other causes and circumstances leading to the connection of 40 dip gallery with Shaft No. 34. Shri P. L. Banerjee (MW 16) claimed that the connection took place due to sudden failure of a coal barrier of more than 3 m. between the advancing gallery and Shaft No. 34.

7.7.4 The length of 40 dip face prior to the occurrence of the accident was estimated by various witnesses like Shri Ram Sankar Sarkar (MW 12), Shri Shibdas Chatterjee (MW 9), Shri C. D. Singh (MW 11) and Shri Mihir Kumar Chatterjee (MW 10) to be around 40 feet to 45 feet (12 m. to 17 m.).

7.7.5 On the basis of the estimates of the above witnesses about the length of the 40 dip gallery and the position of old Shaft No. 34 determined from the plan of the site of accident (Exhibit M/12), P. L. Banerjee (MW 16) deposed that the barrier between the 40 dip face and Shaft No. 34 was more than 3 m. immediately before the accident occurred. But I have not accepted this as the length of 40 dip

face as stated by different witnesses was on the basis of eye estimates only and not on the basis of actual measurement.

## CHAPTER VIII

### 8.1 ANALYSIS OF EVIDENCE— EXTENSION OF SHAFT NO. 34

#### 8.2 UNUSUAL SEEPAGE OF WATER

#### 8.3 RESTARTING OF 40 DIP

#### 8.4 ADVANCE BOREHOLES

#### 8.5 STARTA MOVEMENT

#### 8.6 LOOSENING OF FLOOR STONE

#### 8.7 CAUSE OF THE ACCIDENT

8.1 It was well known that workings of the Nega seam of the old Raniganj Colliery 24 m. above the Narainkuri seam was waterlogged. There were also a number of old shafts in the property, the depths of some of which were not known. One such old shaft was No. 34, which was filled with debris and whose depth was also not known. The management of the mine deposed that they studied the available old plans and records, but could not find the depth of the old shaft. However an AMP of the adjoining workings (Exhibit M/2-A) indicated the depth of Shaft No. 34 as 86 feet which corresponded to the depth of the Nega seam in that area. While granting permission for development in 1984 (Exhibit M/5) the DGMS was very careful and apprehending extension of old shafts upto the Narainkuri seam included the condition of providing flank and central advance holes. In 1988, while developing in the vicinity of old Shaft No. 34, the management of the mine also observed unusual seepage of water. As already mentioned, they stopped the development workings and informed the DGMS as required under Regulation 127 (5) of CMR 1957. Since the existence of old Shaft No. 34 was suspected, the management consulted available plans, documents and other sources of informations so as to ascertain the depth of Shaft No. 34. However, no precise information about its depth was available to them. They also tried to locate the Shaft No. 34 at the surface by visual inspection, but failed to do so as it was filled with debris. Later the management of the mine tried to locate the shaft by providing a long borehole from 27 level off No. 39 dip. Neither the borehole touched the old shaft, nor was there any seepage of water from it. The management of the mine admitted that there was possibility of error in the position of Shaft No. 34 indicated in the working plan (Exh. M/11) because of tracing and retracing from old plan, possibility of shrinkage of the plan as well errors in surveying and plotting. They had also admitted the possibility of deviation in the direction of the long borehole. Obviously, with so many unforeseen parameters, the possibility of proving the existence of an old shaft of hardly 3 m. in diameter by only one long borehole of about 40 m. length is indeed very remote.

8.2 In 1988, the management of the mine rightly decided to suspend the workings and to change the projections of development by passing the suspected old Shaft No. 34. The application for change in projection was made in view of unusual seepage of water at 26, 27 and 28 levels. The revised projection plan about 100 m. away from this area was approved by the DGMS in March, 1988 (Exhibit M/8).

8.3 In November 1989, while developing as per the revised projection of 1988, (Exhibit M/8), the workings touched a dyke in 42 cross-cut section. In order to get a new working area in replacement, Md. Kalim (MW-17) consulted the plan at the survey office, and decided to restart 40 dip face off 28 level. As already mentioned, working in this face had stopped since 1988. The argument of the Management that 40 dip face was restarted from November 8, 1989 to improve ventilation only in the district cannot be accepted as there were other options available to improve ventilation. By starting work at 40 dip, Md. Kalim (MW-17) clearly violated the provision of Regulation 127(5) of CMR 1957 which requires prior written permission of the DGMS. In other words, once the workings around Shaft No. 34 had been stopped in January 1988 due to unusual seepage of

water, Regulation 127 (5) of CMR 1957 does not give any authority to Md. Kalim (MW-17) to restart such workings unilaterally. Thus I hold that from November 8, 1989, Md. Kalim (MW-17) developed 40 dip which was in an area within 60 m. of waterlogged workings without permission of DGMS and in contravention of Regulation 127 (3) of CMR 1957.

8.4 A number of witnesses have deposed that drilling of advance boreholes in a systematic manner by a regular gang was stopped since June, 1989. Subsequently, the advance boreholes were reportedly drilled by general mazdoors. These general mazdoors reportedly used for such drilling were also not regular but were employed on casual basis. These workers were relatively unskilled workers whereas the regular drillers were required to be skilled workers. There were also no marks of any flank boreholes along the sides of 40 dip. There was also no records to indicate that such boreholes were drilled. The workers who had actually drilled the advance boreholes were not produced as witnesses by the management. No competent person was also appointed by the Agent-cum-Manager to supervise the drilling of such advance boreholes. In the absence of any documentary evidence including the minimum statutory record regarding provision of advance boreholes, non-appointment of regular drillers to drill the boreholes and competent person to supervise the drilling, such boreholes, absence of a system of measuring the length and direction of such boreholes, as well as absence of flank boreholes at site during my inspections leads me to conclude that even the central boreholes was also not drilled at 40 dip face.

8.5 Some witnesses, as the Safety Officer P. L. Banerjee (MW-16) have attributed the failure of the coal barrier between 40 dip face and Shaft No. 34 to a major strata movement. This is also the argument of the Indian Mine Managers' Association. The noise of the cracking of the roof rock in the front and behind the face heard by Shri Chandradhari Barai (MW-14) while firing the second round of shots at 40 dip face, the dislodgement of a large piece of floor stone from the junction of 40 dip and 28 level, and the appearance of subsidence and potholes on the surface, have been advanced as evidence of such strata movement. The sound of cracking of rock, had it been there, would have been audible to not only Shri Chandradhari Barai (MW-14) but also to other workers present in the vicinity of 28 level. There was no evidence that other workers heard such a cracking noise. In my view, the absence of any tell-tale evidence of any major strata movement in an around 40 dip, including no visible effect on the roof and especially on the thin rib of coal less than a metre in thickness between 27 level and 40 dip, rules out any such eventuality. It is, therefore, tenuous to suggest that any puncturing of the coal barrier between 40 dip gallery and Shaft No. 34 resulted from strata movement due to crushing of aged and left-out stooks in the overlying Nega seam. If such a strata movement would have taken place it would have led to a large subsidence rather than localised potholes which are common occurrences after drainage of water from old workings.

8.6 It is tenuous to suggest that loosening of the big block of stone from the floor of 40 dip and 28 level junction and its shifting by almost a distance of half a pillar was because of a major strata movement causing the fatal accident. It is quite possible that the floor stone could have got loosened due to its inherent weakness. When there was sudden inrush of water, the loose block of stone perhaps got carried upto a distance of about half a pillar from its original position. In any case, the occurrence of the loose block of stone on the floor of the junction of 40 dip and 28 level had absolutely no connection with the fatal accident.

8.7 On the basis of the evidence, I hold that the cause of the fatal accident was due to direct connection between the advancing 40 dip gallery and waterlogged Shaft No. 34 in the Narainkuri seam connected to the overlying abandoned and waterlogged Nega seam. The accident occurred due to the failure to provide, central and flank boreholes in 40 dip gallery off 28 level advancing towards the waterlogged Shaft No. 34 in the Narainkuri seam. Such boreholes are mandatory under Regulation 127(6) of the CMR 1957 as well as required by the working permission of the DGMS. Further 40 dip gallery off 28 level was advanced towards the waterlogged Shaft No. 34 in an area not approved for working by the DGMS. Incidentally, the fatal accident occurred

within only five days of commencement of working in the gallery in the unapproved area where mining had been stopped in January, 1988 due to unusual seepage of water. This unapproved area was about 100 m. away from the area approved for mining by the DGMS. Thus the fatal accident was due to culpable human negligence.

## CHAPTER IX

### 9.1 ANALYSIS OF RESPONSIBILITY

#### 9.2 AGENT-CUM-MANAGER

#### 9.3 SAFETY OFFICER

#### 9.4 ASSISTANT OFFICER

#### 9.5 SURVEYOR

#### 9.6 HIGHER MANAGEMENT

#### 9.7 OTHERS

9.1 Once the cause of the accident is established the responsibility for the accident has to be fixed. It is evident from the cause of accident that it had occurred due to culpable human negligence. In the subsequent paragraphs, I have analysed the evidence to fix the responsibility.

9.2.1 Md. Kalim (MW-17) was the Manager of the mine since June, 1987 and Agent-cum-Manager since July, 1988. He was therefore well conversant with the mine from December 1987 till November 13, 1989. In December 1987, while working at 26, 27 and 28 level near old Shaft Nos. 33 and 34 of the mine, unusual seepage of water was noticed and the workings in that area was stopped in January, 1988 by the former Agent Shri K. K. Das (MW-18). He then applied to the DGMS for a change in the projections of development in the light of unusual seepage of water. The projection plan (Exh. M/7), by-passing Shaft No. 34 by a clear margin of 100 m. accompanying the revised application submitted to the DGMS in January 1988, was known to Md. Kalim (MW-17) in his capacity as Manager. A copy of the permission letter (Exh. M/8) approving the revised projections was sent by the DGMS to the Manager viz. Md. Kalim (MW-17) in March, 1988. In 1988, a long boreholes was drilled from 27 level towards the expected position of Shaft No. 34. Since the long boreholes did not intercept the old Shaft No. 34 and there was also no percolation of water from the boreholes, Md. Kalim (MW-17) assumed that the old shaft was sunk upto the Nega seam only. Obviously, on the basis of these incomplete investigations, it was not proper for an experienced Manager like Md. Kalim (MW-17) to conclude that the old Shaft No. 34 had gone upto the Nega seam only.

9.2.3 In November, 1989, when the workings of the regular district approved by the DGMS met with a series of dykes, Md. Kalim (MW-17) decided to restart working in the 40 dip off 28 level face, after visiting the survey office, consulting the plan and discussing with the Surveyor. He also admitted to have studied all the previous permission letters and other correspondence from the DGMS relating to mine safety. Thus he was fully aware of the fact that the workings near Shaft No. 34 had been stopped in January 1988 due to unusual seepage of water. He was also aware of the provision of Regulations 127(5) of CMR 1957 which requires that workings which had been stopped due to unusual seepage of water shall not be extended further without previous permission of the DGMS in writing. Since no such permission was obtained his act of restarting 40 dip unilaterally from November, 1989 amounted to wilful and flagrant violation of Regulation 127(5) of CMR 1957.

9.2.2 Md. Kalim (MW-17) also admitted of not maintaining records of the advance central and flank boreholes as well as the plan of the workings required by the permission letter of the DGMS (Exh. M/8) and Regulation 127(6) (b) of CMR 1957. He had also not authorised any competent official to supervise the drilling of advance holes. This was a clear contravention of Regulation 127(6)(b) of CMR 1957. He also did not provide a regular drilling gang for drilling advance boreholes, but employed on casual basis unskilled workers such as General Mazdoors for the job. It is a sad story that Md. Kalim (MW-17) with all these years of experience failed to apprehend an obvious danger which did not appear suddenly but gave enough advance signals. Md. Kalim (MW-17) either due to complacency or

due to an erroneous belief that Shaft No. 34 had not extended beyond the Nega seam failed to visualise the dangers, ultimately leading to the fatal accident. I therefore hold him primarily responsible for the accident which occurred at Mahabir Mine on November 13, 1989. While holding Md. Kalim (MW-17) primarily responsible for the accident, one cannot fail to admire his poise and steadfastness in the witness box and he in his calm and collected manner told the truth. He also deposed that he was directing the operations in the mine and no target of coal production necessitating violations of safety regulations was imposed upon him. A truthful officer as Md. Kalim (MW-17) certainly deserves words of appreciation from me for his conduct during the enquiry.

9.3.1 In the mine, Shri P. L. Banerjee (MW-16) was next in the hierarchy to Md. Kalim (MW-17). He worked as the Safety Officer of Mahabir Mine since June, 1988. Since 1983 he had also worked as Assistant Manager of the same mine. Thus he has been continuously working in the Mahabir Mine since 1983. His duty includes studying and apprising the Manager (i.e. Md. Kalim) of all possible source of danger including inundation. He is also to report to the Manager his observations during his visit to the various parts of the mine, as to whether the provisions of the Mines Act and Regulations framed thereunder are being complied with.

9.3.2 Shri P. L. Banerjee (MW-16) stated that he studied the old plans and found that old shaft No. 34 was filled up with debris. He relied on the various plans available at the mine office to plan out the workings. He could not locate Shaft No. 34 at the surface. He had observed unusual seepage of water at 27 level in January 1988 and had arranged to get a long boreholes drilled. As per his deposition, he was also aware of the possibility of deviation of the long borehole. He had studied the DMS permission of 1984 (Exhibit M/5) and 1988 (Exhibit M/8) and was therefore aware of the conditions of the permission. He was also aware of restarting of 40 dip face in November 8, 1989. He also maintained that there was no seepage of water from 40 dip face and the face was advanced with cover of flank and central boreholes after the work was started from November 8, 1989. But he deposed that there was no method by which he could ensure drilling of advance boreholes in every working face before advancing the same. He only ensured monitoring of such boreholes when he inspected the workings. However, as per his deposition, there was no laid down schedule of his visit and inspection of the working faces. I have already held that the fatal accident occurred because 40 dip face was advanced without cover of advance boreholes in spite of unusual seepage of water in an area not approved for working. These violations were known to Shri P. L. Banerjee (MW-16). Thus he failed to perform his duties under Regulation 41-A(1)(b)(iii) of CMR 1957 to apprise the Agent-cum-Manager Md. Kalim (MW-17) about Shaft No. 34 as a possible source of inundation. He either did not note during his inspection that central and flank boreholes were not being drilled, or willfully allowed the 40 dip face to be advanced without such boreholes in contravention of Regulation 127(6) of CMR 1957 read with Regulation 41-A(1)(f) *ibid*. Thus it is evident that Shri P. L. Banerjee (MW-16) also did not take measures to promote safe practices of drilling of advance boreholes at 40 dip face in contravention of Regulation 127 read with Regulation 41-A(1)(g) of CMR 1957. I therefore also hold him responsible for the fatal accident. Thus it is evident that Shri P. L. Banerjee (MW-16) while being fully aware of the possible dangers, did not take necessary measures to promote safety practices as required under Regulation 41-A(1)(g) of CMR 1957. He is therefore also responsible for the fatal accident.

9.4.1 There were two Assistant Managers in the Mahabir Mine. They were Shri K. Dutta (MW-19) and Shri S. K. Sengupta (CW-1). Shri K. Dutta worked as Assistant Manager of the Mahabir Mine since 1979. He inspected 40 dip twice between November 7 and November 12, 1989 and also on the second shift of November 12, 1989. He knew that work in 40 dip face was stopped in January 1988 because of unusual seepage of water. He also knew that the overlying Nega seam was full of water. He deposed that advance central and flank boreholes of adequate length were provided in 40 dip face but beyond making such a bold statement, he could not either support it with any record maintained

for the purpose or establish through independent witnesses that such boreholes were being systematically and regularly provided. He also could not establish that there was any system of checking such boreholes by supervisory officials before the gallery was advanced.

9.4.2 Therefore as an Assistant Manager of the district, he had failed to ensure that advanced boreholes were drilled in 40 dip face as required under Regulation 42 of CMR 1957 read with Regulation 127(6) of CMR 1957. Thus he had also willfully violated the provision of the law resulting in the accident and is responsible for the same.

9.4.3 The second Assistant Manager Shri S. K. Sengupta (CW-1) joined the mine only on October, 1989. He was on leave for a few days thereafter. He was assigned some other development jobs and did not do the job of supervision of 42 cross-cut district where the accident occurred. Thus he was not responsible for the fatal accident.

9.5.1 Shri P. L. Thacker (MW-15) was Surveyor of Mahabir Mine since 1977. He had observed the unusual seepage of water at 27 level in January, 1988. He had recorded this fact in his statutory Surveyor's Diary as well as recorded the information that the workings were approaching the waterlogged Shaft No. 34. The diary was countersigned by the Manager Md. Kalim (MW-17). It was his duty to point out to the Manager that the workings had reached within 75 m. from waterlogged Shaft No. 34. He has done so in this case. The former Agent Shri K. K. Das (MW-18) deposed that he remembered that Shri P. L. Thacker (MW-15) gave him a report that workings of 27 level was approaching the abandoned Shaft No. 34. Md. Kalim (MW-17) also admitted that his attention was drawn to the danger of inundation through the diary maintained by Shri P. L. Thacker (MW-15). Obviously, Shri P. L. Thacker (MW-15) properly performed the duties enjoined upon him by CMR 1957.

9.5.2 In the circumstances, I do not hold Shri P. L. Thacker (MW-15) responsible for this accident.

9.6.1 Md. Kalim (MW-17) deposed in his cross examination that he used to fix the target of production of coal in consultation with his supervisor. It was invariably a joint decision and not an arbitrary decision imposed by the General Manager who was his official superior. Further in course of working, he was free to discuss and revise his target of production, if there was any problem. He denied the allegation that because of a likely shortfall of target of production he worked the mine at random in unauthorised projections. In respect of application to the DGMS for working permission, he deposed that formal permission of the General Manager is not required but normally he discussed such cases with the General Manager. He deposed that for enforcement of mine safety regulations he had sufficient powers as the Agent-cum-Manager. His immediate superior was the General Manager of Kunustoria Area. The General Manager is advised on safety matters by the Area Safety Officer, who is his staff officer. Md. Kalim (MW-17) had discussed the likely danger of inundation from the old and abandoned shaft with the Area Safety Officer and the General Manager. Md. Kalim (MW-17) deposed that they had always advised him to strictly follow the 'permission' of the DGMS. Thus Md. Kalim (MW-17) had admitted that working of 40 dip off 28 level from November 8, 1989 was done under his orders and without the involvement of his superior officers. Moreover, there was no witness who deposed before the Court of Inquiry regarding the knowledge of the General Manager about commencement of work in the gallery at 40 dip from November 8, 1989. There was also no evidence that General Manager had known that safety regulations were being violated and advance Central and flank boreholes were not being given while driving the gallery. The General Manager was in charge of eleven mines of which Mahabir was one. It was obviously not possible for him to supervise the enforcement of the stipulations contained in the permission of the DGMS to give advance boreholes in accordance with Regulation 127 of CMR 1957. Accordingly, I do not hold that General Manager of Kunustoria Area, responsible for the fatal accident.

9.7.1 There had been lapses on the part of the supervisory officials like the overman and the Sirdar. These lapses are analysed below :

9.7.2 Shri Mihir Kumar Chatterjee (MW-10) was the Overman permanently deployed in the first shift also called the

general shift. He deposed that his job was miscellaneous in nature and though he was not formally entrusted with supervision of advance boreholes, he was generally asked by the Agent-cum-Manager, Md. Kalim (MW-17) to supervise drilling etc. of such boreholes. Shri C. D. Singh (MW-11) was the shift overman of 42 crosscut district and he was on the first shift on November 12, 1989. Shri Shibdas Chatterjee, Overman (MW-9) and Shri Fouzdar Singh (MW-1) were the other two Overmen who were in the second and third shifts respectively on November 12, 1989.

9.7.3 Shri Mihir Kumar Chatterjee (MW-10) and Shri C. D. Singh (MW-11) claimed to have ensured drilling of advance central boreholes of 5.4 m in length and two flank boreholes at 40 dip face in the first shift of November 12, 1989. Shri Shibdas Chatterjee (MW-9) claimed to have seen and measured those advance boreholes on the second shift of the same day. All those overmen also claimed that there was also no unusual seepage of water from the 40 dip face.

9.7.4 I have already held that there was no advance boreholes at 40 dip face off 28 level on November 12, 1989 and there was also unusual seepage of water from the face on the same day. Hence I do not believe the deposition of these overmen regarding drilling of advance boreholes and absence of unusual seepage of water.

9.7.5 Shri Fouzdar Singh (MW-1) was the sole overman in the third shift of November 12, 1989. When the fatal accident occurred and had three far-flung district under his charge. As such, he did not get an opportunity to inspect the 40 dip face before the fatal accident occurred.

9.7.6 Shri Ram Sankar Sarkar (MW-12) and Shri Dodan Pandey (MW-13) were the Sirdars of 42 crosscut district on the second and third shift of November 12, 1989. I also do not believe their deposition that there were advance boreholes at 40 dip face, and that the seepage of water from the face was not unusual.

9.7.7 Shri Chandradhari Barai (MW-14) was the Shot firer of 40 dip face. On the third shift of November 12, 1989 I also do not believe his deposition that he had checked the advance and flank boreholes at 40 dip face before firing the shots on the fateful day of November 13, 1989.

9.7.8 The primary responsibility of safety in mines is that of the management. The subordinate officials in the mine are required to carry out their orders. I have already held that the fact that advance borehole were not drilled and there was unusual seepage of water at 40 dip face was known to the Agent-cum-Manager (MW-17) and other senior officials. If the Agent-cum-Manager and the senior officials would have been alert and alive to their responsibilities for safety in the mine, they could have ensured the drilling of advance boreholes and also taken due note of unusual seepage of water. The fact that they allowed things to drift gave the wrong signal to the subordinate officials as Overmen, Sirdars and Shotfirers. Therefore in spite of their lapses, I do not hold S/Shri Mihir Kumar Chatterjee (MW-10), C. D. Singh (MW-11), Shibdas Chatterjee (MW-9), Ram Sankar Sarkar (MW-12), Dodan Pandey (MW-13) and Chandradhari Barai (MW-14) responsible for the fatal accident.

9.7.9 An analysis of causes of the majority of the accidents and disasters due to inundation would indicate that though the higher officials in a mine are primarily responsible, awareness of safety parameters is required of ordinary workers and their immediate supervisors as Shotfirers, Sirdars and Overmen. Usually an accident due to inundation is preceded by some unusual signs any symptoms as heavy seepage of water etc. It is important that the first level supervisors and workers in an underground coal mine are able to identify such symptoms and bring them to the notice of the higher management. It is essential that such type of training should be given to the supervisor and the workers and an awareness of safety should be installed into them.

9.7.10 The institution of workmen's inspectors and safety committee have been given statutory backing with the hope that the involvement of these institutions in workers safety would go a long way in bringing down the incidence of

accidents and disasters. In this case, both the Workmen's Inspector and the Safety Committee believed the hopes cast in them. The Workmen's Inspector did not question the reasons of restarting 40 dip in an unapproved area. He also did not ensure drilling of advance boreholes at 40 dip face. On the contrary, he deposed incorrectly before me regarding absence of unusual seepage of water and drilling of advance boreholes at 40 dip face on November 12, 1989.

9.7.11 The fact that the overlying Nega seam was waterlogged was known to almost all the supervisory staff and many workers. Yet the aspect of danger of inundation did not figure in the discussions of the Safety Committee which met almost once in a month.

9.7.12 It is accepted that safety of the mine is the responsibility of the management. But it may be appreciated that it cannot be achieved without the active cooperation of workers and the representatives of trade unions. In this case it appears that unusual seepage of water at the faces as well as the non-provision of the advance boreholes was brought to the notice of the local trade union leaders by some workers. Unfortunately no positive action was taken even by them on such information.

## CHAPTER—X

### 10.1 SUMMARY OF FINDINGS

### 10.2 RECOMMENDATIONS

### 10.3 RECOVERY OF EXPENSES

### 10.4 ACKNOWLEDGEMENTS

10.1.1 The fatal accident in the Narainkuri seam of the Mahabir Mine on November 13, 1989 occurred due to inrush of water from the overlying old abandoned and waterlogged Nega seam workings through shaft No. 34. The abandoned and waterlogged shaft No. 34 which had extended upto the Narainkuri seam got connected with the advancing 40 dip gallery off 28 level, causing the accident with loss of six precious lives.

10.1.2 The accident occurred because of the failure to provide sufficient number of central and bank boreholes in 40 dip gallery advancing towards the waterlogged shaft No. 34. Had such cover of advance boreholes been provided the officials of the mine would have been forewarned of the danger of the waterlogged shaft ahead and the fatal accident averted. Such advance boreholes are mandatory under Regulation 127 of CMR 1957. The working permission of the DGMS also clearly stipulated that those advance boreholes were to be provided. Further, the 40 dip gallery off 28 level was advanced in an unauthorised area about 100 m. away from development projections approved for working by the DGMS. The fatal accident occurred within only days of commencement of workings in 40 dip gallery off 28 level where mining operation had been stopped in January, 1988 due to unusual seepage of water. I am of the opinion that the fatal accident was due to culpable negligence on the part of Sarbasree Md. Kalim, Agent-cum-Manager, and P. L. Banerjee, Safety Officer and K. Dutta, Assistant Manager of the Mahabir mine. These three officials contravened the provisions of Regulation 127 of the CMR 1957, as well as the conditions laid down in the working permission of the D.G.M.S.

10.2.1 This fatal accident like most other disaster due to inundation in underground coal mines of our country took place essentially because of human failure in complying with the relevant provisions of Coal Mines Regulations. Whereas compliance of the relevant Coal Mines Regulations is the answer to prevent such fatal accident and disasters, what is disturbing is their recurrence from time to time. In my view, there is an urgent need to make the workers and the first-line supervisory official like Shotfirers, Sirdars and Overman aware of the statutory provisions in this regard vis-a-vis their duties, as well as to train them suitably to be forewarned regarding danger signals regarding inundation so that timely corrective measures could be taken. Here I see a great scope

for strengthening the institutions of Workman's Inspector and Safety Committee which can go a long way in arousing safety consciousness.

10.2.2 Since waterlogged workings will continue to be a source of potential hazard in coal mining in the foreseeable future, the search for methods for more accurate detection of these hazards should be unremitting. The reliance on human judgement to assess potential hazards of inundation has its pitfalls as a number of accidents and disasters in coal mines has amply demonstrated. The coal industry in India must therefore adopt more refined state-of-the-art techniques to detect and delineate the waterlogged workings so that human lapses do not cause accidents and disasters due to inundation. In summary, therefore, I recommend:

- (i) development of awareness among workers and the first-line supervisors of the need for identifying hazards through intensified programmes of education and training;
- (ii) activating the institutions of Safety committee and Workmen's Inspector so that they become relevant to the safety needs of underground coal mining;
- (iii) inculcation in the minds of workers and officials in underground coal mines the need for compliance with the provisions of the safety laws and regulations;
- (iv) provision of infrastructure for drilling advance boreholes to detect the presence of waterlogged workings;
- (v) development through R&D efforts new techniques for detection and delineation of accumulated water-bodies underground, and
- (vi) provision of large diameter boring facilities at a centralized location to access entombed miners in the event of an emergency.

10.3 The last part of the report deals with the recovery of expenses of the Court. Rule 22 of the Mines Rules, 1955, framed under Section 63 of the Mines Act, 1952 stipulates that if the Court of Inquiry finds that the accident is due to

carelessness or negligence on the part of the management, the Court may direct the recovery of its expenses from the Owner, Agent or Manager. The report discloses that the accident had taken place due to the negligence of the Agent-cum-Manager and other officials in not complying with Regulation 127 of the Coal Mines Regulations, 1957. But as the Court of Inquiry has the discretion in the matter of ordering recovery of expenses and as the expenses of the Court have been kept to the minimum and the defaulting officials belong to a Public Sector of the Central Government, I order that there would be no recovery of cost of this Court of Inquiry from any party or official.

10.4 Before concluding the Report, I must record my gratitude for the help by the Assessors Shri B. N. Tewary and Prof. A. K. Ghose. They were present in almost all the sittings of the Court. In spite of their numerous engagements, they also spared their valuable time for discussion and assessment of the evidence and arguments before the Court. I am also grateful to the management of the Eastern Coalfields Ltd., their advocate Shri B. Joshi and the representatives of the Employees' Union, who were parties to the proceedings. I would have liked to mention their names in this part of the Report but consideration of space has prevented me from doing so. However, a list of names of representatives of the Employees' Union, who examined and cross-examined the witnesses before this Court, is at Annexure XIV. I also take this opportunity to thank Shri S. C. Chatterjee, Regional Director of the Central Mine Planning & Design Institute, Asansol; and his Officers, who provided the infrastructural support for this Court to function at Asansol.

(P. C. HOTA)  
MAHABIR COURT OF INQUIRY  
SHRAM SHAKTI BHAWAN  
RAFI MARG  
NEW DELHI-110001

(B. N. TEWARY)  
ASSESSOR

(PROF. A. K. GHOSE)  
ASSESSOR

#### ANNEXURE—I

List of persons who lost their lives in the fatal accident on November 13, 1989 at Mahabir Mine

Sl. No.	Name	Designation	Age
1	2	3	4
1.	Sitaram Dusad	Timber Mazdoor	52
2.	Panna Lal Tiwari	Timber Mazdoor	54
3.	Anandi Turi	Loader	45
4.	Bishu Hazam	Explosive Carrier	51
5.	Agnu Nunja	Line Mazdoor	54
6.	Jhari Bishra	Loader	54

## ANNEXURE—II

NOTIFICATION REGARDING APPOINTMENT  
OF THE COURT OF INQUIRY

MINISTRY OF LABOUR

## NOTIFICATION

New Delhi, the 16th April, 1990

S. O. 327(E).—Whereas an accident occurred in the Mahabir Colliery of Messrs Eastern Coalfields Limited in District Burdwan of West Bengal State, on the 13th November, 1989 causing loss of lives ;

And whereas the Central Government is of opinion that formal inquiry into the causes of and the circumstances attending the accident ought to be held ;

Now, therefore, in exercise of the powers conferred by sub-section (1) of section 24 of the Mines Act, 1952 (35 of 1952), the Central Government hereby appoints Shri K. C. Sharma, retired Additional Secretary, Ministry of Labour to hold such inquiry and also appoints the following persons as assessors in holding the inquiry, namely :—

- (1) Shri B. N. Tewary,  
General Secretary,  
Colliery Mazdoor Sabha (AITUC),  
G. T. Road, Asansol,  
Distt. Burdwan (West Bengal).
- (2) Prof. A. K. Ghosh,  
Professor of Mining Engineering,  
Indian School of Mines,  
Dhanbad—826 004 (Bihar).

[F. No. N-11015/1/90-ISH-II]

R. T. PANDEY, Dy. Secy.

## ANNEXURE—III

NOTIFICATION REGARDING APPOINTMENT  
OF SHRI P. C. HOTA

THE GAZETTE OF INDIA : EXTRAORDINARY

[PART II—SEC. 3(ii)]

MINISTRY OF LABOUR

## NOTIFICATION

New Delhi, the 3rd January, 1991

S. O. 3(E).—In partial modification of the notification of the Government of India in the Ministry of Labour S. O. No. 327(E), dated the 16th April, 1990, the Central Government hereby appoints Shri P. C. Hota, Additional Secretary to the Government of India, Ministry of Labour, to hold the inquiry into the causes of and circumstances attending the accident in the Mahabir Colliery, in place of Shri K. C. Sharma, with immediate effect.

[F. No. N-11015/1/90-ISH-II]

R. T. PANDEY, Dy. Secy.

UNDERTAKING OF SHRI P. C. HOTA  
TO THE HON'BLE CALCUTTA HIGH COURT

Written statement of Shri P. C. Hota, Mahabir Colliery Accident Court of Inquiry, in C. O. No. 7650 (W) of 1990 in Calcutta High Court—Coal Mines Officers Association of India Vs. Mahabir Colliery Accident Court of Inquiry.

That I have been appointed as the Court of Inquiry to inquire into the causes of and circumstances attending the accident which took place in Mahabir Colliery on 13-11-1989, in place of Shri K. C. Sharma, vide Government of India in the Ministry of Labour notification No. N-11015/1/90-ISH-II, dated 3-1-1991 (copy enclosed).

2. I state that I am not bound by the procedure adopted by Shri K. C. Sharma for the conduct of the said inquiry. I further state that I will devise my own procedure for the conduct of the said inquiry in consultation with the parties concerned.

Sd./-

P. C. HOTA,  
Mahabir Colliery,  
Accident Court of Inquiry.

## ANNEXURE—V

NOTICE ISSUED TO THE PARTIES  
BY THE COURT OF INQUIRY

Dated, the 21st March, 1991.

## NOTICE

The undersigned appointed by the Central Government under Section 24 of the Mines Act, 1952, vide Notification No. S. O. 3(E), dated the 3rd January, 1991, to hold the Inquiry into the causes and circumstances attending to the accident in Mahabir Colliery in place of Shri K. C. Sharma, will have a preliminary sitting of the Court on 8-4-1991 at C.M.P.D.I. (Conference Hall) at Asansol from 10 A.M. to devise the procedure of the Court of Inquiry as contemplated under Rule 21 of the Mines Rules, 1955. You are, therefore, requested to attend the Court on the said date at the said time.

2. Further to substantiate the submissions made in the written statements already filed on behalf of your Organisation, you are requested to submit on the said date a complete list of witnesses proposed to be examined by you indicating therein the order in which the witnesses will depose before the Court.

Sd./-

P. C. HOTA,  
Mahabir Colliery,  
Court of Inquiry

To,

All the Parties.

## ANNEXURE—VI

## List of Management Witnesses

S. No.	Name	Designation	Witness Number
1	2	3	4
	S/Shri		
1.	Fouzdar Singh	Overman	MW 1
2.	Ram Chander Mahato	Mining Sirdar	MW 2



1	2	3	4
3.	Saligram Singh	Pit Clerk	MW 3
4.	Nur Mahammad	Loader	MW 4
5.	Ganesh Rai	U/G Loader	MW 5
6.	Joydeb Mondal	Mining Sirdar	MW 6
7.	Bhullan Manda	Shot Firer	MW 7
8.	Ramesh Majhi	Fitter/Boring Machine Operator	MW 8
9.	Shibdas Chatterjee	Overman	MW 9
10.	Mihir Kr. Chatterjee	Overman	MW 10
11.	C.D. Singh	Overman	MW 11
12.	Ram Shankar Sarkar	Mining Sirdar	MW 12
13.	Dodan Pandey	Mining Sirdar	MW 13
14.	Chandradhari Barai	Shot Firer	MW 14
15.	P.L. Thacker	Surveyor	MW 15
16.	P.L. Banerjee	Safety Officer	MW 16
17.	Md. Ka'im	Manager/Agent	MW 17
18.	K.K. Das	Agent	MW 18
19.	K. Dutta	Assistant Manager	MW 19

## ANNEXURE—VII

## List of Employees' Unions witnesses

S. No.	Name	Designation	Witness Number
1	2	3	4
	S/Shri		
1.	Kuldip Das	Driller	UW 1
2.	Munshi Tari	UG Loader	UW 2
3.	Chedi Harijan		UW 3
4.	Ram Chandra Mahato	Loader	UW 4
5.	Bhangi Rajbhar	Dresser/Driller	UW 5
6.	Ram Sudhar Choubey	Overman	UW 6

## ANNEXURE—VIII

## List of Court Witness

S. No.	Name	Designation	Witness Number
1.	Shri Sanat Kr. Sengupta	Assistant Manager	CW 1



## ANNEXURE—IX

## List of Management Exhibits (Exh. M)

S. No.	Exhibit No.	Details of the Exhibits
1	2	3
1	M/1	Hand Plan of Shri Swapan Ghatak (42-L-Section) (C.5 of 'seized documents')
2.	M/2(A)	The Bengal Coal Co. Ltd. Plan of Raneelganj Colliery, Raniganj Seam traced from AMP No. 1121 (Tracing No. 1746 on 25-7-25).
3.	M/2(B)	The Bengal Coal Co. Ltd. Plan of Raneelganj Colliery, Raniganj Seam traced from AMP No. 1121 (Tracing No. 1746 on 25.7.25) from No. 1 of AMP No. 1121 (two pages)
4.	M/3	Photostat copy of letter No. ECL/MB(P)/4009 dt. 16-17/12/83 from the Agent, Mahabir colliery to DGMS
5.	M/4	Plan No. ECL/MB/MU/20 dt. 16-12-1983 Development Permission Plan
6.	M/5	Photostat Copy of letter No. S.3/173/(BD)(MB) II-B/84/1061 dt. 12-3-1984
7.	M/6	Photostat copy of letter No. ECL/MBI DEV: 88/198 dt. 19-1-88 from Agent Mahabir Colliery to DGMS.
8.	M/7	ECL Plan No. ECL/MB/62 dt. 16-1-88 of Mahabir Colliery (R) showing changed projection of proposed development working in N/K seam below waterlogger working of Nega seam under CMR 105, 126 & 127.
9.	M/8	Photostat copy of letter No. S.3/22-03-062/II-A/88 dt. 22-3-88 from DGMS to Agent Mahabir Colliery
10.	M/9	ECL's Part Plan showing Projections of Plan No. ECL/MB/62/62 dt. 16-1-88 superimposed on Projections of Plan No. ECL/MB/20 dt. 16-12-83.
11.	M/10	Photostat copy of letter No. S.3/173 (BD) (MB)/II-B/83/4472 dt. 2-8-83 from DGMS
12.	M/11	Working Plan of Narainkuri Seam in tracing cloth bearing No. 13 dt. 14-5-75 upto 21-4-88 (C.4 of 'seized documents') tracing only.
13.	M/12	Plan of Accident site from ECL Narainkuri seam of Mahabir Colliery as surveyed after the accident.
14.	M12(A)	Plan showing position of shifting of large piece of stone from position A to position B shown there in

## ANNEXURE—X

## List of Employees' Unions Exhibits (Exh. W)

S.No.	Details of Exhibit	No. of Exhibit
1	2	3
1.	Hand Plan of Shri Swapan Ghatak (42-L Section) (C.5 of "seized papers")	W/1
2.	ECL letter No. GM/KMT/17/540/88 dt. 25-7-1988 (B.1 of seized documents).	W/2
3.	ECL letter No. ECL/MB(R)/98/Safety/297 dt. 22-2-89 B.2 of seized documents)	W/3
4.	ECL letter No. ECL/MB (R)/88/Safety/318 dt. 28/30/30-1-88 (B.7 of seized documents)	W/4
5.	Pages No. 1 to 3 of Instruction Book of K.K. Das, Ex. Agent (from 1-11-88 to 10-13-88) A.6 of seized papers	W/5

1	2	3
6.	ECL letter No. ECL/Safety/RNU/1683 dt. 14-1-88 (B.8 of seized documents)	W/6
7.	Plate No. 4 attached to ECL's main Memoranda to Court of Inquiry	W/7
8.	List of Registers, records, letters & plans seized by DGMS u/s 7(2) of Mines Act	W/8
9.	Letter No. M 11.154(B)87/40140 F. dt. 30-11-1961	W/9
10.	Water Danger Plan of N.K. seam (C.1 of 'seized documents')	W/10

## ANNEXURE-XI

## A BRIEF DESCRIPTION OF THE MAHABIR MINE

Mahabir mine is situated in the south eastern part of the Raniganj Coalfield in the district of Burdwan, West Bengal. Geographically, the mine is located approximately between latitude 23 degree 36' to 23 degree 38' north and longitude 87 degree 05' to 87 degree 07' east. The total surface area of the mine is about 612 hectares.

The office of the mine is located about 2 km north west of Raniganj railway station of the Eastern Railway and about 2 km south of the Grand Trunk road. A metalled road, branching out from the feeder road connected the G. T. road to the Raniganj railway station, leads to office of the mine.

Mahabir mine is owned by M/s ECL which was formed as a public sector undertaking in 1975 about two years after the non-coking coal mines of the country were nationalised. On nationalisation, three privately owned small adjoining working mines and a closed mine were amalgamated to form the Mahabir mine. Three working mines were Mahabir, Kajura selected and Searsole mines. The closed mine was the Raniganj mine belonging to the erstwhile M/s Bengal Coal Company.

The important surface features over the property of the Mahabir mine are old Egara and new Egara villages and a part of the Raniganj township. The main Eastern Railway line from Howrah to Delhi runs from north west to south east and divides the property of the Mahabir mine into almost two equal halves. Mahabir mine and its surrounding area was the first recorded centre of coal mining in our country.

## ANNEXURE-XII

## TEXT OF REGULATION 127 OF THE CMR 1957

127. Danger from underground inundation :—(1) Proper provision shall be made in every mine to prevent irruption of water or other liquid matter from the workings of the same mine or of an adjoining mine.

(2) Where work is being done in—

- (i) any seam or section below another seam or section; or
- (ii) any place in seam or section, which is at a lower level than any other place in a lower seam or section; or
- (iii) any place in seam approaching a fault passing through an upper seam or section, which contains or may contain an accumulation of water or other liquid matter.

adequate precautions shall be taken against an irruption of water or other liquid matter into the workings.

(3) No working which has approached within a distance of 60 metres of any such disused or abandoned working (not being workings which have been examined and found to be free from accumulation of water, or other liquid matters), whether in the same mine or in an adjoining mine, shall be extended further except with the prior permission in writing of the Chief Inspector and subject to such conditions as he may specify therein:

Explanation :—For the purpose of this sub-regulation, the distance between the said workings shall mean the shortest distance between the workings of the same seam or between any two seams or section, as the case may be, measured in any direction whether horizontal, vertical or inclined.

2 (X X X X)

Sub-regulations (4), (5) & (6) of the said regulations may be substituted as follows :—

"3(4)(a) Every application for permission to extend any working referred to in sub-regulation (3) shall be accompanied by two copies of the plan and section showing :—

- (i) The outlines of all such disused or abandoned workings in relation to the working approaching them and also the depth of such disused or abandoned workings from the surface.
- (ii) The outlines, the layout and the method of the proposed working for which permission is sought.
- (iii) the faults, dykes and other geological disturbances in relation to working specified in clause (i) or (ii) of the sub-regulation, and
- (iv) Any other information that is available with the management and any other particulars or information that may be required by the Chief Inspector.
- (b) When permission is granted to extend any working referred to in sub-regulation (5), it shall be extended strictly in accordance with the plan and the method approved under, and the conditions specified, in such permission and there shall be no variation therefrom unless such variation is again approved by the Chief Inspector.

(5) Whenever seepage of water, which is not normal to the seam is noticed at any place in any working, or if there be any such suspicion or doubt, such working shall immediately be stopped and the Chief Inspector and the Regional Inspector shall forthwith be informed of such seepage. Such working shall not be extended further except with the prior permission in writing of the Chief Inspector and subject to such conditions as he may specify therein.

(6)(a) The height of any working referred to in such regulation (3) or sub-regulation (5) shall not exceed 2.4 metres and there shall be maintained at least one bore hole near the centre of the working face, and sufficient flank bore holes on each side, where necessary, bore holes above and below the workings at intervals of not more than five metres. All such bore holes shall be maintained and shall be constantly maintained at sufficient distance in advance of the working and such distance shall in no case be less than three metres. These precautions shall be carried out under the direct supervision of an official having Manager's or Overman's Certificate specially authorized for the purpose.

(b) A record showing the exact height and width of such working, the number of bore holes driven, the length of each bore hole, the places at which and the direction in which each bore hole was driven, shall be maintained by the official referred to in clause (a) in a bound named book kept for the purpose and the entries made therein shall be signed

and dated by such competent person and shall be countersigned by the Manager every day. Also plan and section of such working showing the above particulars shall be prepared and maintained and they shall be brought up-to-date at least once in every fifteen days.

(7) Unless specific relaxation is granted by the Chief Inspector in writing under sub-regulation (8), all the provisions of sub-regulation (6) shall be strictly complied with while extending any working referred to in sub-regulation (3) or sub-regulation (5) whether or not the permission granted to extend such workings requires compliance with all or any of the provisions of sub-regulation (6).

(8) If the Chief Inspector is satisfied that the conditions in any mine or part thereof are such as to render compliance with all or any of the provisions specified in sub-regulation (6), unnecessary or impracticable, he may be, by an order in writing and subject to such conditions as may be specified therein relax, vary or dispense with all or any of the conditions and requirements contained in sub-regulation (6), and, if he is of the opinion that the conditions at any mine or part thereof are such as to require additional precautions to be taken, he may by an order in writing require that such additional precautions besides those specified in sub-regulation (5) shall be taken".

#### Photographs of the site of accident



Photograph (C) : Next 20 ft.

#### Photographs of the site of accident ANNEXURE-XIII

Photographic record of the Right rib side of 40 rip gallery as viewed from the gallery entrance towards the site of the accidental connection.




Photograph (a) : Approximately 20 ft. from the site of connection



Photograph (d) : End of Gallery

#### Photographs of the site of accident



Photograph (b) : Next 20 ft.



Photograph (e) : End of the Gallery

## ANNEXURE-XIV

## List of the Organisation and Representatives who Cross Examined the Witnesses

S.No.	Name	Organisation Represented
1	2	3
1.	Sh. A. Maiti, Secretary Sh. Sunil Sen, Organising Secy.	CMS (AITUC) CMS (AITUC)
2.	Sh. G.P. Gowswami, Secretary	CMSI (CITU)
3.	Sh. V.N. Sharma Sh. L.N. Bhattacharya Secy. (Safety) Sh. S.S. Chowdhury, Secy.	Coll. Maz. Un (INTUC) INMWFI (INTUC) CMU (INTUC)
4.	Sh. Saktipada Chatterjee, Jt. Secy. Sh. Jayanta Poddar, Genl. Secy.	CMC (HMS) CMC (HMS)
5.	Sh. H.S. Mukharjee, Vice-President Sh. Rakesh Kumar, Chief Org. Secy. Sh. Keshwa Singh, Asstt. Genl. Secy.	KMC KMC KMC
6.	Sh. D.M. Dass, Genl. Secy.	INMEWA
7.	Sh. K. Prasad, Genl. Secy.	AIMS
8.	Sh. J.K. Banerjee, Genl. Secy.	INMOSSA
9.	Sh. B. Joshi, Advocate	ECL
10.	Sh. D.D. Mukherjee Sh. J. Banerjee, Vice-President	CMBA CMBA
11.	Sh. A.K. Mazumdar	IMMA

नई दिल्ली, 11 दिसम्बर, 1992

## ANNEXURE

BEFORE THE CENTRAL GOVERNMENT INDUSTRIAL  
TRIBUNAL-CUM-LABOUR COURT, BANGALORE

Dated, this 30th day of November, 1992

Present :

Shri M. B. Vishwanath, B.Sc., B.L., Presiding Officer.  
CENTRAL REF. NO. 42/92

I party

The General Secy., Salem Dist. Magnesite Labour Union,  
No. 237, Tharamangalam Road, Old Suramangalam  
Road, Salem-636 005.

Vs

II party

The Chairman-cum-M.D., Tamilnadu Magnesite Ltd.,  
5/53, Omalur Main Road, Jagir Ammapallayan  
Salem-636 302.

## AWARD

In this reference made by the Hon'ble Central Government  
by its order No. L-29012/14/92-IR (Misc.) Dt. 16-4-92 under  
Sec. 10(1)(d) of the I.D. Act 1947 the point for adjudications  
per schedule to the reference is :

का. आ. 70 :- औद्योगिक विवाद अधिनियम, 1947 (1947 का 14) को धारा 17 के अनुसरण में, केन्द्रिय सरकार तमिलनाडू मैग्नेसाइट लिमिटेड, सेलम के प्रबन्धसूत्र के संबद्ध नियोजकों और उनके कर्मचारों के बीच, अनुबंध में निविष्ट औद्योगिक विवाद में केन्द्रिय सरकार औद्योगिक अधिकरण, बंगलूर के पंचपट को प्रकाशित करती है, जो केन्द्रिय सरकार को 9-12-92 को प्राप्त हुआ था।

[संख्या एल-29012/14/92-आई आर (मिस.)]

वो. एम. डेविड, डेस्क अधिकारी

New Delhi, the 11th December, 1992

S.O. 70.—In pursuance of section 17 of the Industrial Disputes Act, 1947 (14 of 1947), the Central Government hereby publishes the award of the Central Government Industrial Tribunal, Bangalore as shown in the Annexure in the Industrial Dispute between the employers in relation to the management of Tamil Nadu Magistrate Limited (Salem and their workmen, which was received by the Central Government on 9-12-92.

[No. L-29012/14/92-IR(Misc.)]

B. M. DAVID, Desk Officer

"Whether the dependents of S/Shri Anamalai/Palani Token No. 1188 and Kaveri/Raman, Token No. 830/12 who were discharged from service on medical grounds by the management of Tamainadu Magnesite Limited, Salem are entitled for employment with the company as per the provisions of the Settlement dated 17-8-87 arrived at between the management and the union?"

2. In the claim statement it is contended that the dependant of workman Shri Anamalai Token No. 1188 and the dependant of workman Kaveri Token No. 830/12 who were discharged from service on medical grounds by the Management of Tamilnadu Magnesite Ltd., Salem are entitled for employment in the company as per provisions of the settlement dt. 17-8-87 arrived between the management and the Union.

3. In the counter statement the fact that Anamalai and Kaveri were workmen who were discharged from service on medical grounds is admitted. In the counter statement it is contended that the dependents are not entitled to employment. It is further contended that the wife of the workman Kaveri has been working for a long time as an employee in the II party and so the dependant of the workman Kaveri is not entitled to employment.

4. Since it was felt that the evidence was not necessary, the case was posted for arguments on merits. At the time of the arguments today the General Secretary representing the I party has filed a memo that the dependent of the workman Anamalai s/o Palani, one of the workman in the schedule to the reference, has been provided with a job by the II party and therefore he does not press the reference against Sh. Anamalai, Token No. 1188.

5. Now the point for consideration is whether the dependant of the workman Kaveri is entitled to employment in the II party company.

6. The I party has produced the zerox copy of the settlement relied on by both parties. This settlement, it is clear remained in force from 1-12-86 to 30-11-89. The workman Kaveri was discharged from service on 14-11-89, after he had put in more than 25 years of service. It is admitted that he was discharged on medical grounds viz., multi valvular heart disease. It is obvious that because of the said serious heart trouble the workman Kaveri was permanently disabled and so he was discharged.

7. The provision 5.4 of the memorandum of settlement entered into between the workmen representatives and the management representatives which included the present II party says :

It is agreed that the companies will provide suitable employment to one direct dependant of the employee only who dies in service or becomes permanently disabled and out of job subject to the fulfilment of the following conditions :—

(i) Medical fitness.

(ii) The incumbent must have the qualifications to fulfil the job requirement.

8. The main provision 5.4, as I understand means that the company should provide suitable employment to one direct dependant of the employee when he dies while in service OR when the employee becomes permanent disabled.

9. It is argued by the officer Srinivasan on behalf of the II party that the phrase "Permanent disabled" relates only to employment injury. It is argued that since the workman did not suffer any injury in the course of his employment, his dependant is not entitled to employment. If we accept the argument advanced on behalf of the II party, it would mean reading into the provision 5.4 something which is not there. The requirement of the provision 5.4 is that the employee should have become permanently disabled, what-

ever may be the reason of permanent disablement. It is admitted that the workman Kaveri was discharged because of the serious heart disease. This means he became permanently disabled and therefore was discharged from service. I reject the argument that "permanently disabled" relates to employment injury.

10. It is argued that the wife of the workman Kaveri has been working in the II party for the last so many years, even before the workman Kaveri was discharged. His wife was recruited along before Kaveri was discharged. It is argued by the Learned officer for the II party that since the wife has been employed and has been working and she is the only dependent, the other dependant of workman Kaveri is not entitled for employment. Because the wife of Kaveri has been working, long before Kaveri was discharged on medical grounds, it is difficult to accept the argument that the other direct dependant of Kaveri is not entitled to employment. The Learned Officer who argued for the II party did not bring to my notice any provision in the settlement Dt. 17-8-87 that only the wife is the direct dependant of a man-employee. Surely, the sons or daughters who are maintained by the man-employee are dependants of that employee. The provision 5.4 does not say that if the wife of the workman is also employed, the other direct dependant is not entitled to employment. The Tribunal should not incorporate into the provision 5.4 a condition which is not there. Surely the workman Kaveri must be having sons or daughters who are direct dependants. One of them is certainly entitled for employment, if the conditions medical fitness and the qualification required for the job are fulfilled.

#### ORDER

The reference with regard to workman Sh. Anamalai, Palani, Token No. 1188 is rejected.

It is hereby declared that one direct dependant of Sh. Kaveri/Raman Token No. 830/12, who was discharged from service on medical grounds, is entitled for employment with the II party company as per the provisions of settlement Dt. 17-8-87 arrived at between the Management and the Union.

Reference accepted in part as stated herein.  
Submit to Government.

(Dictated to Stenographer, typed by him, corrected, signed by me on this 30th day of November, 1992).

M. B. VISHWANATH, Presiding Officer

नई दिल्ली, 11 दिसम्बर, 1992

का. प्रा. 71:—औद्योगिक विवाद अधिनियम, 1947 (19 7 का 14) का धारा 17 के अनुसरण में, केन्द्रीय सरकार मद्रास पोर्ट ट्रस्ट के प्रबन्धन के संकेत निर्देशों और 17 के कार्यों के यका, अनुबंध में निर्दिष्ट औद्योगिक विवाद में औद्योगिक अधिकांश, मद्रास (मद्रास) के पंचपट को प्रकाशित करना है, जो केन्द्रीय सरकार का 9-12-92 को प्रकाशित हुआ था।

[संख्या एन - 33012/5/88-10 भाग I (घ)]

का. एम. डेविड, डेस्क अधिकारी,

New Delhi, the 11th December, 1992

S.O. 71.—In pursuance of section 17 of the Industrial Disputes Act, 1947 (14 of 1947), the Central Government hereby publishes the award of the Industrial Tribunal, Tamil Nadu (Madras) as shown in the Annexure in the Industrial Dispute between the employers in relation to the management of Madras Port Trust and their workmen, which was received by the Central Government on the 9-12-92.

[No. L-33012/5/88-10 Part I

B. M. DAVID, Desk Officer

## ANNEXURE

BEFORE THE INDUSTRIAL TRIBUNAL, TAMILNADU  
MADRAS

Friday, the 23rd Day of October, 1992

## PRESENT:

Thiru M. Gopalaswamy, B.Sc., B.L.,

INDUSTRIAL TRIBUNAL

Industrial Dispute No. 30 of 1989

(On the matter of the dispute for adjudication u/s. 10(1)(d) of the Industrial Disputes Act, 1947 between the workman and the Management of Madras Port Trust, Madras-1)

## Between

Thiru L. Abdul Babu,  
No. 61, Noruppu Medu,  
Alandur Salai, Seidapet,  
Madras-600 015.

## AND

The Chairman,  
Madras Port Trust, Rajaji Road,  
Madras-600 001.

## REFERENCE:

Order No. L.33012/5/88-D. III(P), dt. 13-3-89 of the Minister of Labour Govt. of India

This dispute coming on for final hearing on Monday the 6th day of July, 1992 upon perusing the reference, claim and counter statements and all other material papers on record and upon hearing the arguments of Tvl. R. Ganeson, S. Shathiamurthi and R. Gowthaman, advocates appearing for workman and of Tvl. A. L. Somavaji R. Arumugham, advocates appearing for the management and this dispute having stood over till this day for consideration, this Tribunal made the following award.

## AWARD

This dispute between the workman and the management of Madras Port Trust, Madras-1 arises out of a reference under section 10(1)(d) of the Industrial Disputes Act, 1947 by the Government of India in its order No. L.33012/5/88-D.III (B), dated 13-3-1989 of the Ministry of Labour, for adjudication of the following issue:

"Whether the management of Madras Port Trust is justified in dismissing Shri L. Abdul Babu, D. V. Driver from service with effect from 11-6-1987, if not, to what relief the workman concerned is entitled?"

## (2) The petitioner workman alleges as follows :

He was working as a Driver under the Respondent. He received a chargememo alleging that he committed the misconduct of absenting himself from duty without leave from 23-9-86 to 9-10-86. Such unauthorised absence does not attract the charge framed under the standing order 42-D(ii) but it can be a charge only under Standing Order 42-A. The Petitioner has submitted his explanation to charge memo on 23-12-1986. At the domestic enquiry officer himself examined the Petitioner delinquent. He has produced a certificate of posting under which he sent a post card on 23-9-86 requesting grant of leave on medical grounds. He produced medical certificate on 10-2-87 before the enquiry officer relating the treatment received by him during the period. The enquiry officer's finding that the charges proved is perverse in the absence of evidence. The enquiry officer failed to consider the medical certificate produced by the petitioner and certificate of posting relating to his leave letter. The order of the disciplinary authority in which he approved the findings and

imposed the penalty of dismissing from service is unjust. The appellate authority disposing of appeal passed merely a non-speaking order. Hence it is not valid. The petitioner was not served with any notice of previous punishment which he has suffered. Hence the respondent's act of weighing the past records in inflicting the punishment is bad and illegal. In any event, the order of dismissal from service with effect from 11-6-87 is shockingly disproportionate and liable to be set aside.

## (4) The Management States in its counter as follows :

The charge framed against the petitioner for the misconduct of Unauthorised absence is sustainable in terms of Clause 43(B)(ii) of the Standing Orders. The Petitioner did not give his explanation to the charge memo as early as on 23-12-86, but he gave it only on 5-1-87 just after the notice regarding the commencement of domestic enquiry was issued. Junior Assistant Dural Singh was examined as Management witness at the domestic enquiry to prove the charge. The Petitioner-workman has been punished on 15 earlier occasions. The domestic enquiry officer's findings are sound and sustainable. The punishment of dismissal is fair and adequate. Respondent may be given opportunity to lead evidence if the domestic enquiry is held to be unfair and vitiated. The claim is liable to be dismissed.

## (4) The points for determination are as follows :

(1) Whether the findings of the domestic enquiry officer and the approval of the said findings by the disciplinary authority are perverse and not supported by evidence?

(2) Whether the punishment of dismissal is just and lawful?

(5) This Tribunal held a preliminary enquiry on the issue relating to the fairness of the domestic enquiry, and passed an order by holding that the domestic enquiry have been held fairly. The charge memo issued to the Petitioner-workman Ex. M. 14 dated 23-10-86 states that the Petitioner has been guilty of the misconduct namely absence without prior permission from 23-9-86 to 14-10-86, punishable under Clause 42(B)(ii). Admittedly the Petitioner has not sent his leave application or letter by Registered Post or Telegram but on the other hand he claims that he sent a post card under certificate of posting requesting grant of leave from 23-10-86 to 14-10-86. The enquiry officer in his findings Ex. M. 12 has mentioned that the Petitioner did produce, even if it be after the conclusion of the domestic enquiry, the postal acknowledgement relating to the Certificate of posting and a medical certificate got from a private doctor referring to his illness. The said medical certificate issued by one Dr. Paulsamy is Ex. M. 5. After the expiry of the period of absence ending with 9-10-86, the Petitioner has admittedly resumed duty on 15-10-86. On that date he has presented a leave application in person in respect of the same period for which he earlier sent a post card by certificate of posting. This belated leave application Ex. M. 6 has been received by the respondent office on 15-10-86. He has also sent Ex. M. 9 letter dated 28-12-86 in addition to Ex. M. 10 and Ex. M. 11 letters, both dated 14-1-87, wherein he pleaded that his nervous system has been affected due to electric shock suffered by him 2 years before, that the said disability or disorder has not cured and as a result thereof from September, 1986 he has suffered nervous problems in his right leg, that he was taking treatment for the same from private doctor and that he has already sent in his leave application praying for leave from 23-9-86 onwards.

(6) At the domestic enquiry, the management witness Dural Singh gave evidence regarding the Petitioner's absence from 23-9-86. This witness vide Ex. M. 20 proceedings has proved a belated telegram dated 30-10-86 and a leave letter received from the Petitioner on 15-10-86 which is Ex. M. 6. The Petitioner was examined in the domestic enquiry by the domestic enquiry officer himself without the assistance of a prosecuting officer. In the findings Ex. M. 42 the domestic enquiry officer has not at all examined the value of the

certificate of posting or postal acknowledgement and the private medical certificate produced by the petitioner though belatedly. He should have admitted these two documents as evidence and duly assessed their evidentiary value in examining the truth of the facts relating to the petitioner having sent any leave application supported by private medical certificate. Neither the domestic enquiry officer nor the disciplinary authority who has passed Ex. M. 13 order has given any thought and much less weight to these material documents produced by the Petitioner as well as his plea that he has been suffering from the after effects of electrical shock received by him 2 years prior to 1986. The Respondent has not denied anywhere the fact that the petitioner has suffered electrical shock affecting the nervous system. On a consideration of the materials on record I hold that the domestic enquiry officer's findings and also the concurrent findings recorded by the disciplinary authority are perverse and not supported by legal evidence.

(7) Even on the question considering the past record of the Petitioner in the context of punishment, the respondent has failed to issue a notice informing the petitioner about his past acts of misconduct for enabling him to explain past misconduct and quantum of punishment. In my view of the matter, the punishment of dismissal is extremely harsh and disproportionate. Hence the findings are held to be perverse, there is no basis for imposing any punishment on the petitioner. Both these points are accordingly answered in favour of the petitioner. Therefore the Petitioner deserves to be reinstated in service. However on the question of backwages I feel that it will be fit and proper to restrict the back wages to 60 per cent by depriving the petitioner of the remaining 40 per cent in the peculiar circumstances of the case. In the result, an award is passed directing the respondent to reinstate the Petitioner in service, pay 60 per cent of back wages only and allow continuity of service besides other benefits. No costs.

Dated, this 23rd day of October, 1992.

M. GOPALASWAMY, Industrial Tribunal

WITNESS EXAMINED

For both side : None.

DOCUMENTS MARKED

For Workman

Ex. W. 1 11-6-87—Charge Memo issued to Petitioner-workman (xerox copy).

Ex. W. 2 30-9-88—Conciliation failure report (xerox copy).

For Management :

Ex. M. 1 31-12-86—Order of Chief Mechanical Engineer for appointment of Enquiry Officer (xerox copy).

Ex. M. 2 15-1-87—Letter from Thiru M. Mathew to the Management (xerox copy).

Ex. M. 3 27-1-87—Reply by the Management to Ex. M. 2 (xerox copy).

Ex. M. 4 29-1-87—Enquiry notice (xerox copy).

Ex. M. 5 14-10-86—Medical certificate issued by Dr. V. Maluswamy to the Petitioner-workman (xerox copy).

Ex. M. 6—Letter from Petitioner-workman to the management (xerox copy).

Ex. M. 7—Telegram from Petitioner-workman (xerox copy).

Ex. M. 8 10-2-86—Letter from Petitioner-workman to the Management (xerox copy)

Ex. M. 9 28-12-86—Letter from Petitioner-workman to the Management (xerox copy).

Ex. M. 10 14-1-87—Letter from Petitioner-workman to the Management (xerox copy).

Ex. M. 11 14-1-87—Letter from Petitioner-workman to the Management (xerox copy).

Ex. M. 12 18-2-87—Findings of the Enquiry Officer (xerox copy).

Ex. M. 13 26-2-87—Second show-cause notice issued to the Petitioner-workman (xerox copy).

Ex. M. 14 13-3-87—Explanation by the Petitioner workman (xerox copy).

Ex. M. 15 2-4-87—Enquiry notice (xerox copy).

Ex. M. 16—Leave particulars of the Petitioner-workman (xerox copy).

Ex. M. 17 17-6-87—Appeal preferred by the Petitioner-workman (xerox copy).

Ex. M. 18 21-7-87—Order of appellate authority (xerox copy).

Ex. M. 19 23-10-86—Charge memo issued to the Petitioner-workman (xerox copy).

Ex. M. 20—Proceedings of the Enquiry Officer (xerox copy).

Ex. M. 21—Previous record of punishment awarded to the Petitioner-workman (xerox copy).

नई दिल्ली, 15 दिसम्बर, 1992

को. प्र. 72.—औद्योगिक विवाद अधिनियम, 1947 (1947 का 14) की धारा 17 के अनुसरण में, केन्द्रीय सरकार इंडियन आयल कॉर्पोरेशन लिमिटेड के प्रबंधन के संबंध में निहित औद्योगिक विवाद में उनके कर्मचारियों के बीच, अनुबंध में निहित औद्योगिक विवाद में केन्द्रीय सरकार औद्योगिक अधिकांश, नं. 1, धनबाद के संवत् 1992 का प्रकाशित करती है, जो केन्द्रीय सरकार को 9-12-92 को प्राप्त हुआ था।

[संख्या एल--30012/38/90-आई आर (विधि)]

को. एम. डेविड, डेस्क अधिकारी

New Delhi, the 15th December, 1992

S.O. 72.—In pursuance of section 17 of the Industrial Disputes Act, 1947 (14 of 1947), the Central Government hereby publishes the award of the Central Government Industrial Tribunal, No 1. Dhanbad as shown in the Annexure in the Industrial Dispute between the employers in relation to the management of India oil Corporation Limited and their workmen, which was received by the Central Government on the 9-12-92

[No. L-30012/38/90-1R(Misc.)]

B. M. DAVID, Desk Officer

ANNEXURE

BEFORE THE CENTRAL GOVERNMENT INDUSTRIAL TRIBUNAL NO. 1, DHANBAD.

In the matter of a reference under section 10(1) (d) of the Industrial Disputes Act, 1947

Reference No. 41 of 1991

**PARTIES :**

Employers in relation to the management of  
Indian Oil Corporation Ltd., B. K.  
Pipe Lines, Barauni.

AND

Their Workmen.

**PRESENT :**

Shri S. K. Mitra, Presiding Officer.

**APPEARANCES :**

For the Employers.—Shri N. K. Gupta, Advocate.

For the Workmen.—Shri J. D. Lall, Advocate.

STATE.—Bihar.

INDUSTRY.—Oil.

Dated, the 26th November, 1992.

**AWARD**

By Order No. 1--30012/38/90-I. R. (Misc.), dated, the 18th/19th April, 1991, the Central Government in the Ministry of Labour, has in exercise of the powers conferred by clause (d) of sub-section (1) of Section 10 of the Industrial Disputes Act, 1947, referred the following dispute for adjudication to this Tribunal :

“Whether the action of the management of Indian Oil Corporation Ltd., B. K. Pipe Lines, Barauni in deducting the fitment benefits granted to Shri S. S. Prasad, Operator ‘A’ is justified? If not, to what relief is the workman entitled?”

2. The present industrial dispute between the management of Indian Oil Corporation Ltd., B. K. Pipelines Barauni and their workmen represented by Indian Oil Corporation Ltd. Pipelines Workers' Union, Barauni, over alleged wrongful deduction of wages of the concerned workman was raised by the President, Indian Oil Corporation Ltd., Pipelines Workers' Union, Barauni, by letter dated 15-5-90. Upon failure of conciliation proceeding, the present industrial dispute was referred to this Tribunal for adjudication by the appropriate Government.

3. The order of reference was received in the office of the Tribunal on 8-5-91. The President of the sponsoring union, Sri C. M. Singh, filed statement of claim dt. 3-7-91 in this case and on that date he gave letter of authority to Shri J. D. Lall, Advocate and S. S. Prasad, the concerned workman, to represent workman in the present proceeding. The employers submitted their written statement in denial of the claim of the sponsoring union on 10-1-92. The President of the union submitted a petition on 10-1-92 and stated that in view of long term settlement out of which the industrial dispute has arisen, the union, in order to maintain industrial peace and good relation with the management, do not press the dispute and prayed for disposal of the dispute as not pressed. Simultaneously on the even date the President of the union withdraw the

authority for representation of the case in favour of Shri J. D. Lall, Advocate. But S. S. Prasad, the concerned workman, who was earlier authorised by the President of the union to represent his case before the Tribunal, gave a letter of authority in favour of Shri J. D. Lall on 4-3-92 and submitted a petition on 3-3-92 expressing his desire to continue the industrial dispute.

3. The case of the sponsoring union is that the concerned workman, S. S. Prasad has been working as Operator Grade ‘A’ in the Indian Oil Corporation Ltd., B. K. Pipelines, Barauni. The management of Indian Oil Corporation Ltd. (Refineries & Pipelines Division) entered into a settlement dated 22-2-89 with the workers' Union whereby pay scales and other benefits were revised upwards with effect from 1-5-86. In terms of the aforesaid settlement, the pay scale of the concerned workman was revised and refixed in terms of Clause 3.1.3, by Office Order dated 20-3-69/18-7-69 the management, however without any notice or show-cause issued another order dated 15-11-89 superseding the earlier Office Order and refixed the pay scale of the concerned workman in the revised pay scale and as a result the basic pay of the concerned workman was reduced resulting in a great financial loss to him. The management stated deducting Rs. 600/- per month from the salary of the concerned workman from February, 1991. The concerned workman is entitled to get his salary as fixed by the earlier order. Refixation of his salary by the management by subsequent order is illegal, arbitrary and in violation of Clause 3.1.3. The management had earlier fixed his salary in terms of clause 3.1.3 of the settlement dated 22-2-89 because one D. N. Tiwary, Operator ‘A’ who is junior to him, was drawing higher basic salary in the revised pay scale than him and hence the clause 3.1.3 of the settlement dated 22-2-89 was applicable to him in the matter of fixation of his basic pay which was done by order dated 18-7-89. The concerned workman made several representation to the management against refixation of his basic salary, but no action has been taken thereon. In the circumstances, the union has prayed that the management is not justified in deducting fitment benefit granted to the concerned workman by order dated 18-7-89 in terms of settlement dated 22-2-89.

4. In denial of the claim of the sponsoring union, the management has stated in its written statement that the memorandum of long term settlement was arrived at on 22/25-2-89 with all the unions of all units in R&P Division, of Indian Oil Corporation and the settlement came into effect on 1-5-86. The settlement is still binding and subsisting between the parties. Clause 3 of the aforesaid settlement provides revised scale of pay. Immediately before 1-5-86 the concerned workman was Operator ‘A’ in the scale of pay of Rs. 642-1425 and he was getting basic salary of Rs. 1030/- per month. As per the settlement his basic pay was fixed at Rs. 1900/- w.e.f. 1-5-86 in the revised pay scale. By Office Order dated 18-7-89 the concerned workman was informed about his fitment in the new scale. His pay was fixed at Rs. 1900/- in the revised scale of pay as against his pre-revised pay of Rs. 1030/- with effect from 1-5-86 as per terms of



settlement. His date of annual increment was however preponed from April, 1986 to July, 1986 by mistake. However on review it was noticed that the settlement signed with the unions did not provide any such preponment. After noticing the mistake, the fitment of the concerned workman was again calculated and fitted and a revised office order dated 15-11-89 was issued. As per revised order his date of increment was correctly taken as 1-4-89 and accordingly on 1-4-89 his basic pay was fixed at Rs.2095/- His immediate junior D. N. Tewari was Operator-B on 1-5-1986. His pay was also fixed in the corresponding revised scale with effect from 1-5-86 as per the conciliation settlement. Since the date of promotion of Tewari as Operator-A was 12-6-86, his pay was fixed in higher grade in the revised scale of pay with effect from 12-6-86. His date of annual increment was 1-7-86. By virtue of Tewari's increment due before date of increment of the concerned workman, the pay of Sri Tewari became higher than that of concerned workman. The fitment of the concerned workman and also of Sri Tewari was done in accordance with Clause 3.1.2 of the long term Conciliation Settlement. As provided under Clause 3.1.8 of the Long Term Settlement anomalies arising out of pay structure were discussed with the unions at All India Level Meeting on 11-2-91 at Bombay. The meeting among others was also attended by the President of the sponsoring union and such anomalies were mutually discussed. In the meeting it was decided that an option should be given to the senior employees postponing the date of their pay fixation on promotion (from the present date) to the date of pay fixation on promotion to the comparable junior employees. It was also clarified that for the purpose of seniority, original date of promotion of the employee would be reckoned with. But for the purpose of pay and consequential benefits, date of revised pay fixed would be taken into consideration. In view of the above decision taken after discussion with the union, administrative instructions by circular dated 28-6-89 was issued wherein the workmen were asked to give their option in this regard before 31-7-91. But the concerned workman did not exercise his option. In the context of facts, the concerned workman should not have made any grievance, more so when the union was a party to the decision communicated by the circular as aforesaid. It is not a case of deduction from fitment benefits granted to the concerned workman, but it is a case of the correct fitment given to the concerned workman to which he is entitled in law.

5. The union filed its statement of claim on 22-7-91 and the management submitted its written statement on 10-1-92. On the same date the President of the Union submitted a petition stating that the industrial dispute be disposed of as no pressed. The petition discloses that in view of long term settlement out of which the aforesaid dispute arose, the union, in order to maintain industrial peace and good relationship with the management, do not press the dispute and that neither the union nor the concerned workman has any grievance against the fitment as per the settlement as finally communicated to him. Earlier the President of the union gave authority to Shri I. D. Lall and the concerned workman to

represent the case before this Tribunal by letter of authority dated 3-7-91. The President of the union by letter dated 10-1-92 withdraw the authority for representation given in favour of Shri I. D. Lall, Advocate. But the authority given in favour of the concerned workman was not withdrawn. The concerned workman gave another authority in favour of Shri I. D. Lall Advocate, by petition dated 4-3-92 and submitted a petition on 3-3-92 stating that the compromise petition was not fair and bona-fide and that his interest had been sacrificed by the union for own interest. The union had raised the industrial dispute challenging the management. The union also filed written statement assailing the action of the management and supporting his claim. Hence, he prayed that the compromise petition be rejected.

In rejoinder, the management has reiterated the fascicle of facts as appearing in its written statement and contended that when a dispute concerning individual workman is taken up by the union of which he is a member it becomes a matter affecting the workman in general and on that basis a reference is made under Industrial Disputes Act, the individual workman cannot claim to be heard individually. When an individual workman becomes a party to the dispute under the Industrial Disputes Act, he is a party not independently of the union which has espoused his cause. It is well settled that when an industrial dispute is raised by the union in respect of the grievance of individual workman and reference is made by the Government, the dispute is between the management and the union and not between the management and the individual workman concerned. The individual workman has no locus-standi in the matter. It is also well settled that when there is a bona-fide settlement between the union and the management and a compromise is filed before the Industrial Tribunal, the Tribunal should pass award in terms of the compromise. The question of giving any consent by the workman to the compromise petition does not arise. The union is competent to file a compromise keeping in view the interest of the workman in general and also to maintain industrial peace and harmony. The authority in favour of Shri I. D. Lall was filed by the union on 3-7-91 because the union was/is a party to the dispute. The authority was withdrawn by the union on 10-1-92. Hence, Shri Lall has no authority to represent the union. The workman authorised Shri I. D. Lall, Advocate and the authority in his favour was filed on 4-3-92. Since the workman has no locus standi as he is not a party to the reference, he is not competent to authorise any person to represent him. In the circumstances, the management has prayed that the petition dated 10-1-92 be accepted and an award be passed in terms of the compromise.

6. Shri K. N. Gupta, learned Advocate for the management has contended that there exists no industrial dispute in the eye of law as the union which raised the dispute has not pressed the same. Shri I. D. Lall, learned Advocate for the concerned workman, has resisted this contention and cited the decision reported in 3 SCLC 1769 (1969) (Bombay Union Journalists Vs. The Hindu Bombay and another) and 1972 Lab L.J. 1141 (SC) (Bhagat

Ltd. Vs. Their workmen and another). Both these decisions underline the legal position that when an industrial dispute existed at the time of making order of reference, the dispute does not cease to be there merely because the union which raised the dispute chooses not to pursue it by subsequent withdrawal of support. The withdrawal of such support will not affect the jurisdiction of the Tribunal to adjudicate upon it. This being the legal position, I overrule the contention of Shri Gupta that there exists no industrial dispute in the eye of law.

7. Then again, Shri Gupta has contended that the concerned workman has not right to give authority to Shri J. D. Lall, Advocate, to represent his case as it is not an individual dispute and as a corollary Shri J. D. Lall has no right to represent the concerned workman. In support of this contention Shri Gupta has cited the decision reported in AIR 1961 (SC) 857 (Ram Prasad Biswakarma Vs. Chairman, Industrial Tribunal, Patna and others). Their Lordships of Supreme Court held that when an industrial dispute concerning individual workman is taken up by the union of which the workman is a member, as a matter affecting the workmen in general and on that basis a reference is made under Industrial Disputes Act, the individual workman cannot ordinarily claim to be heard independently of the union. The ordinary rule should be that such representation by an officer of the trade union should continue throughout the proceeding in the absence of exceptional circumstance which may justify the Tribunal to permit other representation of the workman concerned. In the present case the President of the union gave authority to Shri J. D. Lall, Advocate and the concerned workman to represent the case. Thereafter the President withdrew the authority given in favour of Shri J. D. Lall, but he did not revoke the authority given in favour of the concerned workman. Thereafter the concerned workman gave authority in favour of Shri J. D. Lall, Advocate. In the context of these facts, I think that it is not unfitted to permit the concerned workman to be represented by his Advocate. Here again, I am constrained to state that I do not agree with the contention of Shri Gupta and so I overrule his contention.

8. Admittedly, the management of Indian Oil Corporation (Refineries & Pipelines Division) entered into a Long Term Conciliation Settlement dated 22-2-89 with the Workers' Union including the sponsoring union whereby pay scale and other benefits of workmen were revised upwards with effect from 1-5-86 in accordance with the terms of settlement. The pay scale of the concerned workman was revised and refixed in terms 3.1.3 of the said settlement by Office Order dated 20-3-89 18 4-89. But by subsequent order dated 15-11-89 the management superseded the earlier order and refixed the pay scale of the concerned workman in revised pay scale. The contention of the workman is that he has been adversely affected by this revised order. According to the management the earlier fixation of pay of the concerned workman was a mistake and this was refixed by order dated 15-11-89. It is the further case of the management that certain anomalies in the terms of settlement were discussed with the sponsoring union and other union on 11-2-91 and it was decided that

option should be given to the concerned employees postponing the date of their pay fixation on promotion to the date of pay fixation on promotion to the comparable junior employee. It was also clarified that for the purpose of seniority original date of promotion of the employee would be reckoned with. But for the purpose of pay and consequential benefits, date of revised pay fixed would be taken into consideration. Accordingly an option was given to the concerned workman but he did not exercise his option. The management issued administrative instruction dated 28-6-91 for implementing the decision arrived at All India Level Meeting on 11-2-91. In the context of discussion and settlement of anomalies the sponsoring union has presented the petition for not pressing the dispute.

9. It appears that the union presented a statement of claim on 3-7-91 even after administrative instruction for implementation was issued. Shri J. D. Lall has contended that the union was pursuing the dispute even after issuance of administrative instruction for implementation of the decision. Indeed, the union has submitted statement of claim after the necessary circular was issued. But that may be due to various reasons including lack of coordination and mis-conception.

Shri J. D. Lall has contended that the petition of the union praying for disposal of the case as not pressed is mala fide. The union has made it abundantly clear in its petition that in view of the Long Term Settlement out of which the present dispute has arisen it does not press the dispute in order to maintain industrial peace and good relationship. In other words, the intention of the union is to maintain the fabric of industrial peace and good relationship in fact. This intention cannot be considered as mala fide. That apart when an industrial dispute is raised by the union or a group of workmen in respect of the grievance of the individual workman and reference is made by the Government, the dispute is between the management and the union and not between the management and the individual workman. As a matter of fact, the individual workman have no locus-standi in the matter. In such a case when there is bona fide settlement between the union and the management and a compromise is filed before the Tribunal, it has to pass a award in terms of the compromise unless it is shown that the settlement is arrived at by fraud, mis-representation or undue influence. This legal proposition was laid down by the Patna High Court in the case reported in 1968 Lab. I. C. 1430 (Eastern Mangnese and Minerals Ltd. Vs. Presiding Officer, Central Government Industrial Tribunal, Dhanbad and others). In the present case the sponsoring union does not want to proceed with the industrial dispute further in the interest of industrial peace and good relationship. I find no fraud, mis-representation and undue influence as there is no vestige of evidence on record on that score. Accordingly, I accept the petition presented by the sponsoring union and overrule the objection of the concerned workman.

10. Hence, it is ordered that the present industrial dispute be disposed of as not pressed by the sponsoring union.

In the circumstances of the case, I award no cost.

New Delhi, the 15th December, 1992

This is my award.

S. K. MITRA, Presiding Officer.

नई दिल्ली, 15 दिसम्बर, 1992

का. प्र. 73 -- औद्योगिक विवाद अधिनियम, 1947 (1947 का 14) का भाग 17 के अनुच्छेद (ख), केन्द्रिय सरकार द्वारा केन्द्रित मामलों, संख्या--600083 के प्रत्यक्ष विवादों और उनके कार्यकर्ता के बीच, मद्रास में निविष्ट औद्योगिक विवाद में औद्योगिक अधिकरण, तमिलनाडु के संवत् को प्रकाशित करना है जो केन्द्रिय सरकार की 9-12-92 की आज्ञा है।

[संख्या प्र.--29011/31/99--आईआर(मं.)]

का. प्र. देविड, ईस्क अधिकारी

S.O. 73.--In pursuance of section 17 of the Industrial Disputes Act, 1947 (14 of 1947), the Central Government hereby publishes the award of the Industrial Tribunal Tamilnadu as shown in the Annexure in the Industrial Dispute between the employers in relation to the management of Kunnan Granite Company, Madras-600083 and their workmen, which was received by the Central Government on the 9-12-1992.

[No. L-29011|31|89-JR (Misc.)]

B. M. DAVID, Desk Officer

#### ANNEXURE

BEFORE THE INDUSTRIAL TRIBUNAL, TAMIL NADU, MADRAS

Tuesday, the 27th day of November, 1992.

Present :

THIRU M. GOPALASWAMY, B.Sc., B.L. Industrial Tribunal.

#### INDUSTRIAL DISPUTE No. 52 OF 1990

(In the matter of the dispute for adjudication under section 10(1)(d) of the Industrial Disputes Act, 1947 between the workmen and the management of Madras Dock Labour Board, Madras-1.)

Between :

The Workmen represented by :

The General Secretary,

The Madras Harbour Workers Union,

'Bhagat House',

204, Prakasam Salai, Madras-600 108.

And

The Chairman,

Madras Dock Labour Board,

Rajaji Salai, Madras-600 001.

REFERENCE : Order No. L-33011/3/90-IR (Misc.), dated 21-6-1990 of the Ministry of Labour, Government of India, New Delhi.

This dispute coming on this day for final disposal in the presence of Thiru M. Shanmugavelu, Advocate appearing for the workmen and of Thiru R. Arumugam, Advocate appearing for the management, upon perusing the reference, claim and counter statements and other connected papers on record and the parties having filed a joint memo and recording the same, this Tribunal passed the following :

#### AWARD

This dispute between the workmen and the management of Madras Dock Labour Board, Rajaji Salai, Madras-1 arises out of a reference under section 10(1)(d) of the Industrial Disputes Act, 1947 by the Government of India, in its Order No. L-33011/3/90-IR (Misc.) dated 21-6-1990 of the Ministry of Labour, for adjudication of the following issue :

"Whether the demand of the General Secretary, the Madras Harbour Workers Union, Bhagat House, 204, Prakasam Salai, Madras-600 108 for absorption of 59 casual workers (as per list attached) by the management of Madras Dock Labour Board, Rajaji Salai, Madras is justified. If so, to what relief the workmen concerned are entitled?"

## CLEARING AND FORWARDING WORKERS (CASUAL) NAME LIST

DATE OF APPOINTMENT 21-2-1980 (ALL WORKERS)

Serial No.	Name	Card No.	Father name	Designation
1	2	3	4	5
1.	K. Bakthan	1001	Kanniappan	Mazdoor
2.	S. Gowthaman	1002	Seshachalam	Mazdoor
3.	C. Kesavan	1003	Chipamkaram	Mazdoor
4.	M. Narasimman	1004	R. Munusamy	Mazdoor
5.	R. Thanbizane	1005	Rathinam	Mazdoor
6.	S. Palani	1006	Subramoni	Mazdoor
7.	J. Kalidoss	1007	Jeyaraman	Mazdoor
8.	B. Ramachandran	1008	Balakrishnan	Mazdoor
9.	M. Subramani	1009	Mottai	Mazdoor
10.	C. Ramasamy	1010	Kundumani	Mazdoor
11.	K. Malar	1011	Nannan	Maistry
12.	K. Kapali	1012	Kupusamy	Maistry
13.	K. Sundara Moorthy	1013	Kanniappan	Mazdoor
14.	K. Shanmugam	1014	Kannan	Mazdoor
15.	G. Jeyasankar	1015	Gopal	Maistry
16.	M. Purusothaman	1016	Murugesan	Maistry
17.	A. Syed Sabir Rahiman	1017	Abdul Mazit	Maistry
18.	K. Arumugam	1018	Kanniappan	Maistry
19.	K. Delli	1019	Kanniappan	Maistry
20.	B.V. Allapichai	1020	Dasha boy	Maistry
21.	M. Neelakandan	1021	Murugon	Maistry
22.	K. Porumal	1022	Kannappan	Mazdoor
23.	A. Mothu	1023	Arumugua	Mazdoor
24.	K. Nagappan	1024	Psriyasamy	Mazdoor
25.	K. Govindaraj	1025	Blusslai	Mazdoor
26.	R. Thiru Neelakandan	1026	Hagevan	Mazdoor
27.	P. Jayaraman	1027	Ponnusamy	Maistry
28.	K. Gopal	1028	Kanniappan	Maistry
29.	T. Alugu	1029	Periyasamy	Mazdoor
30.	M. Natarajan	1030	Rasilamani	Mazdoor
31.	R. Arumugam	1031	Ranthiathan	Mazdoor
32.	P. Rajendran	1032	Palayam	Mazdoor
33.	V. Ramalingam	1033	Varadhan	Mazdoor
34.	V. Dayadoss	1034	Varadkhan	Mazdoor
35.	A. Ganesan	1035	Al. dian	Mazdoor
36.	O. Selvam	1036	Govindasamy	Mazdoor

1	2	3	4	5
37.	O. Krishnan	1037	Gopal	Mazdoor
38.	J. Syed Nasir	1038	Johnay	Mazdoor
39.	K. Kavikumar	1039	Mithiraj	Mazdoor
40.	B. Rajalingam	1040	Subramani	Mazdoor
41.	K. Antharaj	1041	A. Kaspar	Mazdoor
42.	Slagadsamy	1042	Duraisamy	Mazdoor
43.	G. Pandian	1043	Jeyaraman	Mazdoor
44.	K. Karunakaran	1044	Krishnan	Mazdoor
45.	C. Balakrishnan	1045	Chinnappan	Mazdoor
46.	P. Subramani	1046	Arumugam	Mazdoor
47.	K. Vadhachalam	1047	Narasimman	Mazdoor
48.	V. Sunderraj	1048	Venkatesan	Mazdoor
49.	S. Annemalai	1049	Sinni Maicker	Maistry
50.	R. Ganasunderam	1050	Kathinam	Maistry
51.	B. Joseph	1051	Khanasingh	Maistry
52.	M. Sundaram	1052	Manickam	Mazdoor
53.	M. Palani	1053	Munasamy	Mazdoor
54.	M. Jayaraman	1054	Malayan	Mazdoor
55.	K. Moorthy	1055	Krishnan	Maistry
56.	V. Sundaram	1056	Veeramuthu	Maistry
57.	R. Anandaraaj	1057	Ramadass	Maistry
58.	C. Nelvam	1058	Chinnappa	Maistry
59.	P. Gandhi	1059	Bharathanarathy	Maistry

(2) Parties were served with summons. Both parties were represented by counsel.

(3) Petitioner-Union filed its claim statement on 17-9-90 putting forth the claim of the workmen. In repudiation thereof, the Respondent-Management has filed their counter statement on 11-1-1991.

(4) After several adjournments, when the dispute was called today, both the parties filed a joint memo. It runs as follows :

"The issue involved in the above Industrial Dispute is for the absorption of 59 casual workers in the Respondent Board. Pending the above Industrial Dispute, the Respondent absorbed 59 casual workers involved in this Industrial Dispute in the Respondent Board as permanent workmen as and when vacancies arose.

In these circumstances the Petitioner and Respondent jointly pray that the above Industrial Dispute may be dismissed as withdrawn by the workmen."

(5) In view of the joint memo, industrial dispute is dismissed as withdrawn.

Dated, this 17th day of November, 1992.

M. GOPALASWAMY, Industrial Tribunal

**नई दिल्ली**

नई दिल्ली, 15 दिसम्बर, 1992

क्र. अ. 74 -- औद्योगिक विवाद अधिनियम, 1947 (1947 का 14) को धारा 17 के अनुसरण में, केन्द्रीय सरकार, निम्नलिखित क्लार्क एंड काउन्सिल कंपनी के प्रबन्धकों के संज्ञित निर्देशों और उनके कर्मचारियों के बीच, अनुबंध में निर्दिष्ट औद्योगिक विवाद में केन्द्रीय सरकार औद्योगिक अधीकरण, नं. 1 धनबाद के पंचरट को प्रकाशित करती है, जो केन्द्रीय सरकार को 9-12-92 को प्राप्त हुआ था।

संख्या एन-29011/4/90-आईआर (Misc.)

जी. एम. डेविड, डेस्क अधिकारी

New Delhi, the 15th December, 1992

S.O. 74.—In pursuance of section 17 of the Industrial Disputes Act, 1947 (14 of 1947), the Central Government hereby publishes the award of the Central Government Industrial Tribunal No. 1, Dhanbad as shown in the Annexure in the Industrial Dispute between the employers in relation to the management of M/s. Rajmahal Quartz Sand & Kaolin Co. and their workmen, which was received by the Central Government on 9-12-82.

(No. L-29011/4/90-IR (Misc.))

B. M. DAVID, Desk Officer

**ANNEXURE**

**BEFORE THE CENTRAL GOVERNMENT INDUSTRIAL TRIBUNAL NO. 1, DHANBAD**

in the matter of a reference under section 10(1)(d) of the Industrial Disputes Act, 1947

Reference No. 53 of 1990

**PARTIES :**

Employers in relation to the management of M/s. Rajmahal Quartz-Sand & Kaolin Co.

**AND**

Their Workmen.

**PRESENT:**

Shri S. K. Mitra, Presiding Officer.

**APPEARANCES :**

For the Employers : Shri B. B. Pandey, Advocate.

For the Workmen : Shri U.S. Sinha, Advocate.

STATE : Bihar. INDUSTRY : Minor Mineral.

Dated, the 25th November, 1992

**AWARD**

By Order No. L-29011/4/90-I.R. (Misc.), dated, the 2nd March, 1990, the Central Government in the Ministry of Labour, has, in exercise of the powers conferred by clause (d) of sub-section (1) of sub-section (2-A) of section 10 of the Industrial Disputes Act, 1947, referred the following dispute for adjudication to this Tribunal :

“Whether the demand of Khadan Mazdoor Sangh, Maharajpur, Dist. Sahibganj, for payment of

wages during the period from 16-4-89 to 20-4-89 to a section of workers engaged in the new plant of M/s. Rajmahal Quartz Sand & Kaolin Company's Mangalhat Unit is justified. If so, what relief are the workers concerned entitled to?”

2. The order of reference was received in the office of the Tribunal on 9-3-1990. After receipt of the order of reference, notice was issued to the President, Khadan Mazdoor Sangh, P.O. Maharajpur, Dist. Sahibganj, Bihar, for filing written statement on behalf of the concerned workmen. Thereafter several adjournments were given to the union to file written statement. Ultimately, a petition of the President, Khadan Mazdoor Sangh, Maharajpur was received by this Tribunal on 20-11-1992. In that petition the President has stated that the payment of wages during the period 16-4-89 to 20-4-89 has already been paid by the management and prayed that the present industrial dispute be withdrawn. In view of the petition, I consider that there exists no dispute between the parties.

3. Accordingly, the present industrial dispute be disposed of as ‘withdrawn’.

In the circumstances of the case, I award no cost. This is my award.

S. K. MITRA, Presiding Officer.

नई दिल्ली, 15 दिसम्बर, 1992

क्र. अ. 75 -- औद्योगिक विवाद अधिनियम, 1947 (1947 का 14) को धारा 17 के अनुसरण में, केन्द्रीय सरकार, निम्नलिखित क्लार्क एंड काउन्सिल कंपनी को जलमोरा कोलिरी का मोहरा क्षेत्र नं. 11 के प्रबंधकों के संज्ञित निर्देशों और उनके कर्मचारियों के बीच, अनुबंध में निर्दिष्ट औद्योगिक विवाद में केन्द्रीय सरकार औद्योगिक अधीकरण, (नं. 2), धनबाद के पंचरट को प्रकाशित करती है, जो केन्द्रीय सरकार को 15-12-92 को प्राप्त हुआ था।

(नं. एन. 24012/(12)/86-डीआईआर (कोल-1)

एच. सी. गोड, डेस्क अधिकारी

New Delhi, the 15th December, 1992

S.O. 75.—In pursuance of Section 17 of the Industrial Disputes Act, 1947 (14 of 1947), the Central Government hereby publishes the Award of the Central Government Industrial Tribunal (No. 2) Dhanbad as shown in the Annexure in the Industrial Dispute between the employers in relation to the management of Jealgora Colliery of Bhowra Area No. XI of M/s BCCU and their workmen which was received by the Central Government on 15-12-92.

(No. L-24012/(12)/86-D.IV(B))IR (Col.1)

HARISH GUAR, Desk Officer

**ANNEXURE**

**BEFORE THE CENTRAL GOVERNMENT INDUSTRIAL TRIBUNAL (NO. 2) AT DHANBAD**

**PRESENT :**

Shri B. Ram, Presiding Officer.

In the matter of an industrial dispute under Section 10(1) (d) of the I.D. Act, 1947.

Reference No. 288 of 1986

AND

Their Workmen

**PARTIES :**

Employers in relation to the management of Jealgora Colliery of Bhowra Area No. IX of M/s. Bharat Coking Coal Ltd. and their workmen.

**APPEARANCES :**

On behalf of the workmen.—Shri R. N. Mondal, Assistant Secretary P.C.M.S.

On behalf of the employers.—Shri R. S. Murthy, Advocate.

STATE :—Bihar.

INDUSTRY :—Coal.

Dated, Dhanbad, the 4th December, 1992

**AWARD**

The Govt. of India, Ministry of Labour in exercise of the powers conferred on them under Section 10(1)(d) of the I.D. Act, 1947 has referred the following dispute to this Tribunal for adjudication vide their Order No. L-24012(12)86-D.IV(B), dated, the 13th August, 1986.

**SCHEDULE**

“Whether the action of the Management of Jealgora Colliery of Bhowra Area No. XI of M/s. Bharat Coking Coal Ltd., P.O. Jealgora, Dist. Dhanbad in terminating the services of Shri Pa'agolind Tanti, M.C. Loader is justified? If so, to what relief the workman is entitled?”

2. Soon after the receipt of the order of reference notices were duly served upon the parties. Both the parties appeared before me and filed a Joint etc. Thereafter at the stage of oral evidence, both the parties appeared before me and filed a Joint Compromise Petition under their signature. I heard both the parties on the said petition of compromise and do find that the terms contained therein are fair, proper and beneficial to both of them. Accordingly I accept the same and pass an Award in terms thereof which forms part of the Award as Annexure.

B. Ram, Presiding Officer

**ANNEXURE**

BEFORE THE CENTRAL GOVERNMENT INDUSTRIAL TRIBUNAL NO. 2, DHANBAD.

Reference No. 288/96.

**PARTIES :**

Employers in relation to the Management of Jealgora Colliery of Bhowra Area, B.C.C.L.

**JOINT COMPROMISE PETITION OF THE EMPLOYERS AND THE WORKMEN**

The above mentioned Employers and the workmen/Sponsoring Union most respectfully beg to submit jointly as follows :—

(1) That the representatives of the Employers and the representatives of the workman/Sponsoring Union have jointly negotiated the above matter referred to this Hon'ble Tribunal with a view to arriving at a mutually acceptable and amicably settlement.

(2) That as a result of such mutual negotiations, the parties have agreed to settle the matter covered by the above reference on the following terms and conditions :—

(a) It was agreed that the Management would refer the workman concerned Sri Bal Gobind Tanti who was retired from service from 1-7-90, to the Apex Medical Board of B.C.C.L. as per the existing procedure for determination of his age on the date of the medical examination.

(b) It was further agreed that if the age as assessed by the Apex Medical Board on the date of assessment and by back calculations, the workman concerned was below 60 years he would be entitled to remain in service for further period, he would be given such benefit and if however, as per such age assessment, the workman concerned was less than 60 years as on 1-7-85 and has already crossed the age of 60 years by the date of assessment of his age by the Apex Medical Board, he would be paid back wages.

(c) It was agreed that since the Apex Medical Board, in accordance with the above decision, assessed the age of the workman concerned as 61 years as on 15-11-1991, his date of birth would be deemed to have been superannuated from 15-11-90.

(d) It is agreed that in the light of the clause(c) above, the workman concerned would be deemed to have retired from 15-11-90 instead of from 1-7-90 and he would be paid wages for the period from 1-7-90 to 14-11-90 and other benefits for such period.

(c) It is agreed that this is an over-all settlement in full and final settlement of all the claim of the workman concerned and the Sponsoring Union arising out of the above Reference.

(3) That the Employers and the workmen Sponsoring Union consider and hereby declare that the above terms and conditions are fair, just and reasonable to both the parties.

In view of the above, the Employers and the workmen/sponsoring Union most respectfully pray jointly that the Hon'ble Tribunal may be pleased to accept this Joint Compromise Petition and dispose of the above reference accordingly by giving an Award in terms thereof.

R.N. Mondal  
Secretary.

Rashtriya Colliery Mazdoor Sangh,  
Branch, Bararee Jealgora Colliery,  
for and on behalf of workman.

Sd/- Illegible.

Agent,  
Jealgora Colliery, B.C.C.L.,  
for and on behalf of  
Employers.

Dated: 30-4-92

Dy. C.P.M.,

Bhowra Area, B.C.C. Ltd.,  
for and on behalf of

Sd/- Illegible.  
Employers.  
Advocate for Employer

नई दिल्ली, 15 दिसम्बर, 1992

का. प्र. 76.—औद्योगिक विवाद अधिनियम, 1947 (1947 का 11) की धारा 17 के अनुसूच में, केन्द्रीय सरकार, भारत सरकार कोन विधि, की ईस्ट कटरास कोलियरी क्षेत्र-4 के प्रबंधन के संबंध में निवेदन और उनके कर्मचारों के बीच, अनुबंध में निहित औद्योगिक विवाद में केन्द्रीय सरकार औद्योगिक विचारण, (मं. 2), तत्काल के संघर्ष को प्रकटित करती है, जो केन्द्रीय सरकार को 15-12-92 को प्राप्त हुआ था।

[नं. प्र. -24012/(61)/86-डी 4 (बी) आई आर (का-1)]

प्र. मं. मो. मोड़, ईस्ट कर्मचारी

New Delhi, the 15th December, 1992

S.O. 76.—In pursuance of Section 17 of the Industrial Disputes Act, 1947 (14 of 1947), the Central Government hereby publishes the Award of the Central Government Industrial Tribunal (No. 2), Dhanbad as shown in the Annexure in the Industrial Dispute between the employers in relation to the management of East Katras Colliery Area IV of M/s. B.C.C.L. and their workmen which was received by the Central Government on 15-12-92.

[No.L-24012(61)|86-D-IV(B)|IR(C.I.)]

HARISH GAUR, Desl. Officer

ANNEXURE

BEFORE THE CENTRAL GOVERNMENT  
INDUSTRIAL TRIBUNAL (NO.2) AT DHANBAD  
PRESENT :

Shri B. Ram, Presiding Officer.

In the matter of an industrial dispute under Section 10(1)(d) of the I.D. Act, 1947.

REFERENCE NO. 66 OF 1987

PARTIES :

Employers in relation to the management of East Katras Colliery Area IV of M/s. Bharat Coking Coal Limited and their workmen.

APPEARANCES :

On behalf of the workmen : None.

On behalf of the employers : Shri B. Joshi, Advocate.

STATE : Bihar.

INDUSTRY : Coal.

Dated, Dhanbad, the 7th December, 1992

AWARD

The Govt. of India, Ministry of Labour in exercise of the powers conferred on them under Section 10 (1)(d) of the I.D. Act, 1947 has referred the following dispute to this Tribunal for adjudication vide their Order No. L-24012(61)|86-D-IV(B) dated, the 14th January, 1987.

SCHEDULE

"Whether the action of the Management of East Katras Colliery Area IV of M/s. Bharat Coking Coal Ltd. in not providing job to one dependent of Late Shri Bhoji Bhuia who died while in service is justified? If not, to what relief the workman concerned is entitled?"

2. This reference is pending since 1991 for filing W.S. by the parties. But inspite of several registered notices sent against the parties nobody appeared on behalf of the workmen. I find that Shri B. Joshi, Advocate has been putting his attendance on behalf of the management. This shows that the workman concerned is not very much interested in pursuing with the matter. In the circumstances no dispute award is passed.

B. RAM, Presiding Officer

नई दिल्ली, 15 दिसम्बर, 1992

का. प्र. 77.—औद्योगिक विवाद अधिनियम, 1947 (1947 का 11) की धारा 17 के अनुसूच में, केन्द्रीय सरकार, भारत सरकार कोन विधि, की ईस्ट कटरास कोलियरी क्षेत्र-4 के प्रबंधन के संबंध में निवेदन और उनके कर्मचारों के बीच, अनुबंध में निहित औद्योगिक विवाद में केन्द्रीय सरकार औद्योगिक विचारण, (मं. 2), तत्काल के संघर्ष को प्रकटित करती है, जो केन्द्रीय सरकार को 15-12-92 को प्राप्त हुआ था।

[नं. प्र. -24012/(61)/86-डी 4 (बी) आई आर (का-1)]

प्र. मं. मो. मोड़, ईस्ट कर्मचारी

New Delhi, the 15th December, 1992

S.O. 77.—In pursuance of Section 17 of the Industrial Disputes Act, 1947 (14 of 1947), the Central Government hereby publishes the Award of the Central Government Industrial Tribunal (No. 2), Dhanbad as shown in the Annexure in the Industrial Dispute between the employers in relation to the management of East Barariya Colliery of M/s.



B.C.C.L. and their workmen which was received by the Central Government on 15-12-92.

[No. L-20012(144)|87-D.III(A)|IR(Coal-I)]

HARISH GAUR, Desk Officer

ANNEXURE

BEFORE THE CENTRAL GOVERNMENT INDUSTRIAL TRIBUNAL (NO. 2) AT DHANBAD PRESENT :

Shri B. Ram, Presiding Officer.

In the matter of an industrial dispute under Section 10(1)(d) of the I.D. Act, 1947.

REFERENCE NO. 312 OF 1987

PARTIES :

Employers in relation to the management of East Bassuriya Colliery of M/s. Bharat Coking Coal Ltd. and their workmen.

APPEARANCES :

On behalf of the workmen : Shri D. K. Dey, Secretary, Colliery Karamchari Sangh.

On behalf of the employers : None.

STATE : Bihar. INDUSTRY : Coal.

Dated, Dhanbad, the 7th December, 1992

AWARD

The Govt. of India, Ministry of Labour in exercise of the powers conferred on them under Section 10(1)(d) of the I.D. Act, 1947 has referred the following dispute to this Tribunal for adjudication vide their Order N. L-20012(144)|87-D. III(A), dated, the 21st December, 1987.

SCHEDULE

"Whether the action of the Management of Bassuria Colliery, Kusunda Area of M/s. Bharat Coking Coal Limited, Dhanbad in dismissing Shri Bijay Bhuiya Driller from service with effect from 11-6-84 is justified? If not, to what relief is the workman entitled?"

2. This reference is also pending since March, 1992 for filing W.S. of the parties. I find that till this day no W.S. could be filed. Only on the last date i.e. on 2-12-92 Shri D.K. Dey, Secretary, Dhanbad Colliery Karamchari Sangh filed a petition for passing no dispute award. In the circumstances of the case I find no reason as to why a 'no dispute' award should not be passed when the union itself is praying for passing no dispute award. Hence a 'No Dispute' Award is passed.

B. RAM, Presiding Officer.

नई दिल्ली, 16 दिसम्बर, 1992

का. प्र. 78 :- औद्योगिक विवाद अधिनियम, 1947 (1947 का 14) की धारा 17 के अनुसरण में केन्द्रीय सरकार, बैंक आफ इंडिया 3128 GI/92—10.

के प्रबन्धन के संबंध निर्माताओं और उनके कर्मचारियों के बीच, अनुबंध में निर्दिष्ट औद्योगिक विवाद में केन्द्रीय सरकार औद्योगिक अधिनियम (सं. 2), धनबाद के पंचवट पर प्रकाशित करना है, जो केन्द्रीय सरकार को 15-12-92 को प्राप्त हुआ था।

[संख्या: एल०-12012/255/87-ड-3ए(ए)]

श्री. के. वेणुगोपालन, डेस्क, अधिकारी

New Delhi, the 16th December, 1992

S.O. 78.—In pursuance of Section 17 of the Industrial Disputes Act, 1947 (14 of 1947), the Central Government hereby publishes the Award of the Central Government Industrial Tribunal (No. 2), Dhanbad as shown in the Annexure in the Industrial Dispute between the employers in relation to the management of Bank of India and their workmen, which was received by the Central Government on 15-12-92.

[No. L-12012/255/86 D.III(A)]

V. K. VENUGOPALAN, Desk Officer.

ANNEXURE

BEFORE THE CENTRAL GOVERNMENT INDUSTRIAL TRIBUNAL (NO. 2) AT DHANBAD PRESENT :

Shri B. Ram, Presiding Officer.

In the matter of an industrial dispute under Section 10(1)(d) of the I.D. Act, 1947.

REFERENCE NO. 189 OF 1987

PARTIES :

Employers in relation to the management of Bank of India and their workmen.

APPEARANCES :

On behalf of the workmen : None.

On behalf of the employers : Shri Basu Deva Patre, Industrial Relations Officer.

STATE : Bihar. INDUSTRY : Banking.

Dated, Dhanbad, the 7th December, 1992

AWARD

The Govt. of India, Ministry of Labour in exercise of the powers conferred on them under Section 10(1)(d) of the I.D. Act, 1947 has referred the following dispute to this Tribunal for adjudication vide their Order No. L-12012/255/86-D.II(A), dated, the 5th May, 1987.

SCHEDULE

"Whether the action of the management of Bank of India, Rajrappa Project Branch, Hazaribagh in terminating the services of Shri Upendra Kumar Ram, Subordinate cadre employee with effect from 21-3-85 and not considering him for further employment while recruiting fresh hands under Section 25H of the I.D. Act, is legal and justified? If not, to what relief is the concerned workman entitled?"

2. This reference is pending since March, 1982 for filling W.S. by the workmen. I find that one Shri Basu Deva Patra has been putting his appearance on behalf of the management. On 31-1-92 Shri Patra appeared and filed a petition for passing no dispute award. As regards the workmen I find that nobody ever appeared on behalf of the workmen. Since the workmen is not taking any step nor filling any W.S. the Tribunal has got no other option but to pass no dispute Award. Accordingly a 'No Dispute' award is passed

B. RAM, Presiding Officer

नई दिल्ली, 17 दिसम्बर, 1992

का.पा. 79.—औद्योगिक विवाद अधिनियम, 1947 (1947 का 14) की धारा 17 के अनुसरण में, केन्द्रीय सरकार सी. पी. डब्ल्यू. यो., नई दिल्ली के प्रबन्धन के संबद्ध नियोजकों और उनके कर्मचारों के बीच अनुबंध में निहित औद्योगिक विवाद में केन्द्रीय सरकार औद्योगिक अधिकरण, नई दिल्ली के पंचपट को प्रकाशित करता है, जो केन्द्रीय सरकार को 16 दिसम्बर, 1992 को प्राप्त हुआ था।

[सं. एल 42012/151/90-आई.आर. (ई.पू.) (पी.टी.)]  
के.बी. उन्नी, डेस्क अधिकारी

New Delhi, the 17th December, 1992

S.O. 79.—In pursuance of Section 17 of the Industrial Disputes Act, 1947 (14 of 1947), the Central Government hereby publishes the award of the Central Government Industrial Tribunal, New Delhi as shown in the Annexure, in the industrial dispute between the employers in relation to the management of C.P.W.D. New Delhi and their workmen, which was received by the Central Government on 16-12-92.

[No. L-42012/151/90-IR(DU)(Pt.)]  
K. V. B. UNNY, Desk Officer

#### ANNEXURE

BEFORE SHRI GANPATI SHARMA : PRESID-  
ING OFFICER : CENTRAL GOVT.  
INDUSTRIAL TRIBUNAL : NEW DELHI  
I.D. No. 19/91

In the matter of dispute between :

Shri Sita Ram S/o Shri Tulsi Ram, as repre-  
sented by CPWD Mazdoor Union, E-26  
(Old Qtr.), Raja Bazar, Baba Kharak  
Singh Marg, New Delhi.

Versus

Executive Engineer (Elect.), Electrical  
Division-V, CPWD, Sewa Bhavan, R. K.  
Puram, New Delhi.

APPEARANCES :

Shri Nand Lal for the workman.

Shri Chander Singh, Head Clerk of the  
Management.

#### AWARD

The Central Government in the Ministry of Labour vide its Order No. L-42012/151/90-IR(D.U.) dated 18-2-91 has referred the following industrial dispute to this Tribunal for adjudication :

"Whether the action of the management of CPWD, New Delhi in not regularising the services and not paying the wages from 30-11-88 to 18-3-89 to Shri Sita Ram, Lift Operator is justified ? If not, to what relief the workmen is entitled to ?"

2. The case were fixed today for further proceed-  
ings which the representative for the workman made statement that the matter has been settled and no dispute award may be passed. Head Clerk of the management was also present. In view of this statement. No dispute exist between the Parties I, therefore, pass a no dispute award in this case leaving the parties to bear their own costs.

2nd December, 1992.

GANPATI SHARMA, Presiding Officer

नई दिल्ली, 17 दिसम्बर, 1992

का.पा. 80.—औद्योगिक विवाद अधिनियम, 1947 (1947 का 14) की धारा 17 के अनुसरण में, केन्द्रीय सरकार सी. पी. डब्ल्यू. यो., नई दिल्ली के प्रबन्धन के संबद्ध नियोजकों और उनके कर्मचारों के बीच, अनुबंध में निहित औद्योगिक विवाद में केन्द्रीय सरकार औद्योगिक अधिकरण नई दिल्ली के पंचपट को प्रकाशित करती है, जो केन्द्रीय सरकार को 16 दिसम्बर, 1992 को प्राप्त हुआ था।

[सं. एल- 42012/150/90-आई.आर. (ई.पू.) (पीटी.)]  
के.बी. उन्नी, डेस्क अधिकारी

New Delhi, the 17th December, 1992

S.O. 80.—In pursuance of Section 17 of the Industrial Disputes Act, 1947 (14 of 1947), the Central Government hereby publishes the award of the Central Government Industrial Tribunal, New Delhi as shown in the Annexure, in the industrial dispute between the employers in relation to the management of C.P.W.D. New Delhi and their workmen, which was received by the Central Government on 16-12-1992.

[No. L-42012/150/90-IR(DU)(Pt.)]  
K. V. B. UNNY, Desk Officer

#### ANNEXURE

BEFORE SHRI GANPATI SHARMA : PRESIDING  
OFFICER : CENTRAL GOVT. INDUSTRIAL  
TRIBUNAL, NEW DELHI  
I.D. No. 18/91

In the matter of dispute between :

Shri Avtar Singh, Lift Operator, as represented  
by CPWD Mazdoor Union, E-26 (Old Qtr.),  
Raja Bazar, Baba Kharak Singh Marg, New  
Delhi.

## Versus

Executive Engineer (Elect), Electrical Division  
UI, CPWD, I.P. Bhawan, New Delhi.

## APPEARANCES :

Shri Nand Lal for the workman.

None of the management.

## AWARD

The Central Government in the Ministry of Labour vide its Order No. L-42012/150/90-IR(LU) dated 18-2-91 has referred the following industrial dispute to this Tribunal for adjudication :

"Whether the action of the management of CPWD New Delhi in not regularising the services and not paying the wages to Shri Avtar Singh, Lift Operator from 15-1-1989 to 18-3-1989 is justified? If not, to what relief the workman is entitled to?"

2. The case was fixed on 51-98 and has been taken up today at the request of the representative for the workman who has stated that the matter has been settled and no dispute award may be passed. In view of the statement of the workman representative no dispute exist between the parties. I, therefore, pass a no dispute award in this case leaving the parties to bear their own costs.

2nd December, 1992.

GANPATI SHARMA, Presiding Officer

नई दिल्ली, 17 दिसम्बर, 1992

का.प्र. 81.—औद्योगिक विवाद अधिनियम, 1947 (1947 का 14) की धारा 17 के अनुसूची में, केन्द्रिय सरकार सा.पि.इ.व्यू.डी. नई दिल्ली के प्रबंधन के संबंध निरीक्षणों और उनके कर्मचारियों के बीच, अनुबंध में निविष्ट औद्योगिक विवाद में केन्द्रिय सरकार औद्योगिक अधिकरण, नई दिल्ली के पंचपट को प्रकाशित करती है, जो केन्द्रिय सरकार को 16-12-92 को प्राप्त हुआ था।

[सं. एल- 42012/136/90-आई.प्रार. डी.यू. (पीटी)]

के.बी.बी. उन्नी, डेस्क अधिकारी

New Delhi, the 17th December, 1992

S.O. 81.—In pursuance of Section 17 of the Industrial Disputes Act, 1947 (14 of 1947), the Central Government hereby publishes the award of the Central Government Industrial Tribunal, New Delhi as shown in the Annexure, in the industrial dispute between the employers in relation to the management of C.P.W. Nirman Bhawan and their workmen, which was received by the Central Government on 16-12-92.

[No. L-42012/136/90-IR(DU)(Pt.)]

K. V. B. UNNY, Desk Officer

3128 GI/92—11

## ANNEXURE

BEFORE SHRI GANPATI SHARMA : PRESIDING  
OFFICER, CENTRAL GOVT. INDUSTRIAL  
TRIBUNAL : NEW DELHI

I.D. No. 17/91

In the matter of dispute between :

Shri Madav Nand s/o Shri Khema Nand as  
represented by CPWD Mazdoor Union, E-  
26(Old Qts) Raja Bazar, Baba Kharak Singh  
Marg, New Delhi.

## Versus

Executive Engineer (Electrical) Electrical Division I, CPWD, I.P. Bhawan, New Delhi.

## APPEARANCES :

Shri Nand Lal for the workman

Shri U. M. Kalra for the Management.

## AWARD

The Central Government in the Ministry of Labour vide its order No. L-42012/136/90-I.R. (D.U.) dated 15-2-91 has referred the following industrial dispute to this Tribunal for adjudication :

"Whether the action of the management of C.P.W.D. Nirman Bhawan New Delhi in not giving wages for the period from 31-12-88 to 16-3-89 to Shri Madhav Nand, Lift Operator is justified? If not, what relief the workman is entitled to?"

2. The case was fixed for 12-1-1993 and has been taken up today at the request of the representative for the workman who has stated that the matter has been settled and no dispute award may be passed. The representative for the management Shri U. M. Kalra is also present. In view of this statement no dispute exist between the parties. I, therefore, pass a no dispute award in this case leaving the parties to bear their own costs.

2nd December, 1992.

GANPATI SHARMA, Presiding Officer

नई दिल्ली, 17 दिसम्बर, 1992

का.प्र. 82.—औद्योगिक विवाद अधिनियम, 1947 (1947 का 14) की धारा 17 के अनुसूची में, केन्द्रिय सरकार सा.पि.इ.व्यू.डी. नई दिल्ली के प्रबंधन के संबंध निरीक्षणों और उनके कर्मचारियों के बीच, अनुबंध में निविष्ट औद्योगिक विवाद में केन्द्रिय सरकार औद्योगिक अधिकरण, नई दिल्ली के पंचपट को प्रकाशित करती है, जो केन्द्रिय सरकार को 16-12-92 को प्राप्त हुआ था।

[सं. एल- 42012/ 136/90-आई.प्रार. डी.यू. (पीटी.)]

के.बी.बी. उन्नी, डेस्क अधिकारी

New Delhi, the 17th December, 1992

S.O. 82.—In pursuance of section 17 of the Industrial Disputes Act, 1947 (14 of 1947), the Central Government hereby publishes the award of the

Central Government Industrial Tribunal, New Delhi as shown in the Annexure, in the industrial dispute between the employers in relation to the management of CPWD New Delhi and their workmen, which was received by the Central Government on 16-12-92.

[No. L-42012/134/90-IR(DU) (Pt.)]

K. V. B. UNNY, Desk Officer

### ANNEXURE

BEFORE SHRI GANPATI SHARMA; PRESIDING OFFICER; CENTRAL GOVT. INDUSTRIAL TRIBUNAL; NEW DELHI

I. D. No. 16/91

In the matter of dispute between :

Shri Gudaria, Lift Operator,  
represented by CPWD Mazdoor Union,  
E-26 (Old Qtrr), Raja Bazar,  
Baba Kharak Singh Marg,  
New Delhi,

Versus

Executive Engineer (Elect),  
Vigyan Bhavan Elect. Divn.,  
CPWD, Vigyan Bhavan,  
Maulana Azad Road,  
New Delhi.

### APPEARANCES :

Shri Nand Lal for the workman.

Shri U. M. Kalra for the management.

### AWARD

The Central Government in the Ministry of Labour vide its Order No. L-42012/134/90-I.R.(D.U.) dated 15-2-91 has referred the following industrial dispute to this Tribunal for adjudication :

"Whether the action of the management of CPWD, New Delhi in not regularising the services and not paying the wages from 1-2-89 to 31-3-89 to Shri Gudaria, Lift Operator was justified? If not, to what relief the workman is entitled?"

2. This case was fixed for 5-5-93 and has been taken up at the request of the representative of the workman who has stated that the matter has been settled and no dispute award may be passed. The representative for the management Shri U. M. Kalra is also present. In view of this statement no dispute exist between the parties. I, therefore, pass a no dispute award in this case leaving the parties to bear their own costs.

2nd December, 1992.

GANPATI SHARMA, Presiding Officer

नई दिल्ली, 23 दिसम्बर, 1992

का.आ. 83--केन्द्रीय सरकार ने यह समाधान हो जाने पर कि लोक-हित में ऐसा करना प्रोत्साहित था, औद्योगिक विवाद अधिनियम, 1947 (1947 का 14) की धारा 2 के खंड (इ) के उपखंड (6) के उप-

बंधों के अनुसरण में भारत सरकार के श्रम मंत्रालय की अधिसूचना संख्या प्रा.का. 18:9 दिनांक 26 जून, 1992 द्वारा किसी भी खनिज तेल (कच्चा तेल) मोटर और विमानन स्पिरिट, डीजल तेल, मिट्टी का तेल, इंधन तेल, विविध हाइड्रोकार्बन तेल और उनके मिश्रण, जिनमें सिंथेटिक इंधन, स्टेडक तेल और इसी प्रकार के तेल शामिल हैं, के निर्माण या उत्पादन में लगे उद्योग में सेवाओं का उक्त अधिनियम के प्रयोजनों के लिए 29 जून, 1992 से छह मास की कालावधि के लिए लोक उपयोगी सेवा घोषित किया था,

और केन्द्रीय सरकार की राय है कि लोकहित में उक्त कालावधि की छह मास की और कालावधि के लिए बढ़ाया जाना प्रोत्साहित है,

अतः, अब, औद्योगिक विवाद अधिनियम, 1947 (1947 का 14) की धारा 2 के खंड (इ) के उपखंड (6) के परन्तुका द्वारा प्रवृत्त शक्तियों का प्रयोग करते हुए, केन्द्रीय सरकार उक्त उद्योग को उक्त अधिनियम के प्रयोजनों के लिए 29 दिसम्बर, 1992 से छह मास की और कालावधि के लिए लोक उपयोगी सेवा घोषित करती है।

[संख्या एस-11017/2/84-डी-1 ए.])

एस. एस. प्रशर, प्रवर सचिव

New Delhi, the 23rd December, 1992

S.O. 83.—Whereas the Central Government having been satisfied that the public interest so required had, in pursuance of the provision of sub-clause (vi) of clause (n) of section 2 of the Industrial Disputes Act, 1947 (14 of 1947), declared by the notification of the Government of India in the Ministry of Labour SO No. 1839 dated the 26th June, 1992, the industry engaged in the manufacture or production of mineral oil (crude oil, motor and aviation spirit, diesel oil, kerosene oil, fuel oil, diverse hydrocarbon oils and their blends including synthetic fuels, lubricating oils and the like, to be a public utility service for the purposes of the said Act, for a period of six months, from the 29th June, 1992;

And, whereas, the Central Government is of opinion that public interest requires the extension of the said period of six months;

Now, therefore, in exercise of the powers conferred by the proviso to sub-clause (vi) of clause (n) of section 2 of the Industrial Disputes Act, 1947 (14 of 1947), the Central Government hereby declares the said industry to be a public utility service for the purposes of the said Act, for a further period of six months from the 29th December, 1992.

[No. S-11017/2/84-D I(A)]

S. S. PRASHER, Under Secy.

नई दिल्ली, 24 दिसम्बर, 1992

का.आ. 84--कर्मचारी राज्य सेवा अधिनियम, 1948 (1948 का 54) की धारा-6 की उपधारा (3) द्वारा प्रवृत्त शक्तियों का प्रयोग करते हुए, केन्द्रीय सरकार एतद्वारा 1-1-93 को उस तारीख के रूप में नियम करती है, जिसको उक्त अधिनियम के अध्याय-4 धारा-44 और 45 के सिवाय जो पहले ही प्रवृत्त की जा चुकी है और अध्याय-5 और 6 (धारा-76) की उपधारा (1) और धारा-77, 78, 79 और 81 के

संख्या 84 में उल्लेख की जा चुकी है के उपर्युक्त राज्य प्रदेश राज्य के निम्नलिखित क्षेत्र में प्रवृत्त होंगे, अर्थात् :-

1. जिला रतलाम में रतलाम की नगरपालिका सीमाओं के अंतर्गत आने वाले क्षेत्र, उन क्षेत्रों के अतिरिक्त जहाँ उक्त प्रावधान पहले ही प्रवृत्त किये जा चुके हैं।
2. जिला उज्जैन में उज्जैन की नगरपालिका सीमाओं के अंतर्गत आने वाले क्षेत्र, उन क्षेत्रों के अतिरिक्त जहाँ उक्त प्रावधान पहले ही प्रवृत्त किये जा चुके हैं।
3. जिला सतना में सतना की नगरपालिका सीमाओं के अंतर्गत आने वाले क्षेत्र, उन क्षेत्रों के अतिरिक्त जहाँ उक्त प्रावधान पहले ही प्रवृत्त किये जा चुके हैं।

[संख्या एस-38013/20/92-एस.एस-1]

जे. पी. शुक्ला, अवर सचिव

New Delhi, the 24th December, 1992

**S.O. 84.**—In exercise of the powers conferred by sub-section (3) of Section 1 of the Employees Insurance Act, 1948 (34 of 1948) the Central Government hereby appoints the 1st January, 1993 as the

date on which the provisions of Chapter IV (except Section 44 and 45 which have already been brought into force) and Chapter V and VI (except sub-section (1) of Section 76 and Section 77, 78, 79 and 81 which have already been brought into force) of the said Act shall come into force in the following areas in the State of Madhya Pradesh namely :—

- (i) "Areas comprising of the Municipal limits of Ratlam in Distt. of Ratlam in addition to the areas in which the said provision of the Act have already been brought into force."
- (ii) "Areas comprising the Municipal limits of Ujjain in the Distt. of Ujjain in addition to the areas in which the said provision of the Act have already been brought into force."
- (iii) "Areas comprising of the Municipal limits of Satna in the Distt. of Satna in addition to the areas in which the said provision of the Act have already been brought into force."

[No. S-38013/20/92-SS.I]

J. P. SHUKLA, Under Secy.

